# Volume IV

# Pre Building Condition Survey Report

Name and Address of Structure :	Choti Chopar Station Area

Name of the Project	<b>Contract JMRC-UG1B</b> "Design and Construction of Tunnel between Chandpole and Badi Chouper and reverse line by Shield TBM, Underground Metro Stations at Choti Chouper and Badi Chouper by Cut and Cover Methods on East West Corridor of Jaipur Metro Rail Corporation Limited ."		
Owner :	JAIPUR METRO	Jaipur Metro Rail Corporation	
Contractor :	UUU	Continental Engineering Corporation	
Survey Agency :	Aimil Ltd. Instrumentation & Technologies		

#### Pre Building Condition Survey Report Choti Chopar Station Area

SI. No.	Building No.	
1	CC 0001	
2	CC 0002	
3	CC 0003	
4	CC 0004	
5	CC 0005	
6	CC 0006	
7	CC 0007	
8	CC 0008	
9	CC 0009	
10	CC 0010	
11	CC 0011	
12	CC 0013	
13	CC 0014	
14	CC 0015	
15	CC 0016	
16	CC 0017	
17	CC 0018	
18	CC 0019	
19	CC 0020	
20	CC 0021	



Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Shops Sadhu Singh Dalal Sanghori Bazaar, Choti Chopar Jaipur Unique ID: CC 0001

Report Number: AIMIL/ESG/JMCEC/CC 0001 02/01, Rev. 00, Dated: January 2014

Building Owner Contractor Various Owners CEC Client Sub-Contractor JMRC Limited AIMIL Limited







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

	Table of Contents			
S.No.	Particulars	Page No.		
1	Introduction	2		
2	Survey Details	2		
3	About the Structure	3		
4	Building Ownership Details	3		
5	Project Details	4		
6	General Building Details	4		
7	Summary of Cracks	5		
8	Summary of Defects other than Cracks			
9	Summary of Areas that Could not be surveyed			
10	Defect Photographs			
11	Schematic Diagram of Building			

Introduction

The Jaipur Metro Rail is being constructed to provide the city of Jaipur with a modern and technologically advanced Transit System, to provide a safe and well connected means of transport that reduces traffic congestion. The project consists of two corridors with underground and elevated sections.

The construction of underground rail and road infrastructures in metropolitan and cosmopolitan cities are mostly through developed area under challenging soil conditions.

The alignment of structure is passing through densely inhabitated areas, many structures are falling in the zone of influence of construction activities. It is required to carry out the pre-condition survey of those structures. The scope of work of this survey includes carrying out pre-condition survey of those structures.

	Survey Details				
S.No.	Head	Particulars	Signatures		
1	Date of Survey	16/12/2013			
2	AIMIL Representative				
3	CEC Representative				
4	Structural Designer of CEC				
5	JMRC/DMRC Representative				







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

About the Structure

The structure under consideration is a Multi Story Load Bearing Structure having 4 floors and a basement. The structure was constructed in year 1980 and is 33 years old.

There are 26 defects in the structure out of which 1 are cracks. Category wise distribution of cracks is given in the table below. Overall the Building can be categorised in Category II (Slight)

Category	Number of Cracks	% of Total Cracks
Negligible (< 0.1mm)	0	0%
Very Slight (0.1 to 1mm)	0	0%
Slight (1 to 5mm)	1	100%
Moderate (5 to 15mm)	0	0%
Severe (15 to 25mm)	0	0%
Very Severe (>25mm)	0	0%

The average width of cracks is 2mm and average length of cracks is 1.5m. The maximum crack width is 2mm and minimum width is 2mm.

	Building Ownership Details				
Unique ID/Sub ID	Premises Name	Owner	Signatures		
CC/0001/17					
CC/0001/2					
CC/0001/19					
CC/0001/20					
CC/0001/33					
CC/0001/34					
CC/0001/35					
CC/0001/3					
CC/0001/4					
CC/0001/5					







Project Details				
S. No.	Head	Particulars		
1	Project	Jaipur Metro Rail Project		
2	Section	Chandpole to Bari Chaupar		
3	Client	JMRC Limited		
4	Consultant	DMRC Limited		
5	Contractor	CEC		
6	Design Consultant of Contractor	Omikron Kappa - Indus Consultrans JV		
7	Sub-Contractor	AIMIL Limited		
8	Subject	Pre-Condition Survey Report		

General Building Details (As informed verbally by Building Owner)				
S. No.	Head	Particulars		
1	Building Name	Shops		
2	Building Address	Shops Sadhu Singh Dalal Sanghori Bazaar, Choti Chopar Jaipur		
3	Year of Construction	1980		
4	Number of Floors	B+G+3		
5	Number of Basements	None		
6	Type of Building	Residence		
7	Approximate Height	12 m		
8	Approximate Area	Not Known		
9	Age of Building	33 years		
10	Type of Structure	Load Bearing Structure		
11	Type of Foundation	Not Known		
12	Number of Bore Wells	None		
13	Depth and Diameter of Bore	N.A		
14	Roadways	One Side		
15	Presence of Equipment/Machines	None		







	Summary of Cracks					
Defect ID     Location     Orientation     Appx. Width (mm)     Appx. Length (m)     Category     Photo No.						
1	Roof Varanda of Shop No.767 Ground Floor	Horizontal	2	1.5	Slight	52

	Summary of Defect	ts Other Than Crack	
Defect ID	Location	Description	Photo No
2	Roof Shop Luxmi Agency Ground Floor	Dampness/Seepage	53
3	Roof Shop Baba Ashish Treaders M/S/F	Dampness/Seepage	54
4	Roof Shop Shree Sarvanand General Store M/S/F	Dampness/Seepage	55
5	Wall No. 4 Shop Lucky Treading Co. Ground Floor	Dampness/Seepage	56
6	Wall No. 2 Shop Amar Treaders M/S/F	Peeling of Plaster	57
7	Roof Shop Amar Treaders M/S/F	Peeling of Plaster	58
8	Wall No. 2 Shop J.K. Company M/S/F	Peeling of Plaster	59
9	Roof Shop Second Floor	Peeling of Plaster	60
10	Wall No. 1 & Roof Shop Second Floor	Dampness/Seepage	61
11	Wall No. 3 & Roof Shop Second Floor	Dampness/Seepage	62
12	Wall No. 4 Shop No.1 Second Floor	Dampness/Seepage	63
13	Roof Shop No.6 Second Floor	Dampness/Seepage	64
14	Wall No. 4 Shop No.8 Second Floor	Dampness/Seepage	65
15	Roof Varanda of Shop No.770 Ground Floor	Dampness/Seepage	66
16	Right Side External Column Varanda of Shop No.769 Ground Floor	Damaged Portion	67
17	Right Side External Column Varanda of Shop No.767 Ground Floor	Peeling of Plaster	68
18	Left Side External Column Varanda of Shop No.767 Ground Floor	Peeling of Plaster	69
19	Roof Varanda of Shop No.767 Ground Floor	Peeling of Plaster	70
20	Roof Varanda of Shop No.767 Ground Floor	Dampness/Seepage	71
21	Roof Shop No.768 Ground Floor	Dampness/Seepage	72
22	Wall No. 3 & Roof Shop No.768 Ground Floor	Dampness/Seepage	73
23	Roof Room No. 1 Shop No.767, Basement	Peeling of Plaster	74
24	Roof & Wall No. 2 Room No. 2 Shop No.767, Basement	Peeling of Plaster	75
25	Right Side External Column Varanda of Shop No.766 Ground Floor	Peeling of Plaster	76
26	Wall No. 4 Part A of Shop No.765 Ground Floor	Peeling of Plaster	77

	Summary of Areas that Could not be Surveyed				
Serial No.	No. Location Description		Photo No.		
1	Wall No. 1 & 2 Shop Rani Bangels Ground Floor	Covered With Material & Wooden Works	78		
2	Roof Shop Rani Bangels Ground Floor	Covered With Wooden Work	79		
3	Wall No. 1 Shop Rani Bangels M/S/F	Covered With Material	80		
4	Wall No. 2 Shop Rani Bangels M/S/F	Covered With Material	81		
5	Wall No. 3 Shop Rani Bangels M/S/F	Covered With Material	82		
6	All Walls Shop Luxmi Agency Ground Floor	Covered With Material	83		
7	Wall No. 1 & 4 Shop No.35 & 36 Ground Floor	Covered With Material	84		
8	Wall No. 2 & 4 Shop No.35 & 36 Ground Floor	Covered With Material	85		

9	Wall No. 3 Shop No.35 & 36 Ground Floor	Covered With Material	86
10	Wall No. 1 Shop No.35 & 36 Ground Floor	Covered With Material	87
11	Wall No. 4 Shop No.35 & 36 Ground Floor	Covered With Material	88
12	Wall No. 2 Shop No.35 & 36 Ground Floor	Covered With Material	89
13	Wall No. 3 Shop No.35 & 36 Ground Floor	Covered With Material	90
14	All Walls Shop No.20 Ground Floor	Covered With Material	91
15	All Walls Shop No.19 Ground Floor	Covered With Material	92
16	All Walls Shop No.16 Ground Floor	Covered With Material	93
17	All Walls Shop No.18 Ground Floor	Covered With Material & Glass Work	94
18	Wall No. 2 Shop No.18 M/S/F	Covered With Material	95
19	Shop No.17 Ground Floor	Locked	96
20	All Walls Part A of Shop Baba Ashish Treaders Ground Floor	CoveredWith Material	97
21	All Walls Part D of Shop Baba Ashish Treaders Ground Floor	CoveredWith Material	98
22	All Walls Shop Baba Ashish Treaders M/S/F	CoveredWith Material	99
23	All Walls Shop shree shyam Treaders Ground Floor	CoveredWith Material	100
24	Wall No. 4 Shop shree shyam Treaders M/S/F	CoveredWith Material	101
25	All Walls Shop Shree Sarvanand General Store Ground Floor	CoveredWith Material	102
26	All Walls Shop Shree Sarvanand General Store M/S/F	CoveredWith Material	103
27	All Walls Shop Vedanth Treaders Ground Floor	Covered With Material	104
28	Roof Shop Vedanth Treaders Ground Floor	Covered With Wooden Work	105
29	Shop Sai Baba Confectionery	Locked	106
30	All Walls Shop Manav treaders Ground Floor	Covered With Material	107
31	All Walls Shop Pankaj Treaders Ground Floor	Covered With Material	108
32	Roof Shop Pankaj Treaders Ground Floor	Covered With Wooden Work	109
33	Shop Rani Bangels Ground Floor	Locked	110
34	All Walls Shop Sabbir Bangels Ground Floor	Covered With Material	111
35	Roof Shop Sabbir Bangels Ground Floor	Covered With Wooden Work	112
36	Shop Tanwar Udyog Ground Floor	Locked	113
37	Tanwar Udyog Ground Floor	Locked	114
38	All Walls Shop Bharat Stationers Ground Floor	Covered With Material	115
39	All Walls Shop Ajay Treaders Ground Floor	Covered With Material	116
40	All Walls Shop Lucky Treading Co. Ground Floor	Covered With Material	117
41	All Walls Shop Lucky Treading Co. Ground Floor	Covered With Material	118
42	All Walls Shop Guru Kripa Ground Floor	Covered With Material	119
43	Shop Ground Floor	Locked	120
44	Wall No. 1 & 3 Shop Shree Hardware House Ground Floor	Covered With Material & Wooden Work	121
45	Wall No. 4 Shop Shree Hardware House Ground Floor	Covered With Material & Wooden Work	122
46	All Walls Shop Khandelwal Thaili Bhandar Ground Floor	Covered With Material & Wooden Work	123
47	All Walls Shop Khandelwal Thaili Bhandar M/S/F	Covered With Material & Wooden Work	124
48	All Walls Shop Mahesh Tube Co. Ground Floor	Covered With Material & Wooden Work	125
49	All Walls Shop Amar Treaders Ground Floor	Covered With Material	126
50	All Walls Shop Amar Treaders M/S/F	Covered With Material	127
51	Wall No. 4 Shop J.K. Company M/S/F	Covered With Wooden Work	128
52	Shop J.K. Company M/S/F	View of Wooden Partition	129
53	All Walls Part A of Shop No.11 First Floor	Covered With Material	130
54	All Walls Part B of Shop No.11 First Floor	Covered With Material	131
55	Shop No.6 First Floor	Locked	132
56	All Walls Shop No.12 First Floor	Covered With Material	133
57	All Walls Shop No.4 First Floor	Covered With Material	134

59	All Walls Shop Second Floor	Covered With Material	136
60	Shop No.14 Second Floor	Locked	137
61	Shop No.3 Second Floor	Locked	138
62	Shop No.2 Second Floor	Locked	139
63	Shop No.1 Second Floor	Locked	140
64	Bathroom Shop No.1, Second Floor	Covered With Tile	141
65	Toilet No. 1 Shop No.1, Second Floor	Covered With Tile	142
66	Toilet No. 2 Shop No.1, Second Floor	Covered With Tile	143
67	Wall No. 2 Shop No.1 Second Floor	Covered With Material	144
68	Wall No. 2 Shop No.2 Second Floor	Covered With Material	145
69	Wall No. 1 & 2 Shop No.4 Second Floor	Covered With Material	146
70	Wall No. 1 & 4 Shop No.5 Second Floor	Covered With Material	147
71	Wall No. 1, 2 & 4 Shop No.6 Second Floor	Covered With Material	148
72	Wall No. 1 & 4 Shop No.8 Second Floor	Covered With Material	149
73	Wall No. 1, 2 & 4 Shop No.9 Second Floor	Covered With Material	150
74	Shop No.10 Second Floor	Locked	151
75	Shop No.12 Second Floor	Locked	152
76	Shop No.13 Second Floor	Locked	153
77	Shop No.14 Second Floor	Locked	154
78	Bathroom Shop No.14, Second Floor	Half Covered with tiles	155
79	Toilet No. 1 Shop No.14, Second Floor	Half Covered with tiles	156
80	Toilet No. 2 & 3 Shop No.14, Second Floor	Locked	157
81	All Walls Shop No.770 Upper Ground Floor	Covered With Material	158
82	Wall No. 1 Shop No.769 Ground Floor	Covered With Material	159
83	Wall No. 2 Shop No.769 Ground Floor	Covered With Material	160
84	Roof Shop No.769 Ground Floor	Covered With Falls Celling	161
85	Shop No.769 Basement	No Way To Enterance	162
86	Wall No. 1, 2 & 4 Shop No.767 Ground Floor	Covered With Material	163
87	Wall No. 1 & 4 Shop No.768 Ground Floor	Covered With Material	164
88	Wall No. 1, 2 & 3 Room No. 1 Shop No.767, Basement	Covered With Material	165
89	All Walls Bathroom Shop No.767, Basement	Covered With Tiles	166
90	All Walls Shop No.766 Lower Ground Floor	Covered With Material	167
91	All Walls Shop No.766 Upper Ground Floor	Covered With Material	168
92	Wall No. 1 Part B of Shop No.765 Ground Floor	Covered With Material	169
93	Wall No. 1, 2 & 4 Shop No.764 Ground Floor	Covered With Material	170
94	Wall No. 1 & 2 Shop No.765 Ground Floor	Covered With Material	171







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Photo 1 View of Shop No.770



Photo 2 View of Shop Rani Bangels, Ground Floor



Photo 3 View of Shop Luxmi Agency, Ground Floor



Photo 5 Ground Floor





Photo 4 Ground Floor



Photo 6 Ground Floor







Photo 7 View of Shop No.20, Ground Floor



Photo 8 View of Shop No.19, Ground Floor



Photo 9 View of shop no.16, Ground Floor



Photo 11 View of Baba Ashish Traders, Ground Floor





Photo 10 View of Shop No.18, Ground Floor



Photo 12 View of Shop shree Shyam Traders, Ground Floor







Photo 13 View of Sarvanand General store, Ground Floor



Photo 14 View of Shop Vedanth Traders, Ground Floor



Photo 15 View of Shop Manav Traders, Ground Floor



Photo 17 View of Shop Sabbir Bangels, Ground Floor





Photo 16 View of Shop Pankaj Traders, Ground Floor



Photo 18 View of Shop Bharat Stationers, Ground Floor







Photo 19 View of Shop Ajay Treaders, Ground Floor



Photo 20 view of Shop lucky Treading Co, Ground Floor



Photo 21 View of Shop Guru Kripa, Ground Floor



Photo 23 View of Shop Khandelwal thaili Bhandar, Ground Floor





Photo 22 View of Shop Shree Hardware House, Ground Floor



Photo 24 View of Shop Mahesh Tube Co., Ground Floor







Photo 25 View of Shop Amar Treaders, Ground Floor



Photo 26 View of shop J.K.Company, Ground Floor



Photo 27 View of Shop No.11, First Floor



Photo 28 View of Shop No.12, First Floor



Photo 29 View of Shop No.4, First Floor





Photo 30 View of Shop No.13, First Floor







Photo 31 View of Shop No.1, Second Floor



Photo 32 View of Shop No.2, Second Floor



Photo 33 View of Shop No.3, Second Floor



Photo 34 View of Shop No.4, Second Floor



Photo 35 View of Shop No.5, Second Floor





Photo 36 View of Shop No.6, Second Floor







Photo 37 View of Shop No.7, Second Floor



Photo 38 View of Shop No.8, Second Floor



Photo 39 View of Shop No.9, Second Floor



Photo 40 View of Terrace, Shop No.14, Second Floor



Photo 41 View of Terrace, Shop No.14, Second Floor





Photo 42 Side view of building, Shop No.14, Second Floor







Photo 43 View of Building, Shop No.14, Second Floor




Photo 44 View of Building, Shop No.14, Second Floor



Photo 45 View of Shop No.769, Ground Floor



Photo 47 View of Shop No.766, Ground Floor





Photo 46 View of Shop No.767, Ground Floor



Photo 48 View of Shop No.765, Ground Floor







Photo 49 View of Shop Uppper Ground Floor, Upper Ground Floor



Photo 50 View of Shop No.764, Ground Floor



.

Photo 51 View of Shop No.765, Ground Floor






Photo 53
Dampness/Seepage on Roof of Shop Luxmi Agency of Ground Floor Dampr



Photo 54 Dampness/Seepage on Roof of Shop Baba Ashish Treaders of M/S/F







Photo 55 Dampness/Seepage on Roof of Shop Shree Sarvanand General Store of M/S/F



Photo 56 Dampness/Seepage on Wall No. 4 of Shop Lucky Treading Co. of Ground Floor





Photo 57 Peeling of Plaster on Wall No. 2 of Shop Amar Treaders of M/S/F



Photo 59 Peeling of Plaster on Wall No. 2 of Shop J.K. Company of M/S/F



Photo 58 Peeling of Plaster on Roof of Shop Amar Treaders of M/S/F



Photo 60 Peeling of Plaster on Roof of Shop of Second Floor











Photo 61 Dampness/Seepage on Wall No. 1 & Roof of Shop of Second Floor

Photo 62 Dampness/Seepage on Wall No. 3 & Roof of Shop of Second Floor





Photo 63 Dampness/Seepage on Wall No. 4 of Shop No.1 of Second Floor

Photo 64 Dampness/Seepage on Roof of Shop No.6 of Second Floor



Photo 65 Dampness/Seepage on Wall No. 4 of Shop No.8 of Second Floor



Photo 66 Dampness/Seepage on Roof of Varanda of Shop No.770 of Ground Floor









Photo 67 Damaged Portion on Right Side External Column of Varanda of Shop No.769 of Ground Floor



Photo 68 Peeling of Plaster on Right Side External Column of Varanda of Shop No.767 of Ground Floor





Photo 69 Peeling of Plaster on Wall No. Leftside External Column of Varanda of Shop No.767 of Ground Floor





Photo 71 Dampness/Seepage on Roof of Varanda of Shop No.767 of Ground Floor



Photo 72 Dampness/Seepage on Roof of Shop No.768 of Ground Floor









Photo 73 Dampness/Seepage on Wall No. 3 & Roof of Shop No.768 of Ground Floor



Photo 74 Peeling of Plaster on Roof of Room No. 1 of Shop No.767, Basement





Photo 75 Peeling of Plaster on Roof & Wall No. 2 of Room No. 2 of Shop No.767, Peeling of Plaster on Right Side External Column of Varanda of Shop Basement

Photo 76 No.766 of Ground Floor



Photo 77 Peeling of Plaster on Wall No. 4 of Part A of Shop No.765 of Ground Floor












Photo 79 Roof of Shop Rani Bangels of Ground Floor Covered With Wooden Work



Photo 80 Wall No. 1 of Shop Rani Bangels of M/S/F Covered With Material





Photo 81 Wall No. 2 of Shop Rani Bangels of M/S/F Covered With Material



Photo 83 All Walls of Shop Luxmi Agency of Ground Floor Covered With Material



Photo 84 Wall No. 1 & 4 of Shop No.35 & 36 of Ground Floor Covered With Material







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Photo 85 Wall No. 2 & 4 of Shop No.35 & 36 of Ground Floor Covered With Material



Photo 86 Wall No. 3 of Shop No.35 & 36 of Ground Floor Covered With Material





Photo 87

<u>Photo 8</u>8 Wall No. 1 of Shop No.35 & 36 of Ground Floor Covered With Material Wall No. 4 of Shop No.35 & 36 of Ground Floor Covered With Material





Photo 90

<u>Photo 8</u>9 Wall No. 2 of Shop No.35 & 36 of Ground Floor Covered With Material Wall No. 3 of Shop No.35 & 36 of Ground Floor Covered With Material












Photo 91 All Walls of Shop No.20 of Ground Floor Covered With Material

Photo 92 All Walls of Shop No.19 of Ground Floor Covered With Material





Photo 93 All Walls of Shop No.16 of Ground Floor Covered With Material



Photo 95 Wall No. 2 of Shop No.18 of M/S/F Covered With Material



Photo 94 All Walls of Shop No.18 of Ground Floor Covered With Material & Glass Work



Photo 96 Shop No.17 of Ground Floor Locked







Photo 97 All Walls of Part A of Shop Baba Ashish Traders of Ground Floor CoveredWith Material



Photo 98 All Walls of Part D of Shop Baba Ashish Traders of Ground Floor CoveredWith Material





Photo 99 All Walls of Shop Baba Ashish Traders of M/S/F CoveredWith Material

Photo 100 All Walls of Shop shree shyam Traders of Ground Floor CoveredWith Material



Photo 101 Wall No. 4 of Shop shree shyam Traders of M/S/F CoveredWith Material












Photo 103 All Walls of Shop Shree Sarvanand General Store of M/S/F CoveredWith Material



Photo 104 All Walls of Shop Vedanth Traders of Ground Floor Covered With Material





Photo 105 Roof of Shop Vedanth Treaders of Ground Floor Covered With Wooden Work

Photo 106 Shop Sai Baba Confectionery of Locked



Photo 107 All Walls of Shop Manav traders of Ground Floor Covered With Material



Photo 108 All Walls of Shop Pankaj Traders of Ground Floor Covered With Material









Photo 109 Roof of Shop Pankaj Treaders of Ground Floor Covered With Wooden Work



Photo 110 Shop Rani Bangels of Ground Floor Locked







Photo 11 All Walls of Shop Sabbir Bangels of Ground Floor Covered With Material



Photo 113 Shop Tanwar Udyog of Ground Floor Locked



Photo 112 Roof of Shop Sabbir Bangels of Ground Floor Covered With Wooden Work



Photo 114 Tanwar Udyog of Ground Floor Locked







Photo 115 All Walls of Shop Bharat Stationers of Ground Floor Covered With Material



Photo 116 All Walls of Shop Ajay Treaders of Ground Floor Covered With Material





Photo 117 All Walls of Shop Lucky Treading Co. of Ground Floor Covered With Material





Photo 119 All Walls of Shop Guru Kripa of Ground Floor Covered With Material



Photo 120 Shop of Ground Floor Locked









Photo 121 Wall No. 1 & 3 of Shop Shree Hardware House of Ground Floor Covered With Material & Wooden Work



Photo 122 Wall No. 4 of Shop Shree Hardware House of Ground Floor Covered With Material & Wooden Work





Photo 123 All Walls of Shop Khandelwal Thaili Bhandar of Ground Floor Covered With Material & Wooden Work

Photo 124 All Walls of Shop Khandelwal Thaili Bhandar of M/S/F Covered With Material & Wooden Work



Photo 125 All Walls of Shop Mahesh Tube Co. of Ground Floor Covered With Material & Wooden Work



Photo 126 All Walls of Shop Amar Treaders of Ground Floor Covered With Material











Photo 127 All Walls of Shop Amar Treaders of M/S/F Covered With Material

Photo 128 Wall No. 4 of Shop J.K. Company of M/S/F Covered With Wooden Work





Photo 129 Shop J.K. Company of M/S/F View of Wooden Partition

Photo 130 All Walls of Part A of Shop No.11 of First Floor Covered With Material



Photo 131 All Walls of Part B of Shop No.11 of First Floor Covered With Material












Photo 133 All Walls of Shop No.12 of First Floor Covered With Material



Photo 134 All Walls of Shop No.4 of First Floor Covered With Material



Photo 135 All Walls of Shop No.13 of First Floor Covered With Material



Photo 137 Shop No.14 of Second Floor Locked





Photo 136 All Walls of Shop of Second Floor Covered With Material



Photo 138 Shop No.3 of Second Floor Locked







Photo 139 Shop No.2 of Second Floor Locked



Photo 140 Shop No.1 of Second Floor Locked



Photo 141 Bathroom of Shop No.1, Second Floor Covered With Tile



Photo 143 Toilet No. 2 of Shop No.1, Second Floor Covered With Tiles





Photo 142 Toilet No. 1 of Shop No.1, Second Floor Covered With Tile



Photo 144 Wall No. 2 of Shop No.1 of Second Floor Covered With Material









Photo 145 Wall No. 2 of Shop No.2 of Second Floor Covered With Material

Photo 146 Wall No. 1 & 2 of Shop No.4 of Second Floor Covered With Material





Photo 147 Wall No. 1 & 4 of Shop No.5 of Second Floor Covered With Material

Photo 148 Wall No. 1, 2 & 4 of Shop No.6 of Second Floor Covered With Material



Photo 149 Wall No. 1 & 4 of Shop No.8 of Second Floor Covered With Material












Photo 151 Shop No.10 of Second Floor Locked



Photo 152 Shop No.12 of Second Floor Locked



Photo 153 Shop No.13 of Second Floor Locked



Photo 154 Shop No.14 of Second Floor Locked



Photo 155 Bathroom No. of Shop No.14, Second Floor Half Covered with tiles



Photo 156 Toilet No. 1 of Shop No.14, Second Floor Half Covered with tiles









Photo 157 Toilet No. 2 & 3 of Shop No.14, Second Floor Locked



Photo 158 All Walls of Shop No.770 of Upper Ground Floor Covered With Material





Photo 159 Wall No. 1 of Shop No.769 of Ground Floor Covered With Material

Photo 160 Wall No. 2 of Shop No.769 of Ground Floor Covered With Material



Photo 161 Roof of Shop No.769 of Ground Floor Covered With False Celling



Photo 162 Shop No.769 of Basement Way To Entrance









Photo 163 Wall No. 1, 2 & 4 of Shop No.767 of Ground Floor Covered With Material



Photo 164 Wall No. 1 & 4 of Shop No.768 of Ground Floor Covered With Material



Photo 165 Wall No. 1, 2 & 3 of Room No. 1 of Shop No.767, Basement Covered With Material







Photo 167 Photo 168
All Walls of Shop No.766 of Lower Ground Floor Covered With Material All Walls of Shop No.766 of Upper Ground Floor Covered With Material









Photo 169 Wall No. 1 of Part B of Shop No.765 of Ground Floor Covered With Material




Photo 170 Wall No. 1, 2 & 4 of Shop No.764 of Ground Floor Covered With Material



Photo 171 Wall No. 1 & 2 of Shop No.765 of Ground Floor Covered With Material



Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



House No. 761 Sadhu Singh Dalal Sanghori Bazaar, Choti Chopar Jaipur Unique ID: CC 0001

Report Number: AIMIL/ESG/JMCEC/CC 0001/01, Rev. 00, Dated: December 2013

Building Owner Contractor Mr. Babu Khan Mansuri CEC Client Sub-Contractor JMRC Limited AIMIL Limited







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

	Table of Contents			
S.No.	Particulars	Page No.		
1	Introduction	2		
2	Survey Details	2		
3	About the Structure	3		
4	Building Ownership Details	3		
5	Project Details	4		
6	General Building Details	4		
7	Summary of Cracks	5		
8	Summary of Defects other than Cracks			
9	Summary of Areas that Could not be surveyed			
10	Defect Photographs			
11	Schematic Diagram of Building			

Introduction

The Jaipur Metro Rail is being constructed to provide the city of Jaipur with a modern and technologically advanced Transit System, to provide a safe and well connected means of transport that reduces traffic congestion. The project consists of two corridors with underground and elevated sections.

The construction of underground rail and road infrastructures in metropolitan and cosmopolitan cities are mostly through developed area under challenging soil conditions.

The alignment of structure is passing through densely inhabitated areas, many structures are falling in the zone of influence of construction activities. It is required to carry out the pre-condition survey of those structures. The scope of work of this survey includes carrying out pre-condition survey of those structures.

	Survey Details				
S.No.	Head	Particulars	Signatures		
1	Date of Survey	22/12/2013			
2	AIMIL Representative				
3	CEC Representative				
4	Structural Designer of CEC				
5	JMRC/DMRC Representative				







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

About the Structure

The structure under consideration is a Multi Story Load Bearing Structure having 4 floors. The structure was constructed in year 1980 and is 33 years old.

There are 79 defects in the structure out of which 16 are cracks. Category wise distribution of cracks is given in the table below. Overall the Building can be categorised in Category II (Slight)

Category	Number of Cracks	% of Total Cracks
Negligible (< 0.1mm)	0	0%
Very Slight (0.1 to 1mm)	7	43.75%
Slight (1 to 5mm)	9	56.25%
Moderate (5 to 15mm)	0	0%
Severe (15 to 25mm)	0	0%
Very Severe (>25mm)	0	0%

The average width of cracks is 1.42mm and average length of cracks is 1.92m. The maximum crack width is 4mm and minimum width is 0.35mm.

Building Ownership Details				
Unique ID/Sub ID	Premises Name	Owner	Signatures	
CC 0001-FF-SF-TF	House No 761			







Project Details			
S. No.	Head	Particulars	
1	Project	Jaipur Metro Rail Project	
2	Section	Chandpole to Bari Chaupar	
3	Client	JMRC Limited	
4	Consultant	DMRC Limited	
5	Contractor	CEC	
6	Design Consultant of Contractor	Omikron Kappa - Indus Consultrans JV	
7	Sub-Contractor	AIMIL Limited	
8	Subject	Pre-Condition Survey Report	

General Bui	Iding Details (As informed verbally by Building C	Owner)
S. No.	Head	Particulars
1	Building Name	House No. 761
2	Building Address	House No. 761 Saonu Singn Dalai Sangnori Bazaar, Choti Chopar
3	Year of Construction	1980
4	Number of Floors	G+3
5	Number of Basements	None
6	Type of Building	Residence
7	Approximate Height	12 m
8	Approximate Area	Not Known
9	Age of Building	33 years
10	Type of Structure	Load Bearing Structure
11	Type of Foundation	Not Known
12	Number of Bore Wells	None
13	Depth and Diameter of Bore	N.A
14	Roadways	One Side
15	Presence of Equipment/Machines	None







	S	ummary of Cracks				
Defect ID	Location	Orientation	Appx. Width (mm)	Appx. Length (m)	Category	Photo No.
1	Wall No. 5 Hall No. 2 First Floor	Inclined	0.8	1.2	Very Slight	2
2	Wall No. 5 Hall No. 2 First Floor	Horizontal	0.5	1.2	Very Slight	3
3	Wall No. 6 Hall No. 2 First Floor	Inclined	3	2	Slight	4
4	Wall No. 2 Open Sky No.1 First Floor	Inclined	4	4	Slight	5
5	Wall No. 3 Hall No. 5 First Floor	Inclined	0.4	1.1	Very Slight	6
6	Roof Lobby First Floor	Horizontal	0.8	2.3	Very Slight	7
7	Wall No. 1 Varanda First Floor	Inclined	1	2	Slight	8
8	Roof Varanda First Floor	Horizontal	0.35	1.2	Very Slight	9
9	Wall No. 3, Roof & 4 Varanda First Floor	Inclined	3	4	Slight	10, 10A
10	Wall No. 1 Open Sky No.2 First Floor	Inclined	1.5	2.5	Slight	11, 11A
11	Wall No. 4 Passage No.1 Second Floor	Inclined	1	0.3	Slight	12
12	Wall No. 1 Open Sky Second Floor	Horizontal	1	1.5	Slight	13
13	Wall No. 3 Open Sky Second Floor	Horizontal	0.5	1	Very Slight	14
14	Wall No. 3 Open Sky Second Floor	Inclined	0.8	1.5	Very Slight	15
15	Wall No. 2 Open Sky Second Floor	Horizontal	1.5	2	Slight	16
16	Second Floor	Horizontal	2.5	3	Slight	17, 17A

	Summary of I	Defects Other Than Crack	
Defect ID	Location	Description	Photo No
17	Wall No. 4 & Roof Room No. 1 First Floor	Dampness/Seepage	18
18	Wall No. 1 Room No. 1 First Floor	Peeling of Plaster	19
19	Wall No. 2 & Roof Room No. 1 First Floor	Dampness/Seepage	20
20	Wall No. 1 & 5 Hall No. 2 First Floor	Peeling of Plaster	21
21	Wall No. 5 Hall No. 2 First Floor	Peeling of Plaster	22
22	Wall No. 2 Hall No. 2 First Floor	Peeling of Plaster	23
23	Roof Hall No. 2 First Floor	Dampness/Seepage	24
24	Wall No. 5 Hall No. 2 First Floor	Peeling of Plaster	25
25	Wall No. 4 Hall No. 2 First Floor	Peeling of Plaster	26
26	Wall No. 2 Open Sky No.1 First Floor	Exposed Reinforcement	27
27	Wall No. 2 Open Sky No.1 First Floor	Exposed Reinforcement	28
28	Wall No. 2 Open Sky No.1 First Floor	Peeling of Plaster	29
29	Wall No. 4 Open Sky No.1 First Floor	Peeling of Plaster	30
30	Wall No. 3 Passage No.1 First Floor	Peeling of Plaster	31
31	Wall No. 4 Kitchen No.1 First Floor	Peeling of Plaster	32
32	Wall No. 1 Kitchen No.1 First Floor	Peeling of Plaster	33
33	Wall No. 3 Hall No. 4 First Floor	Peeling of Plaster	34
34	Wall No. 3 Hall No. 4 First Floor	Peeling of Plaster	35
35	Wall No. 1 Hall No. 4 First Floor	Peeling of Plaster	36
36	Roof Hall No. 4 First Floor	Peeling of Plaster	37
37	Wall No. 2 Hall No. 4 First Floor	Peeling of Plaster	38
38	Wall No. 1 Toilet & Bathroom No.1 First Floor	Dampness/Seepage	39
39	Wall No. 4 Toilet & Bathroom No.1 First Floor	Dampness/Seepage	40
40	Wall No. 2 Toilet & Bathroom No.1 First Floor	Dampness/Seepage	41

41	Wall No. 3 Hall No. 6 First Floor	Peeling of Plaster	42
42	Wall No. 1 & 4 Toilet & Washroom No.2 First Floor	Dampness/Seepage	43
43	Wall No. 4 & Roof Toilet & Washroom No.2 First Floor	Dampness/Seepage	44
44	Wall No. 1 Lobby First Floor	Peeling of Plaster	45
45	Wall No. 1 Varanda First Floor	Peeling of Plaster	46
46	Wall No. 3 Varanda First Floor	Peeling of Plaster	47
47	Wall No. 1 Open Sky No.2 First Floor	Peeling of Plaster	48
48	Wall No. 2 & Roof Open Sky No.2 First Floor	Peeling of Plaster	49
49	Wall No. 3 Open Sky No.2 First Floor	Peeling of Plaster	50
50	Wall No. 4 & Roof Bathroom Second Floor	Dampness/Seepage	51
51	Wall No. 1 Bathroom Second Floor	Peeling of Plaster	52
52	Roof Toilet No. 1 Second Floor	Dampness/Seepage	53
53	Wall No. 1 Passage No.1 Second Floor	Peeling of Plaster	54
54	Wall No. 1 & Shade Open Sky Second Floor	Dampness/Seepage	55
55	Wall No. 4 & Roof Open Sky Second Floor	Dampness/Seepage	56
56	Roof Varanda Second Floor	Peeling of Plaster	57
57	Wall No. 2 Varanda Second Floor	Peeling of Plaster	58
58	Wall No. 4 Varanda Second Floor	Peeling of Plaster	59
59	Wall No. 1 Varanda Second Floor	Peeling of Plaster	60
60	Wall No. 3 Varanda Second Floor	Peeling of Plaster	61
61	Wall No. 4 Toilet No. 2 Second Floor	Peeling of Plaster	62
62	Wall No. 4 Hall No. 1 Second Floor	Dampness/Seepage	63
63	Roof Kitchen No.2 Second Floor	Peeling of Plaster	64
64	Wall No. 4 Kitchen No.2 Second Floor	Peeling of Plaster	65
65	Roof Kitchen No.2 Second Floor	Peeling of Plaster	66
66	Wall No. 1 Kitchen No.2 Second Floor	Peeling of Plaster	67
67	Wall No. 3 Kitchen No.2 Second Floor	Peeling of Plaster	68
68	Roof Kitchen No.1 Second Floor	Peeling of Plaster	69
69	Hall No. 3 Second Floor	Peeling of Plaster	70
70	Passage Second Floor	Peeling of Plaster	71
71	Wall No. 1 Staircase SF to TF	Peeling of Plaster	72
72	Wall No. 1 Staircase SF to TF	Peeling of Plaster	73
73	Wall No. 1 Terrace	Peeling of Plaster	74
74	Wall No. 4 Terrace	Dampness/Seepage	75
75	Floor Terrace	Dampness/Seepage	76
76	Wall No. 2, 4 & Roof Toilet & Washroom Terrace	Dampness/Seepage	77
77	Wall No. 1, 4 & Roof Hall No. 1 Terrace	Dampness/Seepage	78
78	Wall No. 4 Parapet Terrace	Dampness/Seepage	79
79	Wall No. 1 Parapet Terrace	Peeling of Plaster	80

	Summary of Areas that Could not be Surveyed				
Serial No.	Location	Description	Photo No.		
1	Hall No. 1 First Floor	Locked	81		
2	Hall No. 1 First Floor	Locked	82		
3	Hall No. 3 First Floor	Locked	83		
4	Kitchen No.2 First Floor	Locked	84		
5	Hall No. 1 First Floor	Locked	85		
6	Wall No. 2 Kitchen No.1 Second Floor	Locked	86		
7	Wall No. 1 Kitchen No.1 Second Floor		87		









Instrumentation & Technologies

#### **Jaipur Metro Rail Corporation**

Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



#### Photo 1 View of Shop



Photo 3 Horizontal Crack on Wall No. 5 of Hall No. 2, First Floor Approx. Width = 0.5mm, Approx. Length = 1.2m. Distance from Wall No.6 = 3m, Height from Floor = 2.5m.



Photo 5 Inclined Crack on Wall No. 2 of Open Sky No.1, First Floor Approx. Width = 4mm, Approx. Length = 4m. Distance from Wall No.4 = 1.8m, Height from Floor = 0m.





Photo 2 Inclined Crack on Wall No. 5 of Hall No. 2, First Floor Approx. Width = 0.8mm, Approx. Length = 1.2m. Distance from Wall No.6 = 4.5m, Height from Floor = 2.5m.



Photo 4 Inclined Crack on Wall No. 6 of Hall No. 2, First Floor Approx. Width = 3mm, Approx. Length = 2m. Distance from Wall No.4 = 0.15m, Height from Floor = 2.1m.



Photo 6 Inclined Crack on Wall No. 3 of Hall No. 5, First Floor Approx. Width = 0.4mm, Approx. Length = 1.1m. Distance from Wall no.2 = 1m, Height from Floor = 2m.





Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Photo 7 Horizontal Crack on Roof of Lobby, First Floor Approx. Width = 0.8mm, Approx. Length = 2.3m. Distance from Wall No.1 = 0.15m, Height from Floor = 2.7m.



Photo 9 Horizontal Crack on Roof of Varanda, First Floor Approx. Width = 0.35mm, Approx. Length = 1.2m. Distance from Wall No.1 = 0.2m, Height from Floor = 2.3m.



Photo 10A Inclined Crack on Wall No. 3,4 & Roof of Varanda, First Floor Approx. Width = 3mm, Approx. Length = 4m. Distance from Wall no.2 = 1.4m, Height from Floor = 2.1m.





Photo 8 Inclined Crack on Wall No. 1 of Varanda, First Floor Approx. Width = 1mm, Approx. Length = 2m. Distance from Wall No.2 = 0.4m, Height from Floor = 1.2m.



Photo 10 Inclined Crack on Wall No. 3,4 & Roof of Varanda, First Floor Approx. Width = 3mm, Approx. Length = 4m. Distance from Wall no.2 = 1.4m, Height from Floor = 2.1m.



Photo 10A Inclined Crack on Wall No. 3,4 & Roof of Varanda, First Floor Approx. Width = 3mm, Approx. Length = 4m. Distance from Wall no.2 = 1.4m, Height from Floor = 2.1m.



Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



JAIPUR METRO

Photo 11 Inclined Crack on Wall No. 1 of Open Sky No.2, First Floor Approx. Width = 1.5mm, Approx. Length = 2.5m. Distance from Wall no.2 = 1.7m, Height from Floor = 2m.



Photo 12 Inclined Crack on Wall No. 4 of Passage No.1, Second Floor Approx. Width = 1mm, Approx. Length = 0.3m. Distance from Wall No.1 = 0.7m, Height from Floor = 2.2m.



Photo 14 Horizontal Crack on Wall No. 3 of Open Sky, Second Floor Approx. Width = 0.5mm, Approx. Length = 1m. Distance from Wall No.1 = 0.7m, Height from Floor = 2.2m.





Photo 11A Inclined Crack on Wall No. 1 of Open Sky No.2, First Floor Approx. Width = 1.5mm, Approx. Length = 2.5m. Distance from Wall no.2 = 1.7m, Height from Floor = 2m.



Photo 13 Horizontal Crack on Wall No. 1 of Open Sky, Second Floor Approx. Width = 1mm, Approx. Length = 1.5m. Distance from Wall no.3 = 0m, Height from Floor = 2.2m.



Photo 15 Inclined Crack on Wall No. 3 of Open Sky, Second Floor Approx. Width = 0.8mm, Approx. Length = 1.5m. Distance from Wall No.2 = 0.25m, Height from Floor = 2.2m.







Photo 16 Horizontal Crack on Wall No. 2 of Open Sky, Second Floor Approx. Width = 1.5mm, Approx. Length = 2m. Distance from Wall No.3 = 0m, Height from Floor = 2.2m.



Photo 17A Horizontal Crack on of , Second Floor Approx. Width = 2.5mm, Approx. Length = 3m.



Photo 17 Horizontal Crack on , Second Floor Approx. Width = 2.5mm, Approx. Length = 3m.



Photo 18 Dampness/Seepage on Wall No. 4 & Roof of Room No. 1 of First Floor



Photo 19 Peeling of Plaster on Wall No. 1 of Room No. 1 of First Floor



Photo 20 Dampness/Seepage on Wall No. 2 & Roof of Room No. 1 of First Floor









Photo 21 Peeling of Plaster on Wall No. 1 & 5 of Hall No. 2 of First Floor



Photo 22 Peeling of Plaster on Wall No. 5 of Hall No. 2 of First Floor



Photo 23 Peeling of Plaster on Wall No. 2 of Hall No. 2 of First Floor



Photo 25 Peeling of Plaster on Wall No. 5 of Hall No. 2 of First Floor



Photo 24 Dampness/Seepage on Roof of Hall No. 2 of First Floor



Photo 26 Peeling of Plaster on Wall No. 4 of Hall No. 2 of First Floor











Photo 27 Exposed Reinforcement on Wall No. 2 of Open Sky No.1 of First Floor

Photo 28 Exposed Reinforcement on Wall No. 2 of Open Sky No.1 of First Floor





Photo 29 Peeling of Plaster on Wall No. 2 of Open Sky No.1 of First Floor






Photo 31 Peeling of Plaster on Wall No. 3 of Passage No.1 of First Floor



Photo 32 Peeling of Plaster on Wall No. 4 of Kitchen No.1 of First Floor









Photo 33 Peeling of Plaster on Wall No. 1 of Kitchen No.1 of First Floor



Photo 34 Peeling of Plaster on Wall No. 3 of Hall No. 4 of First Floor



Photo 35 Peeling of Plaster on Wall No. 3 of Hall No. 4 of First Floor



Photo 36 Peeling of Plaster on Wall No. 1 of Hall No. 4 of First Floor



Photo 37 Peeling of Plaster on Roof of Hall No. 4 of First Floor



Photo 38 Peeling of Plaster on Wall No. 2 of Hall No. 4 of First Floor









Photo 39
Photo 40
Dampness/Seepage on Wall No. 1 Toilet & Bathroom No.1 of First Floor Dampness/Seepage on Wall No. 4 Toilet & Bathroom No.1 of First Floor





Photo 41 Dampness/Seepage on Wall No. 2 of Toilet & Bathroom No.1 of First Floor



Photo 43 Dampness/Seepage on Wall No. 1 & 4 of Toilet & Washroom No.2 of First Floor



Photo 42 Peeling of Plaster on Wall No. 3 of Hall No. 6 of First Floor



Photo 44 Dampness/Seepage on Wall No. 4 & Roof of Toilet & Washroom No.2 of First Floor





Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Photo 45 Peeling of Plaster on Wall No. 1 of Lobby of First Floor



Photo 46 Peeling of Plaster on Wall No. 1 of Varanda of First Floor





<u>Photo 4</u>8

Peeling of Plaster on Wall No. 1 of Open Sky No.2 of First Floor

Photo 47 Peeling of Plaster on Wall No. 3 of Varanda of First Floor



Photo 49 Peeling of Plaster on Wall No. 2 & Roof of Open Sky No.2 of First Floor



Photo 50 Peeling of Plaster on Wall No. 3 of Open Sky No.2 of First Floor











Photo 51 Dampness/Seepage on Wall No. 4 & Roof of Bathroom of Second Floor

Photo 52 Peeling of Plaster on Wall No. 1 of Bathroom of Second Floor





Photo 53 Dampness/Seepage on Roof of Toilet No. 1 of Second Floor

Photo 54 Peeling of Plaster on Wall No. 1 of Passage No.1 of Second Floor



Photo 55 Dampness/Seepage on Wall No. 1 & Shade of Open Sky of Second Floor



Photo 56 Dampness/Seepage on Wall No. 4 & Roof of Open Sky of Second Floor









Photo 57 Peeling of Plaster on Roof of Varanda of Second Floor



Photo 58 Peeling of Plaster on Wall No. 2 of Varanda of Second Floor





Photo 59 Peeling of Plaster on Wall No. 4 of Varanda of Second Floor



<u>Photo 6</u>1 Peeling of Plaster on Wall No. 3 of Varanda of Second Floor



Photo 60 Peeling of Plaster on Wall No. 1 of Varanda of Second Floor



Photo 62 Peeling of Plaster on Wall No. 4 of Toilet No. 2 of Second Floor









Photo 63 Dampness/Seepage on Wall No.4 of Hall No. 1 of Second Floor



Photo 64 Peeling of Plaster on Roof of Kitchen No.2 of Second Floor





Photo 65 Peeling of Plaster on Wall No. 4 of Kitchen No.2 of Second Floor

Photo 66 Peeling of Plaster on Roof of Kitchen No.2 of Second Floor



Photo 67 Peeling of Plaster on Wall No. 1 of Kitchen No.2 of Second Floor



Photo 68 Peeling of Plaster on Wall No. 3 of Kitchen No.2 of Second Floor









Photo 69 Peeling of Plaster on Roof of Kitchen No.1 of Second Floor



Photo 70 Peeling of Plaster on Hall No. 3 of Second Floor



Photo 71 Peeling of Plaster on Passage of Second Floor



Photo 73 Peeling of Plaster on Wall No. 1 of Staircase SF to TF





Photo 72 Peeling of Plaster on Wall No. 1 of Staircase SF to TF



Photo 74 Peeling of Plaster on Wall No. 1 of of Terrace







Photo 75 Dampness/Seepage on Wall No. 4 of of Terrace



Photo 76 Dampness/Seepage on Floor of Terrace





Photo 77 Dampness/Seepage on Wall No. 2, 4 & Roof of Toilet & Washroom of Terrace



Photo 79 Dampness/Seepage on Wall No. 4 of Parapet of Terrace






Photo 80 Peeling of Plaster on Wall No. 1 of Parapet of Terrace









Photo 81 Hall No. 1 of First Floor Locked



Photo 82 Hall No. 1 of First Floor Locked



Photo 83 Hall No. 3 of First Floor Locked



Photo 84 Kitchen No.2 of First Floor Locked



Photo 85 Hall No. 1 of First Floor Locked






Photo 86 Wall No. 2 of Kitchen No.1 of Second Floor Locked





JAIPUR METRO Jaipur Metro Rail Corporation



Photo 87 Wall No. 1 of Kitchen No.1 of Second Floor



Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Shops Atish Ka Khanda, Choti Chopar Jaipur Unique ID: CC 0002

Report Number: AIMIL/ESG/JMCEC/CC 0002 02/01, Rev. 00, Dated: January 2014

Building Owner Contractor Various Owners CEC Client Sub-Contractor JMRC Limited AIMIL Limited







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

	Table of Contents			
S.No.	Particulars	Page No.		
1	Introduction	2		
2	Survey Details	2		
3	About the Structure	3		
4	Building Ownership Details	3		
5	Project Details	4		
6	General Building Details	4		
7	Summary of Cracks	5		
8	Summary of Defects other than Cracks			
9	Summary of Areas that Could not be surveyed			
10	Defect Photographs			
11	Schematic Diagram of Building			

Introduction

The Jaipur Metro Rail is being constructed to provide the city of Jaipur with a modern and technologically advanced Transit System, to provide a safe and well connected means of transport that reduces traffic congestion. The project consists of two corridors with underground and elevated sections.

The construction of underground rail and road infrastructures in metropolitan and cosmopolitan cities are mostly through developed area under challenging soil conditions.

The alignment of structure is passing through densely inhabitated areas, many structures are falling in the zone of influence of construction activities. It is required to carry out the pre-condition survey of those structures. The scope of work of this survey includes carrying out pre-condition survey of those structures.

	Survey Details				
S.No.	Head	Particulars	Signatures		
1	Date of Survey	16/12/2013			
2	AIMIL Representative				
3	CEC Representative				
4	Structural Designer of CEC				
5	JMRC/DMRC Representative				







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

About the Structure

The structure under consideration is a Multi Story Load Bearing Structure having 3 floors. The structure was constructed in year 1860 and is 153 years old.

There are 45 defects in the structure out of which 9 are cracks. Category wise distribution of cracks is given in the table below. Overall the Building can be categorised in Category II (Slight)

Category	Number of Cracks	% of Total Cracks	
Negligible (< 0.1mm)	0	0%	
Very Slight (0.1 to 1mm)	6	66.67%	
Slight (1 to 5mm)	3	33.33%	
Moderate (5 to 15mm)	0	0%	
Severe (15 to 25mm)	0	0%	
Very Severe (>25mm)	0	0%	

The average width of cracks is 0.61mm and average length of cracks is 1.81m. The maximum crack width is 1mm and minimum width is 0.2mm.

Building Ownership Details				
Unique ID/Sub ID	Premises Name	Owner	Signatures	
CC/0002/773-1				
CC/0002/773-2				
CC/0002/773-3				
CC/0002/773-4				
CC/0002/770				
CC/0002/771				
CC/0002/772				
CC/0002/773				
CC/0002/774				
CC/0002/775				







Project Details				
S. No.	Head	Particulars		
1	Project	Jaipur Metro Rail Project		
2	Section	Chandpole to Bari Chaupar		
3	Client	JMRC Limited		
4	Consultant	DMRC Limited		
5	Contractor	CEC		
6	Design Consultant of Contractor	Omikron Kappa - Indus Consultrans JV		
7	Sub-Contractor	AIMIL Limited		
8	Subject	Pre-Condition Survey Report		

General Building Details (As informed verbally by Building Owner)				
S. No.	Head	Particulars		
1	Building Name	Shops		
2	Building Address	Shops Atish Ka Khanda, Choti Chopar Jaipur		
3	Year of Construction	1860		
4	Number of Floors	G+2		
5	Number of Basements	None		
6	Type of Building	Commercial + Residence		
7	Approximate Height	9m		
8	Approximate Area	Not Known		
9	Age of Building	153 years		
10	Type of Structure	Load Bearing Structure		
11	Type of Foundation	Not Known		
12	Number of Bore Wells	None		
13	Depth and Diameter of Bore	N.A		
14	Roadways	One Side		
15	Presence of Equipment/Machines	None		







	Summary of Cracks						
Defect ID	Location	Orientation	Appx. Width (mm)	Appx. Length (m)	Category	Photo No.	
1	Wall No. 2 Part A of Shop No.782 Ground Floor	Horizontal	0.3	1.8	Very Slight	15	
2	Wall No. 1 Part A of Shop No.782 Ground Floor	Horizontal	0.5	2.7	Very Slight	16, 16A	
3	Roof Varanda of Shop No.777 Ground Floor	Horizontal	0.2	2	Very Slight	17	
4	Roof Varanda of Shop No.776 Ground Floor	Horizontal	0.5	1.6	Very Slight	18	
5	Backside of Leftside External Column Varanda of Shop No.773/2 & 773/1 Ground Floor	Horizontal	1	1.4	Slight	19	
6	Backside of External Column Varanda of Shop No.773/2 & 773/1 Ground Floor	Horizontal	1	1.4	Slight	20	
7	Varanda of Shop No.773/2 & 773/1 Ground Floor	Horizontal	0.6	1.4	Very Slight	21	
8	Wall No. 4 Part C of Shop No.773/2 & 773/1 Ground Floor	Inclined	0.35	2	Very Slight	22, 22A	
9	Wall No. 2 Part D of Shop No.773/2 & 773/1 Ground Floor	Inclined	1	2	Slight	23, 23A	

	Summary of Defec	ts Other Than Crack	
Defect ID	Location	Description	Photo No.
10	Roof Varanda of Shop No.782 Ground Floor	Dampness/Seepage	24
11	Internal Beam & External Wall Varanda of Shop No.782 Ground Floor	Peeling of Plaster	25
12	Wall No. 4 Part A of Shop No.782 Ground Floor	Plaster Crack	26
13	Wall No. 3 Part A of Shop No.782 Ground Floor	Peeling of Plaster	27
14	Wall No. 2 & Entrance Gate Shop No.782 A Ground Floor	Peeling of Plaster	28
15	Wall No. 3 Part A of Shop No.782 A Ground Floor	Peeling of Plaster	29
16	Wall No. 2 & Roof Part A of Shop No.782 A Ground Floor	Peeling of Plaster	30
17	Roof Varanda of Shop No.781 Ground Floor	Dampness/Seepage	31
18	Beam Varanda of Shop No.781 Ground Floor	Dampness/Seepage	32
19	Leftside Wall Varanda of Shop No.780 Ground Floor	Dampness/Seepage	33
20	Roof Part C of Shop No.780 Ground Floor	Dampness/Seepage	34
21	Wall No. 4 Part C of Shop No.780 Ground Floor	Dampness/Seepage	35
22	Roof Part B of Shop No.780 Ground Floor	Dampness/Seepage	36
23	Wall No. 4 Part B of Shop No.780 Ground Floor	Dampness/Seepage	37
24	Right Side Wall Varanda of Shop No.777 Ground Floor	Dampness/Seepage	38
25	Roof Part A of Shop No.777 Ground Floor	Dampness/Seepage	39
26	Roof Part B of Shop No.777 Ground Floor	Peeling of Plaster	40
27	Right Side Outer Wall Shop No.776 Ground Floor	Damaged Portion	41
28	Roof Part B of Shop No.776 Ground Floor	Dampness/Seepage	42
29	Roof Part C of Shop No.776 Ground Floor	Dampness/Seepage	43
30	Wall No. 2 Part C of Shop No.776 Ground Floor	Dampness/Seepage	44
31	Wall No. 1, 2 & Roof Part C of Shop No.776 Ground Floor	Dampness/Seepage	45
32	Wall No. 1 & Roof Part A of Shop No.773/2 & 773/1 Ground Floor	Peeling of Plaster	46
33	Wall No. 3 & Roof Part A of Shop No.773/2 & 773/1 Ground Floor	Peeling of Plaster	47
34	Beam Part A of Shop No.773/2 & 773/1 Ground Floor	Plaster Crack	48

35	Wall No. 1 Part B of Shop No.773/2 & 773/1 Ground Floor	Plaster Crack	49
36	Roof Part B of Shop No.773/2 & 773/1 Ground Floor	Peeling of Plaster	50
37	Entry Gate Part C of Shop No.773/2 & 773/1 Ground Floor	Damaged Portion	51
38	Wall No. 4 Part C of Shop No.773/2 & 773/1 Ground Floor	Plaster Crack	52
39	Wall No. 4 Part C of Shop No.773/2 & 773/1 Ground Floor	Peeling of Plaster	53
40	Part C of Shop No.773/2 & 773/1 Ground Floor	Damaged Portion	54
41	Wall No. 4 Part C of Shop No.773/2 & 773/1 Ground Floor	Damaged Portion	55
42	Wall No. 1 Part D of Shop No.773/2 & 773/1 Ground Floor	Damaged Portion	56
43	Wall No. 1 & Roof Part D of Shop No.773/2 & 773/1 Ground Floor	Damaged Portion	57
44	Wall No. 2 Part D of Shop No.773/2 & 773/1 Ground Floor	Peeling of Plaster	58
45	Wall No. 3 & Roof Part B of Shop No.773/2 & 773/1 Ground Floor	Peeling of Plaster	59

Summary of Areas that Could not be Surveyed				
Serial No.	Location	Description Ph		
1	All Walls Part B of Shop No.782 Ground Floor	Covered With Material	60	
2	All Walls Part C of Shop No.782 Ground Floor	Covered With Material	61	
3	Part D & E of Shop No.782 Ground Floor	No Way to Enterance	62	
4	Wall No. 4 Shop No.782 A Ground Floor	Covered With Material	63	
5	Wall No. 1 Shop No.781 Ground Floor	Covered With Material	64	
6	Wall No. 2 Shop No.781 Ground Floor	Covered With Material	65	
7	Wall No. 4 & Roof Shop No.781 Ground Floor	Covered With Material & Wooden Work	66	
8	Wall No. 1 & 2 Part B of Shop No.780 Ground Floor	Covered With Material	67	
9	Wall No. 1 Part B of Shop No.777 Ground Floor	Covered With Material	68	
10	Wall No. 2 Part B of Shop No.777 Ground Floor	Covered With Material	69	
11	Wall No. 4 Part B of Shop No.777 Ground Floor	Covered With almira	70	
12	Wall No. 1 & 2 Part B of Shop No.776 Ground Floor	Covered With material	71	
13	All Walls Part B of Shop No.774 Ground Floor	Covered With material	72	
14	Wall No. 1 Part A of Shop No.774 Ground Floor	Covered With material	73	
15	Shop No.773 Ground Floor	Locked	74	
16	Wall No. 2 & 4 Part A of Shop No.773/4 Ground Floor	Covered With Wooden Racks & Material	75	
17	Wall No. 1 & 4 Part A of Shop No.773/4 Ground Floor	Covered With Wooden Racks & Material	76	
18	All Walls Part B of Shop No.773/4 Ground Floor	Covered With Material	77	
19	Shop No.773/3 Basement	Locked	78	









Photo 1 View of Shop No.775



Photo 2 View of Shop, Ground Floor



Photo 3 View of Shop No.782A, Ground Floor



Photo 5 View of Shop No.780, Ground Floor





Photo 4 View of Shop No.781, Ground Floor



Photo 6 View of Part A, Ground Floor







Photo 7 View of Shop No.777, Ground Floor



Photo 8 View of Shop No.776, Ground Floor



Photo 9 View of Part B Shop No.775, Ground Floor



Photo 11 View of Shop No.774, Ground Floor





Photo 10 View of Part A Shop No.775, Ground Floor



Photo 12 View of Shopno.773/4, Ground Floor







Photo 13 View of Shopno.773/4, Ground Floor



Photo 14 View of Shop No.773/1 & 773/2, Ground Floor





Photo 15 Horizontal Crack on Wall No. 2 of Part A of Shop No.782, Ground Floor Horizontal Crack on Wall No. 1 of Part A of Shop No.782, Ground Floor Approx. Width = 0.3mm, Approx. Length = 1.8m. Distance from Wall No.3 = 0.15m, Height from Floor = 1.9m.






Photo 16A Horizontal Crack on Wall No. 1 of Part A of Shop No.782, Ground Floor Approx. Width = 0.5mm, Approx. Length = 2.7m. Distance from Wall No.3 = 0m, Height from Floor = 1.5m.



Photo 17 Horizontal Crack on Roof of Varanda of Shop No.777, Ground Floor Approx. Width = 0.2mm, Approx. Length = 2m. Distance from Leftside External Column = 1.2m, Height from Floor = 3m.







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Photo 18

Horizontal Crack on Roof of Varanda of Shop No.776, Ground Floor Approx. Width = 0.5mm, Approx. Length = 1.6m. Distance from Rightside External Column= 0m, Height from Floor = 3m.



Photo 20



Photo 19 Horizontal Crack on Backside of Leftside External Column of Varanda of Shop No.773/2 & 773/1, Ground Floor Approx. Width = 1mm, Approx. Length = 1.4m. Height from Floor = 3.5m.



Horizontal Crack on Backside of Ext Col of Varanda of Shop No.773/2 & Horizontal Crack on of Varanda of Shop No.773/2 & 773/1, Ground 773/1, Ground Floor Approx. Width 1mm, Approx. Length 1.4m. Distance Floor Approx. Width = 0.6mm, Approx. Length = 1.4m. Distance Leftside Right & leftside Ext Col, Height Floor 3.5m Ext Col = 0m, Height Floor = 3.5m.



Photo 22 Inclined Crack on Wall No. 4 of Part C of Shop No.773/2 & 773/1, from Wall No.2 = 2.3m, Height from Floor = 0m.













<u>Photo 2</u>3

Inclined Crack on Wall No. 2 of Part D of Shop No.773/2 & 773/1, Ground Floor Approx. Width = 1mm, Approx. Length = 2m. Distance from Wall No.1 = 0.85m, Height from Floor = 1.55m.





Photo 23A Inclined Crack on Wall No. 2 of Part D of Shop No.773/2 & 773/1, Ground Floor Approx. Width = 1mm, Approx. Length = 2m. Distance from Wall No.1 = 0.85m, Height from Floor = 1.55m.



Photo 24 Dampness/Seepage on Roof of Varanda of Shop No.782 of Ground Floor



Photo 25 Peeling of Plaster on Internal Beam & External Wall of Varanda of Shop No.782 of Ground Floor



Photo 26 Plaster Crack on Wall No. 4 of Part A of Shop No.782 of Ground Floor














Photo 28
Peeling of Plaster on Wall No. 2 & Enterance Gate of Shop No.782 A of
Ground Floor
Peeling of Plaster on Wall No. 3 of Part A of Shop No.782 A of Ground
Floor
Floor





Photo 30 Peeling of Plaster on Wall No. 2 & Roof of Part A of Shop No.782 A of Ground Floor

Photo 31 Dampness/Seepage on Roof of Varanda of Shop No.781 of Ground Floor



Photo 32 Dampness/Seepage on Beam of Varanda of Shop No.781 of Ground Floor



Photo 33 Dampness/Seepage on Leftside Wall of Varanda of Shop No.780 of Ground Floor











Photo 34 Dampness/Seepage on Roof of Part C of Shop No.780 of Ground Floor Floor





Photo <u>3</u>6 Dampness/Seepage on Roof of Part B of Shop No.780 of Ground Floor



Photo 38 Dampness/Seepage on Rightside Wall of Varanda of Shop No.777 of Ground Floor

Photo 37 Dampness/Seepage on Wall No. 4 of Part B of Shop No.780 of Ground Floor



Photo 39 Dampness/Seepage on Roof of Part A of Shop No.777 of Ground Floor











Photo 40 Peeling of Plaster on Roof of Part B of Shop No.777 of Ground Floor

Photo 41 Damaged Portion on Rightside Outer Wall of Shop No.776 of Ground Floor





Photo 42 Dampness/Seepage on Roof of Part B of Shop No.776 of Ground Floor Dampness/Seepage on Roof of Part C of Shop No.776 of Ground Floor





 Photo 44
 Photo 45

 Dampness/Seepage on Wall No. 2 of Part C of Shop No.776 of Ground
 Dampness/Seepage on Wall No. 1, 2 & Roof of Part C of Shop No.776

 Floor
 of Ground Floor







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Photo 46 Peeling of Plaster on Wall No. 1 & Roof of Part A of Shop No.773/2 & 773/1 of Ground Floor

Photo 47 Peeling of Plaster on Wall No. 3 & Roof of Part A of Shop No.773/2 & 773/1 of Ground Floor





Photo 48 Plaster Crack on Beam of Part A of Shop No.773/2 & 773/1 of Ground Floor



<u>Photo 4</u>9



Photo 50 Peeling of Plaster on Roof of Part B of Shop No.773/2 & 773/1 of Ground Floor



Photo 51 Damaged Portion on Entry Gate of Part C of Shop No.773/2 & 773/1 of Ground Floor







Photo 52 Plaster Crack on Wall No. 4 of Part C of Shop No.773/2 & 773/1 of Ground Floor



Photo 53 Peeling of Plaster on Wall No. 4 of Part C of Shop No.773/2 & 773/1 of Ground Floor



Photo 54 Damaged Portion on of Part C of Shop No.773/2 & 773/1 of Ground Floor



<u>Photo 5</u>5 Damaged Portion on Wall No. 4 of Part C of Shop No.773/2 & 773/1 of Ground Floor



Photo 56 Ground Floor





Photo 57 Damaged Portion on Wall No. 1 of Part D of Shop No.773/2 & 773/1 of Damaged Portion on Wall No. 1 & Roof of Part D of Shop No.773/2 & 773/1 of Ground Floor









Photo 58 Peeling of Plaster on Wall No. 2 of Part D of Shop No.773/2 & 773/1 of Ground Floor

Photo 59 Peeling of Plaster on Wall No. 3 & Roof of Part B of Shop No.773/2 & 773/1 of Ground Floor



Photo 60 All Walls of Part B of Shop No.782 of Ground Floor Covered With Material





Photo 62 Part D & E of Shop No.782 of Ground Floor No Way to Enterance



Photo 63 Wall No. 4 of Shop No.782 A of Ground Floor Covered With Material









Photo 64 Wall No. 1 of Shop No.781 of Ground Floor Covered With Material



Photo 65 Wall No. 2 of Shop No.781 of Ground Floor Covered With Material





Photo 6 Wall No. 4 & Roof of Shop No.781 of Ground Floor Covered With Material & Wooden Work





Photo 68 Wall No. 1 of Part B of Shop No.777 of Ground Floor Covered With Material





Photo 69 Wall No. 2 of Part B of Shop No.777 of Ground Floor Covered With Material







Photo 70 Wall No. 4 of Part B of Shop No.777 of Ground Floor Covered With almirah



Photo 71 Wall No. 1 & 2 of Part B of Shop No.776 of Ground Floor Covered With material





Photo 72 All Walls of Part B of Shop No.774 of Ground Floor Covered With material



Photo 74 Shop No.773 of Ground Floor Locked



Photo 73 Wall No. 1 of Part A of Shop No.774 of Ground Floor Covered With material



Photo 75 Wall No. 2 & 4 of Part A of Shop No.773/4 of Ground Floor Covered With Wooden Racks & Material







Photo 76 Wall No. 1 & 4 of Part A of Shop No.773/4 of Ground Floor Covered With Wooden Racks & Material



Photo 77 All Walls of Part B of Shop No.773/4 of Ground Floor Covered With Material



Photo 78 Shop No.773/3 of Basement Locked



Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



House No. 779 Temple Atish Ka Khanda, Choti Chopar Jaipur Unique ID: CC 0002

Report Number: AIMIL/ESG/JMCEC/CC 0002/01, Rev. 00, Dated: December 2013

Building Owner Contractor Mr. Padam Kumar CEC Client Sub-Contractor JMRC Limited AIMIL Limited







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

	Table of Contents			
S.No.	Particulars	Page No.		
1	Introduction	2		
2	Survey Details	2		
3	About the Structure	3		
4	Building Ownership Details	3		
5	Project Details	4		
6	General Building Details	4		
7	Summary of Cracks	5		
8	Summary of Defects other than Cracks			
9	Summary of Areas that Could not be surveyed			
10	Defect Photographs			
11	Schematic Diagram of Building			

Introduction

The Jaipur Metro Rail is being constructed to provide the city of Jaipur with a modern and technologically advanced Transit System, to provide a safe and well connected means of transport that reduces traffic congestion. The project consists of two corridors with underground and elevated sections.

The construction of underground rail and road infrastructures in metropolitan and cosmopolitan cities are mostly through developed area under challenging soil conditions.

The alignment of structure is passing through densely inhabitated areas, many structures are falling in the zone of influence of construction activities. It is required to carry out the pre-condition survey of those structures. The scope of work of this survey includes carrying out pre-condition survey of those structures.

	Survey Details				
S.No.	Head	Particulars	Signatures		
1	Date of Survey	22/12/2013			
2	AIMIL Representative				
3	CEC Representative				
4	Structural Designer of CEC				
5	JMRC/DMRC Representative				







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

About the Structure

The structure under consideration is a Multi Story Load Bearing Structure having 3 floors. The structure was constructed in year 1713 and is 300 years old.

There are 34 defects in the structure out of which 11 are cracks. Category wise distribution of cracks is given in the table below. Overall the Building can be categorised in Category II (Slight)

Category	Number of Cracks	% of Total Cracks
Negligible (< 0.1mm)	0	0%
Very Slight (0.1 to 1mm)	4	36.36%
Slight (1 to 5mm)	7	63.64%
Moderate (5 to 15mm)	0	0%
Severe (15 to 25mm)	0	0%
Very Severe (>25mm)	0	0%

The average width of cracks is 1.55mm and average length of cracks is 1.39m. The maximum crack width is 3mm and minimum width is 0.2mm.

Building Ownership Details			
Unique ID/Sub ID	Premises Name	Owner	Signatures
CC/0002/782-773-EE-SE	H. No. 779, Atish Ka Khanda		







Project Details			
S. No.	Head	Particulars	
1	Project	Jaipur Metro Rail Project	
2	Section	Chandpole to Bari Chaupar	
3	Client	JMRC Limited	
4	Consultant	DMRC Limited	
5	Contractor	CEC	
6	Design Consultant of Contractor	Omikron Kappa - Indus Consultrans JV	
7	Sub-Contractor	AIMIL Limited	
8	Subject	Pre-Condition Survey Report	

General Building Details (As informed verbally by Building Owner)			
S. No.	Head	Particulars	
1	Building Name	House No. 779 Temple	
2	Building Address	House No. 779 Temple Atish Ka Khanda, Choti Chopar Jaipur	
3	Year of Construction	1713	
4	Number of Floors	G+2	
5	Number of Basements	None	
6	Type of Building	Commercial + Residence	
7	Approximate Height	9m	
8	Approximate Area	Not Known	
9	Age of Building	300 years	
10	Type of Structure	Load Bearing Structure	
11	Type of Foundation	Not Known	
12	Number of Bore Wells	None	
13	Depth and Diameter of Bore	N.A	
14	Roadways	One Side	
15	Presence of Equipment/Machines	None	







Summary of Cracks						
Defect ID	Location	Orientation	Appx. Width (mm)	Appx. Length (m)	Category	Photo No.
1	Wall No. 3 Open Sky No.1 First Floor	Inclined	0.2	1.2	Very Slight	3, 3A
2	Wall No. 2 Shade Roof First Floor	Horizontal	3	1	Slight	4
3	Wall No. 2 Shade Roof First Floor	Horizontal	2	1	Slight	5
4	Wall No. 3 Varanda No.1 First Floor	Inclined	1	1.1	Slight	6, 6A
5	Shade Open sky No.2 First Floor	Horizontal	0.35	1	Very Slight	7
6	Shade Open sky No.2 First Floor	Horizontal	0.25	1.5	Very Slight	8
7	Wall No. 2 & Roof Kitchen No.1 First Floor	Inclined	3	3	Slight	9
8	Wall No. 4 Hall No. 1 Second Floor	Inclined	0.25	2	Very Slight	10, 10A
9	Perapet Wall No.3 Terrace Second Floor	Vertical	2.5	1	Slight	11, 11A
10	Perapet Wall No.3 Terrace Second Floor	Vertical	2.5	1	Slight	12, 12A
11	Wall No. 1 Staircase FF to SF First Floor	Vertical	2	1.5	Slight	13, 13A

Summary of Defects Other Than Crack				
Defect ID	Location	Description	Photo No.	
12	Main Gate Wall Temple Shri Murli Manohar ji, House no.779 First Floor	Peeling of Plaster	14	
13	Wall No. 2 & 3 Shade First Floor	Peeling of Plaster	15	
14	Roof Room No. 1 First Floor	Peeling of Plaster	16	
15	Roof Store No.1 First Floor	Dampness/Seepage	17	
16	Roof Varanda No.1 First Floor	Dampness/Seepage	18	
17	Floor Open sky No.2 First Floor	Peeling of Plaster	19	
18	Wall No. 1 & Roof Varanda No.2 First Floor	Dampness/Seepage	20	
19	Wall No. 2 Bathroom No. First Floor	Peeling of Plaster	21	
20	Wall No. 2 & Roof Kitchen No.2 First Floor	Dampness/Seepage	22	
21	Wall No. 4 & Roof Room No. 5 First Floor	Dampness/Seepage	23	
22	Roof Room No. 5 First Floor	Peeling of Plaster	24	
23	Floor Open Sky No.1 First Floor	Peeling of Plaster	25	
24	Staircase Steps First Floor	Peeling of Plaster	26	
25	Wall No. 4 Store No.2 First Floor	Peeling of Plaster	27	
26	Wall No. 4 Staircase FF to SF First Floor	Peeling of Plaster	28	
27	Wall No. 2 Staircase FF to SF First Floor	Peeling of Plaster	29	
28	Roof Store no.2 First Floor	Dampness/Seepage	30	
29	Wall No. 4 Teen Shade Store No.1 Second Floor	Peeling of Plaster	31	
30	Wall No. 4 Hall No. 1 Second Floor	Dampness/Seepage	32	
31	Roof Hall No. 1 Second Floor	Dampness/Seepage	33	
32	Wall No. 2 Hall No. 1 Second Floor	Dampness/Seepage	34	
33	Floor Hall No. 1 Second Floor	Peeling of Plaster	35	
34	Shade Roof First Floor	Peeling of Plaster	36	

	Summary of Areas that Could not be Surveyed				
Serial No.	Serial No.         Location         Description         Photo No.				
1 Main Temple First Floor		Locked	37		
2	All Walls Bathroom No. Second Floor	Half Covered with Tiles	38		





Locked

JAIPUR METRO Jaipur Metro Rail Corporation

Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Photo 1 View of Building



Photo 2 View of Tin Shade, Second Floor



Photo 3 Inclined Crack on Wall No. 3 of Open Sky No.1, First Floor Approx. Width = 0.2mm, Approx. Length = 1.2m. Distance from Wall No.2 = 1.7m, Height from Floor = 2m.



Photo 3A Inclined Crack on Wall No. 3 of Open Sky No.1, First Floor Approx. Width = 0.2mm, Approx. Length = 1.2m. Distance from Wall No.2 = 1.7m, Height from Floor = 2m.



Photo 4 Horizontal Crack on Wall No. 2 of Shade Roof, First Floor Approx. Width = 3mm, Approx. Length = 1m. Distance from Wall No.3 = 1.7m, Height from Floor = 3m.





Photo 5 Horizontal Crack on Wall No. 2 of Shade Roof, First Floor Approx. Width = 2mm, Approx. Length = 1m. Distance from Wall No.4 = 1.7m, Height from Floor = 3m.



Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



JAIPUR METRO

Photo 6 Inclined Crack on Wall No. 3 of Varanda No.1, First Floor Approx. Width = 1mm, Approx. Length = 1.1m. Distance from Wall No.2 = 1.3m, Height from Floor = 2m.



Photo 7 Horizontal Crack on Shade of Open sky No.2, First Floor Approx. Width = 0.35mm, Approx. Length = 1m. Distance from Wall No.1 = 0m, Height from Floor = 2.5m.



Photo 9 Inclined Crack on Wall No. 2 & Roof of Kitchen No.1, First Floor Approx. Width = 3mm, Approx. Length = 3m. Distance from Wall No.4 = 0m, Height from Floor = 2.5m.





Photo 6A Inclined Crack on Wall No. 3 of Varanda No.1, First Floor Approx. Width = 1mm, Approx. Length = 1.1m. Distance from Wall No.2 = 1.3m, Height from Floor = 2m.



Photo 8 Horizontal Crack on Shade of Open sky No.2, First Floor Approx. Width = 0.25mm, Approx. Length = 1.5m. Distance from Wall No.1 = 0m, Height from Floor = 2.8m.



Photo 10 Inclined Crack on Wall No. 4 of Hall No. 1, Second Floor Approx. Width = 0.25mm, Approx. Length = 2m. Distance from Wall No.1 = 0m, Height from Floor = 1.3m.





Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Photo 10A Inclined Crack on Wall No. 4 of Hall No. 1, Second Floor Approx. Width = 0.25mm, Approx. Length = 2m. Distance from Wall No.1 = 0m, Height from Floor = 1.3m.



Photo 11A Vertical Crack on Perapet Wall No.3 of Terrace, Second Floor Approx. Width = 2.5mm, Approx. Length = 1m. Distance from Wall No.2 = 5m, Height from Floor = 0m.



Photo 12A Vertical Crack on Perapet Wall No.3 of Terrace, Second Floor Approx. Width = 2.5mm, Approx. Length = 1m. Distance from Wall No.4 = 3m, Height from Floor = 0m.





Photo 11 Vertical Crack on Perapet Wall No.3 of Terrace, Second Floor Approx. Width = 2.5mm, Approx. Length = 1m. Distance from Wall No.2 = 5m, Height from Floor = 0m.



Photo 12 Vertical Crack on Perapet Wall No.3 of Terrace, Second Floor Approx. Width = 2.5mm, Approx. Length = 1m. Distance from Wall No.4 = 3m, Height from Floor = 0m.



Photo 13 Vertical Crack on Wall No. 1 of Staircase FF to SF, First Floor Approx. Width = 2mm, Approx. Length = 1.5m. Distance from Wall No.4 = 0.4m, Height from Floor = 0m.







Photo 13A Vertical Crack on Wall No. 1 of Staircase FF to SF, First Floor Approx. Width = 2mm, Approx. Length = 1.5m. Distance from Wall No.4 = 0.4m, Height from Floor = 0m.



Photo 15 Peeling of Plaster on Wall No. 2 & 3 of Shade of First Floor



Photo 17 Dampness/Seepage on Roof of Store No.1 of First Floor





Photo 14 Peeling of Plaster on Main Gate Wall of Temple Shri Murli Manohar ji, House no.779 of First Floor



Photo 16 Peeling of Plaster on Roof of Room No. 1 of First Floor



Photo 18 Dampness/Seepage on Roof of Varanda No.1 of First Floor







Photo 19 Peeling of Plaster on Floor of Open sky No.2 of First Floor



Photo 20 Dampness/Seepage on Wall No. 1 & Roof of Varanda No.2 of First Floor





Photo 21 Peeling of Plaster on Wall No. 2 of Bathroom No. of First Floor

Photo 22 Dampness/Seepage on Wall No. 2 & Roof of Kitchen No.2 of First Floor



Photo 23 Dampness/Seepage on Wall No. 4 & Roof of Room No. 5 of First Floor












Photo 25 Peeling of Plaster on Floor of Open Sky No.1 of First Floor



Photo 26 Peeling of Plaster on Staircase Steps of of First Floor





Photo 27 Peeling of Plaster on Wall No. 4 of Store No.2 of First Floor

Photo 28 Peeling of Plaster on Wall No. 4 of Staircase FF to SF of First Floor



Photo 29 Peeling of Plaster on Wall No. 2 of Staircase FF to SF of First Floor



Photo 30 Dampness/Seepage on Roof of Store no.2 of First Floor







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Photo 31 Peeling of Plaster on Wall No. 4 of Teen Shade Store No.1 of Second Floor



Photo 32 Dampness/Seepage on Wall No. 4 of Hall No. 1 of Second Floor





Photo 34

Dampness/Seepage on Wall No. 2 of Hall No. 1 of Second Floor

Photo 33 Dampness/Seepage on Roof of Hall No. 1 of Second Floor



Photo 35 Peeling of Plaster on Floor of Hall No. 1 of Second Floor



Photo 36 Peeling of Plaster on Shade Roof of first Floor







# JAIPUR METRO Jaipur Metro Rail Corporation



Photo 37 Main Temple of First Floor Locked



Photo 38 All Walls of Bathroom of Second Floor Half Covered with Tiles



Photo 39 Room No. 1 of Second Floor Locked



Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Shop No. 783-791 Sadhu Singh Dalal Sanghori Bazaar, Choti Chopar Jaipur Unique ID: CC 0003

Report Number: AIMIL/ESG/JMCEC/CC 0003/01, Rev. 00, Dated: January 2014

Building Owner Contractor Various Owners CEC Client Sub-Contractor JMRC Limited AIMIL Limited







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

	Table of Contents			
S.No.	Particulars	Page No.		
1	Introduction	2		
2	Survey Details	2		
3	About the Structure	3		
4	Building Ownership Details	3		
5	Project Details	4		
6	General Building Details	4		
7	Summary of Cracks	5		
8	Summary of Defects other than Cracks			
9	Summary of Areas that Could not be surveyed			
10	Defect Photographs			
11	Schematic Diagram of Building			

Introduction

The Jaipur Metro Rail is being constructed to provide the city of Jaipur with a modern and technologically advanced Transit System, to provide a safe and well connected means of transport that reduces traffic congestion. The project consists of two corridors with underground and elevated sections.

The construction of underground rail and road infrastructures in metropolitan and cosmopolitan cities are mostly through developed area under challenging soil conditions.

The alignment of structure is passing through densely inhabitated areas, many structures are falling in the zone of influence of construction activities. It is required to carry out the pre-condition survey of those structures. The scope of work of this survey includes carrying out pre-condition survey of those structures.

	Survey Details				
S.No.	Head	Particulars	Signatures		
1	Date of Survey	16/12/2013			
2	AIMIL Representative				
3	CEC Representative				
4	Structural Designer of CEC				
5	JMRC/DMRC Representative				







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

About the Structure

The structure under consideration is a Multi Story Load Bearing Structure having 2 floors. The structure was constructed in year 1860 and is 153 years old.

There are 11 defects in the structure out of which 2 are cracks. Category wise distribution of cracks is given in the table below. Overall the Building can be categorised in Category I (Very Slight)

Category	Number of Cracks	% of Total Cracks
Negligible (< 0.1mm)	0	0%
Very Slight (0.1 to 1mm)	2	100%
Slight (1 to 5mm)	0	0%
Moderate (5 to 15mm)	0	0%
Severe (15 to 25mm)	0	0%
Very Severe (>25mm)	0	0%

The average width of cracks is 0.1mm and average length of cracks is 1.6m. The maximum crack width is 0.1mm and minimum width is 0.1mm.

Building Ownership Details				
Unique ID/Sub ID	Premises Name	Owner	Signatures	
CC/0003-783	SK Brothers			
CC/0003-784	Aggrawal			
CC/0003-785	Ramesh & Co.			
CC/0003-786	Atumal Laxmandas & Co.			
CC/0003-787	Rijhumal Pohumal & Sons			
CC/0003-788	Ramji Lal Satya Prakesh			
CC/0003-789	Goel Lawajma Store			
CC/0003-790	Goel Safa Sherwani Store			
CC/0003-791	Vishnu Bano New Aggrawal Lawajma Store			







Project Details				
S. No.	Head	Particulars		
1	Project	Jaipur Metro Rail Project		
2	Section	Chandpole to Bari Chaupar		
3	Client	JMRC Limited		
4	Consultant	DMRC Limited		
5	Contractor	CEC		
6	Design Consultant of Contractor	Omikron Kappa - Indus Consultrans JV		
7	Sub-Contractor	AIMIL Limited		
8	Subject	Pre-Condition Survey Report		

General Bui	Iding Details (As informed verbally by Building C	Owner)
S. No.	Head	Particulars
1	Building Name	Shop No. 783-791
2	Building Address	Shop No. 783-791 Sadhu Singh Dalal Sanghori Bazaar, Choti Chopar Jaipur
3	Year of Construction	1860
4	Number of Floors	G+1
5	Number of Basements	None
6	Type of Building	Commercial
7	Approximate Height	6 m
8	Approximate Area	Not Known
9	Age of Building	153 years
10	Type of Structure	Load Bearing Structure
11	Type of Foundation	Not Known
12	Number of Bore Wells	None
13	Depth and Diameter of Bore	N.A
14	Roadways	One Side
15	Presence of Equipment/Machines	None







Summary of Cracks						
Defect ID	Location	Orientation	Appx. Width (mm)	Appx. Length (m)	Category	Photo No.
1	Roof Varanda of Shop No.791 Ground Floor	Horizontal	0.1	2	Very Slight	10
2	Roof Varanda of Shop No.791 Ground Floor	Horizontal	0.1	1.2	Very Slight	11

Summary of Defects Other Than Crack				
Defect ID	Location	Description	Photo No.	
3	Roof Varanda of Shop No.791 Ground Floor	Peeling of Plaster	12	
4	Roof Varanda of Shop No.790 Ground Floor	Peeling of Plaster	13	
5	Roof Varanda of Shop No.789 Ground Floor	Peeling of Plaster	14	
6	Steps Tiles Shop No.789 Ground Floor	Damaged Portion 15		
7	Steps Tiles Shop No.789 Ground Floor	Dampness/Seepage 16		
8	Varanda of Shop No.786 Ground Floor	Peeling of Plaster 17		
9	Roof Part B of Shop No.785 Ground Floor	Dampness/Seepage 18		
10	Roof Part C of Shop No.785 Ground Floor	Dampness/Seepage 19		
11	Roof Varanda of Shop No.783 Ground Floor	Dampness/Seepage	20	

Summary of Areas that Could not be Surveyed				
Serial No.	Location	Description	Photo No.	
1	All Walls Shop No.791 Ground Floor	Covered With Material	21	
2	All Walls Shop No.790 Ground Floor	Covered With Wooden Work & Material	22	
3	All Walls Shop No.789 Ground Floor	Covered With Wooden Work & Material	23	
4	All Walls Shop No.789 Basement No.1	Covered With Wooden Work & Material	24	
5	All Walls Shop No.789 Basement No.2	Covered With Wooden Work & Material	25	
6	Wall No. 2 Part C of Shop No.787 Ground Floor	Covered With Material	26	
7	Wall No. 1 & 2 Part B of Shop No.787 Ground Floor	Covered With Material	27	
8	Wall No. 2 Part A of Shop No.787 Ground Floor	Covered With Material	28	
9	Wall No. 1, 2 & 4 Shop No.786 Ground Floor	Covered With Material	29	
10	Part A of Shop No.785 Ground Floor	Covered With Material	30	
11	Shop No.784 Ground Floor	Locked	31	
12	All Walls Part B of Shop No.783 Ground Floor	Covered With Material	32	
13	All Walls Part A of Shop No.783 Ground Floor	Covered With Material	33	







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Photo 1 View of Shop No.785



Photo 2 View of Shop No.791, Ground Floor



Photo 3 View of Shop No.790, Ground Floor



Photo 5 View of Shop No.788 , Ground Floor





Photo 4 View of Shop No.789, Ground Floor



Photo 6 View of Shop No.788 , Ground Floor







Photo 7 View of Shop No.787, Ground Floor



Photo 8 View of Shop No.786, Ground Floor



Photo 9 View of Shop No.783, Ground Floor



Photo 10 Horizontal Crack on Roof of Varanda of Shop No.791, Ground Floor Approx. Width = 0.1mm, Approx. Length = 2m. Distance from Rightside External Column = 0.5m, Height from Floor = 3m.





 Photo 1
 Photo 1

 Horizontal Crack on Roof of Varanda of Shop No.791, Ground Floor
 Photo 12

 Approx. Width = 0.1mm, Approx. Length = 1.2m. Distance from Leftside
 Peeling of Plaster on Roof of Varanda of Shop No.791 of Ground Floor

 External Column = 1.4m, Height from Floor = 3m.
 3m.







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line





Photo 13 Peeling of Plaster on Roof of Varanda of Shop No.790 of Ground Floor Peeling of Plaster on Roof of Varanda of Shop No.789 of Ground Floor





Photo 16

Dampness/Seepage on Roof of Varanda of Shop No.787 of Ground

Photo 15 Damaged Portion on Steps Tiles of Shop No.789 of Ground Floor



Photo 17 Peeling of Plaster on of Varanda of Shop No.786 of Ground Floor



Photo 18 Dampness/Seepage on Roof of Part B of Shop No.785 of Ground Floor











Photo 19 Dampness/Seepage on Roof of Part C of Shop No.785 of Ground Floor

Photo 20 Dampness/Seepage on Roof of Varanda of Shop No.783 of Ground Floor





Photo 21 All Walls of Shop No.791 of Ground Floor Covered With Material

Photo 22 All Walls of Shop No.790 of Ground Floor Covered With Wooden Work & Material



Photo 23 All Walls of Shop No.789 of Ground Floor Covered With Wooden Work & Material



Photo 24 All Walls of Shop No.789 of Basement No.1 Covered With Wooden Work & Material





### **Jaipur Metro Rail Corporation**



Photo 25 All Walls of Shop No.789 of Basement No.2 Covered With Wooden Work & Material



Photo 26 Wall No. 2 of Part C of Shop No.787 of Ground Floor Covered With Material





Photo 27 Wall No. 1 & 2 of Part B of Shop No.787 of Ground Floor Covered With Material





Photo 29 Wall No. 1, 2 & 4 of Shop No.786 of Ground Floor Covered With Material



Photo 30 Part A of Shop No.785 of Ground Floor Covered With Material









Photo 31 Shop No.784 of Ground Floor Locked



Photo 32 All Walls of Part B of Shop No.783 of Ground Floor Covered With Material



Photo 33 All Walls of Part A of Shop No.783 of Ground Floor Covered With Material



Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



House No. 758 & Shops 1-4 Choti Chopar Jaipur Unique ID: CC 0004

Report Number: AIMIL/ESG/JMCEC/CC 0004/01, Rev. 00, Dated: January 2014

Building Owner Contractor Various Owners CEC Client Sub-Contractor JMRC Limited AIMIL Limited







Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line

Table of Contents				
S.No.	Particulars	Page No.		
1	Introduction	2		
2	Survey Details	2		
3	About the Structure	3		
4	Building Ownership Details	3		
5	Project Details	4		
6	General Building Details	4		
7	Summary of Cracks	5		
8	Summary of Defects other than Cracks			
9	Summary of Areas that Could not be surveyed			
10	Defect Photographs			
11	Schematic Diagram of Building			

Introduction

The Jaipur Metro Rail is being constructed to provide the city of Jaipur with a modern and technologically advanced Transit System, to provide a safe and well connected means of transport that reduces traffic congestion. The project consists of two corridors with underground and elevated sections.

The construction of underground rail and road infrastructures in metropolitan and cosmopolitan cities are mostly through developed area under challenging soil conditions.

The alignment of structure is passing through densely inhabitated areas, many structures are falling in the zone of influence of construction activities. It is required to carry out the pre-condition survey of those structures. The scope of work of this survey includes carrying out pre-condition survey of those structures.

	Survey Details				
S.No.	Head	Particulars	Signatures		
1	Date of Survey	02/01/2014			
2	AIMIL Representative				
3	CEC Representative				
4	Structural Designer of CEC				
5	JMRC/DMRC Representative				







JAIPUR METRO Jaipur Metro Rail Corporation

Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line

#### About the Structure

The structure under consideration is a Multi Story RCC structure having 3 floors. The structure was constructed in year 2006 and is 7 years old.

There are 79 defects in the structure out of which 9 are cracks. Category wise distribution of cracks is given in the table below. Overall the Building can be categorised in Category II (Slight)

Category	Number of Cracks	% of Total Cracks
Negligible (< 0.1mm)	0	0%
Very Slight (0.1 to 1mm)	7	77.78%
Slight (1 to 5mm)	2	22.22%
Moderate (5 to 15mm)	0	0%
Severe (15 to 25mm)	0	0%
Very Severe (>25mm)	0	0%

The average width of cracks is 0.6mm and average length of cracks is 2.11m. The maximum crack width is 2.5mm and minimum width is	
0.2mm.	

	Building Ownership Details		
Unique ID/Sub ID	Premises Name	Owner	Signatures
CC-0004/FF-SF	H.No. 758		
CC-0004/GF-FF-SF	H.No. 758		
CC-0004/1	United Cording Factory, H.No. 758		
CC-0004/2	United Cording Factory, H.No. 758		
CC-0004/3	United Cording Factory, H.No. 758		
CC-0004/4	United Cording Factory, H.No. 758		







Project Details			
S. No.	Head	Particulars	
1	Project	Jaipur Metro Rail Project	
2	Section	Chandpole to Bari Chaupar	
3	Client	JMRC Limited	
4	Consultant	DMRC Limited	
5	Contractor	CEC	
6	Design Consultant of Contractor	Omikron Kappa - Indus Consultrans JV	
7	Sub-Contractor	AIMIL Limited	
8	Subject	Pre-Condition Survey Report	

General Building Details (As informed verbally by Building Owner)		
S. No.	Head	Particulars
1	Building Name	House No. 758 & Shops 1-4
2	Building Address	House No. 478 & Shops 1-4 Choti Chopar Jaipur
3	Year of Construction	2006
4	Number of Floors	G+2
5	Number of Basements	None
6	Type of Building	Residential + Commercial
7	Approximate Height	9m
8	Approximate Area	Not Known
9	Age of Building	7 years
10	Type of Structure	RCC
11	Type of Foundation	Not Known
12	Number of Bore Wells	None
13	Depth and Diameter of Bore	N.A
14	Roadways	One Side
15	Presence of Equipment/Machines	None







# JAIPUR METRO Jaipur Metro Rail Corporation

	Summary of Cracks					
Defect ID	Location	Orientation	Appx. Width (mm)	Appx. Length (m)	Category	Photo No.
1	Main Entry Shop No. 1, Ground Floor	Inclined	0.2	2	Very Slight	5, 5A
2	Varnadah Roof First Floor	Horizontal	0.3	2	Very Slight	6, 6A
3	Wall No. 2 Store First Floor	Inclined	0.2	3	Very Slight	7
4	Varandah Roof First Floor	Inclined	0.3	2	Very Slight	8
5	Roof Room No. 1 First Floor	Inclined	0.2	2	Very Slight	9
6	Roof Balcony 1 First Floor	Inclined	0.2	2	Very Slight	10
7	Wall No. 4 First Floor	Inclined	1	2	Slight	11
8	Wall No. 2 & 3 Balcony Second Floor	Vertical	2.5	2	Slight	12
9	Wall No. 1 Room No. 1 Second Floor	Inclined	0.5	2	Very Slight	13

	Summary of Der	ects Other Than Crack	
Defect ID	Location	Description	Photo No
10	Main Entry Marble Slab Shop No. 1, Ground Floor	Damaged Portion	14
11	Wall No. 1 & 4 Shop No. 1 Ground Floor	Dampness/Seepage	15
12	Wall No. 1& Roof Shop No. 1 Ground Floor	Dampness/Seepage	16
13	Wall No. 4 Shop No. 1 Ground Floor	Plaster Crack	17
14	Wall No.1&2& Roof, Shop No. 3 Ground Floor	Dampness/Seepage	18
15	Wall No. 2 Shop No. 3 Ground Floor	Dampness/Seepage	19
16	Wall No. 1 Shop No. 3 Ground Floor	Peeling of Plaster	20
17	Roof Shop No. 3 Ground Floor	Peeling of Plaster	21
18	Wall No. 1 Shop No. 4 Ground Floor	Dampness/Seepage	22
19	Wall No. 2 Shop No. 4 Ground Floor	Dampness/Seepage	23
20	Roof Shop No. 4 Ground Floor	Dampness/Seepage	24
21	Wall No. 1 Shop No. 4 Ground Floor	Dampness/Seepage	25
22	Stairs Gate	Plaster Crack	26
23	Wall No. 1 & 3 Stairs GF to FF 0004/ff-sf	Dampness/Seepage	27
24	Roof Passage First Floor	Dampness/Seepage	28
25	Varandah Roof First Floor	Peeling of Plaster	29
26	Roof Kitchen First Floor	Dampness/Seepage	30
27	Wall No. 1 Kitchen First Floor	Peeling of Plaster	31
28	Wall No. 1 & 4 Kitchen First Floor	Peeling of Plaster	32
29	Wall No. 2 Store First Floor	Dampness/Seepage	33
30	Roof Store First Floor	Dampness/Seepage	34
31	Wall No. 2 Room No. 1 First Floor	Dampness/Seepage	35
32	Wall No. 3 Hall No. 1 First Floor	Peeling of Plaster	36
33	Roof First Floor	Dampness/Seepage	37
34	Roof First Floor	Dampness/Seepage	38
35	Wall No. 1 First Floor	Dampness/Seepage	39
36	Wall No. 4 First Floor	Dampness/Seepage	40
37	Wall No. 4 First Floor	Peeling of Plaster	41
38	Roof Balcony 2 First Floor	Dampness/Seepage	42
39	Wall No. 2 First Floor	Dampness/Seepage	43
40	Wall No. 3 First Floor	Peeling of Plaster	44

41	Roof Hall No. 2 Second Floor	Peeling of Plaster	45
42	Roof Hall No. 2 Second Floor	Peeling of Plaster	46
43	Wall No. 1 Hall No. 2 Second Floor	Dampness/Seepage	47
44	Wall No. 1 Hall No. 2 Second Floor	Dampness/Seepage	48
45	Wall No. 1 Hall No. 2 Second Floor	Dampness/Seepage	49
46	Wall No. 1 Hall No. 2 Second Floor	Dampness/Seepage	50
47	Wall No. 2 Hall No. 2 Second Floor	Dampness/Seepage	51
48	Wall No. 1& Roof Hall No. 2 Second Floor	Dampness/Seepage	52
49	Wall No. 4 Hall No. 2 Second Floor	Dampness/Seepage	53
50	Wall No. 4 Hall No. 2 Second Floor	Dampness/Seepage	54
51	Wall No. 4 Hall No. 2 Second Floor	Dampness/Seepage	55
52	Wall No. 4& Roof Hall No. 2 Second Floor	Peeling of Plaster	56
53	Roof Hall No. 2 Second Floor	Plaster Crack	57
54	Roof Hall No. 2 Second Floor	Plaster Crack	58
55	Wall No. 2 Room No. 1 Second Floor	Dampness/Seepage	59
56	Wall No. 1 & Roof Room No. 1 Second Floor	Dampness/Seepage	60
57	Wall No. 4 Room No. 1 Second Floor	Dampness/Seepage	61
58	Wall No.6& Roof Room No. 1 Second Floor	Dampness/Seepage	62
59	Wall No. 4 & Roof Room No. 1 Second Floor	Dampness/Seepage	63
60	Wall No. 6 Hall No. 1 Second Floor	Dampness/Seepage	64
61	Wall No. 6 Hall No. 1 Second Floor	Plaster Crack	65
62	Wall No. 2 Stair SF to Terrace Second Floor	Plaster Crack	66
63	Wall No.2&3& roof, Second Floor	Dampness/Seepage	67
64	Wall No. 1 Stair SF to Terrace	Dampness/Seepage	68
65	Wall No. 2 & 3 Stair FF to SF	Dampness/Seepage	69
66	Roof 0004/gf - sfshop GF	Peeling of Plaster	70
67	Wall No. 2	Peeling of Plaster	71
68	Stair Step GF to FF	Damaged Portion	72
69	Wall No. 4 Toilet No. 1 First Floor	Peeling of Plaster	73
70	Wall No. 2 Toilet No. 1 First Floor	Peeling of Plaster	74
71	Wall No. 2 Toilet No. 1 First Floor	Plaster Crack	75
72	Stair Steps FF to SF	Damaged Portion	76
73	Roof Room No. 1 Second Floor	Peeling of Plaster	77
74	Wall No. 1 Room No. 1 Second Floor	Dampness/Seepage	78
75	Wall No. 2 Room No. 1 Second Floor	Dampness/Seepage	79
76	Wall No. 3 Room No. 1 Second Floor	Peeling of Plaster	80
77	Wall No. 1& Roof Stair SF to Terrace	Dampness/Seepage	81
78	Wall No. 2 Stair SF to Terrace	Dampness/Seepage	82
79	External Façade	Damaged Portion	83

	Summary of Areas that Could not be Surveyed		
Serial No.	Location	Description	Photo No.
1	Roof Shop No. 1 Ground Floor	Covered with False Ceiling	84
2	Wall No. 4 Shop No. 3 Ground Floor	Covered with Material	85
3	Wall No. 4 Shop No. 4 Ground Floor	Covered with Material	86
4	Wall No. 4 Store First Floor	Covered with Material	87
5	All walls Toilet No. 1 First Floor	Covered with Tiles	88
6	Hall No. 1 Second Floor	Locked	89
7	All walls Hall No. 2 Second Floor	Covered with Wood	90
8	Wall No. 3 Room No. 1 Second Floor	Covered with Material	91
9	All walls Toilet No. 1 Second Floor	Covered with Tiles	92





Photo 1 Shop No. 1



Photo 2 Terrace



Photo 3 General View



<u>Photo 4</u> First Floor



 $\label{eq:photo_5} \frac{Photo \ 5}{Photo \ No. \ 1, \ Ground \ Floor, \ Approx.}$  Inclined Crack on of Main Entry, Shop No. 1, Ground Floor, \ Approx. Width = 0.2mm, \ Approx. \ Length = 2m.



 $\label{eq:2.1} \frac{Photo~5}{Photo~5}A$  Inclined Crack on of Main Entry, Shop No. 1, Ground Floor,Approx. Width = 0.2mm, Approx. Length = 2m.







Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line




Photo 6 Horizontal Crack on of Varnadah Roof, First Floor,Approx. Width = 0.3mm, Approx. Length = 2m.



Photo 6A Horizontal Crack on of Varnadah Roof, First Floor,Approx. Width = 0.3mm, Approx. Length = 2m.



Photo 7 Inclined Crack on Wall No. 2 of Store, First Floor,Approx. Width = 0.2mm, Approx. Length = 3m.



Photo 8 Inclined Crack on of Varandah Roof, First Floor Approx. Width = 0.3mm, Approx. Length = 2m.



 $\frac{Photo \ 9}{Inclined \ Crack \ on \ Roof \ of \ Room \ No. \ 1, \ First \ Floor \ Approx. \ Width = 0.2mm, \ Approx. \ Length = 2m.$ 











Photo 11 Inclined Crack on Wall No. 4 of , First Floor Approx. Width = 1mm, Approx. Length = 2m.



Photo 12 Vertical Crack on Wall No. 2 & 3 of Balcony, Second Floor Approx. Width = 2.5mm, Approx. Length = 2m.



Photo 13 Inclined Crack on Wall No. 1 of Room No. 1, Second Floor Approx. Width = 0.5mm, Approx. Length = 2m.



Photo 14 Damaged Portion on of Main Entry Marble Slab of Shop No. 1, Ground Floor



Photo 15 Dampness/Seepage on Wall No. 1 & 4 of Shop No. 1 of Ground Floor



Photo 16 Dampness/Seepage on Wall No.1 & Roof of Shop No. 1 of Ground Floor









Photo 17 Plaster Crack on Wall No. 4 of Shop No. 1 of Ground Floor



Photo 18 Dampness/Seepage on Wall No. 1&2&Roof, Shop No. 3 of Ground Floor





Photo 19 Dampness/Seepage on Wall No. 2 of Shop No. 3 of Ground Floor

Photo 20 Peeling of Plaster on Wall No. 1 of Shop No. 3 of Ground Floor



Photo 21 Peeling of Plaster on Roof of Shop No. 3 of Ground Floor



Photo 22 Dampness/Seepage on Wall No. 1 of Shop No. 4 of Ground Floor









Photo 23 Dampness/Seepage on Wall No. 2 of Shop No. 4 of Ground Floor



Photo 24 Dampness/Seepage on Roof of Shop No. 4 of Ground Floor





Photo 25 Dampness/Seepage on Wall No. 1 of Shop No. 4 of Ground Floor





Photo 27 Dampness/Seepage on Wall No. 1 & 3 of Stairs GF to FF of 0004/ff-sf



Photo 28 Dampness/Seepage on Roof of Passage of First Floor







Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



Photo 29 Peeling of Plaster of Varandah Roof of First Floor



Photo 30 Dampness/Seepage on Roof of Kitchen of First Floor





Photo 32

Peeling of Plaster on Wall No. 1 & 4 of Kitchen of First Floor

Photo 31 Peeling of Plaster on Wall No. 1 of Kitchen of First Floor



Photo 33 Dampness/Seepage on Wall No. 2 of Store of First Floor



Photo 34 Dampness/Seepage on Roof of Store of First Floor









Photo 35 Dampness/Seepage on Wall No. 2 of Room No. 1 of First Floor



Photo 36 Peeling of Plaster on Wall No. 3 of Hall No. 1 of First Floor



Photo 37 Dampness/Seepage on Roof of First Floor



Photo 39 Dampness/Seepage on Wall No. 1 of First Floor





Photo 38 Dampness/Seepage on Roof of First Floor



Photo 40 Dampness/Seepage on Wall No. 4 of First Floor







Photo 41 Peeling of Plaster on Wall No. 4 of First Floor



Photo 42 Dampness/Seepage on Roof of Balcony 2 of First Floor



Photo 43 Dampness/Seepage on Wall No. 2 of First Floor



Photo 44
Peeling of Plaster on Wall No. 3 of First Floor



Photo 45 Peeling of Plaster on Roof of Hall No. 2 of Second Floor



Photo 46 Peeling of Plaster on Roof of Hall No. 2 of Second Floor









Photo 47 Dampness/Seepage on Wall No. 1 of Hall No. 2 of Second Floor



Photo 48 Dampness/Seepage on Wall No. 1 of Hall No. 2 of Second Floor





Photo 49 Dampness/Seepage on Wall No. 1 of Hall No. 2 of Second Floor



<u>Photo 5</u>1 Dampness/Seepage on Wall No. 2 of Hall No. 2 of Second Floor



Dampness/Seepage on Wall No. 1 of Hall No. 2 of Second Floor



Photo 52 Dampness/Seepage on Wall No. 1 & Roof of Hall No. 2 of Second Floor









Photo 53 Dampness/Seepage on Wall No. 4 of Hall No. 2 of Second Floor



Photo 54 Dampness/Seepage on Wall No. 4 of Hall No. 2 of Second Floor





Photo 55 Dampness/Seepage on Wall No. 4 of Hall No. 2 of Second Floor





Photo 57 Plaster Crack on Roof of Hall No. 2 of Second Floor



Photo 58 Plaster Crack on Roof of Hall No. 2 of Second Floor







Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



Photo 59 Dampness/Seepage on Wall No. 2 of Room No. 1 of Second Floor



Photo 60 Dampness/Seepage on Wall No. 1& Roof of Room No. 1 of Second Floor





Photo 62

Dampness/Seepage on Wall No.6 & Roof of Room No. 1 of Second

Floor

Photo 61 Dampness/Seepage on Wall No. 4 of Room No. 1 of Second Floor



Photo 63 Dampness/Seepage on Wall No. 4 & Roof of Room No. 1 of Second Floor



Photo 64 Dampness/Seepage on Wall No. 6 of Hall No. 1 of Second Floor









Photo 65 Plaster Crack on Wall No. 6 of Hall No. 1 of Second Floor



Photo 66 Plaster Crack on Wall No. 2 of Stair SF to Terrace of Second Floor






Photo 67 Dampness/Seepage on Wall No.2&3& roof, Second Floor



Photo 69 Dampness/Seepage on Wall No. 2 & 3 of Stair FF to SF of



<u>Photo 6</u>8 Dampness/Seepage on Wall No. 1 of Stair SF to Terrace of



Photo 70 Peeling of Plaster on Roof of 0004/gf - sfshop GF









Photo 71 Peeling of Plaster on Wall No. 2 of



Photo 72 Damaged Portion of Stair Step GF to FF of



Photo 73 Peeling of Plaster on Wall No. 4 of Toilet No. 1 of First Floor



Photo 74 Peeling of Plaster on Wall No. 2 of Toilet No. 1 of First Floor



Photo 75 Plaster Crack on Wall No. 2 of Toilet No. 1 of First Floor





Photo 76 Damaged Portion of Stair Steps FF to SF of







Photo 77 Peeling of Plaster on Roof of Room No. 1 of Second Floor



Photo 78 Dampness/Seepage on Wall No. 1 of Room No. 1 of Second Floor





Photo 79 Dampness/Seepage on Wall No. 2 of Room No. 1 of Second Floor

Photo 80 Peeling of Plaster on Wall No. 3 of Room No. 1 of Second Floor



Photo 81 Dampness/Seepage on Wall No. 1 & Roof of Stair SF to Terrace of



Photo 82 Dampness/Seepage on Wall No. 2 of Stair SF to Terrace of









Photo 83 Damaged Portion of External Façade



Photo 84 Roof of Shop No. 1 of Ground Floor Covered with False Ceiling





Photo 85 Wall No. 4 of Shop No. 3 of Ground Floor Covered with Material





Photo 87 Wall No. 4 of Store of First Floor Covered with Material





Photo 88 All walls of Toilet No. 1 of First Floor Covered with Tiles







Photo 89 Hall No. 1 of Second Floor Locked



Photo 90 All walls of Hall No. 2 of Second Floor Covered with Wood



Photo 91 Wall No. 3 of Room No. 1 of Second Floor Covered with Material



Photo 92 All walls of Toilet No. 1 of Second Floor Covered with Tiles



Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



House No. 478 & Shops 1-4 Choti Chopar Jaipur Unique ID: CC 0005

Report Number: AIMIL/ESG/JMCEC/CC 0005/01, Rev. 00, Dated: January 2014

Building Owner Contractor Various Owners CEC Client Sub-Contractor JMRC Limited AIMIL Limited







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

	Table of Contents		
S.No.	Particulars	Page No.	
1	Introduction	2	
2	Survey Details	2	
3	About the Structure	3	
4	Building Ownership Details	3	
5	Project Details	4	
6	General Building Details	4	
7	Summary of Cracks	5	
8	Summary of Defects other than Cracks		
9	Summary of Areas that Could not be surveyed		
10	Defect Photographs		
11	Schematic Diagram of Building		

Introduction

The Jaipur Metro Rail is being constructed to provide the city of Jaipur with a modern and technologically advanced Transit System, to provide a safe and well connected means of transport that reduces traffic congestion. The project consists of two corridors with underground and elevated sections.

The construction of underground rail and road infrastructures in metropolitan and cosmopolitan cities are mostly through developed area under challenging soil conditions.

The alignment of structure is passing through densely inhabitated areas, many structures are falling in the zone of influence of construction activities. It is required to carry out the pre-condition survey of those structures. The scope of work of this survey includes carrying out pre-condition survey of those structures.

	Survey Details		
S.No.	Head	Particulars	Signatures
1	Date of Survey	02/01/2014	
2	AIMIL Representative		
3	CEC Representative		
4	Structural Designer of CEC		
5	JMRC/DMRC Representative		







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

About the Structure

The structure under consideration is a Multi Story RCC Framed Structure having 3 floors. The structure was constructed in year 2006 and is 7 years old.

There are 70 defects in the structure out of which 7 are cracks. Category wise distribution of cracks is given in the table below. Overall the Building can be categorised in Category III (Moderate)

Category	Number of Cracks	% of Total Cracks
Negligible (< 0.1mm)	0	0%
Very Slight (0.1 to 1mm)	4	57.14%
Slight (1 to 5mm)	2	28.57%
Moderate (5 to 15mm)	1	14.29%
Severe (15 to 25mm)	0	0%
Very Severe (>25mm)	0	0%

The average width of cracks is 1.49mm and average length of cracks is 1.4m. The maximum crack width is 5mm and minimum width is 0.6mm.

Building Ownership Details					
Unique ID/Sub ID	Premises Name	Owner	Signatures		
CC-0005/FF-SF	H.No. 758				
CC-0005/1	Closed				
CC-0005/2	Khandelwal Thaili Bhandar				
CC-0005/3	Closed				
CC-0005/4	Closed				
CC-0005/5	Bansal Tube Traders, H.No. 758				
CC-0005/6	Bansal Tube Traders, H.No. 758				
CC-0005/7	Bansal Tube Traders, H.No. 758				







Project Details			
S. No.	Head	Particulars	
1	Project	Jaipur Metro Rail Project	
2	Section	Chandpole to Bari Chaupar	
3	Client	JMRC Limited	
4	Consultant	DMRC Limited	
5	Contractor	CEC	
6	Design Consultant of Contractor	Omikron Kappa - Indus Consultrans JV	
7	Sub-Contractor	AIMIL Limited	
8	Subject	Pre-Condition Survey Report	

General Building Details (As informed verbally by Building Owner)				
S. No.	Head	Particulars		
1	Building Name	House No. 478 & Shops 1-4		
2	Building Address	House No. 478 & Shops 1-4 Choti Chopar Jaipur		
3	Year of Construction	2006		
4	Number of Floors	G+2		
5	Number of Basements	None		
6	Type of Building	Residential + Commercial		
7	Approximate Height	9m		
8	Approximate Area	Not Known		
9	Age of Building	7 years		
10	Type of Structure	RCC		
11	Type of Foundation	Not Known		
12	Number of Bore Wells	None		
13	Depth and Diameter of Bore	N.A		
14	Roadways	One Side		
15	Presence of Equipment/Machines	None		







	Summary of Cracks					
Defect ID	Location	Orientation	Appx. Width (mm)	Appx. Length (m)	Category	Photo No.
1	Wall No. 4 Part A Shop No. 7, Ground Floor	Inclined	0.6	0.6	Very Slight	15
2	Roof Part A Shop No. 7, Ground Floor	Horizontal	0.6	2	Very Slight	16
3	Wall No. 3 Part A Shop No. 7, Ground Floor	Horizontal	0.6	0.5	Very Slight	17
4	Wall No. 1 Shop No. 5 Ground Floor	Inclined	0.6	0.7	Very Slight	18, 18A
5	Wall No. 3 Passage House No. 758, First Floor	Inclined	1.5	2	Slight	19, 19A
6	House No. 758, First Floor	Horizontal	5	2.5	Moderate	20
7	Roof House No. 758, First Floor	Inclined	1.5	1.5	Slight	21, 21A

	Summary of De	fects Other Than Crack	
Defect ID	Location	Description	Photo No.
8	Wall No. 1 Shop No. 6 Ground Floor	Peeling of Plaster	22
9	Wall No. 4 Shop No. 6 Ground Floor	Peeling of Plaster	23
10	Wall No. 2 Shop No. 6 Ground Floor	Peeling of Plaster	24
11	Wall No. 2 Shop No. 6 Ground Floor	Peeling of Plaster	25
12	Roof Shop No. 6 Ground Floor	Peeling of Plaster	26
13	Wall No. 2 Shop No. 6 Ground Floor	Plaster Crack	27
14	Roof Part A Shop No. 7, Ground Floor	Peeling of Plaster	28
15	Roof Part A Shop No. 7, Ground Floor	Peeling of Plaster	29
16	Roof Part B Shop No. 7, Ground Floor	Dampness/Seepage	30
17	Roof Part C Shop No. 7, Ground Floor	Dampness/Seepage	31
18	Roof Part C Shop No. 7, Ground Floor	Dampness/Seepage	32
19	Roof Shop No. 8 Ground Floor	Plaster Crack	33
20	Wall No. 1 Shop No. 5 Ground Floor	Peeling of Plaster	34
21	Wall No. 4 Shop No. 5 Ground Floor	Peeling of Plaster	35
22	Wall No. 2 Shop No. 5 Ground Floor	Plaster Crack	36
23	Wall No. 2 Shop No. 5 Ground Floor	Damaged Portion	37
24	Roof Shop No. 10 Ground Floor	Peeling of Plaster	38
25	Wall No. 1 Shop No. 10 Ground Floor	Peeling of Plaster	39
26	Wall No. 1 Shop No. 11 Ground Floor	Peeling of Plaster	40
27	Roof Shop No. 11 Ground Floor	Peeling of Plaster	41
28	Wall No. 4 Shop No. 11 Ground Floor	Peeling of Plaster	42
29	Wall No. 2 Shop No. 11 Ground Floor	Peeling of Plaster	43
30	Wall No. 3 Shop No. 11 Ground Floor	Peeling of Plaster	44
31	Wall No. 1 Shop No. 12 Ground Floor	Peeling of Plaster	45
32	Roof Shop No. 12 Ground Floor	Peeling of Plaster	46
33	Wall No. 1 Shop No. 2 Ground Floor	Peeling of Plaster	47
34	Wall No. 1 Shop No. 15 Ground Floor	Peeling of Plaster	48
35	Wall No. 2 Shop No. 15 Ground Floor	Dampness/Seepage	49
36	Wall No. 1 Shop No. 13 Ground Floor	Peeling of Plaster	50
37	Wall No. 3 Passage 1 House No. 758, First Floor	Peeling of Plaster	51
38	Wall No. 1 House No. 758, First Floor	Peeling of Plaster	52
39	Wall No. 2 House No. 758, First Floor	Peeling of Plaster	53
40	Roof House No. 758, First Floor	Dampness/Seepage	54

41	Wall No. 1 House No. 758, First Floor	Peeling of Plaster	55
42	Wall No. 3 Passage 2 House No. 758, First Floor	Peeling of Plaster	56
43	Roof House No. 758, First Floor	Peeling of Plaster	57
44	Wall No. 4 House No. 758, First Floor	Peeling of Plaster	58
45	Wall No. 1 House No. 758, First Floor	Peeling of Plaster	59
46	Wall No. 2 House No. 758, First Floor	Peeling of Plaster	60
47	Wall No. 3 Stair GF to FF House No. 758, Stair Ground Floor to First Floor	Peeling of Plaster	61
48	Roof House No. 758, First Floor	Dampness/Seepage	62
49	Wall No. 1 House No. 758, First Floor	Peeling of Plaster	63
50	Wall No. 4 Room No. 1 House No. 758, First Floor	Dampness/Seepage	64
51	Wall No. 2 Room No. 1 House No. 758, First Floor	Dampness/Seepage	65
52	Wall No. 3 Room No. 1 House No. 758, First Floor	Dampness/Seepage	66
53	Wall No. 1 Room No. 1 House No. 758, First Floor	Dampness/Seepage	67
54	Wall No. 2 & 3 Room No. 12 House No. 758, First Floor	Peeling of Plaster	68
55	Roof Room No. 11 House No. 758, First Floor	Peeling of Plaster	69
56	Roof Room No. 11 House No. 758, First Floor	Peeling of Plaster	70
57	Wall No. 2 Room No. 11 House No. 758, First Floor	Peeling of Plaster	71
58	Wall No. 3 Room No. 11 House No. 758, First Floor	Dampness/Seepage	72
59	Room No. 5 House No. 758, First Floor	Peeling of Plaster	73
60	Wall No. 1 Bathroom No. House No. 758, First Floor	Peeling of Plaster	74
61	Room No. 9 House No. 758, First Floor	Dampness/Seepage	75
62	Room No. 10 House No. 758, First Floor	Peeling of Plaster	76
63	Wall No. 4 & Roof House No. 758, First Floor	Peeling of Plaster	77
64	Wall No. 4 House No. 758, First Floor	Peeling of Plaster	78
65	Roof of House No. 758, First Floor	Peeling of Plaster	79
66	Wall No. 1 Stair FF to SF House No. 758, Stair First Floor to Second Floor Wall No. 4 & Rool Stair FF to SF House No. 758, Stair	Dampness/Seepage	80
67	First Floor to Second Floor	Dampness/Seepage	81
68	Wall No. 4 Room No. 1 House No. 758, Second Floor	Dampness/Seepage	82
69	Room No. 5 House No. 758, Second Floor	Plaster Crack	83
70	Room No. 6 House No. 758, Second Floor	Plaster Crack	84

	Summary of Areas tha	t Could not be Surveyed	
Serial No.	Location	Description	Photo No.
1	All Walls Shop No. 7 Ground Floor	Covered with Material	85
2	Wall No. 1 & 4 Part C Shop No. 7, Ground Floor	Covered with Material	86
3	Wall No. 2 & 4 Part C Shop No. 7, Ground Floor	Covered with Material	87
4	Wall No. 1 & 4 Shop No. 8 Ground Floor	Covered with Material	88
5	Wall No. 2 & 4 Shop No. 8 Ground Floor	Covered with Material	89
6	All Walls Shop No. 2 Ground Floor	Covered with Material	90
7	Store 1 House No. 758, First Floor	Locked	91
8	House No. 758, First Floor	Locked	92
9	Wall No. 3 Room No. 11 House No. 758, First Floor	Locked	93
10	Room No. 2 House No. 758, First Floor	Locked	94
11	Room No. 3 House No. 758, First Floor	Locked	95
12	Room No. 4 House No. 758, First Floor	Locked	96
13	All wall Hall Ponion of Room No. 6 House No. 758, First	Covered with Tiles	97
14	All Walls Bathroom No. House No. 758, First Floor	Locked	98
15	Bathroom No. House No. 758, First Floor	Locked	99
16	Room No. 7 House No. 758, First Floor	Locked	100
17	Room No. 8 House No. 758, First Floor	Locked	101
18	Room No. 4 House No. 758, Second Floor	Locked	102
19	vvali No. Parapet vvali 2 & Parapet vvali 4 House No. 758. Second Floor		103





Photo 1 General View of Shop No. 15



Photo 2 General View of Shop, Ground Floor



Photo 3 General View of Shop No. 7, Ground Floor



Photo 5 General View of Shop No. 5, Ground Floor





Photo 4 General View of Shop No. 8, Ground Floor



Photo 6 General View of Shop No. 10, Ground Floor



### **Jaipur Metro Rail Corporation**



Photo 7 General View of Shop No. 11, Ground Floor



Photo 8 General View Shop No. 12, Ground Floor



Photo 9 All wall Covered With Materials Shop No. 2, Ground Floor



Photo 11 General View of House No. 758, Second Floor





Photo 10 General View Shop No. 13, Ground Floor



Photo 12 General House No. 758, Second Floor





Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Photo 13 General View of House No. 758, Second Floor



Photo 14 General View of House No. 758, Second Floor



Photo 15 Inclined Crack on Wall No. 4 of Part A, Shop No. 7, Ground Floor Approx. Width = 0.6mm, Approx. Length = 0.6m. Distance from Wall No. 2 = 0.9m, Height from Floor = 2.2m.



Photo 17 Horizontal Crack on Wall No. 3 of Part A, Shop No. 7, Ground Floor Approx. Width = 0.6mm, Approx. Length = 0.5m. Distance from Wall No. 2 = 2.3m, Height from Floor = 2.3m.






Photo 16 Horizontal Crack on Roof of Part A, Shop No. 7, Ground Floor Approx. Width = 0.6mm, Approx. Length = 2m. Distance from Wall No. 2 = 1m, Height from Floor = 3m.



Photo 18 Inclined Crack on Wall No. 1 of Shop No. 5, Ground Floor Approx. Width = 0.6mm, Approx. Length = 0.7m. Distance from Wall No. 3 = 0.3m, Height from Floor = 1.5m.



## **Jaipur Metro Rail Corporation**

Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Photo 18A Inclined Crack on Wall No. 1 of Shop No. 5, Ground Floor Approx. Width = 0.6mm, Approx. Length = 0.7m. Distance from Wall No. 3 = 0.3m, Height from Floor = 1.5m.



Photo 19 Inclined Crack on Wall No. 3 of Passage, House No. 758, First Floor Approx. Width = 1.5mm, Approx. Length = 2m. Distance from Wall No. 2 = 3m, Height from Floor = 2m.



Photo 20 Horizontal Crack on House No. 758, First Floor Approx. Width = 5mm, Approx. Length = 2.5m. Distance from Wall No. 1 = 0.5m, Height from Floor = 3m.





Photo 18A Inclined Crack on Wall No. 1 of Shop No. 5, Ground Floor Approx. Width = 0.6mm, Approx. Length = 0.7m. Distance from Wall No. 3 = 0.3m, Height from Floor = 1.5m.



Photo 19A Inclined Crack on Wall No. 3 of Passage, House No. 758, First Floor Approx. Width = 1.5mm, Approx. Length = 2m. Distance from Wall No. 2 = 3m, Height from Floor = 2m.



Photo 21 Inclined Crack on Roof of , House No. 758, First Floor Approx. Width = 1.5mm, Approx. Length = 1.5m. Distance from Wall No. 1 = 2.5m, Height from Floor = 2m.







Photo 21A Inclined Crack on Roof of , House No. 758, First Floor Approx. Width = 1.5mm, Approx. Length = 1.5m. Distance from Wall No. 1 = 2.5m, Height from Floor = 2m.



Photo 22 Peeling of Plaster on Wall No. 1 of Shop No. 6 of Ground Floor





Photo 23 Peeling of Plaster on Wall No. 4 of Shop No. 6 of Ground Floor

Photo 24 Peeling of Plaster on Wall No. 2 of Shop No. 6 of Ground Floor



Photo 25 Peeling of Plaster on Wall No. 2 of Shop No. 6 of Ground Floor



Photo 26 Peeling of Plaster on Roof of Shop No. 6 of Ground Floor









Photo 27 Plaster Crack on Wall No. 2 of Shop No. 6 of Ground Floor



Photo 28 Peeling of Plaster on Roof of Part A of Shop No. 7, Ground Floor





Photo 29 Peeling of Plaster on Roof of Part A of Shop No. 7, Ground Floor





Photo 31 Dampness/Seepage on Roof of Part C of Shop No. 7, Ground Floor



Photo 32 Dampness/Seepage on Roof of Part C of Shop No. 7, Ground Floor







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Photo 33 Plaster Crack on Roof of Shop No. 8 of Ground Floor



Photo 34 Peeling of Plaster on Wall No. 1 of Shop No. 5 of Ground Floor








Photo 36

Peeling of Plaster on Wall No. 4 of Shop No. 5 of Ground Floor Plaster Crack on Wall No. 2 of Shop No. 5 of Ground Floor



Photo 37 Damaged Portion on Wall No. 2 of Shop No. 5 of Ground Floor



Photo 38 Peeling of Plaster on Roof of Shop No. 10 of Ground Floor









Photo 39 Peeling of Plaster on Wall No. 1 of Shop No. 10 of Ground Floor



Photo 40 Peeling of Plaster on Wall No. 1 of Shop No. 11 of Ground Floor





Photo 41 Peeling of Plaster on Roof of Shop No. 11 of Ground Floor






Photo 43 Peeling of Plaster on Wall No. 2 of Shop No. 11 of Ground Floor



Photo 44 Peeling of Plaster on Wall No. 3 of Shop No. 11 of Ground Floor









Photo 45 Peeling of Plaster on Wall No. 1 of Shop No. 12 of Ground Floor



Photo 46 Peeling of Plaster on Roof of Shop No. 12 of Ground Floor





Photo 47 Peeling of Plaster on Wall No. 1 of Shop No. 2 of Ground Floor

Photo 48 Peeling of Plaster on Wall No. 1 of Shop No. 15 of Ground Floor



Photo 49 Dampness/Seepage on Wall No. 2 of Shop No. 15 of Ground Floor



Photo 50 Peeling of Plaster on Wall No. 1 of Shop No. 13 of Ground Floor









Photo 51 Peeling of Plaster on Wall No. 3 of Passage 1 of House No. 758, First Floor



Photo 52 Peeling of Plaster on Wall No. 1 of of House No. 758, First Floor





Photo 53 Peeling of Plaster on Wall No. 2 of House No. 758, First Floor





Photo 55 Peeling of Plaster on Wall No. 1 of House No. 758, First Floor



Photo 56 Peeling of Plaster on Wall No. 3 of Passage 2 of House No. 758, First Floor









Photo 57 Peeling of Plaster on Roof of House No. 758, First Floor



Photo 58 Peeling of Plaster on Wall No. 4 of House No. 758, First Floor





Photo 59 Peeling of Plaster on Wall No. 1 of of House No. 758, First Floor

Photo 60 Peeling of Plaster on Wall No. 2 of of House No. 758, First Floor



Photo 61 Peeling of Plaster on Wall No. 3 of Stair GF to FF of House No. 758, Stair Ground Floor to First Floor



Photo 62 Dampness/Seepage on Roof of House No. 758, First Floor









Photo 63 Peeling of Plaster on Wall No. 1 of of House No. 758, First Floor



Photo 64 Dampness/Seepage on Wall No. 4 of Room No. 1 of House No. 758, First Floor



Photo 65 Dampness/Seepage on Wall No. 2 of Room No. 1 of House No. 758, First Floor



Photo 66 Dampness/Seepage on Wall No. 3 of Room No. 1 of House No. 758, First Floor



Photo 67 Dampness/Seepage on Wall No. 1 of Room No. 1 of House No. 758, First Floor



Photo 68 Peeling of Plaster on Wall No. 2 & 3 of Room No. 12 of House No. 758, First Floor









Photo 69 Peeling of Plaster on Roof of Room No. 11 of House No. 758, First Floor Peeling of Plaster on Roof of Room No. 11 of House No. 758, First Floor





Photo 71
Peeling of Plaster on Wall No. 2 of Room No. 11 of House No. 758, First Dampness/Seepage on Wall No. 3 of Room No. 11 of House No. 758, First Floor
First Floor
First Floor



Photo 73 Peeling of Plaster on Room No. 5 of House No. 758, First Floor

Photo 74 Peeling of Plaster on Wall No. 1 of Bathroom of House No. 758, First Floor









Photo 75 Dampness/Seepage on Room No. 9 of House No. 758, First Floor



Photo 76 Peeling of Plaster on Room No. 10 of House No. 758, First Floor





Photo 77 Peeling of Plaster on Wall No. 4 & Roof of House No. 758, First Floor

Photo 78 Peeling of Plaster on Wall No. 4 of of House No. 758, First Floor




Photo 79 Peeling of Plaster on Roof of of House No. 758, First Floor



Photo 80 Dampness/Seepage on Wall No. 1 of Stair FF to SF of House No. 758, Stair First Floor to Second Floor











Photo 81 Dampness/Seepage on Wall No. 4 & Roof 4 of Stair FF to SF of House No. 758, Stair First Floor to Second Floor

Photo 82 Dampness/Seepage on Wall No. 4 of Room No. 1 of House No. 758, Second Floor





Photo 83 Plaster Crack on of Room No. 5 of House No. 758, Second Floor

Photo 84 Plaster Crack on Wall No. 2 of Open Sky of House No. 758, Second Floor



Photo 85 All Walls of Shop No. 7 of Ground Floor Covered with Material



Photo 86 Wall No. 1 & 4 of Part C of Shop No. 7, Ground Floor Covered with Material









Photo 87 Wall No. 2 & 4 of Part C of Shop No. 7, Ground Floor Covered with Material



Photo 88 Wall No. 1 & 4 of Shop No. 8 of Ground Floor Covered with Material





Photo 89 Wall No. 2 & 4 of Shop No. 8 of Ground Floor Covered with Material





Photo 92 House No. 758, First Floor Locked







Photo 91 Store 1 of House No. 758, First Floor Locked





Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Photo 93 Room No. 11 of House No. 758, First Floor Locked



Photo 94 Room No. 2 of House No. 758, First Floor Locked



Photo 95 Room No. 3 of House No. 758, First Floor Locked



Photo 97 All wall Half Portion of Room No. 6 of House No. 758, First Floor Covered with Tiles





Photo 96 Room No. 4 of House No. 758, First Floor Locked



Photo 98 First Floor Locked







Photo 99 Bathroom of House No. 758, First Floor Locked



Photo 100 Room No. 7 of House No. 758, First Floor Locked



Photo 101 Room No. 8 of House No. 758, First Floor Locked



Photo 102 Room No. 4 of House No. 758, Second Floor Locked



Photo 103 Steel Work on Parapet Wall 2 & Parapet Wall 4 of House No. 758, Second Floor



Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



Shop No.013-047/221/225 Rana Krishna Market,Chatur Bhuji Khanda,Choti Chopar Jaipur Unique ID: CC 0006

Report Number: AIMIL/ESG/JMCEC/CC 0006/01, Rev. 00, Dated: January 2014

Building Owner Contractor Various Owners CEC Client Sub-Contractor JMRC Limited AIMIL Limited







Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line

	Table of Contents			
S.No.	Particulars	Page No.		
1	Introduction	2		
2	Survey Details	2		
3	About the Structure	3		
4	Building Ownership Details	3		
5	Project Details	4		
6	General Building Details	4		
7	Summary of Cracks	5		
8	Summary of Defects other than Cracks			
9	Summary of Areas that Could not be surveyed			
10	Defect Photographs			
11	Schematic Diagram of Building			

Introduction

The Jaipur Metro Rail is being constructed to provide the city of Jaipur with a modern and technologically advanced Transit System, to provide a safe and well connected means of transport that reduces traffic congestion. The project consists of two corridors with underground and elevated sections.

The construction of underground rail and road infrastructures in metropolitan and cosmopolitan cities are mostly through developed area under challenging soil conditions.

The alignment of structure is passing through densely inhabited areas, many structures are falling in the zone of influence of construction activities. It is required to carry out the pre-condition survey of those structures. The scope of work of this survey includes carrying out pre-condition survey of those structures.

	Survey Details					
S.No.	Head	Particulars	Signatures			
1	Date of Survey	02/01/2014				
2	AIMIL Representative					
3	CEC Representative					
4	Structural Designer of CEC					
5	JMRC/DMRC Representative					







Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line

About the Structure

The structure under consideration is a Single Story Load Bearing Structure having 1 floor and a Basement. The structure was constructed in year 1933 and is 80 years old.

There are 27 defects in the structure out of which 7 are cracks. Category wise distribution of cracks is given in the table below. Overall the Building can be categorised in Category II (Slight)

Category	Number of Cracks	% of Total Cracks
Negligible (< 0.1mm)	0	0%
Very Slight (0.1 to 1mm)	4	57.14%
Slight (1 to 5mm)	3	42.86%
Moderate (5 to 15mm)	0	0%
Severe (15 to 25mm)	0	0%
Very Severe (>25mm)	0	0%

The average width of cracks is 1.23mm and average length of cracks is 2.33m. The maximum crack width is 2.5mm and minimum width is 0.2mm.

	Building Ownership Details				
Unique ID/Sub ID	Premises Name	Owner	Signatures		
CC/0006/1	Vikas & Company				
CC/0006/2	Jai Shree Shyam				
CC/0006/3	Lokesh Kumar				
CC/0006/4	Dinesh Dal Mil				
CC/0006/5	Shri Laxman Agency				
CC/0006/6	Hari Om Traders				
CC/0006/7	Shri Bala Ji Enterprises				
CC/0006/8	Suman Sales Corp.				
CC/0006/9	Vishal Traders				
CC/0006/10	Anand Traders				







Project Details				
S. No.	Head	Particulars		
1	Project	Jaipur Metro Rail Project		
2	Section	Chandpole to Bari Chaupar		
3	Client	JMRC Limited		
4	Consultant	DMRC Limited		
5	Contractor	CEC		
6	Design Consultant of Contractor	Omikron Kappa - Indus Consultrans JV		
7	Sub-Contractor	AIMIL Limited		
8	Subject	Pre-Condition Survey Report		

S. No.	Head	Particulars
1	Building Name	Shop No.013-047/221/225
2	Building Address	Rana Krishna Market, Chatur Bhuji Khanda, Chhoti Chopar
3	Year of Construction	1933
4	Number of Floors	B+G
5	Number of Basements	1
6	Type of Building	Commercial
7	Approximate Height	3m
8	Approximate Area	Not Known
9	Age of Building	80 years
10	Type of Structure	Load Bearing Structure
11	Type of Foundation	Not Known
12	Number of Bore Wells	None
13	Depth and Diameter of Bore	N.A
14	Roadways	One Side
15	Presence of Equipment/Machines	None







# JAIPUR METRO Jaipur Metro Rail Corporation

	Summary of Cracks					
Defect ID	Location	Orientation	Appx. Width (mm)	Appx. Length (m)	Category	Photo No.
1	Wall No. 1 Shop No. 16 Ground Floor	Inclined	0.3	2.3	Very Slight	26, 26A
2	Shop No. 16 Ground Floor	Horizontal	0.3	3	Very Slight	27
3	Shop No. 16 Ground Floor	Inclined	0.2	1.5	Very Slight	28
4	Passage 3 of Shop No. 221 Ground Floor	Vertical	0.8	2	Very Slight	29, 29A
5	Wall No. 2 Passage 3 of Shop No. 221 Ground Floor	Inclined	2	1.5	Slight	30
6	Beam Passage 3 of Shop No. 221 Ground Floor	Inclined	2.5	2	Slight	31, 31A
7	Roof Passage 4 of Shop No. 225 Ground Floor	Inclined	2.5	4	Slight	32

	Summary of Defects Other Than Crack			
Defect ID	Location	Description	Photo No.	
8	Roof Varanda of Shop No. 23 Ground Floor	Peeling of Plaster	33	
9	Wall No. 2, Roof & 4 Shop No. 22 Ground Floor	Peeling of Plaster	34	
10	Wall No. 2, Roof & 4 Shop No. 22 Ground Floor	Peeling of Plaster	35	
11	Roof Shop No. 21 Ground Floor	Peeling of Plaster	36	
12	Roof Passage of Shop No. 26 Ground Floor	Peeling of Plaster	37	
13	Wall No. 2 Shop No. 16 Ground Floor	Peeling of Plaster	38	
14	Roof Shop No. 18 Ground Floor	Peeling of Plaster	39	
15	Roof Shop No. 47 Ground Floor	Peeling of Plaster	40	
16	Wall No. 3 Shop No. 47 Ground Floor	Peeling of Plaster	41	
17	Wall No. 4 Shop No. 47 Ground Floor	Peeling of Plaster	42	
18	Passage 3 of Shop No. 221 Ground Floor	Dampness/Seepage	43	
19	Wall No. 2 Passage 3 of Shop No. 221 Ground Floor	Peeling of Plaster	44	
20	Wall No. 1 Passage 1 of Shop No. 221 Ground Floor	Dampness/Seepage	45	
21	Wall No. 1 Passage 1 of Shop No. 221 Ground Floor	Dampness/Seepage	46	
22	Wall No. 1 Passage 1 of Shop No. 221 Ground Floor	Peeling of Plaster	47	
23	Shop No. 221 Ground Floor	Peeling of Plaster	48	
24	Wall No. 1 Passage 4 of Shop No. 225 Ground Floor	Peeling of Plaster	49	
25	Wall No. 1 Passage 4 of Shop No. 225 Ground Floor	Peeling of Plaster	50	
26	Wall No. 1 Passage 4 of Shop No. 225 Ground Floor	Peeling of Plaster	51	
27	Wall No. 3 Passage 4 of Shop No. 225 Ground Floor	Dampness/Seepage	52	

	Summary of Areas that Could not be Surveyed				
Serial No.	Location	Description	Photo No.		
1	Wall No. 2 & 4 Shop No. 23 Ground Floor	Covered with Material	53		
2	All Walls & Roof Shop No. 22 Ground Floor	Covered with Wooden Work	54		
3	All walls Shop No. 21 Ground Floor	Covered with Material	55		
4	Wall No. 2 & 4 Shop No. 20 Ground Floor	Covered with Material	56		
5	Wall No. 2 & 4 Shop No. 20 Ground Floor	Covered with Material	57		
6	All walls Shop No. 20 Ground Floor	Covered with Material	58		
7	All walls Shop No. 24 Ground Floor	Covered with Material	59		
8	All walls Shop No. 25 Ground Floor	Covered with Material	60		
9	All walls Shop No. 27, Part 1 Ground Floor	Covered with Tiles	61		
10	All walls Shop No. 27, Part 2 Ground Floor	Covered	62		

11	All walls Shop No. 26 Ground Floor	Covered	63
12	All walls Shop No. 25 Ground Floor	Covered	64
13	Wall No. 4 Shop No. 16 Ground Floor	Covered	65
14	Wall No. 2 & 4 Shop No. 32 Ground Floor	Covered	66
15	All walls Shop No. 34 Ground Floor	Covered	67
16	Wall No. 1 & 4 Shop No. 29 Ground Floor	Covered	68
17	Roof Shop No. 29 Ground Floor	Covered	69
18	Wall No. 2 & 4 Shop No. 31 Ground Floor	Covered	70
19	Shop No. 30 Ground Floor	Locked	71
20	Wall No. 1, 2 & 4 Shop No. 33 Ground Floor	Covered with Material	72
21	Wall No. 1, 2 & 4 Shop No. 36 Ground Floor	Covered with Material	73
22	All walls Shop No. 14 Ground Floor	Covered with Material	74
23	All walls Shop No. 13 Ground Floor	Covered with Material	75
24	All walls Shop No. 17 Ground Floor	Covered with Material	76
25	Wall No. 4 Shop No. 18 Ground Floor	Covered with Material	77
26	Wall No. 1 Shop No. 18 Ground Floor	Covered with Material	78
27	Wall No. 2 Shop No. 18 Ground Floor	Covered with Material	79
28	Wall No. 1 & 2 Shop No. 47 Ground Floor	Covered with Material	80
29	Wall No. 1 & 2 Shop No. 47 Ground Floor	Covered with Material	81
30	All Walls Shop No. 38 Ground Floor	Covered with Material	82
31	All Walls Shop No. 39 Ground Floor	Covered with Wooden Work	83
32	All Walls Shop No. 40 Ground Floor	Covered with Material	84
33	All Walls Shop No. 41 Ground Floor	Covered with Material	85
34	All Walls Shop No. 42 Ground Floor	Covered with Material	86
35	All Walls Shop No. 43 Ground Floor	Covered with Material	87
36	All Walls Shop No. 44 Ground Floor	Covered with Material	88
37	Passage 2 of Shop No. 225 Ground Floor	Covered with Material	89
38	Shop No. 225 Ground Floor	Covered with Material	90
39	All Walls Shop No. 15 Ground Floor	Locked	91
40	All Walls Shop No. 19 Ground Floor	Covered with Material	92





A MEMBER OF CONTINENTAL HOLDINGS



Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



Photo 1 Shop No. 32



Photo 2 View of Shop, Ground Floor



Photo 3 Shop No. 28, Ground Floor



Photo 4 Shop No. 45, Ground Floor



Photo 6 Shop No. 29, Ground Floor





Photo 5 Shop No. 34, Ground Floor





Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



Photo 7 Shop No. 31, Ground Floor



Photo 8 Shop No. 33, Ground Floor



Photo 9 Shop No. 36, Ground Floor



Photo 10 Shop No. 14, Ground Floor



Photo 11 Shop No. 13, Ground Floor





Photo 12 Shop No. 17, Ground Floor





Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



Photo 13 Shop No. 18, Ground Floor



Photo 14 Shop No. 47, Ground Floor



Photo 15 Shop No. 37, Ground Floor



Photo 16 Shop No. 37, Ground Floor



Photo 17 Shop No. 38, Ground Floor





Photo 18 Shop No. 39, Ground Floor





Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



Photo 19 Shop No. 40, Ground Floor



Photo 20 Shop No. 41, Ground Floor



Photo 21 Shop No. 42, Ground Floor



Photo 22 Shop No. 43, Ground Floor



Photo 23 Shop No. 221, Ground Floor





Photo 24 Shop No. 225, Ground Floor



Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



JAIPUR METRO

Photo 25 Shop No. 44, Ground Floor



Photo 26 Inclined Crack on Wall No. 1 of Shop No. 16, Ground Floor,Approx. Width = 0.3mm, Approx. Length = 2.3m. Distance from Wall No.4 = 0m, Height from Floor = 0.3m.



Photo 26A Inclined Crack on Wall No. 1 of Shop No. 16, Ground Floor,Approx. Width = 0.3mm, Approx. Length = 2.3m. Distance from Wall No.4 = 0m, Height from Floor = 0.3m.



Photo 28 Inclined Crack on of Shop No. 16, Ground Floor,Approx. Width = 0.2mm, Approx. Length = 1.5m.Distance from Wall No.1 = 0.25m, Height from Floor = 2.1m.



<u>Photo 2</u>7 Horizontal Crack on of Shop No. 16, Ground Floor,Approx. Width = 0.3mm, Approx. Length = 3m.

Distance from Wall No.4 = 0m, Height from Floor = 2m.



Photo 29 Vertical Crack on of Passage 3 of Shop No. 221, Ground Floor,Approx. Width = 0.8mm, Approx. Length = 2m. Distance from Wall No. 4 = 3.5m, Height from Floor = 2m.



Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



JAIPUR METRO

Photo 29A Vertical Crack on of Passage 3 of Shop No. 221, Ground Floor,Approx. Width = 0.8mm, Approx. Length = 2m. Distance from Wall No. 4 = 3.5m, Height from Floor = 2m.



Photo 31 Inclined Crack on Beam of Passage 3 of Shop No. 221, Ground Floor,Approx. Width = 2.5mm, Approx. Length = 2m. Distance from Wall No. 3 = 4m, Height from Floor = 0m.



Photo 32 Inclined Crack on Roof of Passage 4 of Shop No. 225, Ground Floor,Approx. Width = 2.5mm, Approx. Length = 4m. Distance from Wall No. 4 = 8m, Height from Floor = 4m.





Photo 30 Inclined Crack on Wall No. 2 of Passage 3 of Shop No. 221, Ground Floor,Approx. Width = 2mm, Approx. Length = 1.5m. Distance from Wall No. 1 = 0m, Height from Floor = 2.5m.



Photo 31A Inclined Crack on Beam of Passage 3 of Shop No. 221, Ground Floor,Approx. Width = 2.5mm, Approx. Length = 2m. Distance from Wall No. 3 = 4m, Height from Floor = 0m.



Photo <u>3</u>3 Peeling of Plaster on Roof of Varanda of Shop No. 23 of Ground Floor







Photo 34 Peeling of Plaster on Wall No. 2, Roof & 4 of Shop No. 22 of Ground Floor



Photo 35 Peeling of Plaster on Wall No. 2, Roof & 4 of Shop No. 22 of Ground Floor





Photo 36 Peeling of Plaster on Roof of Shop No. 21 of Ground Floor



Photo 38 Peeling of Plaster on Wall No. 2 of Shop No. 16 of Ground Floor



Peeling of Plaster on Roof of Passage of Shop No. 26 of Ground Floor



Photo 39 Peeling of Plaster on Roof of Shop No. 18 of Ground Floor









Photo 40 Peeling of Plaster on Roof of Shop No. 47 of Ground Floor



Photo 41 Peeling of Plaster on Wall No. 3 of Shop No. 47 of Ground Floor





Photo 42 Peeling of Plaster on Wall No. 4 of Shop No. 47 of Ground Floor

Photo 43 Dampness/Seepage on of Passage 3 of Shop No. 221 of Ground Floor



Photo 44 Peeling of Plaster on Wall No. 2 of Passage 3 of Shop No. 221 of Ground Floor



Photo 45 Dampness/Seepage on Wall No. 1 of Passage 1 of Shop No. 221 of Ground Floor







Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



Photo 46 Dampness/Seepage on Wall No. 1 of Passage 1 of Shop No. 221 of Ground Floor



Photo 47 Peeling of Plaster on Wall No. 1 of Passage 1 of Shop No. 221 of Ground Floor





<u>Photo 4</u>9

Peeling of Plaster on Wall No. 1 of Passage 4 of Shop No. 225 of

Ground Floor

Photo 48 Peeling of Plaster on of Shop No. 221 of Ground Floor



Photo 50 Peeling of Plaster on Wall No. 1 of Passage 4 of Shop No. 225 of Ground Floor



Photo 51 Peeling of Plaster on Wall No. 1 of Passage 4 of Shop No. 225 of Ground Floor









Photo 52 Dampness/Seepage on Wall No. 3 of Passage 4 of Shop No. 225 of Ground Floor



Photo 53 Wall No. 2 & 4 of Shop No. 23 of Ground Floor Covered with Material





Photo 54 All Walls & Roof of Shop No. 22 of Ground Floor Covered with Wooden Work

Photo 55 All walls of Shop No. 21 of Ground Floor Covered with Material



Photo 56 Wall No. 2 & 4 of Shop No. 20 of Ground Floor Covered with Material



Photo 57 Wall No. 2 & 4 of Shop No. 20 of Ground Floor Covered with Material









Photo 58 All walls of Shop No. 20 of Ground Floor Covered with Material

Photo 59 All walls of Shop No. 24 of Ground Floor Covered with Material





Photo 60 All walls of Shop No. 25 of Ground Floor Covered with Material



Photo 62 All walls of Shop No. 27, Part 2 of Ground Floor Covered



Photo 61 All walls of Shop No. 27, Part 1 of Ground Floor Covered with Tiles



Photo 63 All walls of Shop No. 26 of Ground Floor Covered







Photo 64 All walls of Shop No. 25 of Ground Floor Covered



Photo 65 Wall No. 4 of Shop No. 16 of Ground Floor Covered



Photo 66 Wall No. 2 & 4 of Shop No. 32 of Ground Floor Covered



Photo 68 Wall No. 1 & 4 of Shop No. 29 of Ground Floor Covered





Photo 67 All walls of Shop No. 34 of Ground Floor Covered



Photo 69 Roof of Shop No. 29 of Ground Floor Covered







Photo 70 Wall No. 2 & 4 of Shop No. 31 of Ground Floor Covered



Photo 71 Shop No. 30 of Ground Floor Locked





Photo 72 Photo 73 Wall No. 1, 2 & 4 of Shop No. 33 of Ground Floor Covered with Material Wall No. 1, 2 & 4 of Shop No. 36 of Ground Floor Covered with Material



Photo 74 All walls of Shop No. 14 of Ground Floor Covered with Material



Photo 75 All walls of Shop No. 13 of Ground Floor Covered with Material











Photo 76 All walls of Shop No. 17 of Ground Floor Covered with Material

Photo 77 Wall No. 4 of Shop No. 18 of Ground Floor Covered with Material





Photo 78 Wall No. 1 of Shop No. 18 of Ground Floor Covered with Material

Photo 79 Wall No. 2 of Shop No. 18 of Ground Floor Covered with Material



Photo 80 Wall No. 1 & 2 of Shop No. 47 of Ground Floor Covered with Material



Photo 81 Wall No. 1 & 2 of Shop No. 47 of Ground Floor Covered with Material











Photo 82 All Walls of Shop No. 38 of Ground Floor Covered with Material

Photo 83 All Walls of Shop No. 39 of Ground Floor Covered with Wooden Work





Photo 84 All Walls of Shop No. 40 of Ground Floor Covered with Material



Photo 86 All Walls of Shop No. 42 of Ground Floor Covered with Material



Photo 85 All Walls of Shop No. 41 of Ground Floor Covered with Material



Photo 87 All Walls of Shop No. 43 of Ground Floor Covered with Material









Photo 88 All Walls of Shop No. 44 of Ground Floor Covered with Material



Photo 89 Passage 2 of Shop No. 225 of Ground Floor Covered with Material





Photo 90 Shop No. 225 of Ground Floor Covered with Material

Photo 91 All Walls of Shop No. 15 of Ground Floor Locked



Photo 92 All Walls of Shop No. 19 of Ground Floor Covered with Material



Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



Chatarbhuj Ka Mandir & Shop No. 222-237 Sadhu Singh Dalal Sanghori Bazaar, Choti Chopar Jaipur Unique ID: CC 0007

Report Number: AIMIL/ESG/JMCEC/CC 0007/01, Rev. 00, Dated: January 2014

Building Owner Contractor Various Owners CEC Client Sub-Contractor JMRC Limited AIMIL Limited







Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line

	Table of Contents			
S.No.	Particulars	Page No.		
1	Introduction	2		
2	Survey Details	2		
3	About the Structure	3		
4	Building Ownership Details	3		
5	Project Details	4		
6	General Building Details	4		
7	Summary of Cracks	5		
8	Summary of Defects other than Cracks			
9	Summary of Areas that Could not be surveyed			
10	Defect Photographs			
11	Schematic Diagram of Building			

Introduction

The Jaipur Metro Rail is being constructed to provide the city of Jaipur with a modern and technologically advanced Transit System, to provide a safe and well connected means of transport that reduces traffic congestion. The project consists of two corridors with underground and elevated sections.

The construction of underground rail and road infrastructures in metropolitan and cosmopolitan cities are mostly through developed area under challenging soil conditions.

The alignment of structure is passing through densely inhabitated areas, many structures are falling in the zone of influence of construction activities. It is required to carry out the pre-condition survey of those structures. The scope of work of this survey includes carrying out pre-condition survey of those structures.

	Survey Details					
S.No.	Head	Particulars	Signatures			
1	Date of Survey	26/12/2013				
2	AIMIL Representative					
3	CEC Representative					
4	Structural Designer of CEC					
5	JMRC/DMRC Representative					







Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line

About the Structure

The structure under consideration is a Single Story Load Bearing Structure having a Basement. The structure was constructed in year 1930 and is 83 years old.

There are 129 defects in the structure out of which 37 are cracks. Category wise distribution of cracks is given in the table below. Overall the Building can be categorised in Category III (Moderate)

Category	Number of Cracks	% of Total Cracks
Negligible (< 0.1mm)	0	0%
Very Slight (0.1 to 1mm)	27	72.97%
Slight (1 to 5mm)	9	24.32%
Moderate (5 to 15mm)	1	2.70%
Severe (15 to 25mm)	0	0%
Very Severe (>25mm)	0	0%

The average width of cracks is 0.76mm and average length of cracks is 1.78m. The maximum crack width is 5mm and minimum width is	
0.15mm.	

		Building Ownership Details	
Unique ID/Sub ID	Premises Name	Owner	Signatures
CC/0007/TEMPLE	Chatarbhuj Ka Mandir		
CC/0007/222	Motilal Shankarlal		
CC/0007/223	Maheshwari Store		
CC/0007/224	Shri Shaym Marketing		
CC/0007/225	Ram Kirshna Market		
CC/0007/226	Shop No. 226		
CC/0007/227	Yuvraj Agency		
CC/0007/228-229	Tilam Sangh Depot		
CC/0007/230	Shri Shyam Pavitra Bhojnalay		
CC/0007/231	Eagle Agency		







Project Details				
S. No.	Head	Particulars		
1	Project	Jaipur Metro Rail Project		
2	Section	Chandpole to Bari Chaupar		
3	Client	JMRC Limited		
4	Consultant	DMRC Limited		
5	Contractor	CEC		
6	Design Consultant of Contractor	Omikron Kappa - Indus Consultrans JV		
7	Sub-Contractor	AIMIL Limited		
8	Subject	Pre-Condition Survey Report		

S. No.	Head	Particulars
1	Building Name	Chatarbhuj Ka Mandir & Shop No. 222-237
2	Building Address	Chatarbhuj Ka Mandir & Shop No. 222-237 Sadhu Singh Dalal Sanghori Bazaar, Choti Chopar Jaipur
3	Year of Construction	1930
4	Number of Floors	B+G
5	Number of Basements	One
6	Type of Building	Commercial
7	Approximate Height	3 m
8	Approximate Area	Not Known
9	Age of Building	83 years
10	Type of Structure	Load Bearing Structure
11	Type of Foundation	Not Known
12	Number of Bore Wells	None
13	Depth and Diameter of Bore	N.A
14	Roadways	One Side
15	Presence of Equipment/Machines	None







# JAIPUR METRO Jaipur Metro Rail Corporation

	Summ	ary of Cracks		1		
Defect ID	Location	Orientation	Appx. Width (mm)	Appx. Length (m)	Category	Photo No
1	Roof Varanda of Shop No.230 Ground Floor	Horizontal	0.4	2	Very Slight	18
2	Roof Varanda of Shop No.230 Ground Floor	Horizontal	0.5	2.2	Very Slight	19
3	Wall No. 3 Part C of Shop No.231 Ground Floor	Inclined	0.6	2.3	Very Slight	20
4	Wall No. 3 Part D of Shop No.231 Ground Floor	Horizontal	1	1.1	Slight	21
5	Wall No. 3 Part D of Shop No.231 Ground Floor	Inclined	0.4	0.5	Very Slight	22
6	Roof Varanda of Shop No.231 Ground Floor	Inclined	0.35	2.1	Very Slight	23
7	Roof Varanda of Shop No.231 Ground Floor	Horizontal	0.8	2	Very Slight	24
8	Roof Varanda of Shop No.232 Ground Floor	Horizontal	0.6	2	Very Slight	25
9	Wall No. 3 Part D of Shop No.233 Ground Floor	Inclined	1	1	Slight	26
10	Wall No. 3 Part D of Shop No.233 Ground Floor	Inclined	0.8	2.2	Very Slight	27
11	Wall No. 2 Part B of Shop No.234 Ground Floor	Inclined	0.2	1.4	Very Slight	28, 28A
12	Roof Part C of Shop No.234 Ground Floor	Horizontal	2	1	Slight	29, 29A
13	Wall No. 1 Part C of Shop No.234 Ground Floor	Inclined	1	2	Slight	30, 30A
14	Wall No. 1 Part E of Shop No.234 Ground Floor	Inclined	0.5	0.6	Very Slight	31
15	Wall No. 2 Part E of Shop No.234 Ground Floor	Horizontal	0.15	2.5	Very Slight	32, 32A
16	Wall No. 1 Part A of Shop No.234 Ground Floor	Inclined	1	0.7	Slight	33, 33A
17	Wall No. 4 Par D of Shop No.229 Ground Floor	Inclined	1	3	Slight	34
18	Roof Varanda of Shop No.228 Ground Floor	Horizontal	0.5	2	Very Slight	35
19	Wall No. 1 Part D of Shop No.227 Ground Floor	Inclined	0.25	1.8	Very Slight	36, 36A
20	Wall No. 2 Part D of Shop No.227 Ground Floor	Inclined	0.6	1	Very Slight	37
21	Wall No. 2 Part D of Shop No.227 Ground Floor	Inclined	0.2	1.8	Very Slight	38, 38A
22	Wall No. 2 Part C of Shop No.227 Ground Floor	Vertical	0.3	1.5	Very Slight	39, 39A
23	Roof Varanda of Shop No.227 Ground Floor	Vertical	0.5	2	Very Slight	40
24	Roof Varanda of Shop No.227 Ground Floor	Horizontal	0.6	2	Very Slight	41
25	Wall No. Roof Beam Shop Ground Floor	Inclined	1.5	1	Slight	42
26	Wall No. 4 & Roof Varanda of Shop Ground Floor	Inclined	5	3.2	Moderate	43
27	Wall No. 4 & Roof Varanda of Shop Ground Floor	Horizontal	1	2.1	Slight	44
28	Roof Varanda of Shop Ground Floor	Horizontal	0.6	1.1	Very Slight	45
29	Roof Varanda of Shop Ground Floor	Horizontal	0.6	2.1	Very Slight	46
30	Wall No. 2 Shop No.219 Part B Ground Floor	Inclined	1.5	3	Slight	47, 47A
31	Roof Varanda of shop no.226 Ground Floor	Vertical	0.6	2	Very Slight	48
32	Wall No. 2 Room No. 5 Ground Floor	Inclined	0.6	1.5	Very Slight	49
33	Wall No. 1 Room No. 8 Ground Floor	Inclined	0.4	1.5	Very Slight	50
34	Wall No. 4 Room No. 9 Ground Floor	Inclined	0.3	2.6	Very Slight	51, 51A
35	Wall No. 2 Room No. 12 Ground Floor	Inclined	0.3	1.2	Very Slight	52, 52A
36	Roof Hall No. 1 Ground Floor	Horizontal	0.3	2	Very Slight	53
37	Roof Hall No. 1 Ground Floor	Horizontal	0.3	2	Very Slight	54

	Summary of Defects Other Than Crack				
Defect ID	Location	Description Photo I			
38	Roof Shop No.230 Ground Floor	Dampness/Seepage	55		
39	Wall No. 1 Shop No.230 Ground Floor	Dampness/Seepage	56		
40	Wall No. 4 Shop No.230 Ground Floor	Dampness/Seepage	57		

41	Wall No. 2 Shop No.230 Ground Floor	Dampness/Seepage	58
42	Roof Varanda of Shop No.230 Ground Floor	Dampness/Seepage	59
43	Wall No. 1 Part B of Shop No.231 Ground Floor	Peeling of Plaster	60
44	Wall No. 4 Part C of Shop No.231 Ground Floor	Peeling of Plaster	61
45	Roof Varanda of Shop No.231 Ground Floor	Dampness/Seepage	62
46	Roof Part A of Shop No.232 Ground Floor	Dampness/Seepage	63
47	Roof & Door Part B of Shop No.232 Ground Floor	Damaged Portion	64
48	Wall No. 1 Part B of Shop No.232 Ground Floor	Dampness/Seepage	65
49	Wall No. 2 Part B of Shop No.232 Ground Floor	Peeling of Plaster	66
50	Wall No. 3 Part B of Shop No.232 Ground Floor	Dampness/Seepage	67
51	Wall No. 1 Part C of Shop No.232 Ground Floor	Dampness/Seepage	68
52	Wall No. 2 Part C of Shop No.232 Ground Floor	Dampness/Seepage	69
53	Wall No. 4 Part D of Shop No.232 Ground Floor	Dampness/Seepage	70
54	Wall No. 2 Part D of Shop No.232 Ground Floor	Dampness/Seepage	71
55	Wall No. 3 Part D of Shop No.232 Ground Floor	Dampness/Seepage	72
56	Roof Varanda of Shop No.232 Ground Floor	Dampness/Seepage	73
57	Rightside External Column	Dampness/Seepage	74
58	Roof Part A of Shop No.233 Ground Floor	Peeling of Plaster	75
59	Wall No. 2 & 4 Part C of Shop No.233 Ground Floor	Dampness/Seepage	76
60	Wall No. 2 Part D of Shop No.233 Ground Floor	Peeling of Plaster	77
61	Wall No. 4 Part D of Shop No.233 Ground Floor	Dampness/Seepage	78
62	Wall No. 1 Part D of Shop No.233 Ground Floor	Peeling of Plaster	79
63	Roof Varanda of Shop No.233 Ground Floor	Peeling of Plaster	80
64	Rightside External Column Varanda of Shop No.233 Ground Floor	Dampness/Seepage	81
65	Rightside External Column Varanda of Shop No.233 Ground Floor	Peeling of Plaster	82
66	Leftside External Column Varanda of Shop No.233 Ground Floor	Damaged Portion	83
67	Roof Varanda of Shop No.233 Ground Floor	Damaged Portion	84
68	R Varanda of Shop No.233 Ground Floor	Damaged Portion	85
69	Wall No. 4 Part A of Shop No.234 Ground Floor	Peeling of Plaster	86
70	Wall No. 2 Part C of Shop No.234 Ground Floor	Dampness/Seepage	87
71	Wall No. 2 Part D of Shop No.234 Ground Floor	Dampness/Seepage	88
72	Wall No. 3 Part E of Shop No.234 Ground Floor	Dampness/Seepage	89
73	Roof Varanda of Shop No.234 Ground Floor	Dampness/Seepage	90
74	Rightside External Column Varanda of Shop No.234 Ground Floor	Dampness/Seepage	91
75	Leftside External Column Varanda of Shop No.234 Ground Floor	Dampness/Seepage	92
76	Wall No. 2 Shop No.235 Ground Floor	Peeling of Plaster	93
77	Roof Varanda of Shop No.235 Ground Floor	Dampness/Seepage	94
78	Leftside External Column Varanda of Shop No.235 Ground Floor	Peeling of Plaster	95
79	Rightside External Column Varanda of Shop No.235 Ground Floor	Damaged Portion	96
80	Leftside External Column Varanda of Shop No.235 Ground Floor	Peeling of Plaster	97
81	Roof Varanda of Shop No.236 & 2 Ground Floor	Dampness/Seepage	98
82	Beam Varanda of Shop No.236 & 2 Ground Floor	Dampness/Seepage	99
83	Beam Varanda of Shop No.236 & 2 Ground Floor	Dampness/Seepage	100
	Wall No. 2 Part D of Shop No.229 Ground Floor	Peeling of Plaster	101
84		Peeling of Plaster	
84 85	Wall No. 1 & 4 Part D of Shop No.229 Ground Floor	Peeling of Plaster	102
	Wall No. 1 & 4 Part D of Shop No.229 Ground Floor Roof Varanda of Shop No.229 Ground Floor	Peeling of Plaster Dampness/Seepage	102 103

89	Wall No. 3 Part A of Shop No.228 Ground Floor	Peeling of Plaster	106
90	Wall No. 1 Part A of Shop No.228 Ground Floor	Peeling of Plaster	107
91	Roof Part A of Shop No.228 Ground Floor	Dampness/Seepage	108
92	Wall No. 4 Part B of Shop No.228 Ground Floor	Peeling of Plaster	109
93	Wall No. 2 Part C of Shop No.228 Ground Floor	Peeling of Plaster	110
94	Wall No. 3 Part C of Shop No.228 Ground Floor	Peeling of Plaster	111
95	Roof Varanda of Shop No.228 Ground Floor	Dampness/Seepage	112
96	Wall No. 4 Part D of Shop No.227 Ground Floor	Peeling of Plaster	113
97	Roof Varanda of Shop No.227 Ground Floor	Dampness/Seepage	114
98	Leftside External Column Varanda of Shop No.227 Ground Floor	Dampness/Seepage	115
99	Roof Varanda of Shop Ground Floor	Peeling of Plaster	116
100	Roof Varanda of Shop Ground Floor	Peeling of Plaster	117
101	Wall No. 4 Varanda of Shop Ground Floor	Peeling of Plaster	118
102	Roof Varanda of Shop Ground Floor	Dampness/Seepage	119
103	Roof Varanda of Shop Ground Floor	Peeling of Plaster	120
104	Wall No. Right side External Column Varanda of Shop Ground Floor	Peeling of Plaster	121
105	Roof Shop No.219 Part a Ground Floor	Peeling of Plaster	122
106	Roof Shop No.219 Part B Ground Floor	Dampness/Seepage	123
107	Roof Shop No.219 Part B Ground Floor	Dampness/Seepage	124
108	Roof Varanda of shop no.226 Ground Floor	Dampness/Seepage	125
109	Pillar Varanda of shop no.226 Ground Floor	Peeling of Plaster	126
110	Wall No. 1 & 4 Room No. 1 Ground Floor	Dampness/Seepage	127
111	Wall No. 2 Room No. 1 Ground Floor	Dampness/Seepage	128
112	Wall No. 3 Room No. 1 Ground Floor	Dampness/Seepage	129
113	Wall No. 1 & 4 Room No. 2 Ground Floor	Dampness/Seepage	130
114	Wall No. 3 Room No. 2 Ground Floor	Peeling of Plaster	131
115	Wall No. 4 Room No. 3 Ground Floor	Peeling of Plaster	132
116	Wall No. 1 & 3 Hall No. 1 Ground Floor	Dampness/Seepage	133
117	Wall No. 2 Hall No. 1 Ground Floor	Peeling of Plaster	134
118	Wall No. 1 Room No. 4 Ground Floor	Peeling of Plaster	135
119	Wall No. 4 Room No. 4 Ground Floor	Dampness/Seepage	136
120	Wall No. 3 Room No. 6 Ground Floor	Dampness/Seepage	137
121	Wall No. 4 Room No. 7 Ground Floor	Dampness/Seepage	138
122	Wall No. 2 & 4 Room No. 8 Ground Floor	Dampness/Seepage	139
123	Wall No. 4 Room No. 9 Ground Floor	Dampness/Seepage	140
124	Wall No. 2 Room No. 11 Ground Floor	Dampness/Seepage	141
125	Wall No. 1 Room No. 13 Ground Floor	Dampness/Seepage	142
126	Wall No. 5 & 6 Hall No. 1 Ground Floor	Dampness/Seepage	143
127	Roof Varanda of Shop No.224 Ground Floor	Dampness/Seepage	144
128	Wall No. 2 Room No. 1 Ground Floor	Dampness/Seepage	145
129	Wall No. 4 Room No. 3 Ground Floor	Dampness/Seepage	146

Summary of Areas that Could not be Surveyed					
Serial No.	Location	Description	Photo No.		
1	Wall No. 1 Part A of Shop No.231 Ground Floor	Covered With Wooden Rack	147		
2	Wall No. 2 Part A of Shop No.231 Ground Floor	Covered With Wooden Rack	148		
3	Roof Part A of Shop No.231 Ground Floor	Covered With Wooden Work	149		
4	Wall No. 4 Part A of Shop No.231 Ground Floor	Covered With Wooden Rack	150		
5	Wall No. 4 Part B of Shop No.231 Ground Floor	Covered With Material & Poster	151		
6	Wall No. 2 Part B of Shop No.231 Ground Floor	Covered With Material & Steel Racks	152		
7	Wall No. 1 Part C of Shop No.231 Ground Floor	Covered With Material & Steel Racks	153		

			-
8	Wall No. 2 Part C of Shop No.231 Ground Floor	Covered With Material	154
9	Wall No. 1 Part D of Shop No.231 Ground Floor	Covered With Material	155
10	Wall No. 4 Part D of Shop No.231 Ground Floor	Covered With photo Frame & Material	156
11	Wall No. 2 Part D of Shop No.231 Ground Floor	Covered With Steel Racks & Material	157
12	Wall No. 1 Part A of Shop No.232 Ground Floor	Covered With wooden work	158
13	Wall No. 2 Part A of Shop No.232 Ground Floor	Covered With wooden work	159
14	All Walls Part A of Shop No.233 Ground Floor	Covered With Material	160
15	All Walls Part B of Shop No.233 Ground Floor	Covered With Material	161
16	Wall No. 1 Part A of Shop No.234 Ground Floor	Covered With Wooden Racks & Material	162
17	Wall No. 2 Part A of Shop No.234 Ground Floor	Covered With Wooden Racks & Material	163
18	Roof Part A of Shop No.234 Ground Floor	Covered With Wooden Work	164
19	Wall No. 4 Part B of Shop No.234 Ground Floor	Covered With Material	165
20	Wall No. 1 Part B of Shop No.234 Ground Floor	Covered With Material	166
21	Wall No. 1 Part C of Shop No.234 Ground Floor		167
22	Wall No. 4 Part D of Shop No.234 Ground Floor	Covered With Material	168
23	Wall No. 1 Part D of Shop No.234 Ground Floor	Covered With Material	169
24	Wall No. 4 Part E of Shop No.234 Ground Floor	Covered With Material	170
25	All Walls Shop No.236 & 2 Ground Floor	View of Shop No.236 & 2	171
26	Wall No. 2 Part B of Shop No.228 Ground Floor	Covered With Material	172
27	Wall No. 1 Part B of Shop No.228 Ground Floor	Covered With Material	173
28	Wall No. 1 Part C of Shop No.228 Ground Floor	Covered With Material	174
29	Wall No. 1 Part D of Shop No.228 Ground Floor	Covered With Material	175
30	Wall No. 4 Part D of Shop No.228 Ground Floor	Covered With Material	176
31	Wall No. 2 Part D of Shop No.228 Ground Floor	Covered With Material	177
32	All Walls & Roof Shop No.218 Ground Floor	Covered With Material & Roof covered with wooden	178
33	Shop No.220 Ground Floor	Locked	179
34	All Walls Shop No.224 Ground Floor	Covered with wooden racks 7 material	180
35	Shop No.223 Ground Floor	Locked	181
36	Wall No. 3 & 1 Room No. 1 Ground Floor	Covered with Material	182
37	Wall No. 1 Room No. 2 Ground Floor	Covered with Material	183
38	Wall No. 2 Room No. 2 Ground Floor	Covered with Material	184
39	Wall No. 1 Room No. 3 Ground Floor	Covered with Material	185
40	Wall No. 2 & 4 Shop No.227 Ground Floor	Covered with Material	186
41	Wall No. 1 Room No. 4 Ground Floor	Covered with Material	187
42	Wall No. 2 Room No. 4 Ground Floor	Covered with Material	188







Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



Photo 1 View of Shop



Photo 2 View of Shop no.230, Ground Floor



Photo 3 View of Shop No.231, Ground Floor



Photo 5 View of shop no.233, Ground Floor





Photo 4 View of Shop No.232,



Photo 6 Shop No.234, Ground Floor







Photo 7 View of Shop No.235, Ground Floor



Photo 8 View of Shop No.236 & 2, Ground Floor



Photo 9 View of Shop No.236 Ground Floor



Photo 11 View of Shop No.229, Ground Floor





Photo 10 View of Shop No.229, Ground Floor



Photo 12 View of Shop No.228, Ground Floor





Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



Photo 13 View of Shop No.227, Ground Floor



Photo 14 Viewof Shop No.216,217 & 218, Ground Floor



Photo 15 View of Shop No.219, Ground Floor



Photo 17 View of shop No.226, Ground Floor





Photo 16 Covered with Material, Ground Floor



Photo 18 Horizontal Crack on Roof of Varanda of Shop No.230, Ground Floor Approx. Width = 0.4mm, Approx. Length = 2m. Distance from Rightside External Column = 0.7m, Height from Floor = 3m.



Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



JAIPUR METRO

<u>Photo 1</u>9

Horizontal Crack on Roof of Varanda of Shop No.230, Ground Floor Approx. Width = 0.5mm, Approx. Length = 2.2m. Distance from Rightside External Column = 0m, Height from Floor = 2.8m.



Photo 21



Photo 20 Inclined Crack on Wall No. 3 of Part C of Shop No.231, Ground Floor Approx. Width = 0.6mm, Approx. Length = 2.3m. Distance from Wall No.1 = 0m, Height from Floor = 2.7m.



Horizontal Crack on Wall No. 3 of Part D of Shop No.231, Ground Floor Approx. Width = 1mm, Approx. Length = 1.1m. Distance from Wall No.1 = 0.5m, Height from Floor = 2.2m.



Photo 23

Inclined Crack on Roof of Varanda of Shop No.231, Ground Floor Approx. Width = 0.35mm, Approx. Length = 2.1m. Distance from Rightside External Column = 0m, Height from Floor = 3m.



Photo 22 Inclined Crack on Wall No. 3 of Part D of Shop No.231, Ground Floor Approx. Width = 0.4mm, Approx. Length = 0.5m. Distance from Wall No.1 = 1.5m, Height from Floor = 2.6m.



Photo 24 Horizontal Crack on Roof of Varanda of Shop No.231, Ground Floor Approx. Width = 0.8mm, Approx. Length = 2m. Distance from Leftside External Column = 0m, Height from Floor = 3m.



**Jaipur Metro Rail Corporation** JAIPUR METRO

Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line





Photo 25 Horizontal Crack on Roof of Varanda of Shop No.232, Ground Floor Approx. Width = 0.6mm, Approx. Length = 2m. Distance from Rightside Approx. Width = 1mm, Approx. Length = 1m. Distance from Wall no.1 = External Column = 0m, Height from Floor = 3m.

Photo 26 Inclined Crack on Wall No. 3 of Part D of Shop No.233, Ground Floor 0.5m, Height from Floor = 2.1m.





Photo 27 Inclined Crack on Wall No. 3 of Part D of Shop No.233, Ground Floor Approx. Width = 0.8mm, Approx. Length = 2.2m. Distance from Wall no.1 = 1m, Height from Floor = 2.4m.



Photo 28A Inclined Crack on Wall No. 2 of Part B of Shop No.234, Ground Floor Approx. Width = 0.2mm, Approx. Length = 1.4m. Distance from Wall No.3 = 0.5m, Height from Floor = 0.7m.




Photo 29



Photo 28 Inclined Crack on Wall No. 2 of Part B of Shop No.234, Ground Floor Approx. Width = 0.2mm, Approx. Length = 1.4m. Distance from Wall No.3 = 0.5m, Height from Floor = 0.7m.



Aimil Ltd. Instrumentation & Technologies



Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line





Photo 29A

Photo 29A Horizontal Crack on Roof of Part C of Shop No.234, Ground Floor Horizontal Crack on Roof of Part C of Shop No.234, Ground Floor Approx. Width = 2mm, Approx. Length = 1m. Distance from Wall No.1 = Approx. Width = 2mm, Approx. Length = 1m. Distance from Wall No.1 = 0m, Height from Floor = 2m. 0m, Height from Floor = 2m.



Photo 30



Photo 30A

Inclined Crack on Wall No. 1 of Part C of Shop No.234, Ground Floor Inclined Crack on Wall No. 1 of Part C of Shop No.234, Ground Floor Approx. Width = 1mm, Approx. Length = 2m. Distance from = m, Height Approx. Width = 1mm, Approx. Length = 2m. Distance from = m, Height from Floor = m. from Floor = m.



Photo 31 Inclined Crack on Wall No. 1 of Part E of Shop No.234, Ground Floor Approx. Width = 0.5mm, Approx. Length = 0.6m. Distance from Wall No.3 = 0.5m, Height from Floor = 2.6m.

Photo 32 Horizontal Crack on Wall No. 2 of Part E of Shop No.234, Ground Floor Approx. Width = 0.15mm, Approx. Length = 2.5m. Distance from Wall no.3 = 0m, Height from Floor = 1.3m.







Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



Photo 32A

Photo 33

= 0m, Height from Floor = 1.5m.

Horizontal Crack on Wall No. 2 of Part E of Shop No.234, Ground Floor Inclined Crack on Wall No. 1 of Part A of Shop No.234, Ground Floor Approx. Width = 0.15mm, Approx. Length = 2.5m. Distance from Wall Approx. Width = 1mm, Approx. Length = 0.7m. Distance from Wall no.3 no.3 = 0m, Height from Floor = 1.3m.



Photo 33A




Inclined Crack on Wall No. 1 of Part A of Shop No.234, Ground Floor = 0m, Height from Floor = 1.5m.

Inclined Crack on Wall No. 4 of Par D of Shop No.229, Ground Floor Approx. Width = 1mm, Approx. Length = 0.7m. Distance from Wall no.3 Approx. Width = 1mm, Approx. Length = 3m. Distance from Wall No.1 = 1.5m, Height from Floor = 0.1m.




Photo 35 Horizontal Crack on Roof of Varanda of Shop No.228, Ground Floor Approx. Width = 0.5mm, Approx. Length = 2m. Distance from Rightside Internal Column = 0.8m, Height from Floor = 3m.







6.11.2013







Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



Photo 36A Inclined Crack on Wall No. 1 of Part D of Shop No.227, Ground Floor Approx. Width = 0.25mm, Approx. Length = 1.8m. Distance from Wall No.3 = 0.8m, Height from Floor = 1.5m.





Photo 37

Inclined Crack on Wall No. 2 of Part D of Shop No.227, Ground Floor Approx. Width = 0.6mm, Approx. Length = 1m. Distance from Wall No.4 = 1m, Height from Floor = 2m.



Photo 38 Inclined Crack on Wall No. 2 of Part D of Shop No.227, Ground Floor Approx. Width = 0.2mm, Approx. Length = 1.8m. Distance from Wall no.3 = 0.8m, Height from Floor = 1.5m.



Photo 39 Vertical Crack on Wall No. 2 of Part C of Shop No.227, Ground Floor Approx. Width = 0.3mm, Approx. Length = 1.5m. Distance from Wall no.3 = 1.3m, Height from Floor = 0m.



Photo 38A Inclined Crack on Wall No. 2 of Part D of Shop No.227, Ground Floor Approx. Width = 0.2mm, Approx. Length = 1.8m. Distance from Wall no.3 = 0.8m, Height from Floor = 1.5m.



Photo 39A Vertical Crack on Wall No. 2 of Part C of Shop No.227, Ground Floor Approx. Width = 0.3mm, Approx. Length = 1.5m. Distance from Wall no.3 = 1.3m, Height from Floor = 0m.



**JAIPUR METRO** 

#### **Jaipur Metro Rail Corporation**

Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



Photo 40 Vertical Crack on Roof of Varanda of Shop No.227, Ground Floor Approx. Width = 0.5mm, Approx. Length = 2m. Distance from Rightside Approx. Width = 0.6mm, Approx. Length = 2m. Distance from Rightside External Column = 1.2m, Height from Floor = 3m.



#### Photo 42

Inclined Crack on Wall No. Roof Beam of Shop, Ground Floor Approx. Width = 1.5mm, Approx. Length = 1m. Distance from Left side External Column = 0.1m, Height from Floor = 2m.



Photo 43 Inclined Crack on Wall No. 4 & Roof of Varanda of Shop, Ground Floor Approx. Width = 5mm, Approx. Length = 3.2m. Distance from Left side External Column = 2.2m, Height from Floor = 1.6m.

Photo 41



Photo 45

Horizontal Crack on Roof of Varanda of Shop, Ground Floor Approx.

Width = 0.6mm, Approx. Length = 1.1m. Distance from Right Side

External Column = 2.5m, Height from Floor = 3m.

Photo 44 Horizontal Crack on Wall No. 4 & Roof of Varanda of Shop, G/F Approx. Width = 1mm, Approx. Length = 2.1m. Distance from Right Side External Column = 0.2m, Height from Floor = 2.95m.





Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



JAIPUR METRO

<u>Photo 4</u>6 Horizontal Crack on Roof of Varanda of Shop, Ground Floor Approx. Width = 0.6mm, Approx. Length = 2.1m. Distance from Left side External Column = 0m, Height from Floor = 3m.



#### Photo 47A



Photo 47 Inclined Crack on Wall No. 2 of Shop No.219 Part B, Ground Floor Approx. Width = 1.5mm, Approx. Length = 3m. Distance from Wall No.3 = 3.5m, Height from Floor = 0m.



Inclined Crack on Wall No. 2 of Shop No.219 Part B, Ground Floor Approx. Width = 1.5mm, Approx. Length = 3m. Distance from Wall No.3 Approx. Width = 0.6mm, Approx. Length = 2m. Distance from External = 3.5m, Height from Floor = 0m.



Photo 49 Inclined Crack on Wall No. 2 of Room No. 5, Ground Floor Approx. Width = 0.6mm, Approx. Length = 1.5m. Distance from Wall No.4 = 0.6m, Height from Floor = 1.8m.



Photo 48 Vertical Crack on Roof of Varanda of shop no.226, Ground Floor Colume = 0m, Height from Floor = 3m.



Photo 50 Inclined Crack on Wall No. 1 of Room No. 8, Ground Floor Approx. Width = 0.4mm, Approx. Length = 1.5m.Distance from Wall No.3 = 1.2m, Height from Floor = 3m.



Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



JAIPUR METRO



Photo 51 Inclined Crack on Wall No. 4 of Room No. 9, Ground Floor Approx. Width = 0.3mm, Approx. Length = 2.6m. Distance from Wall No.1 = 2m, Width = 0.3mm, Approx. Length = 2.6m. Distance from Wall No.1 = 2m, Height from Floor = 0.8m.

Photo 51A Inclined Crack on Wall No. 4 of Room No. 9, Ground Floor Approx.



Photo 52

Inclined Crack on Wall No. 2 of Room No. 12, Ground Floor Approx. Width = 0.3mm, Approx. Length = 1.2m. Distance from Wall No.1 = 1.1m, Height from Floor = 1.5m.



Photo 53 Horizontal Crack on Roof of Hall No. 1, Ground Floor Approx. Width = 0.3mm, Approx. Length = 2m. Distance from Wall no.3 = 0m, Height from Floor = 3m.



Photo 52A Inclined Crack on Wall No. 2 of Room No. 12, Ground Floor Approx. Width = 0.3mm, Approx. Length = 1.2m. Distance from Wall No.1 = 1.1m, Height from Floor = 1.5m.



Photo 54 Horizontal Crack on Roof of Hall No. 1, Ground Floor Approx. Width = 0.3mm, Approx. Length = 2m. Distance from Wall no.3 = 0m, Height from Floor = 3m.







Photo 55 Dampness/Seepage on Roof of Shop No.230 of Ground Floor



Photo 56 Dampness/Seepage on Wall No. 1 of Shop No.230 of Ground Floor





Photo 57 Dampness/Seepage on Wall No. 4 of Shop No.230 of Ground Floor

Photo 58 Dampness/Seepage on Wall No. 2 of Shop No.230 of Ground Floor



Photo 59 Dampness/Seepage on Roof of Varanda of Shop No.230 of Ground Floor





Photo 60 Peeling of Plaster on Wall No. 1 of Part B of Shop No.231 of Ground Floor







Photo 61 Peeling of Plaster on Wall No. 4 of Part C of Shop No.231 of Ground Floor



Photo 62 Dampness/Seepage on Roof of Varanda of Shop No.231 of Ground Floor





Photo 63 Dampness/Seepage on Roof of Part A of Shop No.232 of Ground Floor

Photo 64 Damaged Portion on Roof & Door of Part B of Shop No.232 of Ground Floor



28.11.2013

Photo 65 Dampness/Seepage on Wall No. 1 of Part B of Shop No.232 of Ground Floor



Photo 66 Peeling of Plaster on Wall No. 2 of Part B of Shop No.232 of Ground Floor









Photo 67 Dampness/Seepage on Wall No. 3 of Part B of Shop No.232 of Ground Dampness/Seepage on Wall No. 1 of Part C of Shop No.232 of Ground Floor Floor





 Photo 69
 Photo 70

 Dampness/Seepage on Wall No. 2 of Part C of Shop No.232 of Ground
 Dampness/Seepage on Wall No. 4 of Part D of Shop No.232 of Ground

 Floor
 Floor





 Photo 7
 Photo 7

 Dampness/Seepage on Wall No. 2 of Part D of Shop No.232 of Ground
 Dampness/Seepage on Wall No. 3 of Part D of Shop No.232 of Ground

 Floor
 Floor









Photo 73 Dampness/Seepage on Roof of Varanda of Shop No.232 of Ground Floor



Photo 74 Dampness/Seepage on Rightside External Column of of





Photo 75 Peeling of Plaster on Roof of Part A of Shop No.233 of Ground Floor

Photo 76 Dampness/Seepage on Wall No. 2 & 4 of Part C of Shop No.233 of Ground Floor



Photo 77 Peeling of Plaster on Wall No. 2 of Part D of Shop No.233 of Ground Floor












Photo 79 Peeling of Plaster on Wall No. 1 of Part D of Shop No.233 of Ground Floor



Photo 80 Peeling of Plaster on Roof of Varanda of Shop No.233 of Ground Floor





Photo 81 Dampness/Seepage on Rightside External Column of Varanda of Shop No.233 of Ground Floor

Photo 82 Peeling of Plaster on Rightside External Column of Varanda of Shop No.233 of Ground Floor



Photo 83 Damaged Portion on Leftside External Column of Varanda of Shop No.233 of Ground Floor



Photo 84 Damaged Portion on Roof of Varanda of Shop No.233 of Ground Floor









.

Photo 85 Damaged Portion on Roof of Varanda of Shop No.233 of Ground Floor

Photo 86 Peeling of Plaster on Wall No. 4 of Part A of Shop No.234 of Ground Floor





Photo 87 Dampness/Seepage on Wall No. 2 of Part C of Shop No.234 of Ground Dampness/Seepage on Wall No. 2 of Part D of Shop No.234 of Ground Floor Floor



28.11.2013

Photo 89 Dampness/Seepage on Wall No. 3 of Part E of Shop No.234 of Ground Floor



Photo 90 Dampness/Seepage on Roof of Varanda of Shop No.234 of Ground Floor





Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line





Photo 91 Dampness/Seepage on Rightside External Column of Varanda of Shop I No.234 of Ground Floor

Photo 92 Dampness/Seepage on Leftside External Column of Varanda of Shop No.234 of Ground Floor





<u>Photo 9</u>4

Dampness/Seepage on Roof of Varanda of Shop No.235 of Ground

Floor

Photo 93 Peeling of Plaster on Wall No. 2 of Shop No.235 of Ground Floor



Photo <u>9</u>5 Peeling of Plaster on Leftside External Column of Varanda of Shop No.235 of Ground Floor



Photo 96 Damaged Portion on Rightside External Column of Varanda of Shop No.235 of Ground Floor









Photo 97 Peeling of Plaster on Leftside External Column of Varanda of Shop No.235 of Ground Floor



Photo 98 Dampness/Seepage on Roof of Varanda of Shop No.236 & 2 of Ground Floor





Photo 99 Dampness/Seepage on Beam of Varanda of Shop No.236 & 2 of Ground Floor

Photo 100 Dampness/Seepage on Beam of Varanda of Shop No.236 & 2 of Ground Floor



Photo 101 Peeling of Plaster on Wall No. 2 of Part D of Shop No.229 of Ground Floor







JAIPUR METRO

### **Jaipur Metro Rail Corporation**



Photo 103 Dampness/Seepage on Roof of Varanda of Shop No.229 of Ground Floor



Photo 104 Peeling of Plaster on Wall No. 4 of Part A of Shop No.228 of Ground Floor





Photo 105 Peeling of Plaster on Wall No. 2 of Part A of Shop No.228 of Ground Floor





Photo 107 Peeling of Plaster on Wall No. 1 of Part A of Shop No.228 of Ground Floor





Photo 108 Dampness/Seepage on Roof of Part A of Shop No.228 of Ground Floor







Photo 109 Peeling of Plaster on Wall No. 4 of Part B of Shop No.228 of Ground Floor



Photo 110 Peeling of Plaster on Wall No. 2 of Part C of Shop No.228 of Ground Floor





Photo 111 Peeling of Plaster on Wall No. 3 of Part C of Shop No.228 of Ground Floor





Photo 113 Peeling of Plaster on Wall No. 4 of Part D of Shop No.227 of Ground Floor



Photo 114 Dampness/Seepage on Roof of Varanda of Shop No.227 of Ground Floor









Photo 115 Dampness/Seepage on Leftside External Column of Varanda of Shop No.227 of Ground Floor



Photo 116 Peeling of Plaster on Roof of Varanda of Shop of Ground Floor





Photo 117 Peeling of Plaster on Roof of Varanda of Shop of Ground Floor



Photo 119 Dampness/Seepage on Roof of Varanda of Shop of Ground Floor





Photo 120 Peeling of Plaster on Roof of Varanda of Shop of Ground Floor









Photo 121 Peeling of Plaster on Right side External Column of Varanda of Shop of Ground Floor



Photo 122 Peeling of Plaster on Roof of Shop No.219 Part a of Ground Floor





Photo 123 Dampness/Seepage on Roof of Shop No.219 Part B of Ground Floor

Photo 124 Dampness/Seepage on Roof of Shop No.219 Part B of Ground Floor



Photo 125 Dampness/Seepage on Roof of Varanda of shop no.226 of Ground Floor

Photo 126 Peeling of Plaster on Pillar of Varanda of shop no.226 of Ground Floor











Photo 127 Dampness/Seepage on Wall No. 1 & 4 of Room No. 1 of Ground Floor

Photo 128 Dampness/Seepage on Wall No. 2 of Room No. 1 of Ground Floor





Photo 129 Dampness/Seepage on Wall No. 3 of Room No. 1 of Ground Floor

Photo 130 Dampness/Seepage on Wall No. 1 & 4 of Room No. 2 of Ground Floor



Photo 131 Peeling of Plaster on Wall No. 3 of Room No. 2 of Ground Floor



Photo 132 Peeling of Plaster on Wall No. 4 of Room No. 3 of Ground Floor









Photo 133 Dampness/Seepage on Wall No. 1 & 3 of Hall No. 1 of Ground Floor



Photo 134 Peeling of Plaster on Wall No. 2 of Hall No. 1 of Ground Floor





Photo 135 Peeling of Plaster on Wall No. 1 of Room No. 4 of Ground Floor

Photo 136 Dampness/Seepage on Wall No. 4 of Room No. 4 of Ground Floor



Photo 137 Dampness/Seepage on Wall No. 3 of Room No. 6 of Ground Floor



Photo 138 Dampness/Seepage on Wall No. 4 of Room No. 7 of Ground Floor











Photo 139 Dampness/Seepage on Wall No. 2 & 4 of Room No. 8 of Ground Floor

Photo 140 Dampness/Seepage on Wall No. 4 of Room No. 9 of Ground Floor





Photo 141 Dampness/Seepage on Wall No. 2 of Room No. 11 of Ground Floor

Photo 142 Dampness/Seepage on Wall No. 1 of Room No. 13 of Ground Floor



Photo 143 Dampness/Seepage on Wall No. 5 & 6 of Hall No. 1 of Ground Floor



Photo 144 Dampness/Seepage on Roof of Varanda of Shop No.224 of Ground Floor









Photo 145 Dampness/Seepage on Wall No. 2 of Room No. 1 of Ground Floor

Photo 146 Dampness/Seepage on Wall No. 4 of Room No. 3 of Ground Floor





Photo 147 Wall No. 1 of Part A of Shop No.231 of Ground Floor Covered With Wooden Rack

Photo 148 Wall No. 2 of Part A of Shop No.231 of Ground Floor Covered With Wooden Rack



Photo 149 Roof of Part A of Shop No.231 of Ground Floor Covered With Wooden Work



Photo 150 Wall No. 4 of Part A of Shop No.231 of Ground Floor Covered With Wooden Rack









Photo 151 Wall No. 4 of Part B of Shop No.231 of Ground Floor Covered With Material & Poster



Photo 152 Wall No. 2 of Part B of Shop No.231 of Ground Floor Covered With Material & Steel Racks





Photo 153 Wall No. 1 of Part C of Shop No.231 of Ground Floor Covered With Material & Steel Racks





Photo 155 Wall No. 1 of Part D of Shop No.231 of Ground Floor Covered With Material



Photo 156 Wall No. 4 of Part D of Shop No.231 of Ground Floor Covered With photo Frame & Material









Photo 157 Wall No. 2 of Part D of Shop No.231 of Ground Floor Covered With Steel Racks & Material



Photo 158 Wall No. 1 of Part A of Shop No.232 of Ground Floor Covered With wooden work





Photo 159 Wall No. 2 of Part A of Shop No.232 of Ground Floor Covered With wooden work





Photo 161 All Walls of Part B of Shop No.233 of Ground Floor Covered With Material





Photo 162 Wall No. 1 of Part A of Shop No.234 of Ground Floor Covered With Wooden Racks & Material







Photo 163 Wall No. 2 of Part A of Shop No.234 of Ground Floor Covered With Wooden Racks & Material



Photo 164 Roof of Part A of Shop No.234 of Ground Floor Covered With Wooden Work





Photo 165 Wall No. 4 of Part B of Shop No.234 of Ground Floor Covered With Material

Photo 166 Wall No. 1 of Part B of Shop No.234 of Ground Floor Covered With Material



Photo 167 Wall No. 1 of Part C of Shop No.234 of Ground Floor



Photo 168 Wall No. 4 of Part D of Shop No.234 of Ground Floor Covered With Material









Photo 169 Wall No. 1 of Part D of Shop No.234 of Ground Floor Covered With Material



Photo 170 Wall No. 4 of Part E of Shop No.234 of Ground Floor Covered With Material





Photo 171 All Walls of Shop No.236 & 2 of Ground Floor View of Shop No.236 & 2



Photo 173 Wall No. 1 of Part B of Shop No.228 of Ground Floor Covered With Material



Photo 172 Wall No. 2 of Part B of Shop No.228 of Ground Floor Covered With Material



Photo 174 Wall No. 1 of Part C of Shop No.228 of Ground Floor Covered With Material







Photo 175 Wall No. 1 of Part D of Shop No.228 of Ground Floor Covered With Material



Photo 176 Wall No. 4 of Part D of Shop No.228 of Ground Floor Covered With Material





Photo 177 Wall No. 2 of Part D of Shop No.228 of Ground Floor Covered With Material

Photo 178 All Walls & Roof of Shop No.218 of Ground Floor Covered With Material & Roof covered with wooden



Photo 179 Shop No.220 of Ground Floor Locked





Photo 180 All Walls of Shop No.224 of Ground Floor Covered with wooden racks 7 material







Photo 181 Shop No.223 of Ground Floor Locked




Photo 182 Wall No. 3 & 1 of Room No. 1 of Ground Floor Covered with Material





Photo 183 Wall No. 1 of Room No. 2 of Ground Floor Covered with Material





Photo 185 Wall No. 1 of Room No. 3 of Ground Floor Covered with Material



Photo 186 Wall No. 2 & 4 of Shop No.227 of Ground Floor Covered with Material









Photo 187 Wall No. 1 of Room No. 4 of Ground Floor Covered with Material



Photo 188 Wall No. 2 of Room No. 4 of Ground Floor Covered with Material



Pre - Condition Building Survey for Construction of Underground Stationsfrom Chandpole to Bari Chouper and reversal line



Mandir Shri Roopchaturbhujajhi & Shop No. 1-9 Sadhu Singh Dalal Sanghori Bazaar, Choti Chopar Jaipur Unique ID: CC 0008

Report Number: AIMIL/ESG/JMCEC/CC 0008/01, Rev. 00, Dated: January 2014

Building Owner Contractor Various Owners CEC Client Sub-Contractor JMRC Limited AIMIL Limited







Pre - Condition Building Survey for Construction of Underground Stationsfrom Chandpole to Bari Chouper and reversal line

	Table of Contents			
S.No.	Particulars	Page No.		
1	Introduction	2		
2	Survey Details	2		
3	About the Structure	3		
4	Building Ownership Details	3		
5	Project Details	4		
6	General Building Details	4		
7	Summary of Cracks	5		
8	Summary of Defects other than Cracks			
9	Summary of Areas that Could not be surveyed			
10	Defect Photographs			
11	Schematic Diagram of Building			

Introduction

The Jaipur Metro Rail is being constructed to provide the city of Jaipur with a modern and technologically advanced Transit System, to provide a safe and well connected means of transport that reduces traffic congestion. The project consists of two corridors with underground and elevated sections.

The construction of underground rail and road infrastructures in metropolitan and cosmopolitan cities are mostly through developed area under challenging soil conditions.

The alignment of structure is passing through densely inhabitated areas, many structures are falling in the zone of influence of construction activities. It is required to carry out the pre-condition survey of those structures. The scope of work of this survey includes carrying out pre-condition survey of those structures.

	Survey Details				
S.No.	Head	Particulars	Signatures		
1	Date of Survey	26/12/2013			
2	AIMIL Representative				
3	CEC Representative				
4	Structural Designer of CEC				
5	JMRC/DMRC Representative				







Pre - Condition Building Survey for Construction of Underground Stationsfrom Chandpole to Bari Chouper and reversal line

About the Structure

The structure under consideration is a Multi Story Load Bearing Structure having 2 floors. The structure was constructed in year 1913 and is 100 years old.

There are 83 defects in the structure out of which 21 are cracks. Category wise distribution of cracks is given in the table below. Overall the Building can be categorised in Category III (Moderate)

Category	Number of Cracks	% of Total Cracks
Negligible (< 0.1mm)	0	0%
Very Slight (0.1 to 1mm)	15	71.43%
Slight (1 to 5mm)	5	23.81%
Moderate (5 to 15mm)	1	4.76%
Severe (15 to 25mm)	0	0%
Very Severe (>25mm)	0	0%

The average width of cracks is 0.9mm and average length of cracks is 1.78m. The maximum crack width is 5mm and minimum width is 0.3mm.

	Building Ownership Details				
Unique ID/Sub ID	Premises Name	Owner	Signatures		
CC/0008/003	Babu Bakery Agency				
CC/0008/004	Shri Govind Gopal & Agency				
CC/0008/005	Ramesh & Sons				
CC/0008/006	Basudev Meghraj				
CC/0008/Temple	Mandir Shri Roopchaturbhujajhi				
CC/0008/007	Singhal Enterprises				
CC/0008/001	Shilpa Arts				
CC/0008/009	Babu Lal Rajesh Kumar & Co.				







Project Details				
S. No.	Head	Particulars		
1	Project	Jaipur Metro Rail Project		
2	Section	Chandpole to Bari Chaupar		
3	Client	JMRC Limited		
4	Consultant	DMRC Limited		
5	Contractor	CEC		
6	Design Consultant of Contractor	Omikron Kappa - Indus Consultrans JV		
7	Sub-Contractor	AIMIL Limited		
8	Subject	Pre-Condition Survey Report		

S. No.	Head	Particulars
1	Building Name	Mandir Shri Roopchaturbhujajhi & Shop No. 1-9
2	Building Address	Mandir Shri Roopchaturbhujajhi & Shop No. 1-9 Sadhu Singh Dalal Sanghori Bazaar, Choti Chopar Jaipur
3	Year of Construction	1913
4	Number of Floors	G+1
5	Number of Basements	None
6	Type of Building	Commercial
7	Approximate Height	6 m
8	Approximate Area	Not Known
9	Age of Building	100 years
10	Type of Structure	Load Bearing Structure
11	Type of Foundation	Not Known
12	Number of Bore Wells	None
13	Depth and Diameter of Bore	N.A
14	Roadways	One Side
15	Presence of Equipment/Machines	None







# JAIPUR METRO Jaipur Metro Rail Corporation

	Summar	y of Cracks				
Defect ID	Location	Orientation	Appx. Width (mm)	Appx. Length (m)	Category	Photo No
1	Outer wall Maindoor Ground Floor	Inclined	0.8	2	Very Slight	18
2	Wall No. 3 Open Area Ground Floor	Inclined	0.35	3	Very Slight	19, 19A
3	Wall No. 3 Open Area Ground Floor	Inclined	0.6	2	Very Slight	20, 20A
4	Wall No. 2 Open Area Ground Floor	Vertical	0.8	2.5	Very Slight	21, 21A
5	Wall No. 1 Open Area Ground Floor	Vertical	0.6	2.5	Very Slight	22, 22A
6	Wall No. 6 Open Area Ground Floor	Vertical	0.6	3.5	Very Slight	23, 23A
7	Floor Varanda No.1 Ground Floor	Horizontal	0.3	2.2	Very Slight	24, 24A
8	Roof Varanda No.1 Ground Floor	Inclined	1	0.4	Slight	25
9	Wall No. 1 Varanda No.1 Ground Floor	Inclined	0.6	2	Very Slight	26
10	Wall No. 1 Varanda No.3 First Floor	Vertical	0.3	1.5	Very Slight	27, 27A
11	Wall No. 4 Varanda No.3 First Floor	Inclined	0.8	0.6	Very Slight	28, 28A
12	Wall No. 1 Varanda No.4 First Floor	Vertical	0.4	1.6	Very Slight	29, 29A
13	Wall No. 4 Room No. 1 First Floor	Inclined	1.5	0.5	Slight	30, 30A
14	Wall No. 4 Open area No.2 First Floor	Inclined	5	0.5	Moderate	31, 31A
15	Wall No. 4 Room No. 2 First Floor	Inclined	0.35	1.5	Very Slight	32, 32A
16	Roof Varanda of Shop No.3 Ground Floor	Horizontal	0.5	2	Very Slight	33
17	Roof Varanda of Shop No.3 Ground Floor	Horizontal	0.8	2	Very Slight	34
18	Roof Varanda of Shop No.5 Ground Floor	Horizontal	1	2	Slight	35
19	Backside & Leftside External Column Varanda of Shop No.6 Ground Floor	Inclined	1	1	Slight	36
20	Roof Varanda of Shop No.6 Ground Floor	Horizontal	0.5	2	Very Slight	37
21	Roof Varanda of Shop No.8 Ground Floor	Horizontal	1	2	Slight	38

Summary of Defects Other Than Crack				
Defect ID	Location	Description	Photo No	
22	Wall No. 3 Open Area Ground Floor	Peeling of Plaster	39	
23	Wall No. 2 Open Area Ground Floor	Peeling of Plaster	40	
24	Wall No. 5 Open Area Ground Floor	Peeling of Plaster	41	
25	Wall No. 6 Open Area Ground Floor	Peeling of Plaster	42	
26	External wall Temple Ground Floor	Peeling of Plaster	43	
27	Stircase area Ground Floor	Peeling of Plaster	44	
28	Ground Floor	Peeling of Plaster	45	
29	Column Varanda No.1 Ground Floor	Peeling of Plaster	46	
30	Roof Varanda No.1 Ground Floor	Peeling of Plaster	47	
31	Column Varanda No.1 Ground Floor	Peeling of Plaster	48	
32	Roof Varanda No.1 Ground Floor	Peeling of Plaster	49	
33	Roof Varanda No.2 Ground Floor	Peeling of Plaster	50	
34	Wall No. 4 & Roof Varanda No.3 First Floor	Dampness/Seepage	51	
35	Wall No. 4 Varanda No.3 First Floor	Peeling of Plaster	52	
36	Wall No. 1 Varanda No.4 First Floor	Dampness/Seepage	53	
37	Roof Varanda No.4 First Floor	Peeling of Plaster	54	
38	Roof Varanda No.5 First Floor	Peeling of Plaster	55	
39	Wall No. 4 Open area No.2 First Floor	Peeling of Plaster	56	

40	Roof Shade Open area No.2 First Floor	Peeling of Plaster	57
40	Roof Varanda No.6 First Floor	Peeling of Plaster	57 58
41	Floor Varanda No.6 First Floor	Peeling of Plaster	50 59
	Wall No. 4 Room No. 2 First Floor	Peeling of Plaster	59 60
43	Floor Passage First Floor	Peeling of Plaster	
44	Wall No. 1 & Roof Passage First Floor	Dampness/Seepage	61 62
45	Wall No. 7 Open area No.2 First Floor	Peeling of Plaster	
46	Floor Open Area First Floor	Peeling of Plaster	63 64
47			04
48	Left Side outer Wall Main gate Temple First Floor	Peeling of Plaster	65
49	Left Side outer Wall Main gate Temple First Floor	Peeling of Plaster	66
50	sunshade of main gate Temple First Floor	Peeling of Plaster	67
51	Right side outer wall main gate Temple First Floor	Peeling of Plaster	68
52	Right side outer wall main gate Temple First Floor	Peeling of Plaster	69
53	Right side outer wall main gate Temple First Floor	Peeling of Plaster	70
54	Right side outer wall main gate Temple First Floor	Peeling of Plaster	71
55	Roof Part A of Shop No.4 Ground Floor	Peeling of Plaster	72
56	Wall No. 4 Part A of Shop No.4 Ground Floor	Peeling of Plaster	73
57	Wall No. 1 Part A of Shop No.4 Ground Floor	Peeling of Plaster	74
58	Wall No. 3 Part A of Shop No.4 Ground Floor	Peeling of Plaster	75
59	Wall No. 1 Part B of Shop No.4 Ground Floor	Damaged Portion	76
60	Wall No. 3 Part B of Shop No.4 Ground Floor	Peeling of Plaster	77
61	Wall No. 2 Part B of Shop No.4 Ground Floor	Peeling of Plaster	78
62	Roof Varanda of Shop No.5 Ground Floor	Dampness/Seepage	79
63	External Beam Varanda of Shop No.5 Ground Floor	Dampness/Seepage	80
64	Roof Varanda of Shop No.6 Ground Floor	Dampness/Seepage	81
65	Leftside External Column Varanda of Shop No.6 Ground Floor	Dampness/Seepage	82
66	Rightside External Column Varanda of Shop No.6 Ground Floor	Damaged Portion	83
67	Roof Shop No.8 Ground Floor	Dampness/Seepage	84
68	Roof Varanda of Shop No.8 Ground Floor	Peeling of Plaster	85
69	Internal Rightside Column Varanda of Shop No.8 Ground Floor	Damaged Portion	86
70	Internal Leftside Wall Varanda of Shop No.8 Ground Floor	Damaged Portion	87
71	Leftside External Column Varanda of Shop No.8 Ground Floor	Peeling of Plaster	88
72	Roof Part G of Shop No.9 Ground Floor	Peeling of Plaster	89
72	Wall No. 1 Part G of Shop No.9 Ground Floor	Damaged Portion	90
70	Wall No. 3 Part G of Shop No.9 Ground Floor	Peeling of Plaster	91
74	Wall No. 4 Part F of Shop No.9 Ground Floor	Peeling of Plaster	92
76	Wall No. 1 Part F of Shop No.9 Ground Floor	Peeling of Plaster	93
77	Wall No. 3 Part F of Shop No.9 Ground Floor	Peeling of Plaster	94
78	Wall No. 2 Part F of Shop No.9 Ground Floor	Peeling of Plaster	95
70	Wall No. 2 Part C of Shop No.9 Ground Floor	Peeling of Plaster	96
80	Wall No. 1 Part C of Shop No.9 Ground Floor	Peeling of Plaster	97
81	Wall No. 4 Part B of Shop No.9 Ground Floor	Peeling of Plaster	98
82	Roof Varanda of Shop No.9 Ground Floor	Peeling of Plaster	99
	Rightside External Column Varanda of Shop No.9		
83	Ground Floor	Damaged Portion	100

	Summary of A	Areas that Could not be Surveyed	
Serial No.	Location	Description	Photo No.
1	Staircase FF to SF First Floor	Locked	101
2	Room No. 1 First Floor	Locked	102
3	Shop No.9 First Floor	Locked	103
4	All Walls Shop No.7 First Floor	Covered with Wooden	104
5	Shop No.5 & 6 First Floor	Locked	105
6	All Walls & Roof Shop No.2 First Floor	Covered with Wooden	106
7	All Walls & Roof Shop no.1 First Floor	Covered with Wooden Work	107
8	Shop No.3 & 4 First Floor	Locked	108
9	Wall No. 1 Shop No.3 Ground Floor	Covered With Material	109
10	Wall No. 4 Shop No.3 Ground Floor	Covered With Material	110
11	Wall No. 2 Shop No.3 Ground Floor	Covered With Material	111
12	Roof Shop No.3 Ground Floor	Covered With Falls Celling	112
13	Wall No. 1 Shop No.5 Ground Floor	Covered With Wooden Racks & Material	113
14	Wall No. 4 Shop No.5 Ground Floor	Covered With Wooden Racks & Material	114
15	Wall No. 2 Shop No.5 Ground Floor	Covered With Wooden Racks & Material	115
16	Wall No. 1 Shop No.6 Ground Floor	Covered With Wooden Racks & Material	116
17	Wall No. 4 Shop No.6 Ground Floor	Covered With Wooden Racks & Material	117
18	Wall No. 2 Shop No.6 Ground Floor	Covered With Wooden Racks & Material	118
19	Roof Shop No.6 Ground Floor	Covered With Falls Celling	119
20	Wall No. 1 Shop No.8 Ground Floor	Covered With Wooden Racks & Material	120
21	Wall No. 4 Shop No.8 Ground Floor	Covered With Wooden Racks & Material	121
22	Wall No. 2 Shop No.8 Ground Floor	Covered With Wooden Racks & Material	122







Pre - Condition Building Survey for Construction of Underground Stationsfrom Chandpole to Bari Chouper and reversal line



Photo 1 View of Shop No.9



Photo 2 View of Temple, Ground Floor



Photo 3 View of Temple, Ground Floor



Photo 5 View of Temple, Ground Floor





Photo 4 View of Temple, Ground Floor



Photo 6 View of Temple, First Floor







Photo 7 View of Temple No.2, First Floor



Photo 8 View of Room No.3, First Floor



Photo 9 View of Shop No.7, First Floor



Photo 1 View of Shop No.3 Baba Bakes Agency, Ground Floor





Photo 10 View of Shop No.1 & 2, First Floor



Photo 12 View of Shop No.4, Ground Floor





Pre - Condition Building Survey for Construction of Underground Stationsfrom Chandpole to Bari Chouper and reversal line



Photo 13 View of Shop No.5, Ground Floor



Photo 14 View of Room No.6, Ground Floor



Photo 15 View of Shop No.8, Ground Floor



Photo 16 View of Shop No.9, Ground Floor



Photo 17 View of Shop No.9, Ground Floor





Photo 18 Inclined Crack on Outer wall of Maindoor, Ground Floor Approx. Width = 0.8mm, Approx. Length = 2m. Distance from Wall No.1 = 0m, Height from Floor = 2.25m.



Pre - Condition Building Survey for Construction of Underground Stationsfrom Chandpole to Bari Chouper and reversal line



JAIPUR METRO

Photo 19 Inclined Crack on Wall No. 3 of Open Area, Ground Floor Approx. Width = 0.35mm, Approx. Length = 3m. Distance from Wall No.2 = 3m, Height from Floor = 0m.



Photo 20 Inclined Crack on Wall No. 3 of Open Area, Ground Floor Approx. Width = 0.6mm, Approx. Length = 2m. Distance from Wall No.1 = 1.6m, Height from Floor = 0.6m.



Photo 21 Vertical Crack on Wall No. 2 of Open Area, Ground Floor Approx. Width = 0.8mm, Approx. Length = 2.5m. Distance from Wall No.3 = 0m, Height from Floor = 0m.





Photo 19A Inclined Crack on Wall No. 3 of Open Area, Ground Floor Approx. Width = 0.35mm, Approx. Length = 3m. Distance from Wall No.2 = 3m, Height from Floor = 0m.



Photo 20A Inclined Crack on Wall No. 3 of Open Area, Ground Floor Approx. Width = 0.6mm, Approx. Length = 2m. Distance from Wall No.1 = 1.6m, Height from Floor = 0.6m.



Photo 21A Vertical Crack on Wall No. 2 of Open Area, Ground Floor Approx. Width = 0.8mm, Approx. Length = 2.5m. Distance from Wall No.3 = 0m, Height from Floor = 0m.





Pre - Condition Building Survey for Construction of Underground Stationsfrom Chandpole to Bari Chouper and reversal line



Photo 22 Vertical Crack on Wall No. 1 of Open Area, Ground Floor Approx. Width = 0.6mm, Approx. Length = 2.5m. Distance from Wall No.3 = 2.5m, Height from Floor = 1m.



Photo 23 Vertical Crack on Wall No. 6 of Open Area, Ground Floor Approx. Width = 0.6mm, Approx. Length = 3.5m. Distance from Wall No.5 = 3.5m, Height from Floor = 0m.



Photo 24 Horizontal Crack on Floor of Varanda No.1, Ground Floor Approx. Width = 0.3mm, Approx. Length = 2.2m. Distance from Wall = 0m, Height from Floor = 0m.





Photo 22A Vertical Crack on Wall No. 1 of Open Area, Ground Floor Approx. Width = 0.6mm, Approx. Length = 2.5m. Distance from Wall No.3 = 2.5m, Height from Floor = 1m.



Photo 23A Vertical Crack on Wall No. 6 of Open Area, Ground Floor Approx. Width = 0.6mm, Approx. Length = 3.5m. Distance from Wall No.5 = 3.5m, Height from Floor = 0m.



Photo 24A Horizontal Crack on Floor of Varanda No.1, Ground Floor Approx. Width = 0.3mm, Approx. Length = 2.2m. Distance from Wall = 0m, Height from Floor = 0m.



Pre - Condition Building Survey for Construction of Underground Stationsfrom Chandpole to Bari Chouper and reversal line



JAIPUR METRO

Photo 25 Inclined Crack on Roof of Varanda No.1, Ground Floor Approx. Width = 1mm, Approx. Length = 0.4m. Distance from Wall No.6 = 2m, Height from Floor = 3.5m.



Photo 27 Vertical Crack on Wall No. 1 of Varanda No.3, First Floor Approx. Width = 0.3mm, Approx. Length = 1.5m. Distance from Wall No.3 = 1m, Height from Floor = 0m.



Photo 28 Inclined Crack on Wall No. 4 of Varanda No.3, First Floor Approx. Width = 0.8mm, Approx. Length = 0.6m. Distance from Wall no.1 = 2m, Height from Floor = 1.5m.





Photo 26 Inclined Crack on Wall No. 1 of Varanda No.1, Ground Floor Approx. Width = 0.6mm, Approx. Length = 2m. Distance from Wall No.4 = 3.3m, Height from Floor = 2.2m.



Photo 27A

Vertical Crack on Wall No. 1 of Varanda No.3, First Floor Approx. Width = 0.3mm, Approx. Length = 1.5m. Distance from Wall No.3 = 1m, Height from Floor = 0m.



Photo 28A Inclined Crack on Wall No. 4 of Varanda No.3, First Floor Approx. Width = 0.8mm, Approx. Length = 0.6m. Distance from Wall no.1 = 2m, Height from Floor = 1.5m.



Pre - Condition Building Survey for Construction of Underground Stationsfrom Chandpole to Bari Chouper and reversal line



JAIPUR METRO

Photo 29 Vertical Crack on Wall No. 1 of Varanda No.4, First Floor Approx. Width = 0.4mm, Approx. Length = 1.6m. Distance from Wall No.3 = 1.25m, Height from Floor = 0m.



Photo 30 Inclined Crack on Wall No. 4 of Room No. 1, First Floor Approx. Width = 1.5mm, Approx. Length = 0.5m. Distance from Wall no.1 = 0.5m, Height from Floor = 0.3m.



Photo 31 Inclined Crack on Wall No. 4 of Open area No.2, First Floor Approx. Width = 5mm, Approx. Length = 0.5m. Distance from Wall no.1 = 1.3m, Height from Floor = 0m.





Photo 29A Vertical Crack on Wall No. 1 of Varanda No.4, First Floor Approx. Width = 0.4mm, Approx. Length = 1.6m. Distance from Wall No.3 = 1.25m, Height from Floor = 0m.



#### Photo 30A

Inclined Crack on Wall No. 4 of Room No. 1, First Floor Approx. Width = 1.5mm, Approx. Length = 0.5m. Distance from Wall no.1 = 0.5m, Height from Floor = 0.3m.



Photo 31A Inclined Crack on Wall No. 4 of Open area No.2, First Floor Approx. Width = 5mm, Approx. Length = 0.5m. Distance from Wall no.1 = 1.3m, Height from Floor = 0m.



Pre - Condition Building Survey for Construction of Underground Stationsfrom Chandpole to Bari Chouper and reversal line



JAIPUR METRO

Photo 32 Inclined Crack on Wall No. 4 of Room No. 2, First Floor Approx. Width = 0.35mm, Approx. Length = 1.5m. Distance from Wall no.2 = 0.6m, Height from Floor = 1.7m.



Photo 33 Horizontal Crack on Roof of Varanda of Shop No.3, Ground Floor Approx. Width = 0.5mm, Approx. Length = 2m. Distance from Leftside Column = 0m, Height from Floor = 3.5m.



#### <u>Photo 3</u>5

Horizontal Crack on Roof of Varanda of Shop No.5, Ground Floor Approx. Width = 1mm, Approx. Length = 2m. Distance from Rightside Column = Backsidem, Height from Floor = 3m.





Photo 32A Inclined Crack on Wall No. 4 of Room No. 2, First Floor Approx. Width = 0.35mm, Approx. Length = 1.5m. Distance from Wall no.2 = 0.6m, Height from Floor = 1.7m.



Photo 34 Horizontal Crack on Roof of Varanda of Shop No.3, Ground Floor Approx. Width = 0.8mm, Approx. Length = 2m. Distance from Rightside Column = 0m, Height from Floor = 3.5m.



<u>Photo 3</u>6

Inclined Crack on Backside & Leftside External Column of Varanda of Shop No.6, Ground Floor Approx. Width = 1mm, Approx. Length = 1m. Distance from = m, Height from Floor = 4m.



Pre - Condition Building Survey for Construction of Underground Stationsfrom Chandpole to Bari Chouper and reversal line



JAIPUR METRO

Photo 37 Horizontal Crack on Roof of Varanda of Shop No.6, Ground Floor Approx. Width = 0.5mm, Approx. Length = 2m. Distance from Leftside Column = 0.7m, Height from Floor = 4m.



Photo 39 Peeling of Plaster on Wall No. 3 of Open Area of Ground Floor



Photo 41 Peeling of Plaster on Wall No. 5 of Open Area of Ground Floor





Photo 38 Horizontal Crack on Roof of Varanda of Shop No.8, Ground Floor Approx. Width = 1mm, Approx. Length = 2m.Distance from Rightside External Column = Backsidem, Height from Floor = 4m.



Photo 40 Peeling of Plaster on Wall No. 2 of Open Area of Ground Floor



Photo 42 Peeling of Plaster on Wall No. 6 of Open Area of Ground Floor







Photo 43 Peeling of Plaster on External wall of Temple of Ground Floor



Photo 44 Peeling of Plaster on Stircase area of Ground Floor





Photo 45 Peeling of Plaster on Ground Floor



Photo 47 Peeling of Plaster on Roof of Varanda No.1 of Ground Floor






Photo 48 Peeling of Plaster on Column of Varanda No.1 of Ground Floor









Photo 49 Peeling of Plaster on Roof of Varanda No.1 of Ground Floor



Photo 50 Peeling of Plaster on Roof of Varanda No.2 of Ground Floor





Photo 51 Dampness/Seepage on Wall No. 4 & Roof of Varanda No.3 of First Floor



Photo 53 Dampness/Seepage on Wall No. 1 of Varanda No.4 of First Floor



Photo 52 Peeling of Plaster on Wall No. 4 of Varanda No.3 of First Floor



Photo 54 Peeling of Plaster on Roof of Varanda No.4 of First Floor







Pre - Condition Building Survey for Construction of Underground Stationsfrom Chandpole to Bari Chouper and reversal line



Photo 55 Peeling of Plaster on Roof of Varanda No.5 of First Floor



Photo 56 Peeling of Plaster on Wall No. 4 of Open area No.2 of First Floor






Photo 58

Peeling of Plaster on Roof of Varanda No.6 of First Floor

Photo 57 Peeling of Plaster on Roof Shade of Open area No.2 of First Floor



Photo 59 Peeling of Plaster on Floor of Varanda No.6 of First Floor



Photo 60 Peeling of Plaster on Wall No. 4 of Room No. 2 of First Floor









Photo 61 Peeling of Plaster on Floor of Passage of First Floor



Photo 62 Dampness/Seepage on Wall No. 1 & Roof of Passage of First Floor





<u>Photo 6</u>3 Peeling of Plaster on Wall No. 7 of Open area No.2 of First Floor






Photo 65 Floor



Photo 66 Peeling of Plaster on Left Side outer Wall Main gate of Temple of First Peeling of Plaster on Left Side outer Wall Main gate of Temple of First Floor







23 11 2013

Photo 67 Peeling of Plaster on sunshade of main gate of Temple of First Floor

Photo 68 Peeling of Plaster on Right side outer wall main gate of Temple of First Floor





Photo 69 Peeling of Plaster on Right side outer wall main gate of Temple of First Peeling of Plaster on Right side outer wall main gate of Temple of First Floor Floor



Photo 71
Peeling of Plaster on Right side outer wall main gate of Temple of First
Floor



Photo 72 Peeling of Plaster on Roof of Part A of Shop No.4 of Ground Floor









Photo 73
Peeling of Plaster on Wall No. 4 of Part A of Shop No.4 of Ground Floor Peeling of Plaster on Wall No. 1 of Part A of Shop No.4 of Ground Floor





Photo 75 Peeling of Plaster on Wall No. 3 of Part A of Shop No.4 of Ground Floor Damaged Portion on Wall No. 1 of Part B of Shop No.4 of Ground Floor





Photo 77
Peeling of Plaster on Wall No. 3 of Part B of Shop No.4 of Ground Floor Peeling of Plaster on Wall No. 2 of Part B of Shop No.4 of Ground Floor











Photo 79 Dampness/Seepage on Roof of Varanda of Shop No.5 of Ground Floor

Photo 80 Dampness/Seepage on External Beam of Varanda of Shop No.5 of Ground Floor





Photo 81 Dampness/Seepage on Roof of Varanda of Shop No.6 of Ground Floor

Photo 82 Dampness/Seepage on Leftside External Column of Varanda of Shop No.6 of Ground Floor



Photo 83 Damaged Portion on Rightside External Column of Varanda of Shop No.6 of Ground Floor





Photo 84 Dampness/Seepage on Roof of Shop No.8 of Ground Floor





Pre - Condition Building Survey for Construction of Underground Stationsfrom Chandpole to Bari Chouper and reversal line



26.11.2014

Photo 85 Peeling of Plaster on Roof of Varanda of Shop No.8 of Ground Floor

Photo 86 Damaged Portion on Internal Rightside Column of Varanda of Shop No.8 of Ground Floor





 
 Photo 87
 Photo 88

 Damaged Portion on Internal Leftside Wall of Varanda of Shop No.8 of Ground Floor
 Peeling of Plaster on Leftside External Column of Varanda of Shop No.8 of Ground Floor



Photo 89 Peeling of Plaster on Roof of Part G of Shop No.9 of Ground Floor



Photo 90

Damaged Portion on Wall No. 1 of Part G of Shop No.9 of Ground Floor



Aimil Ltd. Instrumentation & Technologies







Photo 91 Peeling of Plaster on Wall No. 3 of Part G of Shop No.9 of Ground Floor Peeling of Plaster on Wall No. 4 of Part F of Shop No.9 of Ground Floor





Photo 93 Peeling of Plaster on Wall No. 1 of Part F of Shop No.9 of Ground Floor Peeling of Plaster on Wall No. 3 of Part F of Shop No.9 of Ground Floor





Photo 95 Peeling of Plaster on Wall No. 2 of Part F of Shop No.9 of Ground Floor Peeling of Plaster on Wall No. 2 of Part C of Shop No.9 of Ground Floor











Photo 97 Peeling of Plaster on Wall No. 1 of Part C of Shop No.9 of Ground Floor Peeling of Plaster on Wall No. 4 of Part B of Shop No.9 of Ground Floor





Photo 99 Peeling of Plaster on Roof of Varanda of Shop No.9 of Ground Floor

Photo 100 Damaged Portion on Rightside External Column of Varanda of Shop No.9 of Ground Floor



Photo 101 Staircase FF to SF of First Floor Locked





Photo 102 Room No. 1 of First Floor Locked







Photo 103 Shop No.9 of First Floor Locked



Photo 104 All Walls of Shop No.7 of First Floor Covered with Wooden





Photo 105 Shop No.5 & 6 of First Floor Locked







Photo 107 All Walls & Roof of Shop no.1 of First Floor Covered with Wooden Work



Photo 108 Shop No.3 & 4 of First Floor Locked







Photo 109 Wall No. 1 of Shop No.3 of Ground Floor Covered With Material

Photo 110 Wall No. 4 of Shop No.3 of Ground Floor Covered With Material





Photo 111 Wall No. 2 of Shop No.3 of Ground Floor Covered With Material

Photo 112 Roof of Shop No.3 of Ground Floor Covered With Falls Celling





 Photo 1
 13
 Photo 1
 14

 Wall No. 1 of Shop No.5 of Ground Floor Covered With Wooden Racks
 Wall No. 4 of Shop No.5 of Ground Floor Covered With Wooden Racks
 & Material











Photo 115 Wall No. 2 of Shop No.5 of Ground Floor Covered With Wooden Racks & Material Material Photo 116 Wall No. 1 of Shop No.6 of Ground Floor Covered With Wooden Racks & Material





 
 Photo 1
 Photo 1
 Photo 1
 18

 Wall No. 4 of Shop No.6 of Ground Floor Covered With Wooden Racks & Material
 Wall No. 2 of Shop No.6 of Ground Floor Covered With Wooden Racks & Material
 Wall No. 2 of Shop No.6 of Ground Floor Covered With Wooden Racks



Photo 119 Roof of Shop No.6 of Ground Floor Covered With Falls Celling













Photo 121 Wall No. 4 of Shop No.8 of Ground Floor Covered With Wooden Racks & Material Photo 122 Wall No. 2 of Shop No.8 of Ground Floor Covered With Wooden Racks & Material



Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Public Convenience Sadhu Singh Dalal Sanghori Bazaar, Choti Chopar Jaipur Unique ID: CC 0009

Report Number: AIMIL/ESG/JMCEC/CC 0009/01, Rev. 00, Dated: January 2014

Building Owner Contractor Government CEC Client Sub-Contractor JMRC Limited AIMIL Limited







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

	Table of Contents			
S.No.	Particulars	Page No.		
1	Introduction	2		
2	Survey Details	2		
3	About the Structure	3		
4	Building Ownership Details	3		
5	Project Details	4		
6	General Building Details	4		
7	Summary of Cracks	5		
8	Summary of Defects other than Cracks			
9	Summary of Areas that Could not be surveyed			
10	Defect Photographs			
11	Schematic Diagram of Building			

Introduction

The Jaipur Metro Rail is being constructed to provide the city of Jaipur with a modern and technologically advanced Transit System, to provide a safe and well connected means of transport that reduces traffic congestion. The project consists of two corridors with underground and elevated sections.

The construction of underground rail and road infrastructures in metropolitan and cosmopolitan cities are mostly through developed area under challenging soil conditions.

The alignment of structure is passing through densely inhabitated areas, many structures are falling in the zone of influence of construction activities. It is required to carry out the pre-condition survey of those structures. The scope of work of this survey includes carrying out pre-condition survey of those structures.

	Survey Details				
S.No.	Head	Particulars	Signatures		
1	Date of Survey	20/12/2013			
2	AIMIL Representative				
3	CEC Representative				
4	Structural Designer of CEC				
5	JMRC/DMRC Representative				







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

About the Structure

The structure under consideration is a Single Story RCC Framed Structure having a basement. The structure was constructed in year 2001 and is 12 years old.

There are 1 defects in the structure out of which 0 are cracks. Category wise distribution of cracks is given in the table below. Overall the Building can be categorised in Category 0 (Negligible)

Category	Number of Cracks	% of Total Cracks
Negligible (< 0.1mm)	0	0%
Very Slight (0.1 to 1mm)	0	0%
Slight (1 to 5mm)	0	0%
Moderate (5 to 15mm)	0	0%
Severe (15 to 25mm)	0	0%
Very Severe (>25mm)	0	0%

Building Ownership Details				
Unique ID/Sub ID	Premises Name	Owner	Signatures	
CC/0009	Public Convinience			







Project Details				
S. No.	Head	Particulars		
1	Project	Jaipur Metro Rail Project		
2	Section	Chandpole to Bari Chaupar		
3	Client	JMRC Limited		
4	Consultant	DMRC Limited		
5	Contractor	CEC		
6	Design Consultant of Contractor	Omikron Kappa - Indus Consultrans JV		
7	Sub-Contractor	AIMIL Limited		
8	Subject	Pre-Condition Survey Report		

General Bui	Iding Details (As informed verbally by Building O	wner)
S. No.	Head	Particulars
1	Building Name	Public Convenience
2	Building Address	Public Convenience Sadhu Singh Dalal Sanghori Bazaar, Choti Chopar Jaipur
3	Year of Construction	2001
4	Number of Floors	B+G
5	Number of Basements	1
6	Type of Building	Commercial
7	Approximate Height	3 m
8	Approximate Area	Not Known
9	Age of Building	12 years
10	Type of Structure	RCC
11	Type of Foundation	Not Known
12	Number of Bore Wells	None
13	Depth and Diameter of Bore	N.A
14	Roadways	Two Side
15	Presence of Equipment/Machines	None







Summary of Cracks						
Defect ID	Location	Orientation	Appx. Width (mm)	Appx. Length (m)	Category	Photo No.
Summary of Defects Other Than Crack						
Defect ID	Location	Description Photo No		Photo No.		
1	Wall No. 4 Gents Toilet Basement	Dampness/Seepage			4	

	Summary of Areas that Could not be Surveyed					
Serial No.	Location	Description F				
1	All Walls Ladies Toilet Basement	Covered with Tiles	5			
2	All Walls Gents Wash room Basement	Covered with Tiles	6			
3	All Walls Room No. 1 Basement	Covered with Tiles	7			
4	All Walls Gents Toilet Basement		8			







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Photo 1 View of Public Toilet



Photo 2 View of Public Toilet, Basement





Photo 4

Dampness/Seepage on Wall No. 4 of Gents Toilet of Basement

Photo 3 View of Public Toilet, Basement



Photo 5 All Walls of Ladies Toilet of Basement Covered with Tiles



Photo 6 All Walls of Gents Wash room of Basement Covered with Tiles







# JAIPUR METRO Jaipur Metro Rail Corporation




Photo 7 All Walls of Room No. 1 of Basement Covered with Tiles



Photo 8 All Walls of Gents Toilet of Basement



Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Hanumanji Temple Sadhu Singh Dalal Sanghori Bazaar, Choti Chopar Jaipur Unique ID: CC 0010

Report Number: AIMIL/ESG/JMCEC/CC 0010/01, Rev. 00, Dated: January 2014

Building Owner Contractor Mr. Ram Babu Sharma CEC Client Sub-Contractor JMRC Limited AIMIL Limited







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

	Table of Contents			
S.No.	Particulars	Page No.		
1	Introduction	2		
2	Survey Details	2		
3	About the Structure	3		
4	Building Ownership Details	3		
5	Project Details	4		
6	General Building Details	4		
7	Summary of Cracks	5		
8	Summary of Defects other than Cracks			
9	Summary of Areas that Could not be surveyed			
10	Defect Photographs			
11	Schematic Diagram of Building			

Introduction

The Jaipur Metro Rail is being constructed to provide the city of Jaipur with a modern and technologically advanced Transit System, to provide a safe and well connected means of transport that reduces traffic congestion. The project consists of two corridors with underground and elevated sections.

The construction of underground rail and road infrastructures in metropolitan and cosmopolitan cities are mostly through developed area under challenging soil conditions.

The alignment of structure is passing through densely inhabitated areas, many structures are falling in the zone of influence of construction activities. It is required to carry out the pre-condition survey of those structures. The scope of work of this survey includes carrying out pre-condition survey of those structures.

	Survey Details				
S.No.	Head	Particulars	Signatures		
1	Date of Survey	19/12/2013			
2	AIMIL Representative				
3	CEC Representative				
4	Structural Designer of CEC				
5	JMRC/DMRC Representative				







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

#### About the Structure

The structure under consideration is a Single Story RCC Framed Structure . The structure was constructed in year 1967 and is 46 years old.

There are 0 defects in the structure out of which 0 are cracks. Category wise distribution of cracks is given in the table below. Overall the Building can be categorised in Category 0 (Negligible)

Category	Number of Cracks	% of Total Cracks
Negligible (< 0.1mm)	0	0%
Very Slight (0.1 to 1mm)	0	0%
Slight (1 to 5mm)	0	0%
Moderate (5 to 15mm)	0	0%
Severe (15 to 25mm)	0	0%
Very Severe (>25mm)	0	0%

Building Ownership Details				
Unique ID/Sub ID	Premises Name	Owner	Signatures	
CC/0010	Hanuman Temple, In Front of Shop No. 235			







Project Details			
S. No.	Head	Particulars	
1	Project	Jaipur Metro Rail Project	
2	Section	Chandpole to Bari Chaupar	
3	Client	JMRC Limited	
4	Consultant	DMRC Limited	
5	Contractor	CEC	
6	Design Consultant of Contractor	Omikron Kappa - Indus Consultrans JV	
7	Sub-Contractor	AIMIL Limited	
8	Subject	Pre-Condition Survey Report	

General Building Details (As informed verbally by Building Owner)			
S. No.	Head	Particulars	
1	Building Name	Hanumanji Temple	
2	Building Address	Hanumanji Temple Sadhu Singh Dalal Sanghori Bazaar, Choti Chopar Jaipur	
3	Year of Construction	1967	
4	Number of Floors	G	
5	Number of Basements	None	
6	Type of Building	Commercial	
7	Approximate Height	3 m	
8	Approximate Area	Not Known	
9	Age of Building	46 years	
10	Type of Structure	RCC	
11	Type of Foundation	Not Known	
12	Number of Bore Wells	None	
13	Depth and Diameter of Bore	N.A	
14	Roadways	One Side	
15	Presence of Equipment/Machines	None	







Summary of Cracks						
Defect ID	Location	Orientation	Appx. Width (mm)	Appx. Length (m)	Category	Photo No.
Summary of Defects Other Than Crack						
Defect ID	Location	Description		Photo No.		
	Summary of Areas that Could not be Surveyed					
Serial No.	Location	Description Ph		Photo No.		
1	All Walls Hanuman Ji Ka Temple Ground Floor	Covered With Marble and Material 2		2		







# JAIPUR METRO Jaipur Metro Rail Corporation

Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Photo 1 View of Hanuman Ji Ka Temple



Photo 2 All Walls of Hanuman Ji Ka Temple of Ground Floor Covered With Marble and Material



Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



Report Number: AIMIL/ESG/JMCEC/CC 0011/01, Rev. 00, Dated: January 2014

Building Owner Contractor Various Owners CEC Client Sub-Contractor JMRC Limited AIMIL Limited







Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line

	Table of Contents			
S.No.	Particulars	Page No.		
1	Introduction	2		
2	Survey Details	2		
3	About the Structure	3		
4	Building Ownership Details	3		
5	Project Details	4		
6	General Building Details	4		
7	Summary of Cracks	5		
8	Summary of Defects other than Cracks			
9	Summary of Areas that Could not be surveyed			
10	Defect Photographs			
11	Schematic Diagram of Building			

Introduction

The Jaipur Metro Rail is being constructed to provide the city of Jaipur with a modern and technologically advanced Transit System, to provide a safe and well connected means of transport that reduces traffic congestion. The project consists of two corridors with underground and elevated sections.

The construction of underground rail and road infrastructures in metropolitan and cosmopolitan cities are mostly through developed area under challenging soil conditions.

The alignment of structure is passing through densely inhabited areas, many structures are falling in the zone of influence of construction activities. It is required to carry out the pre-condition survey of those structures. The scope of work of this survey includes carrying out pre-condition survey of those structures.

	Survey Details				
S.No.	Head	Particulars	Signatures		
1	Date of Survey	09/12/2013			
2	AIMIL Representative				
3	CEC Representative				
4	Structural Designer of CEC				
5	JMRC/DMRC Representative				







Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line

About the Structure

The structure under consideration is a Multi Story Load Bearing Structure having 2 floors and a basement. The structure was constructed in year 1850 and is 163 years old.

There are 275 defects in the structure out of which 40 are cracks. Category wise distribution of cracks is given in the table below. Overall the Building can be categorised in Category III (Moderate)

Category	Number of Cracks	% of Total Cracks
Negligible (< 0.1mm)	0	0%
Very Slight (0.1 to 1mm)	19	47.50%
Slight (1 to 5mm)	18	45%
Moderate (5 to 15mm)	3	7.50%
Severe (15 to 25mm)	0	0%
Very Severe (>25mm)	0	0%

The average width of cracks is 1.53mm and average length of cracks is 1.63m. The maximum crack width is 5mm and minimum width is 0.15mm.

	Building Ownership Details			
Unique ID/Sub ID	Premises Name	Owner	Signatures	
CC/0011/PS				
CC/0011/170				
CC/0011/169				
CC/0011/168				
CC/0011/167				
CC/0011/165-166				
CC/0011/164				
CC/0011/163				
CC/0011/162				
CC/0011/161				







Project Details			
S. No.	Head	Particulars	
1	Project	Jaipur Metro Rail Project	
2	Section	Chandpole to Bari Chaupar	
3	Client	JMRC Limited	
4	Consultant	DMRC Limited	
5	Contractor	CEC	
6	Design Consultant of Contractor	Omikron Kappa - Indus Consultrans JV	
7	Sub-Contractor	AIMIL Limited	
8	Subject	Pre-Condition Survey Report	

General Bui	Iding Details (As informed verbally by Building C	Dwner)
S. No.	Head	Particulars
1	Building Name	Police Station, Shop No. 160-170
2	Building Address	Police Station, Shop No. 160-170 Choti Chopar Jaipur
3	Year of Construction	1850
4	Number of Floors	B+G+1
5	Number of Basements	1
6	Type of Building	Commercial
7	Approximate Height	6m
8	Approximate Area	Not Known
9	Age of Building	163 years
10	Type of Structure	Load Bearing Structure
11	Type of Foundation	Not Known
12	Number of Bore Wells	None
13	Depth and Diameter of Bore	N.A
14	Roadways	Two Side
15	Presence of Equipment/Machines	None







# JAIPUR METRO Jaipur Metro Rail Corporation

		of Cracks	Appx, Width	Appx. Length	-	
Defect ID	Location	Orientation	(mm)	(m)	Category	Photo No
1	Roof Varanda of Shop No.169B Ground Floor	Horizontal	0.2	1.1	Very Slight	31
2	Roof Varanda of Shop No.169A Ground Floor	Horizontal	0.15	1.1	Very Slight	32
3	Roof Varanda of Shop No.167 Ground Floor	Horizontal	0.8	1.1	Very Slight	33
4	Wall No. 4 Room No. 7A Ground Floor	Horizontal	0.35	1.1	Very Slight	34, 34A
5	Wall No. 2 Toilet No. 1(Part B) Ground Floor	Inclined	0.25	3	Very Slight	35, 35A
6	Wall No. 3 Room No. 9	Inclined	0.2	1.3	Very Slight	36, 36A
7	Roof Room No. 9	Inclined	0.3	2.8	Very Slight	37
8	Roof Part A of Store	Inclined	2	3	Slight	38
9	Wall No. 2 Room No. 110 First Floor	Inclined	0.3	1.25	Very Slight	39
10	Wall No. 3 Room No. 110 First Floor	Horizontal	1	1	Slight	40
11	Wall No. 1 Room No. 110 First Floor	Inclined	2	4	Slight	41, 41A
12	Wall No. 4 Passage No.1 First Floor	Inclined	2.5	1.4	Slight	42, 42A
13	Wall No. 2 Passage No.1 First Floor	Inclined	0.6	1	Very Slight	43
14	Roof Room No. Room First Floor	Inclined	1.5	2	Slight	44
15	Roof Room No. Room First Floor	Inclined	0.8	2	Very Slight	45
16	Open Sky Passage First Floor	Vertical	0.6	1.8	Very Slight	46, 46A
17	Open Sky Passage First Floor	Vertical	0.5	1	Very Slight	47, 47A
18	Wall No. 2 & 4 Room No. S.D.Anubhag Room First Floor	Vertical	-			48
19	Roof Open Sky No.2 First Floor	Vertical	0.6	1.5	Very Slight	49
20	Wall No. 3 Open Sky No.2 First Floor	Vertical	0.15	1.6	Very Slight	50, 50A
21	Wall No. 1 Toilet No. 1 Second Floor	Inclined	1.5	1.5	Slight	51, 51A
22	Wall No. 2 & 4 Toilet No. 1 Second Floor	Horizontal	4	2	Slight	52
23	Open Sky No.2 Third Floor	Inclined	5	2	Moderate	53
24	Wall No. 1 Room No. 4 Second Floor	Horizontal	5	0.4	Moderate	54
25	Room No. 5 Second Floor	Horizontal	3	0.5	Slight	55
26	Wall No. 3 Open Sky No.3 Second Floor	Inclined	1	3	Slight	56, 56A
27	Wall No. 3 Open Sky No.3 Second Floor	Inclined	1.5	1	Slight	57
28	Wall No. 3 & Roof Bathroom No. Second Floor	Inclined	0.5	4	Very Slight	58
29	Wall No. 1 Room No. 12 Second Floor	Inclined	0.6	1	Very Slight	59
30	Wall No. 2 & 4 Room No. 13 Second Floor	Inclined	0.4	1.9	Very Slight	60
31	Wall No. 1 Room No. 12 Second Floor	Inclined	0.8	1.5	Very Slight	61
32	Wall No. 4 Tinshed Kitchen Second Floor	Horizontal	2	0.4	Slight	62
33	Wall No. 1 Tinshed Kitchen Second Floor	Inclined	2	0.5	Slight	63
34	Wall No. 1 Tinshed Kitchen Second Floor	Inclined	3	0.6	Slight	64
35	Wall No. 3 Tinshed Kitchen Second Floor	Inclined	1.5	0.5	Slight	65
36	Wall No. 4 Room No. 14 Second Floor	Inclined	5	2.2	Moderate	66, 66A
37	Wall No. 2 & 3 Room No. 14 Second Floor	Inclined	1.5	2	Slight	67, 67A
38	Front side Wall Part B of Police Kotwali Ground Floor	Inclined	2.5	2	Slight	68
39	Front side Wall Part B of Police Kotwali Ground Floor	Inclined	2	2	Slight	69
40	Front side Wall Part B of Police Kotwali Ground Floor	Inclined	0.5	2	Very Slight	70

Defect ID	Location	Description	Photo No.
41	Roof Varanda of Shop No.169B Ground Floor	Dampness/Seepage	71
42	External Beam Varanda of Shop No.169B Ground Floor	Dampness/Seepage	72
43	Roof Varanda of Shop No.169A Ground Floor	Dampness/Seepage	73
44	External Beam Varanda of Shop No.169A Ground Floor	Dampness/Seepage	74
45	Wall No. 4 Shop No.169A Basement	Damaged Portion	75
46	External Beam Varanda of Shop No.168 Ground Floor	Dampness/Seepage	76
47	Roof Varanda of Shop No.167 Ground Floor	Peeling of Plaster	77
48	External Beam Varanda of Shop No.167 Ground Floor	Dampness/Seepage	78
49	Floor Shop no.165 & 166 Upper Ground Floor	Peeling of Plaster	79
50	Wall No. 4 Shop No.162 Ground Floor	Dampness/Seepage	80
51	Roof Shop No.161 Ground Floor	Dampness/Seepage	81
52	Wall No. 3 Room No. 2 Ground Floor	Peeling of Plaster	82
53	Roof Room No. 2 Ground Floor	Peeling of Plaster	83
54	Roof Varanda No.1 Ground Floor	Peeling of Plaster	84
55	Wall No. 1 Varanda No.1 Ground Floor	Dampness/Seepage	85
56	Wall No. 2 & 3 Varanda No.1 Ground Floor	Dampness/Seepage	86
57	Wall No. 1, 2 & 4 Passage No.1 Ground Floor	Dampness/Seepage	87
58	Roof Passage No.1 Ground Floor	Dampness/Seepage	88
59	Wall No. 2 & 4 Gate No.3 Ground Floor	Dampness/Seepage	89
60	Wall No. 2 & 4 Gate No.4 Ground Floor	Dampness/Seepage	90
61	Wall No. 1, 4 & Roof Room No. 5 Ground Floor	Dampness/Seepage	91
62	Wall No. 2 & Roof Room No. 5 Ground Floor	Dampness/Seepage	92
63	Outer Main Gate Room No. 6 Ground Floor	Peeling of Plaster	93
64	Wall No. 1, 3 & Roof Room No. 6 Ground Floor	Dampness/Seepage	94
65	Roof Room No. 7B Ground Floor	Dampness/Seepage	95
66	Wall No. 2 & 4 Store Ground Floor	Peeling of Plaster	96
67	Wall No. 4 Room No. 7A Ground Floor	Dampness/Seepage	97
68	Wall No. 2 Room No. 7A Ground Floor	Peeling of Plaster	98
	Wall No. 2 Room No. 7A Ground Floor Wall No. 4 Room No. 7A Ground Floor	Peeling of Plaster	98
69 70	Roof Room No. 9 Ground Floor	Peeling of Plaster	100
70	Roof Room No. 9 Ground Floor	Peeling of Plaster	100
	Wall No. 3 Room No. 9 Ground Floor	Peeling of Plaster	-
72	Room No. 8 Ground Floor		102
73		Peeling of Plaster	103
74	Wall No. 2 Room No. 8 Ground Floor	Dampness/Seepage	104
75	Wall No. 4 Room No. 8 Ground Floor	Dampness/Seepage	105
76	Roof Passage No.3 Ground Floor	Dampness/Seepage	106
77	Roof Passage No.3 Ground Floor	Peeling of Plaster	107
78	Wall No. 1 Passage No.3 Ground Floor	Peeling of Plaster	108
79	Room No. 11 Ground Floor	Peeling of Plaster	109
80	Roof Toilet No. 1(Part B) Ground Floor	Dampness/Seepage	110
81	Wall No. 3 Toilet No. 1(Part B) Ground Floor	Peeling of Plaster	111
82	Roof Room No. 10 Ground Floor	Dampness/Seepage	112
83	Wall No. 4 Room No. 10 Ground Floor	Peeling of Plaster	113
84	Wall No. 3 Room No. 10 Ground Floor	Dampness/Seepage	114
85	Wall No. 1 Room No. 10 Ground Floor	Dampness/Seepage	115
86	Wall No. 4 Room No. 11 Ground Floor	Peeling of Plaster	116
87	Wall No. 4 Room No. 11 Ground Floor	Peeling of Plaster	117

89	Wall No. 4 Room No. 7 Ground Floor	Peeling of Plaster	119
90	Roof Room No. 9(lobby)	Peeling of Plaster	120
91	Wall No. 2 Room No. 9(lobby)	Peeling of Plaster	121
92	Wall No. 4 & Roof Room No. 9	Dampness/Seepage	122
93	Wall No. 4 & Roof Room No. 9	Dampness/Seepage	123
94	Wall No. 4 Room No. 9	Peeling of Plaster	124
95	Wall No. 1, 4 & Roof Room No. 3(Lobby)	Dampness/Seepage	125
96	Roof Pantry	Peeling of Plaster	126
97	Wall No. 2, 4 & Roof Room No. 1(office)	Peeling of Plaster	127
98	Wall No. 2 Room No. 1	Dampness/Seepage	128
99	All Walls Room No. 16(Part E)	Dampness/Seepage	129
100	Wall No. 4, 2 & Roof Room No. 16(part D)	Dampness/Seepage	130
101	Wall No. 2 & 3 Room No. 16(Part A)	Peeling of Plaster	131
102	Roof Room No. 15(PartA)	Peeling of Plaster	132
103	Wall No. 1 Room No. 15(PartA)	Peeling of Plaster	133
104	All Walls & Roof Room No. 16(Part B)	Peeling of Plaster	134
105	Wall No. 2 & Roof Room No. 16(Part B)	Peeling of Plaster	135
105	Roof Room No. 14(Part B)	Dampness/Seepage	135
100	Wall No. 4 & Roof Room No. 13	Peeling of Plaster	130
107	Roof Room No. 13	Peeling of Plaster	137
	Roof Room No. 13	Peeling of Plaster	139
109		Peeling of Plaster	
110	Wall No. 1 Passage		140
111	Wall No. 1 Passage	Peeling of Plaster	141
112	Roof Passage	Peeling of Plaster	142
113	Wall No. 4 Passage	Peeling of Plaster	143
114	Roof Passage	Damaged Portion	144
115	Roof Passage	Damaged Portion	145
116	Roof Passage	Damaged Portion	146
117	Roof Passage	Damaged Portion	147
118	Roof Passage	Damaged Portion	148
119	Wall No. 2 Open Sky area	Damaged Portion	149
120	Wall No. 2 Open Sky area	Damaged Portion	150
121	Wall No. 4 Open Sky area	Peeling of Plaster	151
122	Wall No. 3 Open Sky area	Damaged Portion	152
123	Wall No. 3 Open Sky area	Damaged Portion	153
124	Roof Open Sky area	Damaged Portion	154
125	Roof Open Sky area	Damaged Portion	155
126	Roof Open Sky area	Damaged Portion	156
127	Roof Open Sky area	Damaged Portion	157
128	Roof Open Sky area	Damaged Portion	158
129	Wall No. 1 Open Sky area	Peeling of Plaster	159
130	Wall No. 4 Bathroom No.	Damaged Portion	160
131	Wall No. 2, 4 & Roof Toilet No. 1	Dampness/Seepage	161
132	Wall No. 1 Toilet No. 1	Peeling of Plaster	162
133	Wall No. 4 & Roof Toilet No. 2+3+4	Dampness/Seepage	163
134	Wall No. 4 Passage	Dampness/Seepage	164
135	Roof Part A of Store	Peeling of Plaster	165
136	Roof Part B of Store	Peeling of Plaster	166
137	Wall No. 1 & 3 Hall No. 1	Dampness/Seepage	167
138	Roof Hall No. 1	Dampness/Seepage	168
139	Wall No. 2 Hall No. 1	Dampness/Seepage	169
140	Wall No. 4 & 1 Room No. 9	Dampness/Seepage	170
141	Roof Store No.2	Peeling of Plaster	171

142	Roof Store No.2	Peeling of Plaster	172
143	Roof Store No.2	Peeling of Plaster	173
144	Roof Store No.2	Dampness/Seepage	174
145	Wall No. 2 Store No.2	Dampness/Seepage	175
146	Wall No. 1 & 2 Part B Staircase Ground Floor To First Floor Ground Floor	Peeling of Plaster	176
147	Roof Part B Staircase Ground Floor To First Floor Ground Floor	Peeling of Plaster	177
148	Wall No. 4 Part B Staircase Ground Floor To First Floor Ground Floor	Dampness/Seepage	178
149	Roof Part B Staircase Ground Floor To First Floor Ground Floor	Peeling of Plaster	179
150	Roof Part B Staircase Ground Floor To First Floor Ground Floor	Damaged Portion	180
151	Wall No. 3 Open sky area (Part B) First Floor	Peeling of Plaster	181
152	Wall No. 1 Open sky area (Part B) First Floor	Dampness/Seepage	182
153	Wall No. 4 Open sky area (Part B) First Floor	Peeling of Plaster	183
154	Wall No. 4 Open sky area (Part B) First Floor	Peeling of Plaster	184
155	Roof Open sky area (Part B) First Floor	Damaged Portion	185
156	Roof Open sky area (Part B) First Floor	Damaged Portion	186
157	Roof Open sky area (Part B) First Floor	Damaged Portion	187
158	Roof Room No. 110 First Floor	Damaged Portion	188
159	Wall No. 1 Room No. 110 First Floor	Peeling of Plaster	189
160	Roof Passage No.1 First Floor	Dampness/Seepage	190
161	All Walls & Roof Bathroom First Floor	Dampness/Seepage	191
162	All Walls & Roof Bathroom First Floor	Dampness/Seepage	192
163	All Walls & Roof Toilet No. 1 First Floor	Dampness/Seepage	193
164	All Walls & Roof Toilet No. 2 First Floor	Dampness/Seepage	194
165	All Walls & Roof Toilet No. 3 First Floor	Dampness/Seepage	195
166	All Walls & Roof Toilet No. 4 First Floor	Dampness/Seepage	196
167	Roof Room No. 109(Part A) First Floor	Dampness/Seepage	197
168	Roof Room No. 109(Part B) First Floor	Dampness/Seepage	198
169	Roof Room No. 107(Part A) First Floor	Peeling of Plaster	199
170	Roof Room Mess Room First Floor	Dampness/Seepage	200
171	Roof Room Mess Room First Floor	Dampness/Seepage	200
172	Wall No. 2, 3 & Roof Mess Room First Floor	Dampness/Seepage	202
172	Wall No. 1 Store No.1 First Floor	Peeling of Plaster	202
-	Roof & Column Room Mess Room First Floor	-	-
174		Damaged Portion	204
175	Kitchen First Floor	Peeling of Plaster	205
176	Wall No. 2 & 4 Room First Floor	Peeling of Plaster	206
177	Wall No. 2 Room First Floor	Damaged Portion	207
178	Roof Store First Floor	Damaged Portion	208
179	Roof Store First Floor	Damaged Portion	209
180	Wall No. 4 Kitchen First Floor	Plaster Crack	210
181	Wall No. 4 Kitchen First Floor	Peeling of Plaster	211
182	Wall No. 3 Part B of Police Kotwali First Floor	Peeling of Plaster	212
183	Roof Room No. 111 First Floor	Dampness/Seepage	213
184	Backside Outer Wall Part B of Police Kotwali First Floor	Damaged Portion	214
185	Backside Outer Wall Shade Part B of Police Kotwali Second Floor	Damaged Portion	215
186	Backside Outer Wall Part B of Police Kotwali Second Floor	Damaged Portion	216
187	Right-side Outer Wall Part B of Police Kotwali First Floor	Damaged Portion	217
188	Roof Staircase First Floor To Second Floor First Floor	Dampness/Seepage	218
189	Steps Staircase Ground Floor To First Floor First Floor	Damaged Portion	219

190	Wall No. 1, 2, 4 & Roof Hall No. 1(Part A) First Floor	Dampness/Seepage	220
191	Wall No. 1, 2, 4 & Roof Hall No. 1(Part A) First Floor	Dampness/Seepage	221
192	Roof Hall No. 1(Part B) First Floor	Dampness/Seepage	222
193	Roof Hall No. 1(Part B) First Floor	Dampness/Seepage	223
194	Roof Hall No. 1(Part B) First Floor	Dampness/Seepage	224
195	Wall No. 1 & Roof Hall No. 1(Part C) First Floor	Dampness/Seepage	225
196	Roof Hall No. 1(Part B) First Floor	Peeling of Plaster	226
197	Roof Room Dark Room First Floor	Dampness/Seepage	227
198	Roof Room Dark Room First Floor	Dampness/Seepage	228
199	Wall No. 2 S.D.Anubhag Room First Floor	Plaster Crack	229
200	Wall No. 4 S.D.Anubhag Room First Floor	Plaster Crack	230
201	Wall No. 3 Open Sky No.3 Shaft First Floor	Plaster Crack	231
202	Wall No. 4 Open Sky No.3 First Floor	Peeling of Plaster	232
203	Staircase Near Open Sky No.3 First Floor	Damaged Portion	233
200	Wall No. 2 & Shade Open Sky No.2 First Floor	Dampness/Seepage	234
204	Wall No. 2 & 3 Open Sky No.2 First Floor	Dampness/Seepage	235
205	Roof & Gate Part A of Police Kotwali First Floor	Peeling of Plaster	236
200	Wall No. 4 Passage First Floor	Peeling of Plaster	230
	Wall No. 3 Passage First Floor	Peeling of Plaster	237
208		•	-
209	Shade Room No. Tinshed Room Second Floor	Dampness/Seepage	239
210	Wall No. 2, 4 & Roof Room No. 2 Second Floor	Dampness/Seepage	240
211	Wall No. 3 Open Sky Second Floor	Peeling of Plaster	241
212	Roof Toilet No. 1 Second Floor	Peeling of Plaster	242
213	Wall No. 1, 3 & Shade Open Sky Second Floor	Damaged Portion	243
214	Wall No. 1 & 3 Open Sky Second Floor	Peeling of Plaster	244
215	Wall No. 1 & Shade Open Sky No.2 Second Floor	Damaged Portion	245
216	Wall No. 1 & Roof Room Second Floor	Dampness/Seepage	246
217	Wall No. 2, 3 & Roof Room Second Floor	Dampness/Seepage	247
218	Wall	Damaged Portion	248
219	Roof Passage of Part B Second Floor	Peeling of Plaster	249
220	Roof Passage of Part B Second Floor	Peeling of Plaster	250
221	Wall No. 3 Passage of Part B Second Floor	Peeling of Plaster	251
222	Roof Room No. 4 Second Floor	Dampness/Seepage	252
223	Wall No. 3 Room No. 4 Second Floor	Plaster Crack	253
224	Room No. 5 Second Floor	Peeling of Plaster	254
225	Wall No. 3 & Shade Open Sky No.3 Second Floor	Damaged Portion	255
226	Wall No. 3 Open Sky No.3 Second Floor	Peeling of Plaster	256
227	Wall No. 2 Open Sky No.3 Second Floor	Peeling of Plaster	257
228	Roof Room No. 6 Second Floor	Dampness/Seepage	258
229	Wall No. 3 Room No. 6 Second Floor	Peeling of Plaster	259
230	Roof Room No. 6 Second Floor	Peeling of Plaster	260
231	Wall No. 2 Room No. 6 Second Floor	Peeling of Plaster	261
232	Roof Room No. 7 Second Floor	Peeling of Plaster	262
233	Wall No. 1 Room No. 7 Second Floor	Peeling of Plaster	263
234	Roof Kitchen Second Floor	Peeling of Plaster	264
235	Wall No. 2 Bathroom Second Floor	Peeling of Plaster	265
236	Wall No. 4 Bathroom Second Floor	Dampness/Seepage	266
237	Roof Bathroom Second Floor	Dampness/Seepage	267
238	Roof Bathroom Second Floor	Peeling of Plaster	268
239	Wall No. 3, 4, Roof & 2 Toilet No. 1 Second Floor	Dampness/Seepage	269
240	Roof & 4 Bathroom Second Floor	Dampness/Seepage	270
241	Wall No. 1 Room No. 10 Second Floor	Peeling of Plaster	270
	Floor Part B of Police Kotwali Second Floor	Damaged Portion	272

243	Roof Room No. 11 Second Floor	Peeling of Plaster	273
244	Roof Room No. 12 Second Floor	Peeling of Plaster	274
245	Roof Room No. 12 Second Floor	Plaster Crack	275
246	Roof Room No. 13 Second Floor	Dampness/Seepage	276
247	Roof Bathroom Second Floor	Dampness/Seepage	277
248	Wall No. 1 Room No. 12 Second Floor	Peeling of Plaster	278
249	Roof Toilet No. 2 Second Floor	Peeling of Plaster	279
250	Wall No. 2 Toilet No. 2 Second Floor	Dampness/Seepage	280
251	Wall No. 1 Bathroom Second Floor	Dampness/Seepage	281
252	Roof Room No. 15 Second Floor	Peeling of Plaster	282
253	Wall No. 3 Room No. 15 Second Floor	Peeling of Plaster	283
254	Roof Room No. 14 Second Floor	Peeling of Plaster	284
255	Wall No. 3 Room No. 14 Second Floor	Peeling of Plaster	285
256	Wall No. 2, 4 & Roof Kitchen Second Floor	Dampness/Seepage	286
257	Roof Balcony Second Floor	Dampness/Seepage	287
258	Roof Balcony Gate Second Floor	Damaged Portion	288
259	Wall No. 2 & Roof Hall No. 3 Second Floor	Dampness/Seepage	289
260	All Walls & Roof Part B of Police Kotwali Second Floor	Dampness/Seepage	290
261	Roof Toilet No. 1 Second Floor	Dampness/Seepage	291
262	Backside Wall Part B of Police Kotwali Second Floor	Dampness/Seepage	292
263	Backside Wall Part B of Police Kotwali Second Floor	Dampness/Seepage	293
264	Backside Wall Part B of Police Kotwali Second Floor	Dampness/Seepage	294
265	Backside Wall Part B of Police Kotwali Second Floor	Plaster Crack	295
266	Backside Wall Part B of Police Kotwali Second Floor	Plaster Crack	296
267	Backside Wall Part B of Police Kotwali Second Floor	Damaged Portion	297
268	Backside Wall Part B of Police Kotwali Second Floor	Damaged Portion	298
269	Backside Wall Part B of Police Kotwali Second Floor	Damaged Portion	299
270	Backside Fount Part B of Police Kotwali Second Floor	Damaged Portion	300
271	Backside Fount Part B of Police Kotwali Second Floor	Damaged Portion	301
272	Backside Fount Part B of Police Kotwali Second Floor	Damaged Portion	302
273	Shade Part B of Police Kotwali Second Floor	Damaged Portion	303
274	Shade Part B of Police Kotwali Second Floor	Damaged Portion	304
275	Right-side Outer Wall Part B of Police Kotwali Second Floor	Damaged Portion	305

Serial No.	Location	Description	Photo No.
1	Wall No. 4 Shop No.170 Ground Floor	Covered With Wooden Almira	306
2	Wall No. 1 Shop No.170 Ground Floor	Covered With Wooden Almira	307
3	Wall No. 2 Shop No.170 Ground Floor	Covered With Wooden Almira	308
4	Roof Shop No.170 Ground Floor	Covered With Falls Celling	309
5	Wall No. 1 Shop No.169B Ground Floor	Covered With wooden work	310
6	Wall No. 4 Shop No.169B Ground Floor	Covered With wooden work	311
7	Wall No. 2 Shop No.169B Ground Floor	Covered With Glass Work	312
8	Roof Shop No.169B Ground Floor	Covered With wooden work	313
9	All Walls Shop No.169A Ground Floor	Covered With wooden work	314
10	Roof Shop No.169A Ground Floor	Covered With wooden work	315
11	All Walls Shop No.168 Ground Floor	Covered With Wooden Works	316
12	Roof Shop No.168 Ground Floor	Covered With Wooden Works	317
13	All Walls Shop No.167 Ground Floor	Covered With Wooden Works	318
14	Roof Shop No.167 Ground Floor	Covered With Wooden Works	319

15	All Walls Shop no.165 & 166 Ground Floor	Covered With Wooden Works & Glass Work	320
16	Roof Shop no.165 & 166 Ground Floor	Covered With Wooden Works	321
17	All Walls Shop no.165 & 166 Upper Ground Floor	Covered With Wooden Works	322
18	Roof Shop no.165 & 166 Upper Ground Floor	Covered With Wooden Works	323
19	Wall No. 4 Shop No.163 &164 Ground Floor	Covered With Wooden Racks & Material	324
20	Wall No. 4 Shop No.163 &164 Ground Floor	Covered With Wooden Racks & Material	325
21	Wall No. 4 Shop No.162 Ground Floor	Half Wall Covered With Almira	326
22	All Walls Shop No.161 Ground Floor	Covered With Wooden Almira	327
23	Shop No.160 Ground Floor	Locked	328
24	Room No. 3 Ground Floor	Locked	329
25	Wall No. 2 Room No. 7B Ground Floor	Covered With Almira	330
26	Roof Room No. 1	Covered With Falls Celling	331
27	All Walls & Roof Room No. 1(part B)	Covered With Tiles & Wooden work	332
28	All Walls & Roof Room No. 1	Covered With Tiles & Wooden work	333
29	Roof Room No. 14(Part A)	Covered With Falls Celling	334
30	Office	Locked	335
31	Room 3A +3B	Locked	336
32	Wall No. 1 & 4 Part B of Store	Covered With Material	337
33	Wall No. 1 & 2 Part A of Store	Covered With Material	338
34	Wall No. 1 & 2 Part A of Store	Covered With Material	339
35	Room No. 4	Locked	340
36	Room No. 5	Locked	341
37	Room No. 6	Locked	342
38	Room No. 7	Locked	343
39	Room No. 8	Locked	344
40	Room No. 10	Locked	345
41	All Walls & Floor Bathroom First Floor	Covered With Tiles	346
42	All Walls & Floor Bathroom First Floor	Covered With Tiles	347
43	All Walls & Floor Toilet No. 1+2+3+4 First Floor	Covered With Tiles	348
44	All Walls & Floor Toilet No. 1+2+3+4 First Floor	Covered With Tiles	349
45	All Walls & Floor Toilet No. 1+2+3+4 First Floor	Covered With Tiles	350
46	All Walls & Floor Toilet No. 1+2+3+4 First Floor	Covered With Tiles	351
47	All Walls Room No. 109 First Floor	Covered With plastic	352
48	Room No. 108 First Floor	Locked	353
49	Staircase First Floor To Second Floor First Floor	Locked	354
50	Wall No. 1 & 2 Conference Hall First Floor	Covered With Wooden Almira	355
51	Wall No. 1 & 2 Conference Hall First Floor	Covered With Wooden Almira	356
52	All Walls & Floor Toilet & Washroom First Floor	Covered With tiles	357
53	All Walls & Roof Toilet No. 1 Second Floor	Covered With Tiles	358
54	Room No. 9 Second Floor	Locked	359
55	Wall No. 2 Hall No. 2 (PART B) Second Floor	Covered With Wooden Partition	360
56	Wall No. 1 Hall No. 1 Second Floor	Covered With Wooden Partition	361
57	Wall No. 1 Hall No. 2 Second Floor	Covered With Wooden Partition	362
58	Wall No. 2 Hall No. 2 Second Floor	Covered With Wooden Partition	363
59	Toilet No. 1 Second Floor	Covered With Tile	364









Photo 1 View of Police Kotwali



Photo 2 View of Shop no.170, Ground Floor



Photo 3 Side View of Shop no.170, Ground Floor



Photo 5 View of Shop No.169A, Ground Floor





Photo 4 View of shop No.169B, Ground Floor



Photo 6 View of Shop No.168, Ground Floor







Photo 7 View of Shop No.167, Ground Floor



Photo 8 View of Shop No.165 &166, Ground Floor



Photo 9 View of Shop No.162,163 & 164, Ground Floor



Photo 11 View of Shop No.162,163 & 164, Ground Floor





Photo 10 View of Shop No.162,163 & 164, Ground Floor



Photo 12 View of Shop No.161, Ground Floor





Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



Photo 13 View of Police Station, Ground Floor



Photo 14 View of Bathroom Part A, Ground Floor



Photo 15 Under Construction,



Photo 16 View of Room No.107 Part B, First Floor



Photo 17 Backside View of Police Kotwali, First Floor





<u>Photo 1</u>8 First Floor







Photo 19 Under Renovation, First Floor



Photo 20 Under Renovation, First Floor



Photo 21 View of Tin Shed Kitchen, Second Floor



Photo 23 View of Room No.1, Second Floor





Photo 22 View of Tin shed Room, Second Floor



Photo 24 View of Kitchen Part B, Second Floor







Photo 25 View of Tin shed Kitchen, Second Floor



Photo 26 View of Tin shed, Second Floor



Photo 27 View of Kitchen, Second Floor



Photo 28 View of Tin shed open area, Second Floor



Photo 29 View of Bathroom Second Floor





Photo 30 View of Police Kotwali Left side, Ground Floor



Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



JAIPUR METRO

Photo 31

Horizontal Crack on Roof of Varanda of Shop No.169B, Ground Floor,Approx. Width = 0.2mm, Approx. Length = 1.1m.Distance from Right side internal Column = 0m, Height from Floor = 3.1m.



Photo 33

Horizontal Crack on Roof of Varanda of Shop No.167, Ground Floor,Approx. Width = 0.8mm, Approx. Length = 1.1m.Distance from External Column Right Side = 0m, Height from Floor = 3.1m.



Photo 34A Horizontal Crack on Wall No. 4 of Room No. 7A, Ground Floor,Approx. Width = 0.35mm, Approx. Length = 1.1m.Distance from Wall No.1 = 0.1m, Height from Floor = 2.1m.





Photo 32

Horizontal Crack on Roof of Varanda of Shop No.169A, Ground Floor,Approx. Width = 0.15mm, Approx. Length = 1.1m.Distance from Left Side internal Column = 1m, Height from Floor = 3.1m.



Photo 34 Horizontal Crack on Wall No. 4 of Room No. 7A, Ground Floor,Approx. Width = 0.35mm, Approx. Length = 1.1m.Distance from Wall No.1 = 0.1m, Height from Floor = 2.1m.



Photo 35 Inclined Crack on Wall No. 2 of Toilet No. 1(Part B), Ground Floor,Approx. Width = 0.25mm, Approx. Length = 3m.Distance from Wall No.4 = 1.8m, Height from Floor = 1.5m.






Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



Photo 35A Inclined Crack on Wall No. 2 of Toilet No. 1(Part B), Ground Floor,Approx. Width = 0.25mm, Approx. Length = 3m.Distance from Wall No.4 = 1.8m, Height from Floor = 1.5m.



#### Photo 36A

Inclined Crack on Wall No. 3 of Room No. 9, Approx. Width = 0.2mm, Approx. Length = 1.3m.Distance from Wall no.1 = 1.7m, Height from Floor = 1.8m.



 $\frac{Photo \ 36}{Photo \ 36}$ Inclined Crack on Wall No. 3 of Room No. 9, Approx. Width = 0.2mm, Approx. Length = 1.3m.Distance from Wall no.1 = 1.7m, Height from Floor = 1.8m.



#### Photo 37

Inclined Crack on Roof of Room No. 9, Approx. Width = 0.3mm, Approx. Length = 2.8m.Distance from Wall no.1 = 1m, Height from Floor = 2.5m.



Photo 38 Inclined Crack on Roof of Part A of Store, Approx. Width = 2mm, Approx. Length = 3m.Distance from Wall No.2 = 0.6m, Height from Floor = 2.7m.





Photo 39 Inclined Crack on Wall No. 2 of Room No. 110, First Floor,Approx. Width = 0.3mm, Approx. Length = 1.25m.Distance from Wall No.3 = 0.9m, Height from Floor = 2m.



Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



JAIPUR METRO

Photo 40, Horizontal Crack on Wall No. 3 of Room No. 110, First Floor, Approx. Width = 1mm, Approx. Length = 1m.Distance from Wall No.2 = 0.4m, Height from Floor = 1.9m.



#### Photo 41A

Inclined Crack on Wall No. 1 of Room No. 110, First Floor, Approx. Width = 2mm, Approx. Length = 4m.Distance from Wall No.4 = 4.5m, Height from Floor = 0m.



#### Photo 42A



Photo 41 Inclined Crack on Wall No. 1 of Room No. 110, First Floor, Approx. Width = 2mm, Approx. Length = 4m. Distance from Wall No.4 = 4.5m, Height from Floor = 0m.



Photo 42 Inclined Crack on Wall No. 4 of Passage No.1, First Floor, Approx. Width = 2.5mm, Approx. Length = 1.4m.Distance from Wall No.2 = 0.1m, Height from Floor = 0m.



Photo 43 Inclined Crack on Wall No. 4 of Passage No.1, First Floor, Approx. Width Inclined Crack on Wall No. 2 of Passage No.1, First Floor, Approx. Width = 2.5mm, Approx. Length = 1.4m.Distance from Wall No.2 = 0.1m, = 0.6mm, Approx. Length = 1m.Distance from Wall No.4 = 0m, Height Height from Floor = 0m. from Floor = 1.3m.





Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



JAIPUR METRO

Photo 44

Inclined Crack on Roof of Room No. Room, First Floor, Approx. Width = Inclined Crack on Roof of Room No. Room, First Floor, Approx. Width = 1.5mm, Approx. Length = 2m.Distance from Wall No.1 = 0m, Height from Floor = 3.2m.



Photo 45

0.8mm, Approx. Length = 2m.Distance from Wall No.1 = 0m, Height from Floor = 3.2m.





Photo 46 Vertical Crack on of Open Sky Passage, First Floor, Approx. Width =

from Floor = 0m.

Vertical Crack on of Open Sky Passage, First Floor, Approx. Width = 0.6mm, Approx. Length = 1.8m.Distance from Wall No.4 = 1.5m, Height 0.6mm, Approx. Length = 1.8m.Distance from Wall No.4 = 1.5m, Height from Floor = 0m.



Photo 47

Vertical Crack on of Open Sky Passage, First Floor, Approx. Width = 0.5mm, Approx. Length = 1m.Distance from Wall No.4 = 1.2m, Height from Floor = 1.7m.



Photo 47A Vertical Crack on of Open Sky Passage, First Floor, Approx. Width = 0.5mm, Approx. Length = 1m.Distance from Wall No.4 = 1.2m, Height from Floor = 1.7m.









Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



JAIPUR METRO

Photo 48

Vertical Crack on Wall No. 2 & 4 of Room No. S.D.Anubhag Room, First Vertical Crack on Roof of Open Sky No.2, First Floor, Approx. Width = No.2 = 0m, Height from Floor = 3m.

Photo 49 Floor, Approx. Width = 3mm, Approx. Length = 1m. Distance from Wall 0.6mm, Approx. Length = 1.5m. Distance from = Joint Wall No.2 & 3m, Height from Floor = 3.2m.



Photo 50



Vertical Crack on Wall No. 3 of Open Sky No.2, First Floor, Approx. Width = 0.15mm, Approx. Length = 1.6m.Distance from Wall No.2 = 2.2m, Height from Floor = 1.7m.



Photo 51 Inclined Crack on Wall No. 1 of Toilet No. 1, Second Floor, Approx. Width = 1.5mm, Approx. Length = 1.5m.Distance from Wall No.3 = 0.2m, Height from Floor = 1.4m.



Photo 50A Vertical Crack on Wall No. 3 of Open Sky No.2, First Floor, Approx. Width = 0.15mm, Approx. Length = 1.6m.Distance from Wall No.2 = 2.2m, Height from Floor = 1.7m.



Photo 51A Inclined Crack on Wall No. 1 of Toilet No. 1, Second Floor, Approx. Width = 1.5mm, Approx. Length = 1.5m.Distance from Wall No.3 = 0.2m, Height from Floor = 1.4m.





Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line





Photo 53

= 3m.

Photo 52 Horizontal Crack on Wall No. 2 & 4 of Toilet No. 1, Second Inclined Crack on of Open Sky No.2, Third Floor, Approx. Width = 5mm, Floor, Approx. Width = 4mm, Approx. Length = 2m.Distance from = Wall Approx. Length = 2m.Distance from Wall No.2 = 0m, Height from Floor No.2 & 4m, Height from Floor = 0m.



Photo 54



Horizontal Crack on Wall No. 1 of Room No. 4, Second Floor, Approx. Width = 5mm, Approx. Length = 0.4m. Distance from Wall No.3 = 2.5m, Height from Floor = 2.5m.



Photo 56 Inclined Crack on Wall No. 3 of Open Sky No.3, Second Floor, Approx. Width = 1mm, Approx. Length = 3m. Distance from Wall No.1 = 2m, Height from Floor = 0m.



Photo 55 Horizontal Crack on of Room No. 5, Second Floor, Approx. Width = 3mm, Approx. Length = 0.5m.Distance from Wall No.3 = 1m, Height from Floor = 2.5m.



Photo 56A Inclined Crack on Wall No. 3 of Open Sky No.3, Second Floor, Approx. Width = 1mm, Approx. Length = 3m. Distance from Wall No.1 = 2m, Height from Floor = 0m.



Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



JAIPUR METRO

Photo 57 Inclined Crack on Wall No. 3 of Open Sky No.3, Second Floor,Approx. Width = 1.5mm, Approx. Length = 1m. Distance from Wall No.2 = 1.6m, Height from Floor = 2m.



Photo 59 Inclined Crack on Wall No. 1 of Room No. 12, Second Floor,Approx. Width = 0.6mm, Approx. Length = 1m. Distance from Wall No.4 = 1.6m, Height from Floor = 2.2m.



 $\label{eq:photo61} \frac{Photo \ 61}{Photo \ 61}$  Inclined Crack on Wall No. 1 of Room No. 12, Second Floor,Approx. Width = 0.8mm, Approx. Length = 1.5m. Distance from Wall No.3 = 0.5m, Height from Floor = 2.2m.





Photo 58 Inclined Crack on Wall No. 3 & Roof of Bathroom , Second Floor,Approx. Width = 0.5mm, Approx. Length = 4m.



Photo 60 Inclined Crack on Wall No. 2 & 4 of Room No. 13, Second Floor,Approx. Width = 0.4mm, Approx. Length = 1.9m. Distance from Wall No.3 = 1.5m, Height from Floor = 2.1m.



Photo 62 Horizontal Crack on Wall No. 4 of Tin shed Kitchen, Second Floor,Approx. Width = 2mm, Approx. Length = 0.4m. Distance from Wall No.1 = 0m, Height from Floor = 2m.



Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



JAIPUR METRO



Photo 64

Width = 3mm, Approx. Length = 0.6m.

Photo 63 Inclined Crack on Wall No. 1 of Tin shed Kitchen, Second Floor, Approx. Inclined Crack on Wall No. 1 of Tin shed Kitchen, Second Floor, Approx. Width = 2mm, Approx. Length = 0.5m. Distance from Wall No.4 = 1.6m, Height from Floor = 1.9m.



2.2013



Photo 65 Inclined Crack on Wall No. 3 of Tin shed Kitchen, Second Floor, Approx. Width = 1.5mm, Approx. Length = 0.5m. Distance from Wall No.1 = 1.5m, Height from Floor = 2m.



Photo 66A Inclined Crack on Wall No. 4 of Room No. 14, Second Floor, Approx. Width = 5mm, Approx. Length = 2.2m. Distance from Wall No.2 = 1.5m, Height from Floor = 1m.



Photo 66 Inclined Crack on Wall No. 4 of Room No. 14, Second Floor, Approx. Width = 5mm, Approx. Length = 2.2m. Distance from Wall No.2 = 1.5m, Height from Floor = 1m.




Photo 67 Inclined Crack on Wall No. 2 & 3 of Room No. 14, Second Floor, Approx. Width = 1.5mm, Approx. Length = 2m. Distance from = Corner Wall No.2 & 3m, Height from Floor = 0m.







Photo 67A Inclined Crack on Wall No. 2 & 3 of Room No. 14, Second Floor,Approx. Width = 1.5mm, Approx. Length = 2m. Distance from = Corner Wall No.2 & 3m, Height from Floor = 0m.



Photo 69

Inclined Crack on Front side Wall of Part B of Police Kotwali, Ground Floor,Approx. Width = 2mm, Approx. Length = 2m.Distance Right side Stares = 0m, Height Floor = 1.7m.



Photo 68 Inclined Crack on Front side Wall of Part B of Police Kotwali, Ground Floor,Approx. Width = 2.5mm, Approx. Length = 2m. Distance from Right side Stares = 0m, Height from Floor = 0m.



Photo 70 Inclined Crack on Front side Wall of Part B of Police Kotwali, Ground Floor,Approx. Width = 0.5mm, Approx. Length = 2m.



Photo 71 Dampness/Seepage on Roof of Varanda of Shop No.169B of Ground Floor



Photo 72 Dampness/Seepage on External Beam of Varanda of Shop No.169B of Ground Floor









Photo 73 Dampness/Seepage on Roof of Varanda of Shop No.169A of Ground Floor

Photo 74 Dampness/Seepage on External Beam of Varanda of Shop No.169A of Ground Floor





Photo 75 Damaged Portion on Wall No. 4 of Shop No.169A of Basement







Photo 77 Peeling of Plaster on Roof of Varanda of Shop No.167 of Ground Floor














Photo 79 Peeling of Plaster on Floor of Shop no.165 & 166 of Upper Ground Floor

Photo 80 Dampness/Seepage on Wall No. 4 of Shop No.162 of Ground Floor





Photo 81 Dampness/Seepage on Roof of Shop No.161 of Ground Floor



Photo 83 Peeling of Plaster on Roof of Room No. 2 of Ground Floor





Photo 84 Peeling of Plaster on Roof of Varanda No.1 of Ground Floor









Photo 85 Dampness/Seepage on Wall No. 1 of Varanda No.1 of Ground Floor



Photo 86 Dampness/Seepage on Wall No. 2 & 3 of Varanda No.1 of Ground Floor






Photo 87 Dampness/Seepage on Wall No. 1, 2 & 4 of Passage No.1 of Ground Floor



Dampness/Seepage on Roof of Passage No.1 of Ground Floor



<u>Photo 8</u>9 Dampness/Seepage on Wall No. 2 & 4 of Gate No.3 of Ground Floor



Photo 90 Dampness/Seepage on Wall No. 2 & 4 of Gate No.4 of Ground Floor










Photo 91 Dampness/Seepage on Wall No. 1, 4 & Roof of Room No. 5 of Ground Floor

Photo 92 Dampness/Seepage on Wall No. 2 & Roof of Room No. 5 of Ground Floor





Photo 93 Peeling of Plaster on Outer Main Gate of Room No. 6 of Ground Floor

Photo 94 Dampness/Seepage on Wall No. 1, 3 & Roof of Room No. 6 of Ground Floor



Photo 95 Dampness/Seepage on Roof of Room No. 7B of Ground Floor



Photo 96 Peeling of Plaster on Wall No. 2 & 4 of Store of Ground Floor











Photo 97 Dampness/Seepage on Wall No. 4 of Room No. 7A of Ground Floor

Photo 98 Peeling of Plaster on Wall No. 2 of Room No. 7A of Ground Floor





Photo 99 Peeling of Plaster on Wall No. 4 of Room No. 7A of Ground Floor

Photo 100 Peeling of Plaster on Roof of Room No. 9 of Ground Floor



Photo 101 Peeling of Plaster on Roof of Room No. 9 of Ground Floor



Photo 102 Peeling of Plaster on Wall No. 3 of Room No. 9 of Ground Floor





## **Jaipur Metro Rail Corporation**



Photo 103 Peeling of Plaster on of Room No. 8 of Ground Floor



Photo 104 Dampness/Seepage on Wall No. 2 of Room No. 8 of Ground Floor





Photo 105 Dampness/Seepage on Wall No. 4 of Room No. 8 of Ground Floor

Photo 106 Dampness/Seepage on Roof of Passage No.3 of Ground Floor



Photo 107 Peeling of Plaster on Roof of Passage No.3 of Ground Floor



Photo 108 Peeling of Plaster on Wall No. 1 of Passage No.3 of Ground Floor









Photo 109 Peeling of Plaster on of Room No. 11 of Ground Floor



Photo 110 Dampness/Seepage on Roof of Toilet No. 1(Part B) of Ground Floor





Photo 111 Peeling of Plaster on Wall No. 3 of Toilet No. 1(Part B) of Ground Floor

Photo 112 Dampness/Seepage on Roof of Room No. 10 of Ground Floor



Photo 113 Peeling of Plaster on Wall No. 4 of Room No. 10 of Ground Floor












Photo 115 Dampness/Seepage on Wall No. 1 of Room No. 10 of Ground Floor



Photo 116 Peeling of Plaster on Wall No. 4 of Room No. 11 of Ground Floor





Photo 117 Peeling of Plaster on Wall No. 4 of Room No. 11 of Ground Floor

Photo 118 Dampness/Seepage on Roof & 4 of Room No. 10 of Ground Floor



Photo 119 Peeling of Plaster on Wall No. 4 of Room No. 7 of Ground Floor



Photo 120 Peeling of Plaster on Roof of Room No. 9(lobby) of









Photo 121 Peeling of Plaster on Wall No. 2 of Room No. 9(lobby) of



Photo 122 Dampness/Seepage on Wall No. 4 & Roof of Room No. 9 of





Photo 123 Dampness/Seepage on Wall No. 4 & Roof of Room No. 9 of

Photo 124 Peeling of Plaster on Wall No. 4 of Room No. 9 of



Photo 125 Dampness/Seepage on Wall No. 1, 4 & Roof of Room No. 3(Lobby) of



Photo 126 Peeling of Plaster on Roof of Pantry of







Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



Photo 127 Peeling of Plaster on Wall No. 2, 4 & Roof of Room No. 1(office) of



Photo 128 Dampness/Seepage on Wall No. 2 of Room No. 1





Photo 129 Dampness/Seepage on All Walls of Room No. 16(Part E)





Photo 131 Peeling of Plaster on Wall No. 2 & 3 of Room No. 16(Part A)





Photo 132







Photo 133 Peeling of Plaster on Wall No. 1 of Room No. 15(PartA)



Photo 134 Peeling of Plaster on All Walls & Roof of Room No. 16(Part B)



Photo 135 Peeling of Plaster on Wall No. 2 & Roof of Room No. 16(Part B)



Photo 136 Dampness/Seepage on Roof of Room No. 14(Part B)



Photo 137 Peeling of Plaster on Wall No. 4 & Roof of Room No. 13





Photo 138 Peeling of Plaster on Roof of Room No. 13







Photo 139 Peeling of Plaster on Roof of Room No. 13



Photo 140 Peeling of Plaster on Wall No. 1 of Passage



Photo 141 Peeling of Plaster on Wall No. 1 of Passage



Photo 143 Peeling of Plaster on Wall No. 4 of Passage





Photo 142 Peeling of Plaster on Roof of Passage



Photo 144 Damaged Portion on Roof of Passage







Photo 145 Damaged Portion on Roof of Passage



Photo 146 Damaged Portion on Roof of Passage



Photo 147 Damaged Portion on Roof of Passage



Photo 148 Damaged Portion on Roof of Passage



Photo 149 Damaged Portion on Wall No. 2 of Open Sky area





Photo 150 Damaged Portion on Wall No. 2 of Open Sky area







Photo 151 Peeling of Plaster on Wall No. 4 of Open Sky area



Photo 152 Damaged Portion on Wall No. 3 of Open Sky area



Photo 153 Damaged Portion on Wall No. 3 of Open Sky area



Photo 155 Damaged Portion on Roof of Open Sky area





Photo 154 Damaged Portion on Roof of Open Sky area



Photo 156 Damaged Portion on Roof of Open Sky area







Photo 157 Damaged Portion on Roof of Open Sky area



Photo 158 Damaged Portion on Roof of Open Sky area



Photo 159 Peeling of Plaster on Wall No. 1 of Open Sky area



Photo 161 Dampness/Seepage on Wall No. 2, 4 & Roof of Toilet No. 1





Photo 160 Damaged Portion on Wall No. 4 of Bathroom



Photo 162 Peeling of Plaster on Wall No. 1 of Toilet No. 1







Photo 163 Dampness/Seepage on Wall No. 4 & Roof of Toilet No. 2+3+4



Photo 164 Dampness/Seepage on Wall No. 4 of Passage



Photo 165 Peeling of Plaster on Roof of Part A of Store



Photo 167 Dampness/Seepage on Wall No. 1 & 3 of Hall No. 1





Photo 166 Peeling of Plaster on Roof of Part B of Store



Photo 168 Dampness/Seepage on Roof of Hall No. 1







Photo 169 Dampness/Seepage on Wall No. 2 of Hall No. 1



Photo 170 Dampness/Seepage on Wall No. 4 & 1 of Room No. 9



Photo 171 Peeling of Plaster on Roof of Store No.2



Photo 172 Peeling of Plaster on Roof of Store No.2



Photo 173 Peeling of Plaster on Roof of Store No.2





Photo 174 Dampness/Seepage on Roof of Store No.2



#### **Jaipur Metro Rail Corporation**



Photo 175 Dampness/Seepage on Wall No. 2 of Store No.2



Photo 176 Peeling of Plaster on Wall No. 1 & 2 of Part B Staircase Ground Floor To First Floor of Ground Floor



Photo 177 Peeling of Plaster on Roof of Part B Staircase Ground Floor To First Floor of Ground Floor



Photo 178 Dampness/Seepage on Wall No. 4 of Part B Staircase Ground Floor To First Floor of Ground Floor



Photo 179 Peeling of Plaster on Roof of Part B Staircase Ground Floor To First Floor of Ground Floor



Photo 180 Damaged Portion on Roof of Part B Staircase Ground Floor To First Floor of Ground Floor







Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line





Photo 181 Peeling of Plaster on Wall No. 3 of Open sky area (Part B) of First Floor

Photo 182 Dampness/Seepage on Wall No. 1 of Open sky area (Part B) of First Floor





Photo 183 Peeling of Plaster on Wall No. 4 of Open sky area (Part B) of First Floor Peeling of Plaster on Wall No. 4 of Open sky area (Part B) of First Floor



Photo 185 Damaged Portion on Roof of Open sky area (Part B) of First Floor



Photo 186 Damaged Portion on Roof of Open sky area (Part B) of First Floor









Photo 187 Damaged Portion on Roof of Open sky area (Part B) of First Floor



Photo 188 Damaged Portion on Roof of Room No. 110 of First Floor





Photo 189 Peeling of Plaster on Wall No. 1 of Room No. 110 of First Floor

Photo 190 Dampness/Seepage on Roof of Passage No.1 of First Floor



Photo 191 Dampness/Seepage on All Walls & Roof of Bathroom of First Floor



Photo 192 Dampness/Seepage on All Walls & Roof of Bathroom of First Floor











Photo 193 Dampness/Seepage on All Walls & Roof of Toilet No. 1 of First Floor

Photo 194 Dampness/Seepage on All Walls & Roof of Toilet No. 2 of First Floor





Photo 195 Dampness/Seepage on All Walls & Roof of Toilet No. 3 of First Floor

Photo 196 Dampness/Seepage on All Walls & Roof of Toilet No. 4 of First Floor



Photo 197 Dampness/Seepage on Roof of Room No. 109(Part A) of First Floor



Photo 198 Dampness/Seepage on Roof of Room No. 109(Part B) of First Floor











Photo 199 Peeling of Plaster on Roof of Room No. 107(Part A) of First Floor

Photo 200 Dampness/Seepage on Roof of Room Mess Room of First Floor





Photo 201 Dampness/Seepage on Roof of Room Mess Room of First Floor





Photo 203 Peeling of Plaster on Wall No. 1 of Store No.1 of First Floor












Photo 205 Peeling of Plaster of Kitchen of First Floor



Photo 206 Peeling of Plaster on Wall No. 2 & 4 of Room of First Floor



Photo 207 Damaged Portion on Wall No. 2 of Room of First Floor



Photo 209 Damaged Portion on Roof of Store of First Floor



Photo 208 Damaged Portion on Roof of Store of First Floor



Photo 210 Plaster Crack on Wall No. 4 of Kitchen of First Floor









Photo 211 Peeling of Plaster on Wall No. 4 of Kitchen of First Floor



Photo 212 Peeling of Plaster on Wall No. 3 of Part B of Police Kotwali of First Floor





Photo 213 Dampness/Seepage on Roof of Room No. 111 of First Floor

Photo 214 Damaged Portion on Backside Outer Wall of Part B of Police Kotwali of First Floor



Photo 215 Damaged Portion on Backside Outer Wall Shade of Part B of Police Kotwali of Second Floor





Photo 216 Damaged Portion on Backside Outer Wall of Part B of Police Kotwali of Second Floor









Photo 217 Photo 218 Damaged Portion on Right-side Outer Wall of Part B of Police Kotwali of Dampness/Seepage on Roof of Staircase First Floor To Second Floor of First Floor First Floor





Photo 219 Damaged Portion on Steps of Staircase Ground Floor To First Floor of Dampness/Seepage on Wall No. 1, 2, 4 & Roof of Hall No. 1 (Part A) of First Floor





Photo 221 Dampness/Seepage on Wall No. 1, 2, 4 & Roof of Hall No. 1(Part A) of First Floor



Photo 222 Dampness/Seepage on Roof of Hall No. 1(Part B) of First Floor









Photo 223 Dampness/Seepage on Roof of Hall No. 1(Part B) of First Floor



Photo 224 Dampness/Seepage on Roof of Hall No. 1(Part B) of First Floor





Photo 225 Dampness/Seepage on Wall No. 1 & Roof of Hall No. 1(Part C) of First Floor






Photo 227 Dampness/Seepage on Roof of Room Dark Room of First Floor



Photo 228 Dampness/Seepage on Roof of Room Dark Room of First Floor









Photo 229 Plaster Crack on Wall No. 2 of S.D.Anubhag Room of First Floor



Photo 230 Plaster Crack on Wall No. 4 of S.D.Anubhag Room of First Floor





Photo 231 Plaster Crack on Wall No. 3 of Open Sky No.3 Shaft of First Floor

Photo 232 Peeling of Plaster on Wall No. 4 of Open Sky No.3 of First Floor



Photo 233 Damaged Portion of Staircase Near Open Sky No.3 of First Floor



Photo 234 Dampness/Seepage on Wall No. 2 & Shade of Open Sky No.2 of First Floor







Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line





Photo 235 Dampness/Seepage on Wall No. 2 & 3 of Open Sky No.2 of First Floor

Photo 236 Peeling of Plaster on Roof & Gate of Part A of Police Kotwali of First Floor





Photo 238

Photo 237 Peeling of Plaster on Wall No. 4 of Passage of First Floor





Photo 239 Dampness/Seepage on Shade of Room Tin shed Room of Second Floor











Photo 241 Peeling of Plaster on Wall No. 3 of Open Sky of Second Floor



Photo 242 Peeling of Plaster on Roof of Toilet No. 1 of Second Floor





Photo 243 Damaged Portion on Wall No. 1, 3 & Shade of Open Sky of Second Floor

Photo 244 Peeling of Plaster on Wall No. 1 & 3 of Open Sky of Second Floor



Photo 245 Damaged Portion on Wall No. 1 & Shade of Open Sky No.2 of Second Floor



Photo 246 Dampness/Seepage on Wall No. 1 & Roof of Room of Second Floor







Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



Photo 247 Dampness/Seepage on Wall No. 2, 3 & Roof of Room of Second Floor



Photo 248 **Damaged Portion** 





Photo 250

Photo 249 Peeling of Plaster on Roof of Passage of Part B of Second Floor

<u>Photo 2</u>51

Peeling of Plaster on Wall No. 3 of Passage of Part B of Second Floor





Photo 252 Dampness/Seepage on Roof of Room No. 4 of Second Floor









Photo 253 Plaster Crack on Wall No. 3 of Room No. 4 of Second Floor



Photo 254 Peeling of Plaster on of Room No. 5 of Second Floor





Photo 255 Damaged Portion on Wall No. 3 & Shade of Open Sky No.3 of Second Floor

Photo 256 Peeling of Plaster on Wall No. 3 of Open Sky No.3 of Second Floor



Photo 257 Peeling of Plaster on Wall No. 2 of Open Sky No.3 of Second Floor



Photo 258 Dampness/Seepage on Roof of Room No. 6 of Second Floor









10.12.2013

Photo 259 Peeling of Plaster on Wall No. 3 of Room No. 6 of Second Floor

Photo 260 Peeling of Plaster on Roof of Room No. 6 of Second Floor



Photo 261 Peeling of Plaster on Wall No. 2 of Room No. 6 of Second Floor



Photo 263 Peeling of Plaster on Wall No. 1 of Room No. 7 of Second Floor





Photo 262 Peeling of Plaster on Roof of Room No. 7 of Second Floor



Photo 264 Peeling of Plaster on Roof of Kitchen of Second Floor







Photo 265 Peeling of Plaster on Wall No. 2 of Bathroom of Second Floor



Photo 266 Dampness/Seepage on Wall No. 4 of Bathroom of Second Floor



Photo 267 Dampness/Seepage on Roof of Bathroom of Second Floor



Photo 269 Dampness/Seepage on Wall No. 3, 4, Roof & 2 of Toilet No. 1 of Second Floor





Photo 268 Peeling of Plaster on Roof of Bathroom of Second Floor



Photo 270 Dampness/Seepage on Roof & 4 of Bathroom No. of Second Floor







Photo 271 Peeling of Plaster on Wall No. 1 of Room No. 10 of Second Floor

Photo 272 Damaged Portion on Floor of Part B of Police Kotwali of Second Floor





Photo 273 Peeling of Plaster on Roof of Room No. 11 of Second Floor



Photo 275 Plaster Crack on Roof of Room No. 12 of Second Floor





Photo 276 Dampness/Seepage on Roof of Room No. 13 of Second Floor









Photo 277 Dampness/Seepage on Roof of Bathroom of Second Floor



Photo 278 Peeling of Plaster on Wall No. 1 of Room No. 12 of Second Floor





Photo 279 Peeling of Plaster on Roof of Toilet No. 2 of Second Floor





Photo 281 Dampness/Seepage on Wall No. 1 of Bathroom of Second Floor



Photo 282 Peeling of Plaster on Roof of Room No. 15 of Second Floor









Photo 283 Peeling of Plaster on Wall No. 3 of Room No. 15 of Second Floor



Photo 284 Peeling of Plaster on Roof of Room No. 14 of Second Floor





Photo 285 Peeling of Plaster on Wall No. 3 of Room No. 14 of Second Floor

Photo 286 Dampness/Seepage on Wall No. 2, 4 & Roof of Kitchen of Second Floor



Photo 287 Dampness/Seepage on Roof of Balcony of Second Floor



Photo 288 Damaged Portion on Roof of Balcony Gate of Second Floor











Photo 289 Dampness/Seepage on Wall No. 2 & Roof of Hall No. 3 of Second Floor

Photo 290 Dampness/Seepage on All Walls & Roof of Part B of Police Kotwali of Second Floor





Photo 291 Dampness/Seepage on Roof of Toilet No. 1 of Second Floor



Photo 293 Dampness/Seepage on Backside Wall of Part B of Police Kotwali of Second Floor



Photo 292 Dampness/Seepage on Backside Wall of Part B of Police Kotwali of Second Floor



Photo 294 Dampness/Seepage on Backside Wall of Part B of Police Kotwali of Second Floor









Photo 295 Plaster Crack on Backside Wall of Part B of Police Kotwali of Second Floor

Photo 296 Plaster Crack on Backside Wall of Part B of Police Kotwali of Second Floor





Photo 297 Damaged Portion on Backside Wall of Part B of Police Kotwali of Second Floor

Photo 298 Damaged Portion on Backside Wall of Part B of Police Kotwali of Second Floor



Photo 299 Damaged Portion on Backside Wall of Part B of Police Kotwali of Second Floor





Photo 300 Damaged Portion on Backside Fount of Part B of Police Kotwali of Second Floor



JAIPUR METRO

#### **Jaipur Metro Rail Corporation**



Photo 301 Damaged Portion on Backside Fount of Part B of Police Kotwali of Second Floor



Photo 302 Damaged Portion on Backside Fount of Part B of Police Kotwali of Second Floor





Photo 303 Photo 304
Damaged Portion on Shade of Part B of Police Kotwali of Second Floor Damaged Portion on Shade of Part B of Police Kotwali of Second Floor



Photo 305 Damaged Portion on Right-side Outer Wall of Part B of Police Kotwali of Second Floor

Photo 306 Wall No. 4 of Shop No.170 of Ground Floor Covered With Wooden Almira









Photo 307 Wall No. 1 of Shop No.170 of Ground Floor Covered With Wooden Almira



Photo 308 Wall No. 2 of Shop No.170 of Ground Floor Covered With Wooden Almira





Photo 309 Roof of Shop No.170 of Ground Floor Covered With Falls Celling





Photo 311 Wall No. 4 of Shop No.169B of Ground Floor Covered With wooden work



Photo 312 Wall No. 2 of Shop No.169B of Ground Floor Covered With Glass Work











Photo 313 Roof of Shop No.169B of Ground Floor Covered With wooden work

Photo 314 All Walls of Shop No.169A of Ground Floor Covered With wooden work





Photo 315 Roof of Shop No.169A of Ground Floor Covered With wooden work

Photo 316 All Walls of Shop No.168 of Ground Floor Covered With Wooden Works





Photo 317 Roof of Shop No.168 of Ground Floor Covered With Wooden Works














Photo 319 Roof of Shop No.167 of Ground Floor Covered With Wooden Works

Photo 320 All Walls of Shop no.165 & 166 of Ground Floor Covered With Wooden Works & Glass Work





Photo 321 Roof of Shop no.165 & 166 of Ground Floor Covered With Wooden Works






Photo 323 Roof of Shop no.165 & 166 of Upper Ground Floor Covered With Wooden Works





Photo 324 Wall No. 4 of Shop No.163 &164 of Ground Floor Covered With Wooden Racks & Material







Photo 325 Wall No. 4 of Shop No.163 &164 of Ground Floor Covered With Wooden Racks & Material



Photo 326 Wall No. 4 of Shop No.162 of Ground Floor Half Wall Covered With Almira





Photo 327 All Walls of Shop No.161 of Ground Floor Covered With Wooden Almira

Photo 328 Shop No.160 of Ground Floor Locked



Photo 329 Room No. 3 of Ground Floor Locked



Photo 330 Wall No. 2 of Room No. 7B of Ground Floor Covered With Almira







Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



Photo 331 Roof of Room No. 1 of Covered With Falls Celling



Photo 332 All Walls & Roof of Room No. 1(part B) of Covered With Tiles & Wooden work





Photo 333 All Walls & Roof of Room No. 1 of Covered With Tiles & Wooden work






Photo 335 Office of Locked





Photo 336 Room No. Room 3A +3B of Locked







Photo 337 Wall No. 1 & 4 of Part B of Store of Covered With Material



Photo 338 Wall No. 1 & 2 of Part A of Store of Covered With Material



Photo 339 Wall No. 1 & 2 of Part A of Store of Covered With Material



Photo 341 Room No. 5 of Locked





Photo 340 Room No. 4 of Locked



Photo 342 Room No. 6 of Locked





Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



Photo 343 Room No. 7 of Locked



Photo 344 Room No. 8 of Locked





Photo 346

All Walls & Floor of Bathroom of First Floor Covered With Tiles

Photo 345 Room No. 10 of Locked



Photo 347 All Walls & Floor of Bathroom of First Floor Covered With Tiles



Photo 348 All Walls & Floor of Toilet No. 1+2+3+4 of First Floor Covered With Tiles











Photo 349 All Walls & Floor of Toilet No. 1+2+3+4 of First Floor Covered With Tiles

Photo 350 All Walls & Floor of Toilet No. 1+2+3+4 of First Floor Covered With Tiles





Photo 351 All Walls & Floor of Toilet No. 1+2+3+4 of First Floor Covered With Tiles



All Walls of Room No. 109 of First Floor Covered With plastic



Photo 353 Room No. 108 of First Floor Locked




Photo 354 Staircase First Floor To Second Floor of First Floor Locked











Photo 355 Wall No. 1 & 2 of Conference Hall of First Floor Covered With Wooden Wall No. 1 & 2 of Conference Hall of First Floor Covered With Wooden Almira





Photo 357 All Walls & Floor of Toilet & Washroom of First Floor Covered With tiles

Photo 358 All Walls & Roof of Toilet No. 1 of Second Floor Covered With Tiles



Photo 359 Room No. 9 of Second Floor Locked





Photo 360 Wall No. 2 of Hall No. 2 (PART B) of Second Floor Covered With Wooden Partition







Photo 361 Wall No. 1 of Hall No. 1 of Second Floor Covered With Wooden Partition



Photo 362 Wall No. 1 of Hall No. 2 of Second Floor Covered With Wooden Partition



Photo 363 Wall No. 2 of Hall No. 2 of Second Floor Covered With Wooden Partition



Photo 364 Toilet No. 1 of Second Floor Covered With Tile



Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



Shop No. 181-184 Sadhu Singh Dalal Sanghori Bazaar, Choti Chopar Jaipur Unique ID: CC 0013

Report Number: AIMIL/ESG/JMCEC/CC 0013/01, Rev. 00, Dated: January 2014

Building Owner Contractor Various Owners CEC Client Sub-Contractor JMRC Limited AIMIL Limited







Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line

Table of Contents			
S.No.	Particulars	Page No.	
1	Introduction	2	
2	Survey Details	2	
3	About the Structure	3	
4	Building Ownership Details	3	
5	Project Details	4	
6	General Building Details	4	
7	Summary of Cracks	5	
8	Summary of Defects other than Cracks		
9	Summary of Areas that Could not be surveyed		
10	Defect Photographs		
11	Schematic Diagram of Building		

Introduction

The Jaipur Metro Rail is being constructed to provide the city of Jaipur with a modern and technologically advanced Transit System, to provide a safe and well connected means of transport that reduces traffic congestion. The project consists of two corridors with underground and elevated sections.

The construction of underground rail and road infrastructures in metropolitan and cosmopolitan cities are mostly through developed area under challenging soil conditions.

The alignment of structure is passing through densely inhabitated areas, many structures are falling in the zone of influence of construction activities. It is required to carry out the pre-condition survey of those structures. The scope of work of this survey includes carrying out pre-condition survey of those structures.

	Survey Details				
S.No.	Head	Particulars	Signatures		
1	Date of Survey	09/12/2013			
2	AIMIL Representative				
3	CEC Representative				
4	Structural Designer of CEC				
5	JMRC/DMRC Representative				







Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line

About the Structure

The structure under consideration is a Multi Story Load Bearing Structure having 2 floors. The structure was constructed in year 1913 and is 100 years old.

There are 28 defects in the structure out of which 8 are cracks. Category wise distribution of cracks is given in the table below. Overall the Building can be categorised in Category II (Slight)

Category	Number of Cracks	% of Total Cracks
Negligible (< 0.1mm)	0	0%
Very Slight (0.1 to 1mm)	3	37.50%
Slight (1 to 5mm)	5	62.50%
Moderate (5 to 15mm)	0	0%
Severe (15 to 25mm)	0	0%
Very Severe (>25mm)	0	0%

The average width of cracks is 1.48mm and average length of cracks is 2.24m. The maximum crack width is 2.5mm and minimum width is 0.2mm.

	Building Ownership Details			
Unique ID/Sub ID	Premises Name	Owner	Signatures	
CC/0013/181	Badrinarayan Surajmal Sarraf			
CC/0013/182	Vijay Prakash Khandaka Jwellers			
CC/0013/183	Surajmal Ravindra Kumar Jwellers			
CC/0013/184	Badrinarayan Nathumal Sarraf			







Project Details			
S. No.	Head	Particulars	
1	Project	Jaipur Metro Rail Project	
2	Section	Chandpole to Bari Chaupar	
3	Client	JMRC Limited	
4	Consultant	DMRC Limited	
5	Contractor	CEC	
6	Design Consultant of Contractor	Omikron Kappa - Indus Consultrans JV	
7	Sub-Contractor	AIMIL Limited	
8	Subject	Pre-Condition Survey Report	

S. No.	Head	Particulars
1	Building Name	Shop No. 181-184
2	Building Address	Shop No. 181-184 Sadhu Singh Dalal Sanghori Bazaar, Choti Chopar Jaipur
3	Year of Construction	1853
4	Number of Floors	G+1
5	Number of Basements	None
6	Type of Building	Commercial
7	Approximate Height	6 m
8	Approximate Area	Not Known
9	Age of Building	160 years
10	Type of Structure	Load Bearing Structure
11	Type of Foundation	Not Known
12	Number of Bore Wells	None
13	Depth and Diameter of Bore	N.A
14	Roadways	One Side
15	Presence of Equipment/Machines	None







# JAIPUR METRO Jaipur Metro Rail Corporation

	Summary of Cracks					
Defect ID	Location	Orientation	Appx. Width (mm)	Appx. Length (m)	Category	Photo No.
1	Wall No. 2 Shop No.181 Ground Floor	Inclined	2	4	Slight	5
2	Wall No. 2 Shop No.181 Ground Floor	Inclined	2	1.3	Slight	6
3	Wall No. 1 Shop No.181 Ground Floor	Inclined	0.8	4	Very Slight	7
4	Wall No. 1 Shop No.181 Ground Floor	Inclined	0.8	4	Very Slight	8
5	Left Side External Column Varanda Shop No. 181, Ground Floor	Inclined	2.5	0.8	Slight	9
6	Roof Varanda Shop No. 182, Ground Floor	Horizontal	0.2	0.8	Very Slight	10
7	Roof Varanda Shop No. 182, Ground Floor	Horizontal	1	1.3	Slight	11
8	Wall No. 1, Roof & 4 Shop No.184 Upper Ground Floor	Inclined	2.5	1.7	Slight	12

Summary of Defects Other Than Crack				
Defect ID	Location	Description	Photo No.	
9	Wall No. 4 Shop No.181 Ground Floor	Dampness/Seepage	13	
10	Wall No. 2 Shop No.181 Ground Floor	Dampness/Seepage	14	
11	Wall No. 1 Shop No.181 Ground Floor	Dampness/Seepage	15	
12	Roof Shop No.181 Ground Floor	Damaged Portion	16	
13	Roof Shop No.181 Ground Floor	Damaged Portion	17	
14	Roof Shop No.181 Ground Floor	Damaged Portion	18	
15	Roof Varanda Shop No. 181, Ground Floor	Dampness/Seepage	19	
16	Left Side External Column Varanda Shop No. 181, Ground Floor	Damaged Portion	20	
17	Left Side External Column Varanda Shop No. 181, Ground Floor	Damaged Portion	21	
18	Roof Varanda Shop No. 182, Ground Floor	Dampness/Seepage	22	
19	Roof Varanda Shop No. 183, Ground Floor	Dampness/Seepage	23	
20	Backside external Column Varanda Shop No. 183, Ground Floor	Damaged Portion	24	
21	Wall No. 4 Shop No.183 Ground Floor	Dampness/Seepage	25	
22	Wall No. 3 Shop No.183 Ground Floor	Dampness/Seepage	26	
23	Wall No. 1 & Roof Shop No.183 Ground Floor	Dampness/Seepage	27	
24	Roof Varanda Ground Floor	Dampness/Seepage	28	
25	Shop No.184 Upper Ground Floor	Dampness/Seepage	29	
26	Roof Shop No.184 Upper Ground Floor	Dampness/Seepage	30	
27	Wall No. 3 Shop No.184 Upper Ground Floor	Dampness/Seepage	31	
28	Wall No. 1 Shop No.184 Upper Ground Floor	Dampness/Seepage	32	

	Summary of Areas that Could not be Surveyed				
Serial No.	Location	Description	Photo No.		
1	All Walls & Roof Shop No.182 Ground Floor	Covered With wooden Works & Glass work	33		
2	All Walls & Roof Shop No.183 Ground Floor	Covered With wooden Works & Glass work	34		
3	Wall No. 2 Shop No.183 Ground Floor	Covered With Wooden Almira	35		
4	All Walls Shop No.184 Shop No. 184, Ground Floor	Covered With Wooden Almira	36		



Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



Photo 1 View of Shop No.181



Photo 2 View of Shop No.182, Ground Floor



Photo 3 View of Shop No.183, Ground Floor



Photo 5 Inclined Crack on Wall No. 2 of Shop No.181, Ground Floor Approx. Width = 2mm, Approx. Length = 4m. Distance from Wall no.3 = 2.5m, Height from Floor = 0.8m.





Photo 4 View of Shop No.184, Ground Floor



Photo 6 Inclined Crack on Wall No. 2 of Shop No.181, Ground Floor Approx. Width = 2mm, Approx. Length = 1.3m. Distance from Wall no.3 = 1.7m, Height from Floor = 2.6m.





Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



Photo 7 Inclined Crack on Wall No. 1 of Shop No.181, Ground Floor Approx. Width = 0.8mm, Approx. Length = 4m. Distance from Wall no.3 = 0.15m, Height from Floor = 0m.



#### Photo 9

Inclined Crack on Left Side External Column of Varanda , Shop No. 181, Ground Floor Approx. Width = 2.5mm, Approx. Length = 0.8m. Distance from = m, Height from Floor = 0.3m.



#### Photo 11

Horizontal Crack on Roof of Varanda , Shop No. 182, Ground Floor Approx. Width = 1mm, Approx. Length = 1.3m. Distance from = Backside of RightSide External Columnm, Height from Floor = 3.5m.





Photo 8 Inclined Crack on Wall No. 1 of Shop No.181, Ground Floor Approx. Width = 0.8mm, Approx. Length = 4m. Distance from Wall no.3 = 0.15m, Height from Floor = 0m.



#### Photo 10

Horizontal Crack on Roof of Varanda , Shop No. 182, Ground Floor Approx. Width = 0.2mm, Approx. Length = 0.8m. Distance from Left Side Extenal Column = 1.5m, Height from Floor = 3.5m.



#### <u>Photo 1</u>2

Inclined Crack on Wall No. 1,4 & Roof of Shop No.184, Upper Ground Floor Approx. Width = 2.5mm, Approx. Length = 1.7m. Distance from Wall no.3 = 1.6m, Height from Floor = 1m.





Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



Photo 13 Dampness/Seepage on Wall No. 4 of Shop No.181 of Ground Floor

Photo 14 Dampness/Seepage on Wall No. 2 of Shop No.181 of Ground Floor





Photo 16

Damaged Portion on Roof of Shop No.181 of Ground Floor

Photo 15 Dampness/Seepage on Wall No. 1 of Shop No.181 of Ground Floor



Photo 17 Damaged Portion on Roof of Shop No.181 of Ground Floor



Photo 18

Photo 18 Damaged Portion on Roof of Shop No.181 of Ground Floor





Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



JAIPUR METRO

Photo 19 Dampness/Seepage on Roof of Varanda of Shop No. 181, Ground Floor

Photo 20 Damaged Portion on Left Side External Column of Varanda of Shop No. 181, Ground Floor





Photo 21 Damaged Portion on Left Side External Column of Varanda of Shop No. 181, Ground Floor

Photo 22 Dampness/Seepage on Roof of Varanda of Shop No. 182, Ground Floor





Photo 23 Dampness/Seepage on Roof of Varanda of Shop No. 183, Ground Floor 183, Ground Floor









Photo 25 Dampness/Seepage on Wall No. 4 of Shop No.183 of Ground Floor

Photo 26 Dampness/Seepage on Wall No. 3 of Shop No.183 of Ground Floor





Photo 27 Dampness/Seepage on Wall No. 1 & Roof of Shop No.183 of Ground Floor

Photo 28 Dampness/Seepage on Roof of Varanda of Ground Floor



Photo 29 Dampness/Seepage on of Shop No.184 of Upper Ground Floor



Photo 30 Dampness/Seepage on Roof of Shop No.184 of Upper Ground Floor









Photo 31 Dampness/Seepage on Wall No. 3 of Shop No.184 of Upper Ground Floor



Photo 32 Dampness/Seepage on Wall No. 1 of Shop No.184 of Upper Ground Floor





 Photo 33
 Photo 34

 All Walls & Roof of Shop No.182 of Ground Floor Covered With wooden
 All Walls & Roof of Shop No.183 of Ground Floor Covered With wooden

 Works & Glass work
 Works & Glass work



Photo 35 Wall No. 2 of Shop No.183 of Ground Floor Covered With Wooden Almira

Photo 36 All Walls of Shop No.184 of Shop No. 184, Ground Floor Covered With Wooden Almira



Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Shop No. 181-184 Sadhu Singh Dalal Sanghori Bazaar, Choti Chopar Jaipur Unique ID: CC 0014

Report Number: AIMIL/ESG/JMCEC/CC 0014/01, Rev. 00, Dated: January 2014

Building Owner Contractor Various Owners CEC Client Sub-Contractor JMRC Limited AIMIL Limited







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

	Table of Contents			
S.No.	Particulars	Page No.		
1	Introduction	2		
2	Survey Details	2		
3	About the Structure	3		
4	Building Ownership Details	3		
5	Project Details	4		
6	General Building Details	4		
7	Summary of Cracks	5		
8	Summary of Defects other than Cracks			
9	Summary of Areas that Could not be surveyed			
10	Defect Photographs			
11	Schematic Diagram of Building			

Introduction

The Jaipur Metro Rail is being constructed to provide the city of Jaipur with a modern and technologically advanced Transit System, to provide a safe and well connected means of transport that reduces traffic congestion. The project consists of two corridors with underground and elevated sections.

The construction of underground rail and road infrastructures in metropolitan and cosmopolitan cities are mostly through developed area under challenging soil conditions.

The alignment of structure is passing through densely inhabitated areas, many structures are falling in the zone of influence of construction activities. It is required to carry out the pre-condition survey of those structures. The scope of work of this survey includes carrying out pre-condition survey of those structures.

	Survey Details				
S.No.	Head	Particulars	Signatures		
1	Date of Survey	09/12/2013			
2	AIMIL Representative				
3	CEC Representative				
4	Structural Designer of CEC				
5	JMRC/DMRC Representative				







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

About the Structure

The structure under consideration is a Multi Story Load Bearing Structure having 2 floors. The structure was constructed in year 1853 and is 250 years old.

There are 104 defects in the structure out of which 30 are cracks. Category wise distribution of cracks is given in the table below. Overall the Building can be categorised in Category III (Moderate)

Category	Number of Cracks	% of Total Cracks
Negligible (< 0.1mm)	0	0%
Very Slight (0.1 to 1mm)	18	60%
Slight (1 to 5mm)	11	36.67%
Moderate (5 to 15mm)	1	3.33%
Severe (15 to 25mm)	0	0%
Very Severe (>25mm)	0	0%

The average width of cracks is 1.08mm and average length of cracks is 1.95m. The maximum crack width is 5mm and minimum width is 0.15mm.

Building Ownership Details					
Unique ID/Sub ID	Premises Name	Owner	Signatures		
CC-0014/COLLEGE	Rastra Bhasa College	Govt. of Rajasthan			
CC-0014/020-021	Lodilal RadhaGopal Sarraf	Mr. Giriraj			
CC-0014/22	Surajmal Sarraf	Mr. Naval Kishore			
CC-0014/172	Lodilal RadhaGopal Sarraf	Mr. Lalulal Sarrafa			
CC-0014/173	Lodilal RadhaGopal Sarraf	Mr. Heeralal Aggarwal			
CC-0014/174	Surbhi Jwelers	Mr. Lalulal Sarrafa			
CC-0014/175	SriRam Jwelers	Mr. Kailash Chand			
CC-0014/176	Ballam ram Bansidhar Sarraf	Mr. Rajesh Sokiya			
CC-0014/177	Damodarlal Pannalal Sarraf	Mr. Panna Lal Ji			
CC-0014/178	Khandka Omji Jwelers	Mr. Shri Kumar Khandaka			
CC-0014/180	Padamprakash Khandka .lwelers	Mr. Ashok Kumar			
INDIA	A MEMBERS OF CONTINENTAL HOLDINGS				



Project Details				
S. No.	Head	Particulars		
1	Project	Jaipur Metro Rail Project		
2	Section	Chandpole to Bari Chaupar		
3	Client	JMRC Limited		
4	Consultant	DMRC Limited		
5	Contractor	CEC		
6	Design Consultant of Contractor	Omikron Kappa - Indus Consultrans JV		
7	Sub-Contractor	AIMIL Limited		
8	Subject	Pre-Condition Survey Report		

S. No.	Head	Particulars
1	Building Name	Rastra Bhasa College & Shops
2	Building Address	Shop No. 172-180 Sadhu Singh Dalal Sanghori Bazaar, Choti Chopar Jaipur
3	Year of Construction	1853
4	Number of Floors	G+1
5	Number of Basements	None
6	Type of Building	Commercial
7	Approximate Height	6 m
8	Approximate Area	Not Known
9	Age of Building	150 years
10	Type of Structure	Load Bearing Structure
11	Type of Foundation	Not Known
12	Number of Bore Wells	None
13	Depth and Diameter of Bore	N.A
14	Roadways	One Side
15	Presence of Equipment/Machines	None







	Summar	y of Cracks				
Defect ID	Location	Orientation	Appx. Width (mm)	Appx. Length (m)	Category	Photo No.
1	Part A Shop no.15, Ground Floor	Horizontal	1.5	0.5	Slight	22
2	Roof Varanda Shop No.21, Ground Floor	Horizontal	0.4	1.5	Very Slight	23
3	Roof Varanda Shop No.21, Ground Floor	Horizontal	0.5	0.6	Very Slight	24
4	Roof Varanda Shop No.174, Ground Floor	Horizontal	5	1.5	Moderate	25
5	Roof Varanda Shop No.174, Ground Floor	Horizontal	1.5	1.5	Slight	26
6	Roof Shop No.176 Ground Floor	Horizontal	0.15	2	Very Slight	27
7	Roof Shop No.176 Ground Floor	Horizontal	2	2.5	Slight	28
8	Wall No. 4 Shop No.176 Ground Floor	Vertical	1	2	Slight	29
9	Wall No. 1 Shop No.176 Ground Floor	Inclined	0.5	1.6	Very Slight	30, 30A
10	Wall No. 1 Shop No.176 Ground Floor	Inclined	0.8	1.5	Very Slight	31, 31A
11	Wall No. 4 Shop No.172 Ground Floor	Inclined	0.4	1.5	Very Slight	32
12	Wall No. 4 Shop No.172 Ground Floor	Inclined	0.4	1.5	Very Slight	33
13	Wall No. 1 & 3 Hall No. 1(Part-I) First Floor	Inclined	0.8	1.6	Very Slight	34
14	Roof Hall No. 1(Part-I) First Floor	Horizontal	2	1.7	Slight	35
15	Wall No. 3 Hall No. 1(Part-I) First Floor	Vertical	1	3.5	Slight	36, 36A
16	Wall No. 4 & Roof Hall No. 1(Part-I) First Floor	Inclined	1.5	3.5	Slight	37
17	Wall No. 7 Hall No. 1(Part-I) First Floor	Vertical	0.5	1.2	Very Slight	38
18	Wall No. 4 Hall No. 1(Part-I) First Floor	Inclined	0.5	1.1	Very Slight	39
19	Wall No. 1 Hall No. 1(Part-I) First Floor	Inclined	0.8	0.5	Very Slight	40
20	Roof Hall No. 1(Part-I) First Floor	Horizontal	0.25	1.8	Very Slight	41
21	Wall No. 4 Hall No. 1(Part-I) First Floor	Inclined	0.35	2	Very Slight	42
22	Wall No. 1 Hall No. 1 (Part-II) First Floor	Inclined	2.5	2.5	Slight	43
23	Roof Hall No. 1 (Part-II) First Floor	Horizontal	1.5	3	Slight	44
24	Wall No. 3 Hall No. 1 (Part-II) First Floor	Inclined	0.2	1.5	Very Slight	45
25	Roof Hall No. 1 (Part-II) First Floor	Horizontal	1.5	3.2	Slight	46
26	Roof Room No. 2 First Floor	Horizontal	0.2	2	Very Slight	47
27	Wall No. 2 Open Area 3 College & Temple, First Floor	Inclined	3	1.5	Slight	48
28	Outer Wall Right Side College + Temple First Floor	Inclined	0.4	1.6	Very Slight	49
29	Outer Wall Right Side College + Temple First Floor	Inclined	0.6	4	Very Slight	50
30	College + Temple First Floor	Inclined	0.6	4	Very Slight	51

	Summary of Defects Other Than Crack					
Defect ID	Location	Description Pho				
31	Roof Varanda Shop No.14, Ground Floor	Dampness/Seepage	52			
32	Wall No. 1 Part A Shop No.14, Ground Floor	Peeling of Plaster	53			
33	Wall No. 2 Part A Shop No.14, Ground Floor	Peeling of Plaster	54			
34	Roof Part A Shop No.14, Ground Floor	Peeling of Plaster	55			
35	Roof Part A Shop No.14, Ground Floor	Peeling of Plaster	56			
36	Wall No. 1 Part B Shop No.14, Ground Floor	Peeling of Plaster	57			
37	Wall No. 2 Part B Shop No.14, Ground Floor	Peeling of Plaster	58			
38	Wall No. 4 Part B Shop No.14, Ground Floor	Peeling of Plaster	59			
39	Roof Part B Shop No.14, Ground Floor	Peeling of Plaster	60			

40	Wall No. 1 Part C Shop No.14, Ground Floor	Peeling of Plaster	61
41	Wall No. 2 Part C Shop No.14, Ground Floor	Peeling of Plaster	62
42	Wall No. 3 Part C Shop No.14, Ground Floor	Peeling of Plaster	63
43	Roof Part C Shop No.14, Ground Floor	Peeling of Plaster	64
44	Roof Part B Shop no.15, Ground Floor	Dampness/Seepage	65
45	Roof Part C Shop no.15, Ground Floor	Peeling of Plaster	66
46	Wall No. 3 Part C Shop no.15, Ground Floor	Peeling of Plaster	67
47	Roof Varanda Shop no.15, Ground Floor	Damaged Portion	68
48	Roof Varanda Shop No.21, Ground Floor	Peeling of Plaster	69
49	Leftside Wall Shop No.21 Ground Floor	Dampness/Seepage	70
50	Roof Varanda Shop no.22, Ground Floor	Peeling of Plaster	71
51	Right Side External Wall Varanda Shop no.22, Ground Floor	Damaged Portion	72
52	Right Side External Wall Varanda Shop no.22, Ground Floor	Dampness/Seepage	73
53	External Beam Varanda Shop no.22, Ground Floor	Damaged Portion	74
54	Roof Varanda Shop No.173, Ground Floor	Dampness/Seepage	75
55	Roof Varanda Shop No.174, Ground Floor	Dampness/Seepage	76
56	Roof Varanda Shop No.175, Ground Floor	Dampness/Seepage	77
57	External Beam Varanda Shop No.175, Ground Floor	Dampness/Seepage	78
58	Wall No. 1 Shop No.176 Ground Floor	Peeling of Plaster	79
59	Roof Varanda Shop No.177, Ground Floor	Peeling of Plaster	80
60	Roof Varanda Shop No.178, Ground Floor	Dampness/Seepage	81
61	External Beam Varanda Shop No.178, Ground Floor	Peeling of Plaster	82
62	Roof Varanda Shop No.180, Ground Floor	Dampness/Seepage	83
63	Roof Varanda Shop No.172, Ground Floor	Dampness/Seepage	84
64	Roof Shop No.172 Ground Floor	Peeling of Plaster	85
65	Wall No. 4 Shop No.172 Ground Floor	Dampness/Seepage	86
	Wall No. 4 Shop No.172 Ground Floor	Plaster Crack	87
66			
67 68	Wall No. 1 Shop No.172 Ground Floor Wall No. 1 & Roof Varanda College & Temple, First Floor	Dampness/Seepage Dampness/Seepage	88 89
69	Wall No. 1 Varanda College & Temple, First Floor	Peeling of Plaster	90
70	Roof Varanda College & Temple, First Floor	Dampness/Seepage	91
71	Wall No. 6 Varanda no.2 College & Temple, First Floor	Peeling of Plaster	92
72	Wall No. 4 Varanda no.2 College & Temple, First Floor	Peeling of Plaster	93
73	Wall No. 7 Varanda no.2 College & Temple, First Floor	Peeling of Plaster	94
74	Wall No. 2 Varanda no.2 College & Temple, First Floor	Peeling of Plaster	95
75	Wall No. 4 Varanda no.2 College & Temple, First Floor	Peeling of Plaster	96
76	Roof Varanda no.2 College & Temple, First Floor	Peeling of Plaster	97
77	Wall No. 1 & 4 Open Varanda College & Temple, First Floor	Peeling of Plaster	98
78	Wall No. 2 Open Varanda College & Temple, First Floor Roof Shade Open Varanda College & Temple, First	Dampness/Seepage	99
79	Floor	Dampness/Seepage	100
80	Wall No. 2 & 4 Room No. 3 (Part-I) First Floor	Dampness/Seepage	101
81	Wall No. 2, 3 & Roof Room No. 3 (Part-II) First Floor	Dampness/Seepage	102
82	Wall No. 4 Room No. 3 (Part-II) First Floor	Dampness/Seepage	103
83	Wall No. 1 Varanda 1 College & Temple, First Floor	Peeling of Plaster	104
84	Floor Hall No. 1(Part-I) First Floor	Peeling of Plaster	105
85	Floor Hall No. 1(Part-I) First Floor	Peeling of Plaster	106
	Wall No. 3 Hall No. 1(Part-I) First Floor	Peeling of Plaster	107

88	Roof Hall No. 1 (Part-II) First Floor	Peeling of Plaster	109
89	Wall No. 3 Hall No. 1 (Part-II) First Floor	Peeling of Plaster	110
90	Floor Hall No. 1 (Part-II) First Floor	Peeling of Plaster	111
91	Wall No. 4 Hall No. 1 (Part-II) First Floor	Peeling of Plaster	112
92	Wall No. 5 Open Area 2 College & Temple, First Floor	Peeling of Plaster	113
93	Shade Open Area 2 College & Temple, First Floor	Peeling of Plaster	114
94	Wall No. 3 Room No. 2 First Floor	Peeling of Plaster	115
95	Wall No. 3 Room No. 2 First Floor	Peeling of Plaster	116
96	Roof Room No. 2 First Floor	Peeling of Plaster	117
97	Roof Room No. 2 First Floor	Damaged Portion	118
98	Wall No. 1 Open Area 3 College & Temple, First Floor	Dampness/Seepage	119
99	All Wall Room No. 5 First Floor	Dampness/Seepage	120
100	All Wall Room No. 5 First Floor	Dampness/Seepage	121
101	Wall No. 3 Open Area 3 College & Temple, First Floor	Peeling of Plaster	122
102	Outer Wall Right Side Room No. 5 First Floor	Peeling of Plaster	123
103	Shade College + Temple First Floor	Peeling of Plaster	124
104	Outer Wall College + Temple First Floor	Damaged Portion	125

	Summary of Areas t	hat Could not be Surveyed	
Serial No.	Location	Description	Photo No.
1	Roof Part A Shop no.15, Ground Floor	Covered With Falls Celling	126
2	Wall No. 1 Part A Shop no.15, Ground Floor	Covered with Material & wooden Works	127
3	Wall No. 2 Part A Shop no.15, Ground Floor	Covered with Material & wooden Works	128
4	All Wall Part B Shop no.15, Ground Floor	Covered with Material	129
5	All Wall Part C Shop no.15, Ground Floor	Covered with Material & wooden Works	130
6	Shop No.16 Ground Floor	Locked	131
7	Shop No.17 Ground Floor	Locked	132
8	All Wall Shop No.173 Ground Floor	Covered With Wooden Racks & Material	133
9	All Wall Shop No.174 Ground Floor	Covered With Glass work	134
10	All Wall & Roof Shop No.175 Ground Floor	Covered With wooden Racks & Works	135
11	All Wall Shop No.177 Ground Floor	Covered With Glass & Wooden Work	136
12	Part B Shop No.177, Ground Floor	Locked	137
13	Wall No. 1, 2, 4 & Roof Shop No.178 Ground Floor	Covered With Wooden Works	138
14	All Wall & Roof Shop No.180 Ground Floor	Covered With Wooden work & Falls Celling	139
15	Wall No. 2 Shop No.172 Ground Floor	Covered With Wooden Rack	140
16	Room No. 1 First Floor	Locked	141
17	Wall No. 5 & 6 Room No. 3 (Part-I) First Floor	Covered With tiles	142
18	Wall No. 2 Hall No. 1(Part-I) First Floor	Covered With Wooden Work	143
19	All Wall Room No. 2 First Floor	Covered With Material	144
20	Room No. 4 First Floor	Locked	145









Photo 1 View of Shop no.22



Photo 2 View of Shop No.14, Ground Floor



Photo 3 , Shop No.14, Ground Floor



Photo 4 View of shop no.15 , Ground Floor



Photo 6 View of Shop No.21, Ground Floor





Photo 5 View of Shop No.21, Ground Floor







Photo 7 View of Shop no.22, Ground Floor



Photo 8 View of Shop No.173, Ground Floor



Photo 9 View of Shop no.174, Ground Floor



Photo 11 View of Shop No.176, Ground Floor





Photo 10 View of Shop No.175, Ground Floor



Photo 12 View of shop No.177, Ground Floor







Photo 13 View of shop No.178, Ground Floor



Photo 14 View of shop No.180, Ground Floor



Photo 15 View of Shop No.172, Ground Floor



Photo 17 View of Temple , First Floor





Photo 16 View of Temple Right Side, First Floor



Photo 18 View of Temple Left side , First Floor







<u>Photo 1</u>9 First Floor



Photo 20 View of Rashtiye Bhasha College + Temple, First Floor



Photo 21 View of Rashtiye Bhasha College + Temple, First Floor



Photo 23 Horizontal Crack on Roof of Varanda, Shop No.21, Ground Floor Approx. Width = 0.4mm, Approx. Length = 1.5m. Distance from Left External Column = 0m, Height from Floor = 3m.





Photo 22 Horizontal Crack on of Part A, Shop no.15, Ground Floor Approx. Width = 1.5mm, Approx. Length = 0.5m. Distance from Wall No.1 = 0.15m, Height from Floor = 2.3m.



Photo 24 Horizontal Crack on Roof of Varanda, Shop No.21, Ground Floor Approx. Width = 0.5mm, Approx. Length = 0.6m. Height from Floor = 3m.





Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Photo 25 Horizontal Crack on Roof of Varanda, Shop No.174, Ground Floor, Approx. Width = 5mm, Approx. Length = 1.5m.Distance from Right External Column = 0m,Height from Floor = 3.5m.



Photo 27 Horizontal Crack on Roof of Shop No.176, Ground Floor Approx. Width = 0.15mm, Approx. Length = 2m. Distance from Wall no.1 = 0.25m, Height from Floor = 3.5m.



Photo 29 Vertical Crack on Wall No. 4 of Shop No.176, Ground Floor Approx. Width = 1mm, Approx. Length = 2m. Distance from Wall No.1 = 0.1m, Height from Floor = 2.3m.





Photo 26 Horizontal Crack on Roof of Varanda, Shop No.174, Ground Floor Approx. Width = 1.5mm, Approx. Length = 1.5m.Distance from Right External Column = 0m, Height from Floor = 3.5m.



Photo 28 Horizontal Crack on Roof of Shop No.176, Ground Floor Approx. Width = 2mm, Approx. Length = 2.5m. Distance from Wall No.1 = 0.1m, Height from Floor = 3.5m.



Photo 30 Inclined Crack on Wall No. 1 of Shop No.176, Ground Floor Approx. Width = 0.5mm, Approx. Length = 1.6m. Distance from Wall No.1 = 0.4m, Height from Floor = 1.2m.





Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Photo 30A Inclined Crack on Wall No. 1 of Shop No.176, Ground Floor Approx. Width = 0.5mm, Approx. Length = 1.6m. Distance from Wall No.1 = 0.4m, Height from Floor = 1.2m.




Photo 31A Inclined Crack on Wall No. 1 of Shop No.176, Ground Floor Approx. Width = 0.8mm, Approx. Length = 1.5m. Distance from Wall No.3 = 0.25m, Height from Floor = 0m.



Photo <u>3</u>3 Inclined Crack on Wall No. 4 of Shop No.172, Ground Floor Approx. Width = 0.4mm, Approx. Length = 1.5m. Distance from Wall No.1 = 0.05m, Height from Floor = 1.3m.





Photo 31 Inclined Crack on Wall No. 1 of Shop No.176, Ground Floor Approx. Width = 0.8mm, Approx. Length = 1.5m. Distance from Wall No.3 = 0.25m, Height from Floor = 0m.



Photo 32 Inclined Crack on Wall No. 4 of Shop No.172, Ground Floor Approx. Width = 0.4mm, Approx. Length = 1.5m. Distance from Wall No.1 = 0.05m, Height from Floor = 1.3m.



Photo 34 Inclined Crack on Wall No. 1 & 3 of Hall No. 1(Part-I), First Floor Approx. Width = 0.8mm, Approx. Length = 1.6m. Distance from Wall No.3 = 0.3m, Height from Floor = 3.6m.



Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



JAIPUR METRO

Photo 35 Horizontal Crack on Roof of Hall No. 1(Part-I), First Floor Approx. Width = 2mm, Approx. Length = 1.7m. Distance from Wall No.3 = 0m, Height from Floor = 4m.



#### Photo 36A

Vertical Crack on Wall No. 3 of Hall No. 1(Part-I), First Floor Approx. Width = 1mm, Approx. Length = 3.5m. Distance from Wall No.1 = 2.5m, Height from Floor = 0.3m.



Photo 38 Vertical Crack on Wall No. 7 of Hall No. 1(Part-I), First Floor Approx. Width = 0.5mm, Approx. Length = 1.2m. Distance from Wall No.4 = 0.5m, Height from Floor = 2.8m.





Photo 36 Vertical Crack on Wall No. 3 of Hall No. 1(Part-I), First Floor Approx. Width = 1mm, Approx. Length = 3.5m. Distance from Wall No.1 = 2.5m, Height from Floor = 0.3m.



Photo 37 Inclined Crack on Wall No. 4 & Roof of Hall No. 1(Part-I), First Floor Approx. Width = 1.5mm, Approx. Length = 3.5m. Distance from Wall No.3 = 0m, Height from Floor = 2.6m.



Photo 39 Inclined Crack on Wall No. 4 of Hall No. 1(Part-I), First Floor Approx. Width = 0.5mm, Approx. Length = 1.1m. Distance from Wall No.1 = 1.5m, Height from Floor = 3m.



JAIPUR METRO

# **Jaipur Metro Rail Corporation**

Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Photo 40 Inclined Crack on Wall No. 1 of Hall No. 1(Part-I), First Floor Approx. Width = 0.8mm, Approx. Length = 0.5m. Distance from Wall No.3 = Cornerm, Height from Floor = 2.6m.



Photo 42 Inclined Crack on Wall No. 4 of Hall No. 1(Part-I), First Floor Approx. Width = 0.35mm, Approx. Length = 2m. Distance from Wall No.2 = 3.5m, Height from Floor = 3.5m.



Photo 44 Horizontal Crack on Roof of Hall No. 1 (Part-II), First Floor Approx. Width = 1.5mm, Approx. Length = 3m. Distance from Wall No.1 = 3.3m, Height from Floor = 4m.





Photo 41 Horizontal Crack on Roof of Hall No. 1(Part-I), First Floor Approx. Width = 0.25mm, Approx. Length = 1.8m. Distance from Wall No.4 = 0.5m, Height from Floor = 4m.



Photo 43 Inclined Crack on Wall No. 1 of Hall No. 1 (Part-II), First Floor Approx. Width = 2.5mm, Approx. Length = 2.5m. Distance from Wall No.3 = 1m, Height from Floor = 2m.



Photo 45 Inclined Crack on Wall No. 3 of Hall No. 1 (Part-II), First Floor Approx. Width = 0.2mm, Approx. Length = 1.5m. Distance from Wall No.1 = 3.7m, Height from Floor = 2.5m.





Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Photo 46 Horizontal Crack on Roof of Hall No. 1 (Part-II), First Floor Approx. Width = 1.5mm, Approx. Length = 3.2m. Distance from Wall No.2 = 4.2m, Height from Floor = 4m.



<u>Photo 4</u>8



<u>Photo 4</u>7 Horizontal Crack on Roof of Room No. 2, First Floor Approx. Width = 0.2mm, Approx. Length = 2m.



Inclined Crack on Wall No. 2 of Open Area 3, College & Temple, First Floor, Approx. Width = 3mm, Approx. Length = 1.5m.Distance from Wall no.3 = 2.8m, Height from Floor = 1.3m.



<u>Photo 5</u>0

Inclined Crack on Outer Wall Right Side of College + Temple, First Floor, Approx. Width = 0.6mm, Approx. Length = 4m.Distance from Backside Outer Wall = 5.8m, Height from Floor = 0.5m.



Photo 49 Inclined Crack on Outer Wall Right Side of College + Temple, First Floor, Approx. Width = 0.4mm, Approx. Length = 1.6m.Distance from Backside Outer Wall = 7m, Height from Floor = 2.8m.



Photo 51 Inclined Crack on of College + Temple, First Floor Approx. Width = 0.6mm, Approx. Length = 4m.Distance from Backside Outer Wall = 5.8m, Height from Floor = 0.5m.









Photo 52 Dampness/Seepage on Roof of Varanda of Shop No.14, Ground Floor Peeling of Plaster on Wall No. 1 of Part A of Shop No.14, Ground Floor





Photo 54 Peeling of Plaster on Wall No. 2 of Part A of Shop No.14, Ground Floor

Photo 55 Peeling of Plaster on Roof of Part A of Shop No.14, Ground Floor



Photo 56 Peeling of Plaster on Roof of Part A of Shop No.14, Ground Floor



Photo 57 Peeling of Plaster on Wall No. 1 of Part B of Shop No.14, Ground Floor











Photo 58
Peeling of Plaster on Wall No. 2 of Part B of Shop No.14, Ground Floor Peeling of Plaster on Wall No. 4 of Part B of Shop No.14, Ground Floor





Photo 60 Peeling of Plaster on Roof of Part B of Shop No.14, Ground Floor

Photo 61 Peeling of Plaster on Wall No. 1 of Part C of Shop No.14, Ground Floor





Photo 62 Peeling of Plaster on Wall No. 2 of Part C of Shop No.14, Ground Floor Peeling of Plaster on Wall No. 3 of Part C of Shop No.14, Ground Floor











Photo 64 Peeling of Plaster on Roof of Part C of Shop No.14, Ground Floor

Photo 65 Dampness/Seepage on Roof of Part B of Shop no.15, Ground Floor





Photo 6 Peeling of Plaster on Roof of Part C of Shop no.15, Ground Floor

Photo 67 Peeling of Plaster on Wall No. 3 of Part C of Shop no.15, Ground Floor



Photo 68 Damaged Portion on Roof of Varanda of Shop no.15, Ground Floor



Photo 69 Peeling of Plaster on Roof of Varanda of Shop No.21, Ground Floor









09.12.2013 13:38

Photo 70 Dampness/Seepage on Leftside Wall of Shop No.21 of Ground Floor

Photo 71 Peeling of Plaster on Roof of Varanda of Shop no.22, Ground Floor





Photo 72 Damaged Portion on Right Side External Wall of Varanda of Shop no.22, Ground Floor



Photo 73 Dampness/Seepage on Right Side External Wall of Varanda of Shop no.22, Ground Floor



Photo 74 Damaged Portion on External Beam of Varanda of Shop no.22, Ground Floor Dampness/Seepage on Roof of Varanda of Shop No.173, Ground Floor











Photo 76 Dampness/Seepage on Roof of Varanda of Shop No.174, Ground Floor Dampness/Seepage on Roof of Varanda of Shop No.175, Ground Floor





Photo 78 Dampness/Seepage on External Beam of Varanda of Shop No.175, Ground Floor






Photo 80 Peeling of Plaster on Roof of Varanda of Shop No.177, Ground Floor



Photo 81 Dampness/Seepage on Roof of Varanda of Shop No.178, Ground Floor







Photo 82 Peeling of Plaster on External Beam of Varanda of Shop No.178, Ground Floor



Photo 83 Dampness/Seepage on Roof of Varanda of Shop No.180, Ground Floor





Photo 84 Dampness/Seepage on Roof of Varanda of Shop No.172, Ground Floor

Photo 85 Peeling of Plaster on Roof of Shop No.172 of Ground Floor



Photo 86 Dampness/Seepage on Wall No. 4 of Shop No.172 of Ground Floor



Photo 87 Plaster Crack on Wall No. 4 of Shop No.172 of Ground Floor









Photo 88 Dampness/Seepage on Wall No. 1 of Shop No.172 of Ground Floor



Photo 89 Dampness/Seepage on Wall No. 1 & Roof of Varanda of College & Temple, First Floor






<u>Photo 9</u>0 Peeling of Plaster on Wall No. 1 of Varanda of College & Temple, First Floor

<u>Photo 9</u>1 Dampness/Seepage on Roof of Varanda of College & Temple, First Floor



Photo 92 First Floor









Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line





Photo 94 Photo 95 Peeling of Plaster on Wall No. 7 of Varanda no.2 of College & Temple, Peeling of Plaster on Wall No. 2 of Varanda no.2 of College & Temple, First Floor First Floor





<u>Photo 9</u>6 First Floor



Photo 97 Peeling of Plaster on Wall No. 4 of Varanda no.2 of College & Temple, Peeling of Plaster on Roof of Varanda no.2 of College & Temple, First Floor



Photo 98 Peeling of Plaster on Wall No. 1 & 4 of Open Varanda of College & Temple, First Floor

Photo 99 Dampness/Seepage on Wall No. 2 of Open Varanda of College & Temple, First Floor



DOL







Photo 100 Dampness/Seepage on Roof Shade of Open Varanda of College & Temple, First Floor



Photo 101 Dampness/Seepage on Wall No. 2 & 4 of Room No. 3 (Part-I) of First Floor





Photo 102 Dampness/Seepage on Wall No. 2, 3 & Roof of Room No. 3 (Part-II) of First Floor Photo 103 Dampness/Seepage on Wall No. 4 of Room No. 3 (Part-II) of First Floor



Photo 104 Peeling of Plaster on Wall No. 1 of Varanda 1 of College & Temple, First Floor

Photo 105 Peeling of Plaster on Floor of Hall No. 1(Part-I) of First Floor









Photo 106 Peeling of Plaster on Floor of Hall No. 1(Part-I) of First Floor



Photo 107 Peeling of Plaster on Wall No. 3 of Hall No. 1(Part-I) of First Floor





Photo 108 Dampness/Seepage on Wall No. 1 of Hall No. 1 (Part-II) of First Floor






Photo 110 Peeling of Plaster on Wall No. 3 of Hall No. 1 (Part-II) of First Floor



Photo 111 Peeling of Plaster on Floor of Hall No. 1 (Part-II) of First Floor









Photo 112 Peeling of Plaster on Wall No. 4 of Hall No. 1 (Part-II) of First Floor



Photo 113 Peeling of Plaster on Wall No. 5 of Open Area 2 of College & Temple, First Floor





Photo 114 Peeling of Plaster on Shade of Open Area 2 of College & Temple, First Floor

Photo 115 Peeling of Plaster on Wall No. 3 of Room No. 2 of First Floor



Photo 116 Peeling of Plaster on Wall No. 3 of Room No. 2 of First Floor





Photo 117 Peeling of Plaster on Roof of Room No. 2 of First Floor







Photo 118 Damaged Portion on Roof of Room No. 2 of First Floor



Photo 119 Dampness/Seepage on Wall No. 1 of Open Area 3 of College & Temple, First Floor





Photo 120 Dampness/Seepage on All Wall of Room No. 5 of First Floor

Photo 121 Dampness/Seepage on All Wall of Room No. 5 of First Floor





Photo 122 Peeling of Plaster on Wall No. 3 of Open Area 3 of College & Temple, First Floor














Photo 124 Peeling of Plaster on Shade of College + Temple of First Floor

Photo 125 Damaged Portion on Outer Wall of College + Temple of First Floor





Photo 126 Roof of Part A of Shop no.15, Ground Floor Covered With Falls Celling Wall No. 1 of Part A of Shop no.15, Ground Floor Covered with Material & wooden Works





 Photo 128
 Photo 129

 Wall No. 2 of Part A of Shop no.15, Ground Floor Covered with Material & Wall No. All Wall of Part B of & Shop no.15, Ground Floor Covered with Material & Wall No. All Wall of Part B of & Shop no.15, Ground Floor Covered with Material & Wall No. All Wall of Part B of & Shop no.15, Ground Floor Covered with Material & Wall No. All Wall of Part B of & Shop no.15, Ground Floor Covered with Material & Wall No. All Wall of Part B of & Shop no.15, Ground Floor Covered with Material & Wall No. All Wall of Part B of & Shop no.15, Ground Floor Covered with Material & Wall No. All Wall of Part B of & Shop no.15, Ground Floor Covered with Material & Wall No. All Wall of Part B of & Shop no.15, Ground Floor Covered with Material & Wall No. All Wall of Part B of & Shop no.15, Ground Floor Covered with Material & Wall No. All Wall of Part B of & Shop no.15, Ground Floor Covered with Material & Wall No. All Wall of Part B of & Shop no.15, Ground Floor Covered with Material & Wall No. All Wall of Part B of & Shop no.15, Ground Floor Covered with Material & Wall No. All Wall of Part B of & Shop no.15, Ground Floor Covered with Material & Wall No. All Wall of Part B of & Shop no.15, Ground Floor Covered with Material & Wall No. All Wall No. All Wall of Part B of & Shop no.15, Ground Floor Covered with Material & Wall No. All Wall No. A









Photo 130 Wall No. All Wall of Part C of Shop no.15, Ground Floor Covered with Material & wooden Works



Photo 131 Shop No.16 of Ground Floor Locked





Photo 132 Shop No.17 of Ground Floor Locked





Photo 134 All Wall of Shop No.174 of Ground Floor Covered With Glass work



Photo 135 All Wall & Roof of Shop No.175 of Ground Floor Covered With wooden Racks & Works









Photo 136 All Wall of Shop No.177 of Ground Floor Covered With Glass & Wooden Work



Photo 137 Part B of Shop No.177, Ground Floor Locked





 
 Photo 138
 Photo 139

 Wall No. 1, 2, 4 & Roof of Shop No.178 of Ground Floor Covered With Wooden Works
 All Wall & Roof of Shop No.180 of Ground Floor Covered With Wooden work & Falls Celling



Photo 140 Wall No. 2 of Shop No.172 of Ground Floor Covered With Wooden Rack



Photo 141 Room No. 1 of First Floor Locked











Photo 142 Wall No. 5 & 6 of Room No. 3 (Part-I) of First Floor Covered With tiles

Photo 143 Wall No. 2 of Hall No. 1(Part-I) of First Floor Covered With Wooden Work



Photo 144 All Wall of Room No. 2 of First Floor Covered With Material



Photo 145 Room No. 4 of First Floor Locked



Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



Lohia Institute & Shops Choti Chopar Jaipur Unique ID: CC 0015

Report Number: AIMIL/ESG/JMCEC/CC 0015/01, Rev. 00, Dated: December 2013

Building Owner Contractor Various Owners CEC Client Sub-Contractor JMRC Limited AIMIL Limited







Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line

	Table of Contents			
S.No.	Particulars	Page No.		
1	Introduction	2		
2	Survey Details	2		
3	About the Structure	3		
4	Building Ownership Details	3		
5	Project Details	4		
6	General Building Details	4		
7	Summary of Cracks	5		
8	Summary of Defects other than Cracks			
9	Summary of Areas that Could not be surveyed			
10	Defect Photographs			
11	Schematic Diagram of Building			

Introduction

The Jaipur Metro Rail is being constructed to provide the city of Jaipur with a modern and technologically advanced Transit System, to provide a safe and well connected means of transport that reduces traffic congestion. The project consists of two corridors with underground and elevated sections.

The construction of underground rail and road infrastructures in metropolitan and cosmopolitan cities are mostly through developed area under challenging soil conditions.

The alignment of structure is passing through densely inhabitated areas, many structures are falling in the zone of influence of construction activities. It is required to carry out the pre-condition survey of those structures. The scope of work of this survey includes carrying out pre-condition survey of those structures.

	Survey Details				
S.No.	Head	Particulars	Signatures		
1	Date of Survey	09/12/2013			
2	AIMIL Representative				
3	CEC Representative				
4	Structural Designer of CEC				
5	JMRC/DMRC Representative				







Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line

About the Structure

The structure under consideration is a Multi Story Load Bearing Structure having 3 floors. The structure was constructed in year 1813 and is 200 years old.

There are 48 defects in the structure out of which 16 are cracks. Category wise distribution of cracks is given in the table below. Overall the Building can be categorised in Category III (Moderate)

Category	Number of Cracks	% of Total Cracks
Negligible (< 0.1mm)	0	0%
Very Slight (0.1 to 1mm)	10	62.50%
Slight (1 to 5mm)	5	31.25%
Moderate (5 to 15mm)	1	6.25%
Severe (15 to 25mm)	0	0%
Very Severe (>25mm)	0	0%

The average width of cracks is 1.18mm and average length of cracks is 1.56m. The maximum crack width is 5mm and minimum width is 0.15mm.

Building Ownership Details				
Unique ID/Sub ID	Premises Name	Owner	Signatures	
CC/0015/010	Jaichand Soni			
CC/0015/FF-SF				







Project Details				
S. No.	Head	Particulars		
1	Project	Jaipur Metro Rail Project		
2	Section	Chandpole to Bari Chaupar		
3	Client	JMRC Limited		
4	Consultant	DMRC Limited		
5	Contractor	CEC		
6	Design Consultant of Contractor	Omikron Kappa - Indus Consultrans JV		
7	Sub-Contractor	AIMIL Limited		
8	Subject	Pre-Condition Survey Report		

General Building Details (As informed verbally by Building Owner)				
S. No.	Head	Particulars		
1	Building Name	Lohia Institute & Shops		
2	Building Address	Lohia Institute & Shops Choti Chopar Jaipur		
3	Year of Construction	1813		
4	Number of Floors	G+2		
5	Number of Basements	1		
6	Type of Building	Commercial		
7	Approximate Height	9m		
8	Approximate Area	Not Known		
9	Age of Building	200 years		
10	Type of Structure	Load Bearing Structure		
11	Type of Foundation	Not Known		
12	Number of Bore Wells	None		
13	Depth and Diameter of Bore	N.A		
14	Roadways	One Side		
15	Presence of Equipment/Machines	None		







# JAIPUR METRO Jaipur Metro Rail Corporation

	Summary of Cracks					
Defect ID	Location	Orientation	Appx. Width (mm)	Appx. Length (m)	Category	Photo No.
1	Wall No. 4 Store First Floor	Inclined	0.5	0.7	Very Slight	7, 7A
2	Wall No. 4 Room No. 4 Lohia Institute, First Floor	Inclined	0.3	2.6	Very Slight	8, 8A
3	Wall No. 4 Room No. 5 Lohia Institute, First Floor	Inclined	0.4	1.5	Very Slight	9, 9A
4	Wall No. 3 & Roof Hall No. 1 Lohia Institute, First Floor	Inclined	0.15	4	Very Slight	10, 10A
5	Roof Hall No. 1 Lohia Institute, First Floor	Inclined	1	1.5	Slight	11
6	Wall No. 2 Staircase FF to SF	Inclined	0.4	2	Very Slight	12, 12A
7	Wall No. 2 Staircase FF to SF	Inclined	2	1.4	Slight	13, 13A
8	Wall No. 1 Hall No. 1 Lohia Institute, Second Floor	Inclined	2.5	1.7	Slight	14, 14A
9	Front Wall Lohia Institute Ground Floor	Inclined	0.35	2.1	Very Slight	15, 15A
10	Front Wall Lohia Institute Ground Floor	Inclined	0.35	1.9	Very Slight	16
11	Front Wall Lohia Institute Ground Floor	Inclined	0.35	1	Very Slight	17
12	Front Wall Lohia Institute Ground Floor	Inclined	0.5	0.6	Very Slight	18, 18A
13	Front Wall Lohia Institute Ground Floor	Inclined	0.6	1.5	Very Slight	19, 19A
14	Leftside Outer Wall Lohia Institute Ground Floor	Inclined	1.5	0.5	Slight	20, 20A
15	Leftside Outer Wall Lohia Institute Ground Floor	Inclined	3	0.8	Slight	21
16	Leftside Outer Wall Lohia Institute Ground Floor	Inclined	5	1.2	Moderate	22

Summary of Defects Other Than Crack			
Defect ID	Location	Description	Photo No.
17	Wall No. 1 Part A of Shop no.10 Ground Floor	Dampness/Seepage	23
18	Wall No. 4 Room No. 1 Lohia Institute, First Floor	Peeling of Plaster	24
19	Roof Room No. 1 Lohia Institute, First Floor	Peeling of Plaster	25
20	Wall No. 3 Room No. 1 Lohia Institute, First Floor	Peeling of Plaster	26
21	Wall No. 2 Room No. 2 Lohia Institute, First Floor	Dampness/Seepage	27
22	Wall No. 1 Lobby First Floor	Peeling of Plaster	28
23	Wall No. 2 Lobby First Floor	Peeling of Plaster	29
24	Wall No. 2 Lobby First Floor	Peeling of Plaster	30
25	Wall No. 5 Lobby First Floor	Dampness/Seepage	31
26	Wall No. 4 Lobby First Floor	Peeling of Plaster	32
27	Roof Store First Floor	Dampness/Seepage	33
28	Wall No. 4 Store First Floor	Dampness/Seepage	34
29	Wall No. 3 Store First Floor	Peeling of Plaster	35
30	All Walls & Roof Room No. 4 Lohia Institute, First Floor	Dampness/Seepage	36
31	Wall No. 3 Lobby First Floor	Peeling of Plaster	37
32	Wall No. 1 Room No. 5 Lohia Institute, First Floor	Peeling of Plaster	38
33	Wall No. 3 Room No. 5 Lohia Institute, First Floor	Peeling of Plaster	39
34	Wall No. 2 Room No. 5 Lohia Institute, First Floor	Peeling of Plaster	40
35	Steps Staircase Area First Floor	Damaged Portion	41
36	Floor Hall No. 1 Lohia Institute, First Floor	Damaged Portion	42
37	Floor Hall No. 1 Lohia Institute, First Floor	Damaged Portion	43
38	Wall No. 2 Hall No. 1 Lohia Institute, First Floor	Peeling of Plaster	44

39	Wall No. 3 & Roof Hall No. 1 Lohia Institute, First Floor	Dampness/Seepage	45
40	Wall No. 1 Hall No. 1 Lohia Institute, First Floor	Damaged Portion	46
41	Wall No. 1 Hall No. 1 Lohia Institute, First Floor	Damaged Portion	47
42	Wall No. 4 Hall No. 1 Lohia Institute, First Floor	Damaged Portion	48
43	Wall No. 4 Hall No. 1 Lohia Institute, First Floor	Damaged Portion	49
44	Wall No. 1 Hall No. 1 Lohia Institute, Second Flloor	Damaged Portion	50
45	Floor Hall No. 2 Lohia Institute, Second Flloor	Damaged Portion	51
46	Front Wall Lohia Institute Ground Floor	Damaged Portion	52
47	Front Wall Lohia Institute Ground Floor	Damaged Portion	53
48	Leftside Outer Wall Lohia Institute Ground Floor	Peeling of Plaster	54

Summary of Areas that Could not be Surveyed				
Serial No.	Location	Description	Photo No.	
1	Shop No.9 Ground Floor	View of Locked Shop	55	
2	Wall No. 4 Room No. 3 Lohia Institute, First Floor	Covered With Books	56	
3	Wall No. 2 Room No. 1 Lohia Institute, First Floor	Covered With Books & wooden Almira	57	
4	Roof Lobby First Floor	View of Tinshed Roof	58	
5	All Walls Toilet No. 1 Second Floor	Half Covered With Tiles	59	







Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



Photo 1 View of shop No.10



Photo 2 View of Part B of Shop, Ground Floor



Photo 3 View of Part A of Shop, Ground Floor



Photo 5 Covered With TinShed, Lohia Institute, Second Flloor





Photo 4 Covered With TinShed, Lohia Institute, Second Flloor



Photo 6 Covered With TinShed, Second Flloor



JAIPUR METRO

#### **Jaipur Metro Rail Corporation**

Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



Photo 7 Inclined Crack on Wall No. 4 of Store, First Floor, Approx. Width = 0.5mm, Approx. Length = 0.7m. Distance from Wall No. 1 = 0.3m, Height from Floor = 1.7m.





Photo 7A Inclined Crack on Wall No. 4 of Store, First Floor, Approx. Width = 0.5mm, Approx. Length = 0.7m. Distance from Wall No. 1 = 0.3m, Height from Floor = 1.7m.



Photo 8A

Approx. Width = 0.3mm, Approx. Length = 2.6m.


Distance from Wall No. 1 = 1.4m, Height from Floor = 0m.

Photo 8 Inclined Crack on Wall No. 4 of Room No. 4, Lohia Institute, First Floor, Inclined Crack on Wall No. 4 of Room No. 4, Lohia Institute, First Floor, Approx. Width = 0.3mm, Approx. Length = 2.6m. Distance from Wall No. 1 = 1.4m, Height from Floor = 0m.



Photo 9 Inclined Crack on Wall No. 4 of Room No. 5, Lohia Institute, First Floor, Inclined Crack on Wall No. 4 of Room No. 5, Lohia Institute, First Floor, Approx. Width = 0.4mm, Approx. Length = 1.5m. Distance from Wall no. 1 = 2m, Height from Floor = 0.2m.

Photo 9A





Aimil Ltd. Instrumentation & Technologies

Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



JAIPUR METRO

Photo 10 Inclined Crack on Wall No. 3 & Roof of Hall No. 1, Lohia Institute, First Floor, Approx. Width = 0.15mm, Approx. Length = 4m. Distance from Wall No.2 = 1.7m, Height from Floor = 1m.



Photo 11 Inclined Crack on Roof of Hall No. 1, Lohia Institute, First Floor, Approx. Width = 1mm, Approx. Length = 1.5m. Distance from Wall No.3 = 0.7m, Height from Floor = 3.5m.



Photo 12A Inclined Crack on Wall No. 2 of Staircase FF to SF, Approx. Width = 0.4mm, Approx. Length = 2m. Distance from Wall No.3 = 0.4m, Height from Floor = 1.8m.





Photo 10A Inclined Crack on Wall No. 3 & Roof of Hall No. 1, Lohia Institute, First Floor, Approx. Width = 0.15mm, Approx. Length = 4m. Distance from Wall No.2 = 1.7m, Height from Floor = 1m.



Photo 12 Inclined Crack on Wall No. 2 of Staircase FF to SF, Second Floor, Approx. Width = 0.4mm, Approx. Length = 2m. Distance from Wall No.3 = 0.4m, Height from Floor = 1.8m.



<u>Photo 1</u>3

Inclined Crack on Wall No. 2 of Staircase FF to SF, Approx. Width = 2mm, Approx. Length = 1.4m. Distance from Wall No.4 = 0.1m, Height from Floor = 0.2m.







Photo 13A Inclined Crack on Wall No. 2 of Staircase FF to SF, Approx. Width = 2mm, Approx. Length = 1.4m. Distance from Wall No. 4 = 0.1m, Height from Floor = 0.2m.



Photo 14A Inclined Crack on Wall No. 1 of Hall No. 1, Lohia Institute, Second Floor, Approx. Width = 2.5mm, Approx. Length = 1.7m. Distance from Wall No.3 = 2.5m, Height from Floor = 0m.



Photo 15A Inclined Crack on Front Wall of Lohia Institute, Ground Floor, Approx. Width = 0.35mm, Approx. Length = 2.1m. Distance from Rightside Outer Wall = 2.6m, Height from Floor = 0m.





Photo 14 Inclined Crack on Wall No. 1 of Hall No. 1, Lohia Institute, Second Floor, Approx. Width = 2.5mm, Approx. Length = 1.7m. Distance from Wall No.3 = 2.5m, Height from Floor = 0m.



Photo 15 Inclined Crack on Front Wall of Lohia Institute, Ground Floor, Approx. Width = 0.35mm, Approx. Length = 2.1m. Distance from Rightside Outer Wall = 2.6m, Height from Floor = 0m.



Photo 16 Inclined Crack on Front Wall of Lohia Institute, Ground Floor, Approx. Width = 0.35mm, Approx. Length = 1.9m. Distance from Rightside Outer Wall = 3.8m, Height from Floor = 2m.



#### **Jaipur Metro Rail Corporation**

Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



<u>Photo 1</u>7

Inclined Crack on Front Wall of Lohia Institute, Ground Floor, Approx. Width = 0.35mm, Approx. Length = 1m.

Distance from Rightside Outer Wall = 6m, Height from Floor = 1.9m.





Photo 18 Inclined Crack on Front Wall of Lohia Institute, Ground Floor, Approx. Width = 0.5mm, Approx. Length = 0.6m. Distance from Rightside Outer Wall = 9m, Height from Floor = 2m.



Photo 18A Inclined Crack on Front Wall of Lohia Institute, Ground Floor, Approx. Width = 0.5mm, Approx. Length = 0.6m. Distance from Rightside Outer Wall = 9m, Height from Floor = 2m.



Photo 19A Inclined Crack on Front Wall of Lohia Institute, Ground Floor, Approx. Width = 0.6mm, Approx. Length = 1.5m. Distance from Rightside Outer Wall = 6.5m, Height from Floor = 1.5m.



Photo 19 Inclined Crack on Front Wall of Lohia Institute, Ground Floor, Approx. Width = 0.6mm, Approx. Length = 1.5m. Distance from Rightside Outer Wall = 6.5m, Height from Floor = 1.5m.



Photo 20 Inclined Crack on Leftside Outer Wall of Lohia Institute, Ground Floor, Approx. Width = 1.5mm, Approx. Length = 0.5m. Distance from front side wall = 1.7m, Height from Floor = 0.4m.





Pre - Condition Building Survey for Construction of Underground Stations from Chandpole to Bari Chouper and reversal line



Photo 20A Inclined Crack on Leftside Outer Wall of Lohia Institute, Ground Floor, Approx. Width = 1.5mm, Approx. Length = 0.5m. Distance from front side wall = 1.7m, Height from Floor = 0.4m.



Photo 22 Inclined Crack on Leftside Outer Wall of Lohia Institute, Ground Floor, Approx. Width = 5mm, Approx. Length = 1.2m. Distance from front side wall = 3.4m, Height from Floor = 2.9m.



Photo 24 Peeling of Plaster on Wall No. 4 of Room No. 1 of Lohia Institute, First Floor





Photo 21 Inclined Crack on Leftside Outer Wall of Lohia Institute, Ground Floor Approx. Width = 3mm, Approx. Length = 0.8m. Distance from front side






Photo 23 Dampness/Seepage on Wall No. 1 of Part A of Shop no.10 of Ground Floor



Photo 25 Peeling of Plaster on Roof of Room No. 1 of Lohia Institute, First Floor







Photo 26 Peeling of Plaster on Wall No. 3 of Room No. 1 of Lohia Institute, First Floor



Photo 27 Dampness/Seepage on Wall No. 2 of Room No. 2 of Lohia Institute, First Floor





Photo 28 Peeling of Plaster on Wall No. 1 of Lobby of First Floor



Photo 30 Peeling of Plaster on Wall No. 2 of Lobby of First Floor



Photo 29 Peeling of Plaster on Wall No. 2 of Lobby of First Floor



Photo 31 Dampness/Seepage on Wall No. 5 of Lobby of First Floor







Photo 32 Peeling of Plaster on Wall No. 4 of Lobby of First Floor



Photo 33 Dampness/Seepage on Roof of Store of First Floor



Photo 34 Dampness/Seepage on Wall No. 4 of Store of First Floor



Photo 36 Dampness/Seepage on All Walls & Roof of Room No. 4 of Lohia Institute, First Floor





Photo 35 Peeling of Plaster on Wall No. 3 of Store of First Floor



Photo 37 Peeling of Plaster on Wall No. 3 of Lobby of First Floor









Photo 38 Peeling of Plaster on Wall No. 1 of Room No. 5 of Lohia Institute, First Peeling of Plaster on Wall No. 3 of Room No. 5 of Lohia Institute, First Floor

Photo 39 Floor





<u>Photo 4</u>0 Peeling of Plaster on Wall No. 2 of Room No. 5 of Lohia Institute, First Floor

Photo 41 Damaged Portion on Steps of Staircase Area of First Floor



2013 11:25

Photo 42 Damaged Portion on Floor of Hall No. 1 of Lohia Institute, First Floor












Photo 44 Peeling of Plaster on Wall No. 2 of Hall No. 1 of Lohia Institute, First Floor



Photo 45 Dampness/Seepage on Wall No. 3 & Roof of Hall No. 1 of Lohia Institute, First Floor





Photo 46 Damaged Portion on Wall No. 1 of Hall No. 1 of Lohia Institute, First Floor





Photo 48 Damaged Portion on Wall No. 4 of Hall No. 1 of Lohia Institute, First Floor





Photo 49 Damaged Portion on Wall No. 4 of Hall No. 1 of Lohia Institute, First Floor









Photo 50 Damaged Portion on Wall No. 1 of Hall No. 1 of Lohia Institute, Second Filoor Photo 51 Damaged Portion on Floor of Hall No. 2 of Lohia Institute, Second Floor





Photo 52 Damaged Portion on Front Wall of Lohia Institute of Ground Floor



Photo 54 Peeling of Plaster on Leftside Outer Wall of Lohia Institute of Ground Floor



Photo 53 Damaged Portion on Front Wall of Lohia Institute of Ground Floor



Photo 55 Shop No.9 of Ground Floor Locked







Photo 56 Wall No. 4 of Room No. 3 of Lohia Institute, First Floor Covered With Books



Photo 57 Wall No. 2 of Room No. 1 of Lohia Institute, First Floor Covered With Books & wooden Almira



Photo 58 Roof of Lobby of First Floor View of Tinshed Roof



Photo 59 All Walls of Toilet No. 1 of Second Floor Half Covered With Tiles



# JAIPUR METRO Jaipur Metro Rail Corporation

Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Shop No. 1-8 Choti Chopar Jaipur Unique ID: CC 0016

Report Number: AIMIL/ESG/JMCEC/CC 0016/01, Rev. 00, Dated: December 2013

Building Owner Contractor Various Owners CEC Client Sub-Contractor JMRC Limited AIMIL Limited







# JAIPUR METRO Jaipur Metro Rail Corporation

Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

	Table of Contents			
S.No.	Particulars	Page No.		
1	Introduction	2		
2	Survey Details	2		
3	About the Structure	3		
4	Building Ownership Details	3		
5	Project Details	4		
6	General Building Details	4		
7	Summary of Cracks	5		
8	Summary of Defects other than Cracks			
9	Summary of Areas that Could not be surveyed			
10	Defect Photographs			
11	Schematic Diagram of Building			

Introduction

The Jaipur Metro Rail is being constructed to provide the city of Jaipur with a modern and technologically advanced Transit System, to provide a safe and well connected means of transport that reduces traffic congestion. The project consists of two corridors with underground and elevated sections.

The construction of underground rail and road infrastructures in metropolitan and cosmopolitan cities are mostly through developed area under challenging soil conditions.

The alignment of structure is passing through densely inhabitated areas, many structures are falling in the zone of influence of construction activities. It is required to carry out the pre-condition survey of those structures. The scope of work of this survey includes carrying out pre-condition survey of those structures.

	Survey Details				
S.No.	Head	Particulars	Signatures		
1	Date of Survey	09/12/2013			
2	AIMIL Representative				
3	CEC Representative				
4	Structural Designer of CEC				
5	JMRC/DMRC Representative				







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

About the Structure

The structure under consideration is a Multi Story Load Bearing Structure having 3 floors. The structure was constructed in year 1813 and is 200 years old.

There are 24 defects in the structure out of which 7 are cracks. Category wise distribution of cracks is given in the table below. Overall the Building can be categorised in Category III (Moderate)

Category	Number of Cracks	% of Total Cracks
Negligible (< 0.1mm)	0	0%
Very Slight (0.1 to 1mm)	4	57.14%
Slight (1 to 5mm)	2	28.57%
Moderate (5 to 15mm)	1	14.29%
Severe (15 to 25mm)	0	0%
Very Severe (>25mm)	0	0%

The average width of cracks is 1.59mm and average length of cracks is 1.99m. The maximum crack width is 5mm and minimum width is 0.15mm.

	Building Ownership Details			
Unique ID/Sub ID	Premises Name	Owner	Signatures	
CC/0016/001	Rameshwarlal Bhaurilal Modi		Done	
CC/0016/003	Tulsidas Jindaram		Done	
CC/0016/004	Ram Narayan Modi		Done	
CC/0016/006A	Raghu Nath		Done	
CC/0016/007	Maliram Falod & Co.		Done	
CC/0016/008	Suresh Kumar & Co.		Done	







Project Deta	ails	
S. No.	Head	Particulars
1	Project	Jaipur Metro Rail Project
2	Section	Chandpole to Bari Chaupar
3	Client	JMRC Limited
4	Consultant	DMRC Limited
5	Contractor	CEC
6	Design Consultant of Contractor	Omikron Kappa - Indus Consultrans JV
7	Sub-Contractor	AIMIL Limited
8	Subject	Pre-Condition Survey Report
General Buil	lding Details (As informed verbally by Building Ow	vner)
S. No.	Head	Particulars
1	Building Name	Shop No. 1-8
2	Building Address	Shop No. 1-8 Choti Chopar Jaipur
3	Year of Construction	1813

I	Ballaing Name	
2	Building Address	Shop No. 1-8 Choti Chopar Jaipur
3	Year of Construction	1813
4	Number of Floors	G+2
5	Number of Basements	None
6	Type of Building	Commercial
7	Approximate Height	9m
8	Approximate Area	Not Known
9	Age of Building	200 years
10	Type of Structure	Load Bearing Structure
11	Type of Foundation	Not Known
12	Number of Bore Wells	None
13	Depth and Diameter of Bore	N.A
14	Roadways	One Side
15	Presence of Equipment/Machines	None







	Summary of Cracks					
Defect ID	Location	Orientation	Appx. Width (mm)	Appx. Length (m)	Category	Photo No.
1	Outer Leftside Wall Shop no.1 Ground Floor	Vertical	5	2	Moderate	7
2	Outerwall Shop no.1 Ground Floor	Horizontal	2.5	2.1	Slight	8
3	Left Side Wall Varanda of Shop no.1 Ground Floor	Horizontal	2.5	2	Slight	9
4	Roof Varanda of Shop no.1 Ground Floor	Horizontal	0.4	2	Very Slight	10
5	Roof Varanda of Shop No.4 Ground Floor	Horizontal	0.15	2	Very Slight	11
6	Roof Varanda of Shop No.4 Ground Floor	Horizontal	0.2	1.2	Very Slight	12
7	Roof Varanda of Shop No.8 Ground Floor	Horizontal	0.35	2.6	Very Slight	13

	Summary of Defects Other Than Crack				
Defect ID	Location	Description	Photo No.		
8	Outer Rightside Wall Shop no.1 Ground Floor	Peeling of Plaster	14		
9	Roof & External Beam Varanda of Shop no.1 Ground Floor	Dampness/Seepage	15		
10	Outerwall & Right Side External Column Varanda of Shop no.1 Ground Floor	Peeling of Plaster	16		
11	Roof Varanda of Shop No.4 Ground Floor	Peeling of Plaster	17		
12	Outer wall Right Side Varanda of Shop No.4 Ground Floor	Peeling of Plaster	18		
13	External Beam Varanda of Shop No.4 Ground Floor	Dampness/Seepage	19		
14	Roof Varanda of Shop No.4 Ground Floor	Peeling of Plaster	20		
15	Wall No. 1 Part B Shop no.6A Ground Floor	Peeling of Plaster	21		
16	Roof Part A Shop no.6A Ground Floor	Dampness/Seepage	22		
17	Roof Part B Shop no.6A Ground Floor	Peeling of Plaster	23		
18	Roof Varanda of shop no.6A Ground Floor	Dampness/Seepage	24		
19	External Beam Varanda of shop no.6A Ground Floor	Dampness/Seepage	25		
20	Roof Varanda of Shop No.7 Ground Floor	Peeling of Plaster	26		
21	External Beam Varanda of Shop No.8 Ground Floor	Dampness/Seepage	27		
22	Roof Varanda of Shop No.8 Ground Floor	Dampness/Seepage	28		
23	Leftside External Column Varanda of Shop No.8 Ground Floor	Damaged Portion	29		
24	Roof Shop No.8 Ground Floor	Peeling of Plaster	30		

	Summary of Areas that Could not be Surveyed				
Serial No.	Location	Description	Photo No.		
1	All Walls Shop no.1 Ground Floor	Covered With Wooden Work & Material	31		
2	Shop No.2 Ground Floor	Locked	32		
3	All Walls Shop No.3 Ground Floor	Covered with Material	33		
4	All Walls Shop No.4 Ground Floor	Covered with Material & wooden Works	34		
5	Wall No. 2 Part A Shop no.6A Ground Floor	Covered With material	35		
6	All Walls Part B Shop no.6A Ground Floor	Covered with Material & wooden Works	36		
7	Shop no.6B Ground Floor	locked	37		

8	All Walls Shop No.7 Ground Floor	Covered with Material & wooden Works	38
9	Roof Shop No.7 Ground Floor	Covered with Falls Celling	39
10	All Walls Shop No.8 Ground Floor	Covered with Material & wooden Works	40







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



#### Photo 1 View of Shop



Photo 2 View of Shop No.3, Ground Floor



Photo 3 View of Shop No.4, Ground Floor



Photo 5 View of Shop No.7, Ground Floor





Photo 4 View of Shop No.6A raghunath Das, Ground Floor



Photo 6 View of shop No.8, Ground Floor





Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Photo 7 Vertical Crack on Outer Leftside Wall of Shop no.1, Ground Floor, Approx. Width = 5mm, Approx. Length = 2m. Distance from Leftside Wall = 0.4m, Height from Floor = 0m.



#### Photo 9

Horizontal Crack on Left Side Wall of Varanda of Shop no.1, Ground Floor, Approx. Width = 2.5mm, Approx. Length = 2m. Distance from Backside of left side External Column = 0m, Height from



Photo 11 Horizontal Crack on Roof of Varanda of Shop No.4, Ground Floor, Approx. Width = 0.15mm, Approx. Length = 2m. Distance from Backside Leftside External Column = 0m, Height from





Photo 8 Horizontal Crack on Outerwall of Shop no.1, Ground Floor, Approx. Width = 2.5mm, Approx. Length = 2.1m. Distance from Leftside Wall = 0m, Height from Floor = 2m.



Photo 10 Horizontal Crack on Roof of Varanda of Shop no.1, Ground Floor, Approx. Width = 0.4mm, Approx. Length = 2m. Distance from Backside of Right side External Column = 0m, Height



Photo 12 Horizontal Crack on Roof of Varanda of Shop No.4, Ground Floor, Approx. Width = 0.2mm, Approx. Length = 1.2m. Distance from Right Side External Column = 1.5m, Height from Floor =







Photo 13 Horizontal Crack on Roof of Varanda of Shop No.8, Ground Floor, Approx. Width = 0.35mm, Approx. Length = 2.6m. Distance from Backside Leftside External Column = 0m, Height from



Photo 14 Peeling of Plaster on Outer Rightside Wall of Shop no.1 of Ground Floor





Photo 15 Dampness/Seepage on Roof & External Beam of Varanda of Shop no.1 of Ground Floor

Photo 16 Peeling of Plaster on Outerwall & Right Side External Column of Varanda of Shop no.1 of Ground Floor



Photo 17 Peeling of Plaster on Roof of Varanda of Shop No.4 of Ground Floor



Photo 18 Peeling of Plaster on Outer wall Right Side of Varanda of Shop No.4 of Ground Floor









Photo 19 Dampness/Seepage on External Beam of Varanda of Shop No.4 of Ground Floor



Photo 20 Peeling of Plaster on Roof of Varanda of Shop No.4 of Ground Floor





Photo 21 Peeling of Plaster on Wall No. 1 of Part B Shop no.6A of Ground Floor








Photo 23 Peeling of Plaster on Roof of Part B Shop no.6A of Ground Floor











Photo 25 Dampness/Seepage on External Beam of Varanda of shop no.6A of Ground Floor



Photo 26 Peeling of Plaster on Roof of Varanda of Shop No.7 of Ground Floor



Photo 27 Dampness/Seepage on External Beam of Varanda of Shop No.8 of Ground Floor



Photo 28 Dampness/Seepage on Roof of Varanda of Shop No.8 of Ground Floor



Photo 29 Damaged Portion on Leftside External Column of Varanda of Shop No.8 of Ground Floor



Photo 30 Peeling of Plaster on Roof of Shop No.8 of Ground Floor









Photo 31 All Walls of Shop no.1 of Ground Floor Covered With Wooden Work & Material



Photo 32 Shop No.2 of Ground Floor Locked





Photo 33 All Walls of Shop No.3 of Ground Floor Covered with Material



Photo 34 All Walls of Shop No.4 of Ground Floor Covered with Material & wooden Works



Photo 35 Wall No. 2 of Part A Shop no.6A of Ground Floor Covered With material & All Walls of Part B Shop no.6A of Ground Floor Covered with Material & wooden Works









Photo 37 Shop no.6B of Ground Floor locked



Photo 38 All Walls of Shop No.7 of Ground Floor Covered with Material & wooden Works



Photo 39 Roof of Shop No.7 of Ground Floor Covered with Falls Celling



Photo 40 All Walls of Shop No.8 of Ground Floor Covered with Material & wooden Works







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Shri Mahadev Mandir Sadhu Singh Dalal Sanghori Bazaar, Choti Chopar Jaipur Unique ID: CC 0017

Report Number: AIMIL/ESG/JMCEC/CC 0017/01, Rev. 00, Dated: January 2014

Building Owner Contractor Mr. Durga Shankar CEC Client Sub-Contractor JMRC Limited AIMIL Limited







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

	Table of Contents			
S.No.	Particulars	Page No.		
1	Introduction	2		
2	Survey Details	2		
3	About the Structure	3		
4	Building Ownership Details	3		
5	Project Details	4		
6	General Building Details	4		
7	Summary of Cracks	5		
8	Summary of Defects other than Cracks			
9	Summary of Areas that Could not be surveyed			
10	Defect Photographs			
11	Schematic Diagram of Building			

Introduction

The Jaipur Metro Rail is being constructed to provide the city of Jaipur with a modern and technologically advanced Transit System, to provide a safe and well connected means of transport that reduces traffic congestion. The project consists of two corridors with underground and elevated sections.

The construction of underground rail and road infrastructures in metropolitan and cosmopolitan cities are mostly through developed area under challenging soil conditions.

The alignment of structure is passing through densely inhabitated areas, many structures are falling in the zone of influence of construction activities. It is required to carry out the pre-condition survey of those structures. The scope of work of this survey includes carrying out pre-condition survey of those structures.

	Survey Details				
S.No.	Head	Particulars	Signatures		
1	Date of Survey	19/12/2013			
2	AIMIL Representative				
3	CEC Representative				
4	Structural Designer of CEC				
5	JMRC/DMRC Representative				







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

#### About the Structure

The structure under consideration is a Single Story Load Bearing Structure . The structure was constructed in year 1767 and is 246 years old.

There are 0 defects in the structure out of which 0 are cracks. Category wise distribution of cracks is given in the table below. Overall the Building can be categorised in Category 0 (Negligible)

Category	Number of Cracks	% of Total Cracks
Negligible (< 0.1mm)	0	0%
Very Slight (0.1 to 1mm)	0	0%
Slight (1 to 5mm)	0	0%
Moderate (5 to 15mm)	0	0%
Severe (15 to 25mm)	0	0%
Very Severe (>25mm)	0	0%

Building Ownership Details				
Unique ID/Sub ID	Premises Name	Owner	Signatures	
CC/0017	Shri Mahadev Mandir			







Project Deta	Project Details				
S. No.	Head	Particulars			
1	Project	Jaipur Metro Rail Project			
2	Section	Chandpole to Bari Chaupar			
3	Client	JMRC Limited			
4	Consultant	DMRC Limited			
5	Contractor	CEC			
6	Design Consultant of Contractor	Omikron Kappa - Indus Consultrans JV			
7	Sub-Contractor	AIMIL Limited			
8	Subject	Pre-Condition Survey Report			

General Building Details (As informed verbally by Building Owner)					
S. No.	Head	Particulars			
1	Building Name	Shri Mahadev Mandir			
2	Building Address	Shri Mahadev Mandir Sadhu Singh Dalal Sanghori Bazaar, Choti Chopar Jaipur			
3	Year of Construction	1767			
4	Number of Floors	G			
5	Number of Basements	None			
6	Type of Building	Commercial			
7	Approximate Height	3 m			
8	Approximate Area	Not Known			
9	Age of Building	246 years			
10	Type of Structure	Load Bearing Structure			
11	Type of Foundation	Not Known			
12	Number of Bore Wells	None			
13	Depth and Diameter of Bore	N.A			
14	Roadways	One Side			
15	Presence of Equipment/Machines	None			







	Summary of Cracks					
Defect ID	Location	Orientation	Appx. Width (mm)	Appx. Length (m)	Category	Photo No.
Summary of Defects Other Than Crack						
Defect ID	Location	Description		Photo No.		
Summary of Areas that Could not be Surveyed						
Serial No.	Location	Description Ph			Photo No.	
1	All Walls	Covered with	Marble			2







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line




Photo 1



Photo 2 All Walls of Covered with Marble



Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Shri Rojgareshwar Mahadev Mandir Sadhu Singh Dalal Sanghori Bazaar, Choti Chopar Jaipur Unique ID: CC 0018

Report Number: AIMIL/ESG/JMCEC/CC 0018/01, Rev. 00, Dated: January 2014

Building Owner Contractor Mr. A. K Sharma CEC Client Sub-Contractor JMRC Limited AIMIL Limited







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

	Table of Contents			
S.No.	Particulars	Page No.		
1	Introduction	2		
2	Survey Details	2		
3	About the Structure	3		
4	Building Ownership Details	3		
5	Project Details	4		
6	General Building Details	4		
7	Summary of Cracks	5		
8	Summary of Defects other than Cracks			
9	Summary of Areas that Could not be surveyed			
10	Defect Photographs			
11	Schematic Diagram of Building			

Introduction

The Jaipur Metro Rail is being constructed to provide the city of Jaipur with a modern and technologically advanced Transit System, to provide a safe and well connected means of transport that reduces traffic congestion. The project consists of two corridors with underground and elevated sections.

The construction of underground rail and road infrastructures in metropolitan and cosmopolitan cities are mostly through developed area under challenging soil conditions.

The alignment of structure is passing through densely inhabitated areas, many structures are falling in the zone of influence of construction activities. It is required to carry out the pre-condition survey of those structures. The scope of work of this survey includes carrying out pre-condition survey of those structures.

	Survey Details			
S.No.	Head	Particulars	Signatures	
1	Date of Survey	19/12/2013		
2	AIMIL Representative			
3	CEC Representative			
4	Structural Designer of CEC			
5	JMRC/DMRC Representative			







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

#### About the Structure

The structure under consideration is a Single Story Load Bearing Structure . The structure was constructed in year 1800 and is 213 years old.

There are 1 defects in the structure out of which 0 are cracks. Category wise distribution of cracks is given in the table below. Overall the Building can be categorised in Category 0 (Negligible)

Category	Number of Cracks	% of Total Cracks
Negligible (< 0.1mm)	0	0%
Very Slight (0.1 to 1mm)	0	0%
Slight (1 to 5mm)	0	0%
Moderate (5 to 15mm)	0	0%
Severe (15 to 25mm)	0	0%
Very Severe (>25mm)	0	0%

Building Ownership Details			
Unique ID/Sub ID	Premises Name	Owner	Signatures
CC/0018	Shri Rojgareshwar Mahadev Mandir		







Project Deta	Project Details				
S. No.	Head	Particulars			
1	Project	Jaipur Metro Rail Project			
2	Section	Chandpole to Bari Chaupar			
3	Client	JMRC Limited			
4	Consultant	DMRC Limited			
5	Contractor	CEC			
6	Design Consultant of Contractor	Omikron Kappa - Indus Consultrans JV			
7	Sub-Contractor	AIMIL Limited			
8	Subject	Pre-Condition Survey Report			

S. No.	Head	Particulars
1	Building Name	Shri Rojgareshwar Mahadev Mandir
2	Building Address	Shri Rojgareshwar Mahadev Mandir Sadhu Singh Dalal Sanghori Bazaar, Choti Chopar Jaipur
3	Year of Construction	1800
4	Number of Floors	G
5	Number of Basements	None
6	Type of Building	Commercial
7	Approximate Height	3 m
8	Approximate Area	Not Known
9	Age of Building	213 years
10	Type of Structure	Load Bearing Structure
11	Type of Foundation	Not Known
12	Number of Bore Wells	None
13	Depth and Diameter of Bore	N.A
14	Roadways	All Side
15	Presence of Equipment/Machines	None







Defect ID	Location	Orientation	Appx. Width (mm)	Appx. Length (m)	Category	Photo No.
Summary of Defects Other Than Crack						
Defect ID Location Description Photo			Photo No.			
1 Roof Shri Rojgareshwar Mandir Ground Floor Peeling of Plaster				4		

Summary of Areas that Could not be Surveyed				
Serial No.	Location	Description	Photo No.	









Photo 1 View of Rojgareshwar Mandir



Photo 2 View of Rojgareshwar Mandir, Ground Floor



Photo 3 Side View of Rojgareshwar mandir, Ground Floor



Photo 4 Peeling of Plaster on Roof of Shri Rojgareshwar Mandir of Ground Floor



Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Barahling Mahadev Temple Sadhu Singh Dalal Sanghori Bazaar, Choti Chopar Jaipur Unique ID: CC 0019

Report Number: AIMIL/ESG/JMCEC/CC 0019/01, Rev. 00, Dated: January 2014

Building Owner Contractor Mr. Kamlesh CEC Client Sub-Contractor JMRC Limited AIMIL Limited







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

	Table of Contents			
S.No.	Particulars	Page No.		
1	Introduction	2		
2	Survey Details	2		
3	About the Structure	3		
4	Building Ownership Details	3		
5	Project Details	4		
6	General Building Details	4		
7	Summary of Cracks	5		
8	Summary of Defects other than Cracks			
9	Summary of Areas that Could not be surveyed			
10	Defect Photographs			
11	Schematic Diagram of Building			

Introduction

The Jaipur Metro Rail is being constructed to provide the city of Jaipur with a modern and technologically advanced Transit System, to provide a safe and well connected means of transport that reduces traffic congestion. The project consists of two corridors with underground and elevated sections.

The construction of underground rail and road infrastructures in metropolitan and cosmopolitan cities are mostly through developed area under challenging soil conditions.

The alignment of structure is passing through densely inhabitated areas, many structures are falling in the zone of influence of construction activities. It is required to carry out the pre-condition survey of those structures. The scope of work of this survey includes carrying out pre-condition survey of those structures.

	Survey Details			
S.No.	Head	Particulars	Signatures	
1	Date of Survey	19/12/2013		
2	AIMIL Representative			
3	CEC Representative			
4	Structural Designer of CEC			
5	JMRC/DMRC Representative			







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

#### About the Structure

The structure under consideration is a Single Story Load Bearing Structure . The structure was constructed in year 1960 and is 53 years old.

There are 4 defects in the structure out of which 0 are cracks. Category wise distribution of cracks is given in the table below. Overall the Building can be categorised in Category 0 (Negligible)

Category	Number of Cracks	% of Total Cracks
Negligible (< 0.1mm)	0	0%
Very Slight (0.1 to 1mm)	0	0%
Slight (1 to 5mm)	0	0%
Moderate (5 to 15mm)	0	0%
Severe (15 to 25mm)	0	0%
Very Severe (>25mm)	0	0%

Building Ownership Details				
Unique ID/Sub ID	Premises Name	Owner	Signatures	
CC/0019	Barahling Mahadev Temple			







Project Deta	Project Details			
S. No.	Head	Particulars		
1	Project	Jaipur Metro Rail Project		
2	Section	Chandpole to Bari Chaupar		
3	Client	JMRC Limited		
4	Consultant	DMRC Limited		
5	Contractor	CEC		
6	Design Consultant of Contractor	Omikron Kappa - Indus Consultrans JV		
7	Sub-Contractor	AIMIL Limited		
8	Subject	Pre-Condition Survey Report		

S. No.	Head	Particulars
1	Building Name	Barahling Mahadev Temple
2	Building Address	Barahling Mahadev Temple Sadhu Singh Dalal Sanghori Bazaar, Chot Chopar Jaipur
3	Year of Construction	1960
4	Number of Floors	G
5	Number of Basements	None
6	Type of Building	Commercial
7	Approximate Height	3 m
8	Approximate Area	Not Known
9	Age of Building	53 years
10	Type of Structure	Load Bearing Structure
11	Type of Foundation	Not Known
12	Number of Bore Wells	None
13	Depth and Diameter of Bore	N.A
14	Roadways	All Side
15	Presence of Equipment/Machines	None







	Summary of Cracks					
Defect ID	Location	Orientation	Appx. Width (mm)	Appx. Length (m)	Category	Photo No.
	Summary of Defects Other Than Crack					
Defect ID	Location		Desc	ription		Photo No.
1	Wall No. Floor Barahling Temple Ground Floor	Plaster Crack				2
2 Leftside Wall Barahling Temple Ground Floor Plaster Crack				3		
3	Leftside Wall Barahling Temple Ground Floor	Plaster Crack		4		
4	Rightside Wall Barahling Temple Ground Floor	Peeling of Plaster		5		

	Summary of Areas that Could not be Surveyed				
Serial No.	Location	Description	Photo No.		
1	All Walls Barahling Temple Ground Floor	Covered With Tiles	6		









Photo 1 view of Barahling Temple



Photo 2 Plaster Crack on Wall No. Floor of Barahling Temple of Ground Floor





Photo 3 Plaster Crack on Wall No. Leftside Wall of Barahling Temple of Ground Plaster Crack on Wall No. Leftside Wall of Barahling Temple of Ground Floor Floor



Photo 5 Peeling of Plaster on Wall No. Rightside Wall of Barahling Temple of Ground Floor



Photo 6 All Walls of Barahling Temple of Ground Floor Covered With Tiles



Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Shiv Temple Sadhu Singh Dalal Sanghori Bazaar, Choti Chopar Jaipur Unique ID: CC 0020

Report Number: AIMIL/ESG/JMCEC/CC 0020/01, Rev. 00, Dated: January 2014

Building Owner Contractor Panditji CEC Client Sub-Contractor JMRC Limited AIMIL Limited







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

	Table of Contents		
S.No.	Particulars	Page No.	
1	Introduction	2	
2	Survey Details	2	
3	About the Structure	3	
4	Building Ownership Details	3	
5	Project Details	4	
6	General Building Details	4	
7	Summary of Cracks	5	
8	Summary of Defects other than Cracks		
9	Summary of Areas that Could not be surveyed		
10	Defect Photographs		
11	Schematic Diagram of Building		

Introduction

The Jaipur Metro Rail is being constructed to provide the city of Jaipur with a modern and technologically advanced Transit System, to provide a safe and well connected means of transport that reduces traffic congestion. The project consists of two corridors with underground and elevated sections.

The construction of underground rail and road infrastructures in metropolitan and cosmopolitan cities are mostly through developed area under challenging soil conditions.

The alignment of structure is passing through densely inhabitated areas, many structures are falling in the zone of influence of construction activities. It is required to carry out the pre-condition survey of those structures. The scope of work of this survey includes carrying out pre-condition survey of those structures.

	Survey Details			
S.No.	Head	Particulars	Signatures	
1	Date of Survey	19/12/2013		
2	AIMIL Representative			
3	CEC Representative			
4	Structural Designer of CEC			
5	JMRC/DMRC Representative			







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

#### About the Structure

The structure under consideration is a Single Story Load Bearing Structure . The structure was constructed in year 1960 and is 53 years old.

There are 3 defects in the structure out of which 0 are cracks. Category wise distribution of cracks is given in the table below. Overall the Building can be categorised in Category 0 (Negligible)

Category	Number of Cracks	% of Total Cracks	Crack Meter
Negligible (< 0.1mm)	0	0%	Not Required
Very Slight (0.1 to 1mm)	0	0%	Not Required
Slight (1 to 5mm)	0	0%	Not Required
Moderate (5 to 15mm)	0	0%	Not Required
Severe (15 to 25mm)	0	0%	Not Required
Very Severe (>25mm)	0	0%	Not Required

Building Ownership Details				
Unique ID/Sub ID	Premises Name	Owner	Signatures	
CC/0020	Shiv Temple			







Project Deta	Project Details			
S. No.	Head	Particulars		
1	Project	Jaipur Metro Rail Project		
2	Section	Chandpole to Bari Chaupar		
3	Client	JMRC Limited		
4	Consultant	DMRC Limited		
5	Contractor	CEC		
6	Design Consultant of Contractor	Omikron Kappa - Indus Consultrans JV		
7	Sub-Contractor	AIMIL Limited		
8	Subject	Pre-Condition Survey Report		

General Bui	Iding Details (As informed verbally by Building O	wner)
S. No.	Head	Particulars
1	Building Name	Shiv Temple
2	Building Address	Shiv Temple Sadhu Singh Dalal Sanghori Bazaar, Choti Chopar Jaipur
3	Year of Construction	1960
4	Number of Floors	G
5	Number of Basements	None
6	Type of Building	Commercial
7	Approximate Height	3 m
8	Approximate Area	Not Known
9	Age of Building	53 years
10	Type of Structure	Load Bearing Structure
11	Type of Foundation	Not Known
12	Number of Bore Wells	None
13	Depth and Diameter of Bore	N.A
14	Roadways	All Side
15	Presence of Equipment/Machines	None







Summary of Cracks									
Defect ID	Location	Orientation	Appx. Width (mm)	Appx. Length (m)	Category	Photo No.			
Summary of Defects Other Than Crack									
Defect ID	Location	Description		Photo No.					
1	Leftside Perapet Wall Shiv Ji Ka Temple Ground Floor	Damaged Portion		2					
2	Backside Perapet Wall No.1 Shiv Ji Ka Temple Ground Floor	und Damaged Portion			3				
3	Rightside Perapet Wall Shiv Ji Ka Temple Ground Floor	Damaged Portion				4			

Summary of Areas that Could not be Surveyed								
Serial No.	Location	Description	Photo No.					
1	All Walls Shiv Ji Ka Temple Ground Floor		5					









Photo 1 View of Shiv Ji Ka Temple



Photo 2 Damaged Portion on Leftside Perapet Wall of Shiv Ji Ka Temple of Ground Floor



Photo 3 Damaged Portion on Backside Perapet Wall No.1 of Shiv Ji Ka Temple of Ground Floor



Photo 4 Damaged Portion on Rightside Perapet Wall of Shiv Ji Ka Temple of Ground Floor



Photo 5 All Walls of Shiv Ji Ka Temple of Ground Floor



Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Fountain Choti Chopar Jaipur Unique ID: CC 0021

Report Number: AIMIL/ESG/JMCEC/CC 0021/01, Rev. 00, Dated: January 2014

Building Owner Contractor Government CEC Client Sub-Contractor JMRC Limited AIMIL Limited







#### **Jaipur Metro Rail Corporation**

Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

	Table of Contents		
S.No.	Particulars	Page No.	
1	Introduction	2	
2	Survey Details	2	
3	About the Structure	3	
4	Building Ownership Details	3	
5	Project Details	4	
6	General Building Details	4	
7	Summary of Cracks	5	
8	Summary of Defects other than Cracks		
9	Summary of Areas that Could not be surveyed		
10	Defect Photographs		
11	Schematic Diagram of Building		

Introduction

The Jaipur Metro Rail is being constructed to provide the city of Jaipur with a modern and technologically advanced Transit System, to provide a safe and well connected means of transport that reduces traffic congestion. The project consists of two corridors with underground and elevated sections.

The construction of underground rail and road infrastructures in metropolitan and cosmopolitan cities are mostly through developed area under challenging soil conditions.

The alignment of structure is passing through densely inhabitated areas, many structures are falling in the zone of influence of construction activities. It is required to carry out the pre-condition survey of those structures. The scope of work of this survey includes carrying out pre-condition survey of those structures.

		Survey Details	
S.No.	Head	Particulars	Signatures
1	Date of Survey	03/01/2014	
2	AIMIL Representative		
3	CEC Representative		
4	Structural Designer of CEC		
5	JMRC/DMRC Representative		







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

About the Structure

The structure under consideration is a Single Story Load Bearing Structure .

There are 12 defects in the structure out of which 1 are cracks. Category wise distribution of cracks is given in the table below. Overall the Building can be categorised in Category I (Very Slight)

Category	Number of Cracks	% of Total Cracks
Negligible (< 0.1mm)	0	0%
Very Slight (0.1 to 1mm)	1	100%
Slight (1 to 5mm)	0	0%
Moderate (5 to 15mm)	0	0%
Severe (15 to 25mm)	0	0%
Very Severe (>25mm)	0	0%

The average width of cracks is 0.5mm and average length of cracks is 3m. The maximum crack width is 0.5mm and minimum width is 0.5mm.

		Building Ownership Details	
Unique ID/Sub ID	Premises Name	Owner	Signatures
CC-002/Fountain	Fountain		







Project Detai	ls	
S. No.	Head	Particulars
1	Project	Jaipur Metro Rail Project
2	Section	Chandpole to Bari Chaupar
3	Client	JMRC Limited
4	Consultant	DMRC Limited
5	Contractor	CEC
6	Design Consultant of Contractor	Omikron Kappa - Indus Consultrans JV
7	Sub-Contractor	AIMIL Limited
8	Subject	Pre-Condition Survey Report

S. No.	Head	Particulars
1	Building Name	Fountain
2	Building Address	Fountain Choti Chopar Jaipur
3	Year of Construction	Not Known
4	Number of Floors	G
5	Number of Basements	None
6	Type of Building	Commercial
7	Approximate Height	3m
8	Approximate Area	Not Known
9	Age of Building	Not Known
10	Type of Structure	Load Bearing Structure
11	Type of Foundation	Not Known
12	Number of Bore Wells	None
13	Depth and Diameter of Bore	N.A
14	Roadways	All Side
15	Presence of Equipment/Machines	None







	Summary	of Cracks				
Defect ID	Location	Orientation	Appx. Width (mm)	Appx. Length (m)	Category	Photo No.
1	Wall No. 2 Boundary Wall B Ground Floor	Horizontal	0.5	3	Very Slight	5

	Summary of Def	ects Other Than Crack	
Defect ID	Location	Description	Photo No.
2	Wall No. 3 Left Side From Gate Ground Floor	Damaged Portion	6
3	Boundary Wall B Ground Floor	Peeling of Plaster	7
4	Floor Boundary Wall B Ground Floor	Peeling of Plaster	8
5	Wall No. 1 & Floor Boundary Wall B Ground Floor	Peeling of Plaster	9
6	Boundary Wall B Ground Floor	Plaster Crack	10
7	External Wall No. 3 Boundary Wall B Ground Floor	Plaster Crack	11
8	External Wall No. 3 Boundary Wall B Ground Floor	Peeling of Plaster	12
9	Wall No.2 & Floor Boundary Wall B Ground Floor	Damaged Portion	13
10	Wall No. 2 & Floor Boundary Wall B Ground Floor	Peeling of Plaster	14
11	Wall No. 2 & 4 Boundary Wall B Ground Floor	Peeling of Plaster	15
12	Floor Boundary Wall B Ground Floor	Peeling of Plaster	16

	Summary of Areas that	Could not be Surveyed	
Serial No.	Location	Description	Photo No.







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Photo 1



Photo 2 View of Shop, Ground Floor





Photo 3 Right View, Ground Floor

Photo 4 Ground Floor



Photo 5 Horizontal Crack on Wall No. 2 of Boundary Wall B, Ground Floor Approx. Width = 0.5mm, Approx. Length = 3m. Distance from Wall No. 4 = 2m, Height from Floor = 0.4m.



Photo 6 Damaged Portion on Wall No. 3 of Left Side From Gate of Ground Floor







### **Jaipur Metro Rail Corporation**



Photo 7 Peeling of Plaster on Boundary Wall B of Ground Floor



Photo 8 Peeling of Plaster on Floor of Boundary Wall B of Ground Floor





Photo 9 Peeling of Plaster on Wall No. 1 & Floor of Boundary Wall B of Ground Floor

Photo 10 Plaster Crack on Boundary Wall B of Ground Floor



Photo 1 Plaster Crack on External Wall No. 3 of Boundary Wall B of Ground Floor





Photo 12 Peeling of Plaster on External Wall No. 3 of Boundary Wall B of Ground Floor










Photo 13 Damaged Portion on Wall No. 2 & Floor of Boundary Wall B of Ground Floor Peeling of Plaster on Wall No. 2 & Floor of Boundary Wall B of Ground Floor





Photo 15 Peeling of Plaster on Wall No. 2 & 4 of Boundary Wall B of Ground Floor




Photo 16 Peeling of Plaster on Floor of Boundary Wall B of Ground Floor











Revision	3								
Description of Revision									
evision Drawn By	<u>.</u>								
h By Approved By	_								
By Date									
	CLIENT: DMRC/JMRC	CONSULTANT: OMIKRON KAPPA - INDUS CONSULTRANS JV							
Jaipur Metro Phase 1B	CONTRACT:	MAIN CONTRACTOR: CEC	Ground Floor Plan			Shop No. 17 Locked			
		SUB-CONTRACTOR: AIMIL LIMITED							
Shop No. 17, Chhoti Chopar	DRAWING TITLE: Ground Floor Plan of	PROJECT TITLE: Design and Construction of Tun line by Shield TBM, Undergroun by Cut & Cover methods on Eas			Passage 1	— — Shutte Main Enter	er — — rance	   Passage 1	
SCALE: Not to Scale REVISION: R0		PROJECT TITLE: Design and Construction of Tunnel between Chandpole & Badi Chouper and reversal line by Shield TBM, Underground Metro Stations at Choti Choupar and Badi Choupar by Cut & Cover methods on East West Corridor of Jaipur Metro Phase 1B			`				
















DRAWING TITLE:     DRAWING NO.:       Ground Floor Plan of     AIMIL/ESG/12315/ CC-0001-12 /01       Shop Sai Baba, Chhoti     SCALE:       Chopar     Not to Scale		CONTRACT: Jaipur Metro Phase 1B	- DMRC/JMRC	16.11.2013 Date	Dr. PRC Approved By	n NP Drawn By	Description of Revision	Revision 00
PROJECT TITLE: Design and Construction of Tunnel between Chandpole & Badi Chouper and reversal line by Shield TBM, Underground Metro Stations at Choti Choupar and Badi Choupar by Cut & Cover methods on East West Corridor of Jaipur Metro Phase 1B	SUB-CONTRACTOR: AIMIL LIMITED	MAIN CONTRACTOR: CEC	CONSULTANT: OMIKRON KAPPA - INDUS CONSULTRANS JV					
		Ground Floor Plan						
Passage 2								
— Shutter – Main Enteranc		Sai Baba Locked						
 e								
   Passage 2								






























































































































				1					
Revision	00			-					
Description of Revision									
				-					
Drawn By	ĄP			-					
Approved By	Dr. PRC								
Date	16.11.2013					ł			
				-		Wall N	lo. 4		
			CONSULTANT: OMIKRON KAPPA - INDUS CONSULTRANS JV						_
	Ĺ	,,	NT: CAPPA ANS JN						Wall No. 2
									2
			S						
			MA			Up			
		CONTRACT:	MAIN CONTRACTOR: CEC	Upper Ground Floor Plan	Wa	Upper Ground Floor	Show and the second sec		
	Jaipu	RACT:	CEC	ound Flo	Wall No. 1	Gro	Z		
	Jaipur Metro Phase 1B		FOR:	or Plan		und	0 7		
	Phase					Floo	50		
	₿			-		or			Stair Down
			SUB-CONTRACTOR: AIMIL LIMITED						+
			AIMIL LIMITED						
			CTOR:				Wa	ll No. 3	
с Р	Sh ch	코		-					
Chopar	Shop No. 766, Chhoti	DRAWING TITLE:	PROJECT TITLE: Design and Constructic line by Shield TBM, Un by Cut & Cover method						
	766, Ch	3 TITLE	T TITLE Construc Id TBM, U						
	hoti		E tion of Tr Undergrou ods on E						
$\vdash$			unnel bet und Metro ast West						
Not to Scale	ÄLE	RAWING	ween Chi o Stations Corridor						
to Sca		G NO.:	andpole 8 s at Choti of Jaipur						
(D)		DRAWING NO.: AIMIL/ESG/12315/ CC-0001-766 /02	PROJECT TITLE: Design and Construction of Tunnel between Chandpole & Badi Chouper and reversal line by Shield TBM, Underground Metro Stations at Choti Choupar and Badi Choupar by Cut & Cover methods on East West Corridor of Jaipur Metro Phase 1B						
	REVI	01-766	ouper an and Bac ase 1B						
 דר	REVISION:	/02	d reversa li Choupa						
R			-						




walvo.2 walvo.2 walvo.2 walvo.2 walvo.2 walvo.2 walvo.2 walvo.2 walvo.2 walvo.2 walvo.4 Upper Ground Floor walvo.1 walvo.1 walvo.1 walvo.2 walvo.1 walvo.2 walvo.1 walvo.2 walvo.1 walvo.2 walvo.2 walvo.1 walvo.2 walvo.1 walvo.2 walvo.1 walvo.2 walvo.2 walvo.2 walvo.2 walvo.2 walvo.1 walvo.2 w						_	
T:			Jaipur Metro Phase 1B			Description of Revision	Revision
Wall No. 2 Wall No. 765 Upper Ground Floor Upper Ground Floor MKICONTRACTOR: CEC Wall No. 3 Wall No. 3	of Shop		CONTRACT:	CLIENT: DMRC/JMRC			
Wall No. 2 Shop No. 765 Upper Ground Floor Hand	PROJECT TITLE: Design and Construction of Tunnel between Chandpole & Badi Cho line by Shield TBM, Underground Metro Stations at Choti Choupar by Cut & Cover methods on East West Corridor of Jaipur Metro Pha	SUB-CONTRACTOR: AIMIL LIMITED	MAIN CONTRACTOR: CEC	CONSULTANT: OMIKRON KAPPA - INDUS CONSULTRANS JV			
WallNo. 2 Shop No. 765 Upper Ground Floor			Upper Ground Floor Plan				
Shop No. 765 Upper Ground Floor			Wall No. 1				
Shop No. 765 Upper Ground Floor							
Stair Down			Shop No. 765 Upper Ground Floor	Wall No. 4	t		
		Wall No. 3					
				Wall No. 2			














Not to Scale RU	Chopar				Date	Approved By	Drawn By	Description of Revision	Revision
ž	o. 763, Chhoti		Jaipur Metro Phase 1B		16.11.2013	Dr. PRC	_		
DRAWING NO.: AIMIL/ESG/12315/ CC-0001-763 /02	DRAWING TITLE: Upper Ground Floor Plan of		CONTRACT:	CLIENT: DMRC/JMRC			5		3
PROJECT TITLE: Design and Construction of Tunnel between Chandpole & Badi Chouper and reversal line by Shield TBM. Underground Metro Stations at Choti Choupar and Badi Choupar by Cut & Cover methods on East West Corridor of Jaipur Metro Phase 1B	PROJECT TITLE: Design and Construction of Tunne line by Shield TBM, Underground I by Cut & Cover methods on East V	SUB-CONTRACTOR: AIMIL LIMITED	MAIN CONTRACTOR: CEC	CONSULTANT: OMIKRON KAPPA - INDUS CONSULTRANS JV					
			Upper Ground Floor Plan						
			Wall No. 3						
			Shop No. 763 Upper Ground Floor	Wall No. 1	t				
	•	Wall No. 2							
			Wall No. 4	Jown	Stair Down				


































































































































Revision 8 Description of Revision † II<sup>₽</sup>M Toilet .oN IIbW 4 lleW .oN IIbW L L Wall No. Wall Wa Wall No. 4 Bath Wall 2 Wall 1 Room Drawn By Ę Wall No. 4  $\overline{}$ Approved By Dr. PRC ω Room 6 Entry Entry Vall No. 2 Entry 16.11.2013 .oN IIBW L Entry Entry Date Wall No. 4 Wall No. 3 Wall No. 3 Room DMRC/JMRC CLIENT: OMIKRON KAPPA - INDUS CONSULTRANS JV CONSULTANT: ω Vall No. 2 .oN IIbW 7 .oN IIbW .oN IIbW L Entry Entry Passage 2 Wall No. 4 Wall No. 4 Wall No. 3 Wall No. Room Open Sky Room 9 0N **II**eW دی. دن ω S.oN IIbW .oN IIBW L .oN IIBW Entry MAIN CONTRACTOR: Wall No. 4 Wall No. 3 Room Entry CONTRACT: Wall No. 4 Wall No. Wall No. 4 Room 10 CEC Jaipur Metro Phase 1B .00 llbW Wall No. 4 2 First Floor Plan ω Entry Wall No. 4 Wall No. Room Wall No. S.oN IIbW L .oN IIbW .oN ∥sW ∽ ω Entry SUB-CONTRACTOR: 7 AIMIL LIMITED .oN IIBW L Entry Wall No. Wall No. 4 Room 11 Wall No. 4 Wall No. 3 ω First Floor Plan of House No. 758 DRAWING TITLE: Design and Construction of Tunnel between Chandpole & Badi Chouper and reversal line by Shield TBM, Underground Metro Stations at Choti Choupar and Badi Choupar by Cut & Cover methods on East West Corridor of Jaipur Metro Phase 1B PROJECT TITLE: S.oN IIbW Up for 1st Floor .oN IIbW L Entry -Entry Entry 6.oN IIbW Wall No. Wall No. 4 2nd Floor Room 12 Wall No. 2 loî qU Wall No. 2 Wall No. Toilet/Bath Room 1 Wall No. SCALE: Not to Scale ω DRAWING NO.: AIMIL/ESG/12315/ CC-0005/FF-SF /01 4.oN IIbW .oN IIbW 7 S ON IIBW REVISION: R0



































































00 Revision			
Description of Revision			
NP Drawn By			
Dr. PRC Approved By			
16.11.2013 Date			S a
CLIENT: DMRC/JMRC	CONSULTANT: OMIKRON KAPPA - INDUS CONSULTRANS JV	Wall No. 4	Stair Up
CONTRACT: Jaipur Metro Phase 1B	MAIN CONTRACTOR: <u>Ground Floor P</u> CEC	Shop No. 169 A Basement	Wall No. 2
	AIMIL LIMITED		Wall No. 3
DRAWING TITLE: Basement Floor Plan of Shop No. 169 A, Chhoti Chopar	PROJECT TITLE: Design and Construction of Tunnel between Chandpole & Badi Chouper and reversal line by Shield TBM, Underground Metro Stations at Choti Choupar and Badi Choupar by Cut & Cover methods on East West Corridor of Jaipur Metro Phase 1B		
DRAWING NO.: AIMIL/ESG/12315/ CC-0011-169 A /01 SCALE: Not to Scale	I between Chandpole & Badi Chc Metro Stations at Choti Choupar Vest Corridor of Jaipur Metro Phc		
11-169 A /01 REVISION: R0	Super and reversal and Badi Choupar ase 1B		














































































SCALE: REVISION: R0	Shop No. 179, Chhoti Chopar		Jaipur Metro Phase 1B		Approved By Date	Drawn By Appr	Description of Revision	Revision
C-001	Ground Floor Plan of			DMRC/JMRC	20042	_		3
Design and Construction of Tunnel between Chandpole & Badi Chouper and reversal line by Shield TBM, Underground Metro Stations at Choti Choupar and Badi Choupar by Cut & Cover methods on East West Corridor of Jaipur Metro Phase 1B	Design and Construction of Tunr line by Shield TBM, Underground by Cut & Cover methods on Eas	AIMIL LIMITED	CEC	CONSULTRANS JV				
	PROJECT TITLE:	SUB-CONTRACTOR:	MAIN CONTRACTOR:	CONSULTANT:				
		an	Ground Floor Plan					
L								
	_							
	∣ Varandah							
	— Shut Main Ent		Shop No. 179 Not Permitted					
	ter — – erance							
Ъ 	∣ ∣ Varandah							
	[							





CONSULTANCE CONSUL	Dr. PRC 16.11.2013	NP	00
Part C Part C Part B Part B Part B Part B Part B Part B Part B Part B Part B Part A Part A Pa	CLIEN		
Part C Part C Part B Shop No - 14 Bansidhar Laxmi Narayan Part A Verandah Road Ground Floor Plan	CONS		
Part C Part C Part C Part C Part B Shop No - 14 Bansidhar Laxmi Narayan Part A Wall No. 4 Part A Wall No. 4 Part B Entry Part A Wall No. 4 Part B Part A Mall No. 4 Part A Part A Mall No. 4 Part A Part			
Part C Wall No. 3 Part B Part B Shop No - 14 Bansidhar Laxmi Narayan Entry Part A Wall No. 4 Part A Wall No. 4 Entry Part A Wall No. 4			
Wall No. 3 Part B Part B Mall No. 4 Wall No. 3 Wall No. 3 Part A Wall No. 4 Part A Wall No. 4			
Part C Wall No. 3 Part B Part B Shop No - 14 Bansidhar Laxmi Narayan Entry Part A Wall No. 4			
Part C Wall No. 3 Part B Part B Shop No - 14 Bansidhar Laxmi Narayan Wall No. 3			
Part C Part C Part B Part B Shop No - 14 Bansidhar Laxmi Narayan			
Wall No. 3 Wall No. 3			
Part C			




















































Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Badi Chouper and reversal line



Shop No. 773-3 Atish ka Khanda Jaipur Unique ID:CC/0002

Report Number: AIMIL/ESG/JMCEC/CC/0002/773-3/01, Rev. 00, Dated: July 2014

Building Owner Contractor Mr. Pradeep Jaipuriya CEC Client Sub-Contractor JMRC Limited AIMIL Limited







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

Table of Contents				
S.No.	Particulars	Page No.		
1	Introduction	2		
2	Survey Details	2		
3	About the Structure	3		
4	Building Ownership Details	3		
5	Project Details	4		
6	General Building Details	4		
7	Summary of Cracks	5		
8	Summary of Defects other than Cracks			
9	Summary of Areas that Could not be surveyed			
10	Defect Photographs			
11	Schematic Diagram of Building			

Introduction

The Jaipur Metro Rail is being constructed to provide the city of Jaipur with a modern and technologically advanced Transit System, to provide a safe and well connected means of transport that reduces traffic congestion. The project consists of two corridors with underground and elevated sections.

The construction of underground rail and road infrastructures in metropolitan and cosmopolitan cities are mostly through developed area under challenging soil conditions.

The alignment of structure is passing through densely inhabitated areas, many structures are falling in the zone of influence of construction activities. It is required to carry out the pre-condition survey of those structures. The scope of work of this survey includes carrying out pre-condition survey of those structures.

	Survey Details					
S.No.	Head	Particulars	Signatures			
1	Date of Survey	26/6/2014	ALL LIMI & Quent			
2	AIMIL Representative	MOND. QUIDMEAN	* NEW DELI			
3	CEC Representative					
4	Structural Designer of CEC					
5	JMRC/DMRC Representative					







R METRO Jaipur Metro Rail Corporation

Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

About the Structure

The structure under consideration is a Multi Story Load Bearing Structure having 2 floors. The structure was constructed in year 1914 & 100 Years Old.

There are 7 defects in the structure out of which 2 are cracks. Category wise distribution of cracks is given in the table below. Overall the Building can be categorised in Category 1 (Very Slight)

Category	Number of Cracks	% of Total Cracks	Crack Meter
Negligible (< 0.1mm)	0	0%	Not Required
Very Slight (0.1 to 1mm)	2	100%	Required
Slight (1 to 5mm)	0	0%	Not Required
Moderate (5 to 15mm)	0	0%	Not Required
Severe (15 to 25mm)	0	0%	Not Required
Very Severe (>25mm)	0	0%	Not Required

Building Ownership Details					
Unique ID/Sub ID Premises Name Owner Signatures					
CC/0002/773-3	Basant Medical Store, Shop No.773-3	Mr. Pradeep Jaipuriya			







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

Project Details						
S. No.	Head	Particulars				
1	Project	Jaipur Metro Rail Project				
2	Section	Chandpole to Bari Chaupar				
3	Client	JMRC Limited				
4	Consultant	DMRC Limited				
5	Contractor	CEC				
6	Design Consultant of Contractor	Omikron Kappa - Indus Consultrans JV				
7	Sub-Contractor	AIMIL Limited				
8	Subject	Pre-Condition Survey Report				

General Building Details (As informed verbally by Building Owner)					
S. No.	Head	Particulars			
1	Building Name	Basant Medical Stores, Shop No. 773-3			
2	Building Address	Mr. Pradeep Jaipuriya,Atish ka Khanda, Jaipur			
3	Year of Construction	1914			
4	Number of Floors	G+1			
5	Number of Basements	Not Known			
6	Type of Building	Commercial			
7	Approximate Height	6m			
8	Approximate Area	Not Known			
9	Age of Building	100Years			
10	Type of Structure	Load Bearing Structure			
11	Type of Foundation	Not Known			
12	Number of Bore Wells	Not Known			
13	Depth and Diameter of Bore	N.A			
14	Roadways	One Sides			
15	Presence of Equipment/Machines	None			







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Badi Chouper and reversal line

	Summary of Cracks							
Defect ID	Location	Orientation	Appx. Width (mm)	Appx. Length (m)	Category	Photo No.		
1	Vrandah Roof of Shop No. 773-3, Ground Floor	Horizontal	0.5	1.8	Very Slight	1		
2	Vrandah Roof of Shop No. 773-3, Ground Floor	Horizontal	0.6	1.8	Very Slight	2		

	Summary of Defects Other Than Crack					
Defect ID	Location	Description	Photo No.			
1	Roof of Shop No. 773-3, Ground Floor	Plaster Removal	3			
2	Roof of Shop No. 773-3, Ground Floor	Plaster Crack	4			
3	Wall No.3 of Shop No. 773-3, Ground Floor	Plaster Crack	5			
4	Wall No.3 of Shop No. 773-3, Ground Floor	Dampness/ Seepage	6			
5	Roof of Shop No. 773-3, Ground Floor	Plaster Crack	7			

Summary of Areas that Could not be Surveyed						
Serial No.	Location	Description	Photo No.			







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Badi Chouper and reversal line



Photo 1 Horizontal Crack on Vrandah Roof of Shop No. 773-3, Ground Floor,Approx. Width = 0.50mm,Approx. Length = 1.8m. Distance from Left Hand Column = 0m,Height from Floor =3.00m.



Photo 3 Plaster Removal on Roof of Shop No. 773-3, Ground Floor




Photo 5 Plaster Crack on Wall No.3 of Shop No. 773-3, Ground Floor






Photo 2 Horizontal Crack on Vrandah Roof of Shop No. 773-3, Ground Floor,Approx. Width = 0.60mm,Approx. Length = 1.8m. Distance from Right Hand Column = 0m,Height from Floor =3.00m.




Photo 4 Plaster Crack on Roof of Shop No. 773-3, Ground Floor



Photo 6 Dampness/ Seepage on Wall No.3 of Shop No. 773-3, Ground Floor





Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line



Photo 7 Plaster Crack on Roof of Shop No. 773-3, Ground Floor





