

Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Badi Chouper and reversal line



Shop No.52 Triplia Bazaar Jaipur Unique ID:CC-BC/UP/0001

Report Number: AIMIL/ESG/JMCEC/CC-BC/UP/0001-52/01, Rev. 00, Dated: July 2014

Building Owner Contractor Mr. Shankar CEC Client Sub-Contractor JMRC Limited AIMIL Limited







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

Table of Contents				
S.No.	Particulars	Page No.		
1	Introduction	2		
2	Survey Details	2		
3	About the Structure	3		
4	Building Ownership Details	3		
5	Project Details	4		
6	General Building Details	4		
7	Summary of Cracks	5		
8	Summary of Defects other than Cracks			
9	Summary of Areas that Could not be surveyed			
10	Defect Photographs			
11	Schematic Diagram of Building			

Introduction

The Jaipur Metro Rail is being constructed to provide the city of Jaipur with a modern and technologically advanced Transit System, to provide a safe and well connected means of transport that reduces traffic congestion. The project consists of two corridors with underground and elevated sections.

The construction of underground rail and road infrastructures in metropolitan and cosmopolitan cities are mostly through developed area under challenging soil conditions.

The alignment of structure is passing through densely inhabitated areas, many structures are falling in the zone of influence of construction activities. It is required to carry out the pre-condition survey of those structures. The scope of work of this survey includes carrying out pre-condition survey of those structures.

	Survey Details					
S.No.	Head	Particulars	Signatures			
1	Date of Survey	26/6/2014	ALL LIMI CH Gwan			
2	AIMIL Representative	MOND. QUIDARAN	+ NEW DELT			
3	CEC Representative					
4	Structural Designer of CEC					
5	JMRC/DMRC Representative					







R METRO Jaipur Metro Rail Corporation

Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

About the Structure

The structure under consideration is a Multi Story Load Bearing Structure having 1 floors. The structure was constructed in year 1914 & 100 Years Old.

There are 3 defects in the structure out of which 1 are cracks. Category wise distribution of cracks is given in the table below. Overall the Building can be categorised in Category 1 (Very Slight)

Category	Number of Cracks	% of Total Cracks	Crack Meter
Negligible (< 0.1mm)	0	0%	Not Required
Very Slight (0.1 to 1mm)	1	100%	Required
Slight (1 to 5mm)	0	0%	Not Required
Moderate (5 to 15mm)	0	0%	Not Required
Severe (15 to 25mm)	0	0%	Not Required
Very Severe (>25mm)	0	0%	Not Required

Building Ownership Details					
Unique ID/Sub ID	Premises Name	Owner	Signatures		
CC-BC/UP/0001-52	Shop No. 52	Mr. Shankar			







Project Deta	Project Details					
S. No.	Head	Particulars				
1	Project	Jaipur Metro Rail Project				
2	Section	Chandpole to Bari Chaupar				
3	Client	JMRC Limited				
4	Consultant	DMRC Limited				
5	Contractor	CEC				
6	Design Consultant of Contractor	Omikron Kappa - Indus Consultrans JV				
7	Sub-Contractor	AIMIL Limited				
8	Subject	Pre-Condition Survey Report				

S. No.	Head	Particulars	
1	Building Name	Shop No. 52	
2	Building Address	Tripolia Bazaar, Jaipur	
3	Year of Construction	1914	
4	Number of Floors	G	
5	Number of Basements	Not Known	
6	Type of Building	Commercial	
7	Approximate Height	3m	
8	Approximate Area	Not Known	
9	Age of Building	100Years	
10	Type of Structure	Load Bearing Structure	
11	Type of Foundation	Not Known	
12	Number of Bore Wells	Not Known	
13	Depth and Diameter of Bore	N.A	
14	Roadways	One Sides	
15	Presence of Equipment/Machines	None	







Summary of Cracks						
Defect ID	Location	Orientation	Appx. Width (mm)	Appx. Length (m)	Category	Photo No.
1	Vrandah Roof of Shop No. 773-3, Ground Floor	Horizontal	1	2.5	Very Slight	1

	Summary of Defects Other Than Crack				
Defect ID	Defect ID     Location     Description     Photo No.				
1	Roof of Shop No. 52, Ground Floor	Plaster Removal	2		
2	Roof of Shop No. 52, Ground Floor	Dampness/ Seepage	3		

	Summary of Areas that Could not be Surveyed				
Serial No.	Location	Description	Photo No.		
1	Wall No. 2 & 4 of Shop No. 52, Ground Floor	Covered with Material	4		










Photo 1 Horizontal Crack on Vrandah Roof of Shop No. 52, Ground Floor,Approx. Width = 1mm,Approx. Length = 2.5m. Distance from Left Hand Column = 0m,Height from Floor =3.00m.



Photo 2 Plaster Removal on Roof of Shop No. 52, Ground Floor




Photo 3 Dampness/ Seepage on Roof of Shop No. 52, Ground Floor



Photo 4 Covered with Materials, Wall No. 2 & 4 of Shop No. 52, Ground Floor









Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Badi Chouper and reversal line



Shop No.92A Triplia Bazaar Jaipur Unique ID:CC-BC/UP/0001

Report Number: AIMIL/ESG/JMCEC/CC-BC/UP/0001-92-A/01, Rev. 00, Dated: July 2014

Building Owner Contractor Mr. Omkaleshwar Agrawal CEC

Client Sub-Contractor JMRC Limited AIMIL Limited







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

Table of Contents			
S.No.	Particulars	Page No.	
1	Introduction	2	
2	Survey Details	2	
3	About the Structure	3	
4	Building Ownership Details	3	
5	Project Details	4	
6	General Building Details	4	
7	Summary of Cracks	5	
8	Summary of Defects other than Cracks		
9	Summary of Areas that Could not be surveyed		
10	Defect Photographs		
11	Schematic Diagram of Building		

Introduction

The Jaipur Metro Rail is being constructed to provide the city of Jaipur with a modern and technologically advanced Transit System, to provide a safe and well connected means of transport that reduces traffic congestion. The project consists of two corridors with underground and elevated sections.

The construction of underground rail and road infrastructures in metropolitan and cosmopolitan cities are mostly through developed area under challenging soil conditions.

The alignment of structure is passing through densely inhabitated areas, many structures are falling in the zone of influence of construction activities. It is required to carry out the pre-condition survey of those structures. The scope of work of this survey includes carrying out pre-condition survey of those structures.

	Survey Details					
S.No.	Head	Particulars	Signatures			
1	Date of Survey	26/6/2014	ALL LIMI CHAMMAN			
2	AIMIL Representative	MOND. QUIDMEAN	+ NEW DELT			
3	CEC Representative					
4	Structural Designer of CEC					
5	JMRC/DMRC Representative					







R METRO Jaipur Metro Rail Corporation

Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

About the Structure

The structure under consideration is a Multi Story Load Bearing Structure having 1 floors. The structure was constructed in year 1914 & 100 Years Old.

There are 2 defects in the structure out of which 0 are cracks. Category wise distribution of cracks is given in the table below. Overall the Building can be categorised in Category 0 (Negligible)

Category	Number of Cracks	% of Total Cracks	Crack Meter
Negligible (< 0.1mm)	0	0%	Not Required
Very Slight (0.1 to 1mm)	1	100%	Required
Slight (1 to 5mm)	0	0%	Not Required
Moderate (5 to 15mm)	0	0%	Not Required
Severe (15 to 25mm)	0	0%	Not Required
Very Severe (>25mm)	0	0%	Not Required

Building Ownership Details				
Unique ID/Sub ID	Premises Name	Owner	Signatures	
CC-BC/UP/0001-92-A	Shop No. 92A	Mr. Omkaleshwar Agrawal		







Project Detai	Project Details					
S. No.	Head	Particulars				
1	Project	Jaipur Metro Rail Project				
2	Section	Chandpole to Bari Chaupar				
3	Client	JMRC Limited				
4	Consultant	DMRC Limited				
5	Contractor	CEC				
6	Design Consultant of Contractor	Omikron Kappa - Indus Consultrans JV				
7	Sub-Contractor	AIMIL Limited				
8	Subject	Pre-Condition Survey Report				

S. No.	Head	Particulars	
1	Building Name	Shop No. 92A, Surajmal & Sons	
2	Building Address	Tripolia Bazaar, Jaipur	
3	Year of Construction	1914	
4	Number of Floors	G	
5	Number of Basements	Not Known	
6	Type of Building	Commercial	
7	Approximate Height	3m	
8	Approximate Area	Not Known	
9	Age of Building	100Years	
10	Type of Structure	Load Bearing Structure	
11	Type of Foundation	Not Known	
12	Number of Bore Wells	Not Known	
13	Depth and Diameter of Bore	N.A	
14	Roadways	One Sides	
15	Presence of Equipment/Machines	None	







	Summary of Cracks						
Defect ID	Location Orientation Appx. Width (mm) Appx. Length (mm)				Photo No.		
	Summary of Defects Other Than Crack						
Defect ID	Location	Description				Photo No.	
1 Roof of Vrandah of Shop No.92A, Ground Floor Plaster Removal					1		
2	2 Roof of Vrandah of Shop No.92A, Ground Floor Dampness/ Seepage				2		
2	Root of Mandan of Shop No.32A, Ground Hoor	Dampness/ S	eepaye			2	

	Summary of Areas that Could not be Surveyed					
Serial No.	Serial No. Location Description					
1	Roof of Shop No. 92A, Ground Floor	Covered with Wooden Ceiling	3			
2	Wall No. 2 & 4 of Shop No. 92A, Ground Floor	Covered with Material	4			
3	Wall No. 1 of Shop No. 92A, Ground Floor	Covered with Material	5			










Photo 1 Plaster Removal on Roof of Varandah of Shop No. 92A, Ground Floor



Photo 2 Dampness/ Seepage on Roof of Varandah of Shop No. 92A, Ground Floor



Photo 3 Covered with Wooden Ceiling, Roof of Shop No. 92A, Ground Floor







Photo 5 Covered with Materials, Wall No. 1 of Shop No. 92A, Ground Floor









JUR METRO Jaipur Metro Rail Corporation

Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Badi Chouper and reversal line



Shop No. E62 Tripolia Bazaar Jaipur Unique ID:CC-BC/UP/0002

Report Number: AIMIL/ESG/JMCEC/CC-BC/UP/0002-E-62/01, Rev. 00, Dated: July 2014

Building Owner Contractor Mr. Ratanlal Panchari CEC Client Sub-Contractor JMRC Limited AIMIL Limited







Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

Table of Contents				
S.No.	Particulars	Page No.		
1	Introduction	2		
2	Survey Details	2		
3	About the Structure	3		
4	Building Ownership Details	3		
5	Project Details	4		
6	General Building Details	4		
7	Summary of Cracks	5		
8	Summary of Defects other than Cracks			
9	Summary of Areas that Could not be surveyed			
10	Defect Photographs			
11	Schematic Diagram of Building			

Introduction

The Jaipur Metro Rail is being constructed to provide the city of Jaipur with a modern and technologically advanced Transit System, to provide a safe and well connected means of transport that reduces traffic congestion. The project consists of two corridors with underground and elevated sections.

The construction of underground rail and road infrastructures in metropolitan and cosmopolitan cities are mostly through developed area under challenging soil conditions.

The alignment of structure is passing through densely inhabitated areas, many structures are falling in the zone of influence of construction activities. It is required to carry out the pre-condition survey of those structures. The scope of work of this survey includes carrying out pre-condition survey of those structures.

	Survey Details				
S.No.	Head	Particulars	Signatures		
1	Date of Survey	26/6/2014	AND CAMMEN		
2	AIMIL Representative	MOND. QUIDMEAN	* WEW DELT		
3	CEC Representative				
4	Structural Designer of CEC				
5	JMRC/DMRC Representative				







IPUR METRO Jaipur Metro Rail Corporation

Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

About the Structure

The structure under consideration is a Multi Story Load Bearing Structure having Ground floors. The structure was constructed in year 1913 & 100 Years Old.

There are 0 defects in the structure out of which 0 are cracks. Category wise distribution of cracks is given in the table below. Overall the Building can be categorised in Category 0 (Negligible)

Category	Number of Cracks	% of Total Cracks	Crack Meter
Negligible (< 0.1mm)	0	0%	Not Required
Very Slight (0.1 to 1mm)	0	0%	Not Required
Slight (1 to 5mm)	0	0%	Not Required
Moderate (5 to 15mm)	0	0%	Not Required
Severe (15 to 25mm)	0	0%	Not Required
Very Severe (>25mm)	0	0%	Not Required

Building Ownership Details				
Unique ID/Sub ID Premises Name Owner Signatures				
CC-BC/UP/0002-E-62	Shop No. E62	Mr. Ratanlal Panchari		







JAIPUR METRO Jaipur Metro Rail Corporation

Pre - Condition Building Survey for Construction of Underground Stations from from Chandpole to Bari Chouper and reversal line

Project Detai	Project Details				
S. No.	Head	Particulars			
1	Project	Jaipur Metro Rail Project			
2	Section	Chandpole to Bari Chaupar			
3	Client	JMRC Limited			
4	Consultant	DMRC Limited			
5	Contractor	CEC			
6	Design Consultant of Contractor	Omikron Kappa - Indus Consultrans JV			
7	Sub-Contractor	AIMIL Limited			
8	Subject	Pre-Condition Survey Report			

S. No.	Head	Particulars	
1	Building Name	Shop No. E62	
2	Building Address	Tripolia Bazaar,Jaipur	
3	Year of Construction	1913	
4	Number of Floors	G	
5	Number of Basements	Not Known	
6	Type of Building	Commercial	
7	Approximate Height	3m	
8	Approximate Area	Not Known	
9	Age of Building	100 years	
10	Type of Structure	Load Bearing Structure	
11	Type of Foundation	Not Known	
12	Number of Bore Wells	Not Known	
13	Depth and Diameter of Bore	N.A	
14	Roadways	One Sides	
15	Presence of Equipment/Machines	None	







	Summary of Cracks						
Defect ID	Location	Orientation	Appx. Width (mm)	Appx. Length (m)	Category	Photo No.	
	Summary of Defects Other Than Crack						
			oradik				
Defect ID	Location	Description				Photo No.	
1	Outer Wall of Shop No. E62, Ground Floor	Plaster Removal				1	
2	Wall No. 4 of Shop No. E62, Ground Floor	Damage			2		
3	All Walls of Shop No. E62, Ground Floor	Repairing Work			3		
4	Beam of Shop No. E62, Ground Floor	Peeling of Plaster			4		

Summary of Areas that Could not be Surveyed				
Serial I	No.	Location	Description	Photo No.









Photo 1 Plaster Removal of Outer Wall of Shop No. E62, Ground Floor



Photo 2 Damage of Wall No. 4 of Shop No. E62, Ground Floor



Photo 3 Repairing Work on All Walls of Shop No. E62, Ground Floor



Photo 4 Peeling of Plaster on Beam of Shop No. E62, Ground Floor





