

Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Bari Chouper and reversal line

Sl. No.	Unique ID	Sub-ID	Building Usage	Building Name	Address	Building Owner	Contact No. of Owner	Age of Building (Years)	Number of Floors	Bore Well	Front Photo Number
1	CP-0003	CP/0003-2	Commercial	Ravi Shankar Juice	Chandpole Gate	Not Known	Not Known	100	G+1	No	1 , 2 & 3
2		CP/0003-FF	Commercial								4
3	CP-0004	CP/0004-1	Commercial	Desi Sarab	Chandpole Gate	Not Known	Not Known	100	G+3	No	5 & 6
4		CP/0004-FF-TF									7
5	CP-0012	CP/0012-FF	Residential	Not Known	Chandpole Gate	Not Known	Not Known	100	G+1	No	8 & 9

Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Bari Chouper and reversal line



Photo No. 1



Photo No. 2



Photo No. 3



Photo No. 4



Photo No. 5



Photo No. 6



Photo No. 7



Photo No. 8



Photo No. 9