



Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Bari Choupar and reversal line

| S. No. | Unique ID | Sub-ID | Building Usage | Building Name | Address | Building Owner | Contact No. of Owner | Age of Building (Years) | Number of Floors | Bore Well | Front Photo Number |
|--------|------------|---------------|----------------|-----------------------------------|--------------|----------------------|----------------------|-------------------------|------------------|-----------|--------------------|
| 1 | BC-0001-A | BC-0001-A | Commercial | S. S. Marketing | Badi Choupar | Not Known | Not Known | 100 | G | No | 1,2 |
| 2 | BC/0004-10 | BC/0004-10 | Commercial | Janak Bhawan Charity Shop | Badi Choupar | Not Known | Not Provided | 100 | B+G+1 | No | 3,4 |
| 3 | BC/0005 | BC/0005-22 | Commercial | Sharma Paan Bhandar | Badi Choupar | Mr. Govind Ji Sharma | 9414821131 | 100 | G+1 | No | 5,6,7 |
| 4 | BC/0006 | BC/0006-10 | Commercial | Closed | Badi Choupar | Not Known | Not Known | 80 | G+1 | No | 8,9,10 |
| 5 | BC/0008 | BC/0008-19 | Commercial | Syochand Gorilal Bajaj | Badi Choupar | Not Known | Not Known | 100 | G | No | 11,12,13 |
| 6 | BC/0011 | BC/0011-09 | Commercial | P.H. Textiles | Badi Choupar | Not Known | Not Known | 300 | G | No | 14,15 |
| 7 | | BC/0011-10 | | Munna Lal Taksaali Sarraf | | Mr. Ishwar Lal Jain | 2567147 | | | | 16,17 |
| 8 | | BC/0011-11 | | Mahalaxmi Saree Imporium | | Not Known | Not Known | | | | 18,19 |
| 9 | BC/0018 | BC/0018-SF-26 | Commercial | Closed office, Shop No. 249 & 251 | Badi Choupar | Not Known | Not Known | 300 | B+G+2 | No | 20 |



Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Bari Chouper and reversal line

| S. No. | Unique ID | Sub-ID | Building Usage | Building Name | Address | Building Owner | Contact No. of Owner | Age of Building (Years) | Number of Floors | Bore Well | Front Photo Number |
|--------|-----------|---------------|----------------|--|---------------------|----------------|----------------------|-------------------------|------------------|-----------|--------------------|
| 10 | BC/0018 | BC/0018-SF-30 | Commercial | R.C.Rana Creation Godown, Shop No. 242 & 241 | Purohit Ji Ka Katla | Not Known | 2652673 | 300 | B+G+3 | No | 21,22,23 |
| 11 | | BC/0018-G-25 | | shop closed | | Not Known | Not Known | | | | 24 |
| 12 | | BC/0018-G-57 | | Shiddham Shop No.74 | | Not Known | 9414063392 | | | | 25,26 |
| 13 | | BC/0018-B-20 | | Shop No.17,18 &19 | | Not Known | Not Known | | | | 27,28 |
| 14 | | BC/0018-FF-03 | | Prem Chand Shant Kumar Jain, Shop No. 117 | | Not Known | 2574475 | | | | 29,30 |
| 15 | | BC/0018-FF-04 | | | | Not Known | Not Known | | | | 31 |
| 16 | | BC/0018-FF-34 | | Purshottam Mendiratta & Co.Godown Shop No. 142 | | Mr. Purshottam | 2521802 | | | | 32,33 |
| 17 | | BC/0018-SF-02 | | Sanjay Bangles, Godown, Shop No. 218 | | Not Known | Not Known | | | | 34,35,36,37 |
| 18 | | BC/0018-SF-15 | | Godown | | Not Known | Not Known | | | | 38,39 |

Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Badi Chouper and reversal line



Photo No. 1



Photo No. 2



Photo No. 3



Photo No. 4



Photo No. 5



Photo No. 6



Photo No. 7



Photo No. 8



Photo No. 9



Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Badi Chouper and reversal line



Photo No. 10



Photo No. 11



Photo No. 12



Photo No. 13



Photo No. 14



Photo No. 15



Photo No. 16



Photo No. 17



Photo No. 18



Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Badi Chouper and reversal line



Photo No. 19



Photo No. 20



Photo No. 21



Photo No. 22



Photo No. 23



Photo No. 24



Photo No. 25



Photo No. 26



Photo No. 27

Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Badi Chouper and reversal line



Photo No. 28



Photo No. 29



Photo No. 30



Photo No. 31



Photo No. 32



Photo No. 33



Photo No. 34



Photo No. 35



Photo No. 36



Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Badi Chouper and reversal line



Photo No. 37



Photo No. 38



Photo No. 39