



Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Bari Chouper and reversal line

S. No.	Unique ID	Sub-ID	Building Usage	Building Name	Address	Building Owner	Contact No. of Owner	Age of Building (Years)	Number of Floors	Bore Well	Front Photo Number
1	BC-RA/DL/0004	BC-RA/DL/0004-022	Commercial	Mehachand Jain & Sons	22, Ramganj Bazar, Badi Chopad	Not Known	Not Known	150	G+2	No	1,2
2		BC-RA/DL/0004-FF-SF	Residential	H. No. 342, Above Shop No. 22		Mr. Md. Zafar Khan/ Asad Khan	2606527				3
3	BC-RA/DL/0006	BC-RA/DL/0006-024	Commercial	Om Prakash Aggarwal & Sons	24, Ramganj Bazar, Badi Chopad	Mr. Khandaku Ji	Not Known	150	G+2	No	4,5
4		BC-RA/DL/0006-FF-SF	Residential	Savitri Sadan, Above Shop No. 24		Not Known	Not Known				6,7
5	BC-RA/DL/0007	BC-RA/DL/0007-FF-SF-TF	Residential	Above Shop No. 25	25, Ramganj Bazar, Badi Chouper	Not Known	Not Known	150	G+3	No	8,9
6	BC-RA/DL/0011	BC-RA/DL/0011-FF-TF	Residential	Above Shop No. 29	Ramganj Bazar, Badi Chopad	Not Known	Not Known	150	G+3	No	10,11
7	BC-RA/DL/0014	BC-RA/DL/0014-FF-TF	Residential	No Specific Name	32, Ramganj Bazar	Not Known	Not Known	100	G+3	No	12,13
8	BC-RA/DL/0018	BC-RA/DL/0018-FF-TF	Residential	No Specific Name	36, Ramganj Bazar	Mr. Hariram	Not Known	100	G+3	No	14,15
9	BC-RA/DL/0023	BC-RA/DL/0023-FF-SF	Residential	No Specific Name	43, Ramganj Bazar	Not Known	Not Known	100	G+2	No	16,17

Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Bari Chouper and reversal line

Sl. No.	Unique ID	Sub-ID	Building Usage	Building Name	Address	Building Owner	Contact No. of Owner	Age of Building (Years)	Number of Floors	Bore Well	Front Photo Number
10	BC-RA/DL/0040	BC-RA/DL/0040/48	Commercial	Rai Medical Store	46 - 48, Ramganj Market	Not Known	Not Known	100	G+3	No	18,19
11	BC-RA/DL/0043	BC-RA/DL/0043/FF-SF	Residential	No Specific Name	51, Ramganj Market	Not Known	Not Known	100	G+2	No	20,21
12	BC-RA/DL/0045	BC-RA/DL/0045/53	Commercial	Ram Avatar Vijay	53, Ramganj Market	Mr. Ram Avatar	9928322536	100	G+2	No	22,23
13	BC-RA/DL/0051	BC-RA-DL/0051/FF-SF	Residential	No Specific Name	59 - 60, Ramganj Market	Not Known	Not Known	100	G+2	No	24,25
14	BC-RA/DL/0052	BC-RA-DL/0052/65	Commercial	Sh. Fatehpuria Medicos	61 - 65, Ramganj Market	Mr. Prabhu Naryan Fatehpuria	Not Known	100	G+3	No	26
15	BC-RA/DL/0055	BC-RA-DL/0055/1	Commercial	Masjid	1 -2, Ramganj Market	Not Known	Not Known	100	G+3	No	27
16	BC-RA/DL/0069	BC-RA-DL/0069/83	Commercial	Rijvi Dental Clinic	83, Ramganj Market	Mr. Dr. Suhail Rizvi	Not Known	10	G+1	No	28,29
17		BC-RA-DL/0069/FF	Residential	No Specific Name		Not Known	Not Known				30,31
18	BC-RA/DL/0074	BC-RA/DL/0074/23	Commercial	No Specific Name	1 - 110, Radha Govind Complex, ManiRam Ji Ki Kothi, Ramganj Bazaar	Not Known	Not Known	10	B+G+2	No	32
19		BC-RA/DL/0074/24	Commercial	Trilok Jhandelwal		Not Known	Not Known				33,34

Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Bari Chouper and reversal line

Sl. No.	Unique ID	Sub-ID	Building Usage	Building Name	Address	Building Owner	Contact No. of Owner	Age of Building (Years)	Number of Floors	Bore Well	Front Photo Number
20	BC-RA/DL/0074	BC-RA/DL/0074/25	Commercial	Suhag Ghar	1 - 110, Radha Govind Complex, ManiRam Ji Ki Kothi, Ramganj Bazaar	Not Known	Not Known	10	B+G+2	No	35
21		BC-RA/DL/0074/26		G.D. Jewellers		Not Known	Not Known				36
22		BC-RA/DL/0074/37		Gopal Sah Kishan Sah Gote Wale Shop No. G-11		Not Known	Not Known				37
23		BC-RA/DL/0074/39		Shyam Sales, Shop No.G1/G2/G3		Mr. Ashish Goyal	8890905304				38,39,40,41
24		BC-RA/DL/0074/40		Shop No. G-4		Not Known	Not Known				42
25		BC-RA/DL/0074/41		K.K. Trading, Shop No. G-5		Not Known	Not Known				43,44
26		BC-RA/DL/0074/52		Shop No. 34/35		Not Known	9468846811				45
27		BC-RA/DL/0074/54		Roop Nikhar, Shop no. 30		Mr. Anil Ji	Not Known				46
28		BC-RA/DL/0074/55		Laxmi Banthan, Shop no. 31		Mr. Anil ji	Not Known				47



Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Bari Chouper and reversal line

Sl. No.	Unique ID	Sub-ID	Building Usage	Building Name	Address	Building Owner	Contact No. of Owner	Age of Building (Years)	Number of Floors	Bore Well	Front Photo Number
29	BC-RA/DL/0074	BC-RA/DL/0074/56	Commercial	Rathe Govind Jewellers, Shop No. F-50	T-110, Radha Govind Complex, ManiBam li	Mr. Vinod Gupta	9828014998	10	B+G+2	No	48
30		BC-RA/DL/0074/62		Shringar Centre		Not Known	Not Known				49
31		BC-RA/DL/0074/63		Siddhivinayak Creation, Shop No. 14 A		Not Known	9214325889				50
32		BC-RA/DL/0074/67		GopalSah KishanSah GoteWale Shop No.F-11		Mr. Gopal Ji	7737489871				51
33		BC-RA/DL/0074/83		Hari Krishna Sarees, Shop No. F-20, F21		Not Known	9928837032				52,53,54,55
34		BC-RA/DL/0074/84		Shree Balaji Trading Company		Mr. Mr.Bazrang Lal	9829672366				56,57
35		BC-RA/DL/0074/88		Shri Kanchan Fabrics, Shop No. F-27		Not Known	Not Known				58
36		BC-RA/DL/0074/96		Kanchan Fabrics, Shop No. S-19		Mr. Amit Parekh	9829019489				59
37		BC-RA/DL/0074/104		Mahaveer Creation, Shopn No. S-11		Mr. Ashok Ji	9828437894				60



Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Badi Chouper and reversal line

S. No.	Unique ID	Sub-ID	Building Usage	Building Name	Address	Building Owner	Contact No. of Owner	Age of Building (Years)	Number of Floors	Bore Well	Front Photo Number
38	BC-RA/DL/0074	BC-RA/DL/0074/108	Commercial	Aggrawal Creation, Shop No. 15	T-110, Radha Govind Complex, ManiPam li	Not Known	Not Known	10	B+G+2	No	61,62
39		BC-RA/DL/0074/110		Shree Shyam Enterprises		Not Known	Not Known				63
40		BC-RA/DL/0074/SF-111		S 23		Not Known	Not Known				64
41		BC-RA/DL/0074/SF-112		S 22		Not Known	Not Known				65
42		BC-RA/DL/0074/SF-113		S 38		Not Known	Not Known				66
43		BC-RA/DL/0074/SF-114		S 39		Not Known	Not Known				67
44		BC-RA/DL/0074/SF-115		S 40		Not Known	Not Known				68
45		BC-RA/DL/0074/SF-116		S 41		Not Known	Not Known				69
46		BC-RA/DL/0074/SF-117		S 42 & S 43		Not Known	Not Known				70



Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Badi Chouper and reversal line

S. No.	Unique ID	Sub-ID	Building Usage	Building Name	Address	Building Owner	Contact No. of Owner	Age of Building (Years)	Number of Floors	Bore Well	Front Photo Number
47	BC-RA/DL/0074	BC-RA/DL/0074/SF-118	Commercial	S 44 & S 45	1 - 110, Radha Govind Complex, ManiRam Ji Ki Kothi, Ramganj Bazaar	Not Known	Not Known	10	B+G+2	No	71,72
48		BC-RA/DL/0074/SF-119		S 14		Not Known	Not Known				73
49		BC-RA/DL/0074/SF-120		S 22 & S 23		Not Known	Not Known				74
50		BC-RA/DL/0074/SF-121		S 47		Not Known	Not Known				75
51		BC-RA/DL/0074/SF-122		S 48		Not Known	Not Known				76
52		BC-RA/DL/0074/SF-123		S 49		Not Known	Not Known				77
53		BC-RA/DL/0074/SF-124		S 50		Not Known	Not Known				78
54	BC-RA/DL/0075	BC-RA/DL/0075/05 (G)	Commercial	Closed Shop No.101	H.No.223, Rasta Thakur Pachewar, Ramganj Bazar	Not Known	Not Known	100	B+G+3	No	79
55		BC-RA/DL/0075/07 (G)		Closed Shop No.103		Not Known	Not Known				80



Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Badi Chouper and reversal line

Sl. No.	Unique ID	Sub-ID	Building Usage	Building Name	Address	Building Owner	Contact No. of Owner	Age of Building (Years)	Number of Floors	Bore Well	Front Photo Number
56	BC-RA/DL/0075	BC-RA/DL/0075/08 (G)	Commercial	Hayat Creations Shop No.104	H.No.223,Ra sta Thakur Pachewar,Ra mganj Bazar	Not Known	Not Known	100	B+G+3	No	81
57		BC-RA/DL/0075/09 (G)		Closed Shop No.105		Not Known	Not Known				82
58		BC-RA/DL/0075/16 (G)		Closed Shop No.116		Not Known	Not Known				83
59		BC-RA/DL/0075/17 (G)		Namkeen Shop		Mr. Gopalji	Gopalji				84
60		BC-RA/DL/0075/19 (G)		Closed Shop No.125		Not Known	Not Known				85
61		BC-RA/DL/0075/20 (G)		Closed Shop No.124		Not Known	Not Known				86
62		BC-RA/DL/0075/B/02		Closed Shop No.2		Not Known	Not Known				87
63		BC-RA/DL/0075/B/05		Closed Shop No.5		Mr. Manisha	Not Known				88
64		BC-RA/DL/0075/B/06		Closed Shop No.6		Not Known	Not Known				89



Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Badi Chouper and reversal line

SL. No.	Unique ID	Sub-ID	Building Usage	Building Name	Address	Building Owner	Contact No. of Owner	Age of Building (Years)	Number of Floors	Bore Well	Front Photo Number
65	BC-RA/DL/0075	BC-RA/DL/0075/B/07	Commercial	Closed Shop No.7	H.No.223,Ra sta Thakur Pachewar,Ra mganj Bazar	Not Known	Not Known	100	B+G+3	No	90
66		BC-RA/DL/0075/B/10		Closed Shop No.10		Not Known	Not Known				91
67		BC-RA/DL/0075/B/11		Nosheen Colonisers Shop No.11		Not Known	Not Known				92
68		BC-RA/DL/0075/B/12		Nosheen Colonisers Shop No.12		Not Known	Not Known				93
69		BC-RA/DL/0075/FF/01		Lungi Corner, Godown, Shop No. 214		Mr. Faqar Md.	Not Known				94
70		BC-RA/DL/0075/FF/02		Sagar Sari Centre Godown, Shop No. 215		Not Known	Not Known				95
71		BC-RA/DL/0075/FF/04		Closed Shop No. 217		Not Known	Not Known				96
72		BC-RA/DL/0075/FF/05		Closed Shop No. 218		Not Known	Not Known				97
73		BC-RA/DL/0075/FF/06		Closed Shop No. 219		Not Known	Not Known				98



Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Badi Chouper and reversal line

S. No.	Unique ID	Sub-ID	Building Usage	Building Name	Address	Building Owner	Contact No. of Owner	Age of Building (Years)	Number of Floors	Bore Well	Front Photo Number
74	BC-RA/DL/0075	BC-RA/DL/0075/FF/07	Commercial	Closed Shop No. 220	H.No.223,Ra sta Thakur Pachewar,Ra mganj Bazar	Not Known	Not Known	100	B+G+3	No	99
75		BC-RA/DL/0075/FF/08		Closed Shop No. 221		Not Known	Not Known				100
76		BC-RA/DL/0075/FF/10		Helping Hand Foundation, Shop No. 223		Not Known	Not Known				101
77		BC-RA/DL/0075/FF/11		Closed Shop No. 224		Not Known	Not Known				102
78		BC-RA/DL/0075/FF/12		Closed Shop No. 225		Not Known	Not Known				103
79		BC-RA/DL/0075/FF/15		Closed Shop No. 203		Not Known	Not Known				104
80		BC-RA/DL/0075/FF/16		Closed Shop No. 204		Not Known	Not Known				105
81		BC-RA/DL/0075/FF/18		Closed Shop No. 206		Not Known	Not Known				106
82		BC-RA/DL/0075/FF/21		Farid Textiles Godown, Shop No. 210		Not Known	Not Known				107





Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Badi Chouper and reversal line

S. No.	Unique ID	Sub-ID	Building Usage	Building Name	Address	Building Owner	Contact No. of Owner	Age of Building (Years)	Number of Floors	Bore Well	Front Photo Number
83	BC-RA/DL/0075	BC-RA/DL/0075/FF/22	Commercial	Lungi Corner, Godown, Shop No. 211	H.No.223, Rasta Thakur Pachewar, Ramganj Bazar	Not Known	Not Known	100	B+G+3	No	108
84		BC-RA/DL/0075/FF/23		Abdul Hameed, Shop No.212		Mr. Abdul Hameed	982948806				109
85		BC-RA/DL/0075/FF/24		Closed Shop No. 213		Not Known	Not Known				110
86		BC-RA/DL/0075/FF/25		Closed Shop No. 207		Not Known	Not Known				111
87		BC-RA/DL/0075/SF/02		Jaipur Jems & Crafts, Shop No. 302 & 303		Mr. Aziza Begum	2567804				112
88		BC-RA/DL/0075/SF/03		Emerated Gems of India		Mr. Ansar Ahmad Mukhtar Ahmad	Not Known				113
89		BC-RA/DL/0075/SF/06		Closed Shop No. 308		Not Known	Not Known				114
90		BC-RA/DL/0075/SF/07		Closed Shop No. 309		Not Known	Not Known				115
91		BC-RA/DL/0075/SF/08		Basiruddin Ahmad, Shop No. 310		Mr. Basiruddin Ahmad	9928823172				116



Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Badi Chouper and reversal line

Sl. No.	Unique ID	Sub-ID	Building Usage	Building Name	Address	Building Owner	Contact No. of Owner	Age of Building (Years)	Number of Floors	Bore Well	Front Photo Number
92	BC-RA/DL/0075	BC-RA/DL/0075/SF/09	Commercial	Closed Shop No. 311	H.No.223, Rasta Thakur Pachewar, Ramganj Bazar	Not Known	Not Known	100	B+G+3	No	117
93		BC-RA/DL/0075/SF/10		Closed Shop No. 312		Not Known	Not Known				118
94		BC-RA/DL/0075/SF/11		Closed Shop No. 313		Not Known	Not Known				119
95		BC-RA/DL/0075/SF/12		Closed Shop No. 314		Not Known	Not Known				120
96		BC-RA/DL/0075/SF/13		Closed Shop No. 315		Not Known	Not Known				121
97		BC-RA/DL/0075/SF/14		Closed Shop No. 316		Not Known	Not Known				122
98		BC-RA/DL/0075/SF/16		Closed Shop No. 318		Not Known	Not Known				123
99		BC-RA/DL/0075/SF/17		Closed Shop No. 319		Not Known	Not Known				124
100		BC-RA/DL/0075/SF/19		Closed Shop No. 321		Not Known	Not Known				125
101		BC-RA/DL/0075/TF/01		Amir Gems Godown, Shop No. 414		Not Known	23101322				126



Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Badi Chouper and reversal line

Sl. No.	Unique ID	Sub-ID	Building Usage	Building Name	Address	Building Owner	Contact No. of Owner	Age of Building (Years)	Number of Floors	Bore Well	Front Photo Number
102	BC-RA/DL/0075	BC-RA/DL/0075/TF/02	Commercial	Closed Shop No. 315	H.No.223,Ra sta Thakur Pachewar,Ramganj Bazar	Not Known	Not Known	100	B+G+3	No	127
103		BC-RA/DL/0075/TF/03		Mohd. Anees Advocate Office, Shop No. 416		Not Known	Not Known				128
104		BC-RA/DL/0075/TF/04		Closed Shop No. 417		Not Known	Not Known				129
105		BC-RA/DL/0075/TF/06		Closed Shop No. 419		Not Known	Not Known				130
106		BC-RA/DL/0075/TF/07		Closed Shop No. 420		Not Known	Not Known				131
107		BC-RA/DL/0075/TF/08		Closed Shop No. 421		Not Known	Not Known				132
108		BC-RA/DL/0075/TF/09		Closed Shop No. 422		Not Known	Not Known				133
109		BC-RA/DL/0075/TF/10		Closed Shop No. 423		Not Known	Not Known				134
110		BC-RA/DL/0075/TF/11		Closed Shop No. 424		Not Known	Not Known				135



Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Badi Chouper and reversal line

Sl. No.	Unique ID	Sub-ID	Building Usage	Building Name	Address	Building Owner	Contact No. of Owner	Age of Building (Years)	Number of Floors	Bore Well	Front Photo Number
111	BC-RA/DL/0075	BC-RA/DL/0075/TF/12	Commercial	Closed Shop No. 425	H.No.223,Ra sta Thakur Pachewar,Ra mganj Bazar	Not Known	Not Known	100	B+G+3	No	136
112		BC-RA/DL/0075/TF/13		Closed Shop No. 401		Not Known	Not Known				137
113		BC-RA/DL/0075/TF/15		Closed Shop No. 403		Not Known	Not Known				138
114		BC-RA/DL/0075/TF/17		Closed Shop No. 405		Not Known	Not Known				139
115		BC-RA/DL/0075/TF/18		Closed Shop No. 406		Not Known	Not Known				140
116		BC-RA/DL/0075/TF/20		Closed Shop No. 408		Not Known	Not Known				141
117		BC-RA/DL/0075/TF/21		Closed Shop No. 409		Not Known	Not Known				142
118		BC-RA/DL/0075/TF/25		S.M. Enterprises Shop No. 413		Not Known	9352419188				143

Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Bari Chouper and reversal line



Photo No. 1



Photo No. 2



Photo No. 3



Photo No. 4



Photo No. 5



Photo No. 6



Photo No. 7



Photo No. 8



Photo No. 9

Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Bari Chouper and reversal line



Photo No. 10



Photo No. 11



Photo No. 12



Photo No. 13



Photo No. 14



Photo No. 15



Photo No. 16



Photo No. 17



Photo No. 18

Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Bari Chouper and reversal line



Photo No. 19



Photo No. 20



Photo No. 21



Photo No. 22



Photo No. 23



Photo No. 24



Photo No. 25



Photo No. 26



Photo No. 27

Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Bari Chouper and reversal line



Photo No. 28



Photo No. 29



Photo No. 30



Photo No. 31



Photo No. 32



Photo No. 33



Photo No. 34



Photo No. 35



Photo No. 36

Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Bari Chouper and reversal line



Photo No. 37



Photo No. 38



Photo No. 39



Photo No. 40



Photo No. 41



Photo No. 42



Photo No. 43



Photo No. 44



Photo No. 45

Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Bari Chouper and reversal line



Photo No. 46



Photo No. 47



Photo No. 48



Photo No. 49



Photo No. 50



Photo No. 51



Photo No. 52



Photo No. 53



Photo No. 54

Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Bari Chouper and reversal line



Photo No. 55



Photo No. 56



Photo No. 57



Photo No. 58



Photo No. 59



Photo No. 60



Photo No. 61



Photo No. 62



Photo No. 63

Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Bari Chouper and reversal line



Photo No. 64



Photo No. 65



Photo No. 66



Photo No. 67



Photo No. 68



Photo No. 69



Photo No. 70



Photo No. 71



Photo No. 72

Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Bari Chouper and reversal line



Photo No. 73



Photo No. 74



Photo No. 75



Photo No. 76



Photo No. 77



Photo No. 78



Photo No. 79



Photo No. 80



Photo No. 81

Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Bari Chouper and reversal line



Photo No. 82



Photo No. 83



Photo No. 84



Photo No. 85



Photo No. 86



Photo No. 87



Photo No. 88



Photo No. 89



Photo No. 90

Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Bari Chouper and reversal line



Photo No. 91



Photo No. 92



Photo No. 93



Photo No. 94



Photo No. 95



Photo No. 96



Photo No. 97



Photo No. 98



Photo No. 99

Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Bari Chouper and reversal line



Photo No. 100



Photo No. 101



Photo No. 102



Photo No. 103



Photo No. 104



Photo No. 105



Photo No. 106



Photo No. 107



Photo No. 108

Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Bari Chouper and reversal line



Photo No. 109



Photo No. 110



Photo No. 111



Photo No. 112



Photo No. 113



Photo No. 114



Photo No. 115



Photo No. 116



Photo No. 117

Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Bari Chouper and reversal line



Photo No. 118



Photo No. 119



Photo No. 120



Photo No. 121



Photo No. 122



Photo No. 123



Photo No. 124



Photo No. 125



Photo No. 126

Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Bari Chouper and reversal line



Photo No. 127



Photo No. 128



Photo No. 129



Photo No. 130



Photo No. 131



Photo No. 132



Photo No. 133



Photo No. 134



Photo No. 135

Locked Report of Pre - Condition Building Survey for Construction of Underground Section from Chandpole to Bari Chouper and reversal line



Photo No. 136



Photo No. 137



Photo No. 138



Photo No. 139



Photo No. 140



Photo No. 141



Photo No. 142



Photo No. 143